










Re-Inspection-Report_TFSAFE_5VN8M_11200_102_17-01-22			
Base Location	JTC	Date:	17-Jan-22
Base Code	5VN8M	Team #:	102
Camp Name-BLD #	11200	System Voltage	230/400
Building Type	Office	Inspection Phase	Re Inspection
Previous Report #:	Inspection-Report_TFSAFE_5VN8M_11200_102_20-11-21_63-69		
Physical Building Location Description:	Mayor cell building.		
	Overall Building Electrical System:		Fair
Building Picture:	Inspector Name: Liam McCormack		
	Signed:		
	Inspector Name:		Matthew Stead
	Signed:		
	QC Name:		Brian Thornton
	Signed:		
LHS Deficiencies:			
Deficiency Number:	63	RAC 2	Description of Deficiency Location:
	Air-conditioning units 1-9		
	Number of Occurrences		9
	Deficiency Category :		Improper Use / Damaged
	Equipment Category:		WLT
	Imminent Danger?		No
	If 'Yes' : Action Taken:		N/A
	SOR Issued To:		O&M Provider
Description of Deficiency: (or Mitigated State)	The rotary isolators compression glands are showing signs of deterioration.		
Code Source:	BritishStandard	Deficiency Status:	ReInsp-Open
Code Reference:	642: Inspection		
Deficiency Number:	64	RAC 2	Description of Deficiency Location:
	Throughout exterior of building.		
	Number of Occurrences		64
	Deficiency Category :		Unlisted Equipment
	Equipment Category:		WLT
	Imminent Danger?		No
	If 'Yes' : Action Taken:		N/A
	SOR Issued To:		O&M Provider
Description of Deficiency: (or Mitigated State)	Some conductors installed have no visible listings compliant to BS7671 regulations.		
Code Source:	BritishStandard	Deficiency Status:	ReInsp-Open
Code Reference:	511: Compliance with standards		

Deficiency Number: 65		RAC 2	Description of Deficiency Location:	
		Rear wall		
		Number of Occurrences		1
		Deficiency Category :		Unlisted Equipment
		Equipment Category:		WLT
		Imminent Danger?		No
		If 'Yes' : Action Taken:		N/A
		SOR Issued To:		O&M Provider
Description of Deficiency:		The light fixture installed has no visible listings compliant to BS7671		
(or Mitigated State)		regulations. Potentially counterfeit.		
Code Source:		BritishStandard	Deficiency Status: ReInsp-Open	
Code Reference:		511: Compliance with standards		
Deficiency Number: 66		RAC 2	Description of Deficiency Location:	
		Rear wall.		
		Number of Occurrences		1
		Deficiency Category :		Improper Use / Damaged
		Equipment Category:		WLT
		Imminent Danger?		No
		If 'Yes' : Action Taken:		N/A
		SOR Issued To:		O&M Provider
Description of Deficiency:		The conduit is not fully supported.		
(or Mitigated State)				
Code Source:		BritishStandard	Deficiency Status: Closed / Repaired	
Code Reference:		522: Selection and erection of wiring systems in relation to external influences		
Deficiency Number: 67		RAC 3	Description of Deficiency Location:	
		Rear wall.		
		Number of Occurrences		1
		Deficiency Category :		Poor Workmanship
		Equipment Category:		WLT
		Imminent Danger?		No
		If 'Yes' : Action Taken:		N/A
		SOR Issued To:		Task Force SAFE
Description of Deficiency:		The IP rated junction boxes lid was not installed correctly. Repaired by TFS.		
(or Mitigated State)				
Code Source:		BritishStandard	Deficiency Status: Closed Previously	
Code Reference:		522: Selection and erection of wiring systems in relation to external influences		

Deficiency Number:	68	RAC 2	Description of Deficiency Location:
	Air-conditioning units 1-7		
	Number of Occurrences		7
	Deficiency Category :	Improper Use / Damaged	
	Equipment Category:	WLT	
	Imminent Danger?	No	
	If 'Yes' : Action Taken:	N/A	
SOR Issued To:		O&M Provider	
Description of Deficiency:	The flexible cables feeding the AC units are showing signs of deterioration.		
(or Mitigated State)			
Code Source:	BritishStandard	Deficiency Status:	ReInsp-Open
Code Reference:			
Deficiency Number:	69	RAC 2	Description of Deficiency Location:
	Air-conditioning units 1- 9		
	Number of Occurrences		9
	Deficiency Category :	Improper Use / Damaged	
	Equipment Category:	WLT	
	Imminent Danger?	No	
	If 'Yes' : Action Taken:	N/A	
SOR Issued To:		O&M Provider	
Description of Deficiency:	The flexible cable installed seems to be not listed for outside use.		
(or Mitigated State)			
Code Source:	BritishStandard	Deficiency Status:	ReInsp-Open
Code Reference:	522: Selection and erection of wiring systems in relation to external influences		
Deficiency Number:	70	RAC	Description of Deficiency Location:
	Number of Occurrences		
	Deficiency Category :		
	Equipment Category:		
	Imminent Danger?		
	If 'Yes' : Action Taken:		
SOR Issued To:			
Description of Deficiency:			
(or Mitigated State)			
Code Source:		Deficiency Status:	
Code Reference:			

Re-Inspection-Report_TFSAFE_5VN8M_11200_102_17-01-22			
Base Location	JTC	Date:	17-Jan-22
Base Code	5VN8M	Team #:	102
Camp Name-BLD #	11200	System Voltage	230/400
Building Type	Office	Inspection Phase	Re Inspection
Previous Report #:	Inspection-Report_TFSAFE_5VN8M_11200_102_20-11-21_63-69		
Physical Building Location Description:	Mayor cell building.		
Overall Building Electrical System:			Fair
Building Picture:	Inspector Name:	Liam McCormack	
	Signed:		
	Inspector Name:	Matthew Stead	
	Signed:		
	QC Name:	Brian Thornton	
	Signed:		
Summary of Findings:			
<p>Air-conditioning units show now listings compliant with BS7671, Some conductor identifications are un-haronized to BS7671 (18th Edition)</p>			