

## PIC18F97J60 Family Silicon Errata and Data Sheet Clarification

The PIC18F97J60 Family devices that you have received conform functionally to the current Device Data Sheet (DS39762F), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC18F97J60 Family silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A3**).

Data Sheet clarifications and corrections start on [page 8](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
  - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC18F97J60 Family silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

| Part Number | Device ID     | DEVICE IDs <sup>(1),(2)</sup> |        |        |        |
|-------------|---------------|-------------------------------|--------|--------|--------|
|             |               | Silicon Revision ID           |        |        |        |
|             |               | A0                            | A1     | A2     | A3     |
| PIC18F66J60 | 0001 1000 000 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F66J65 | 0001 1111 000 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F67J60 | 0001 1111 001 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F86J60 | 0001 1000 001 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F86J65 | 0001 1111 010 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F87J60 | 0001 1111 011 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F96J60 | 0001 1000 010 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F96J65 | 0001 1111 100 | 0000                          | 0 0001 | 0 0001 | 0 0011 |
| PIC18F97J60 | 0001 1111 101 | 0000                          | 0 0001 | 0 0001 | 0 0011 |

**Note 1:** The Device IDs (DEVID1 and DEVUD2) are located at addresses 3 FFFFh:3FFFFh, in the device configuration space. They are shown in binary in the format: 'DEVID2 DEVID1'.

**2:** Refer to the "PIC18F97J60 Family Flash Microcontroller Programming Specification" (DS39688) for detailed information on Device and Revision IDs for your specific device.

# PIC18F97J60 FAMILY

**TABLE 2: SILICON ISSUE SUMMARY**

| Module                              | Feature                      | Item Number | Issue Summary  | Affected Revisions <sup>(1)</sup> |    |    |    |
|-------------------------------------|------------------------------|-------------|--|-----------------------------------|----|----|----|
|                                     |                              |             |  | A0                                | A1 | A2 | A3 |
| Resets                              | SFR Reset values             | 1.          | MCLR and BOR Resets behave as POR Reset  | X                                 | X  | X  | X  |
| I/O (PORTJ)                         | Port pin's impedance state   | 2.          | PORTJ pins do not go to high-impedance state after POR Reset   | X                                 | X  | X  | X  |
| I/O (PORTJ) and External Memory Bus | External Memory Bus          | 3.          | In EMB mode PORTJ pins are not driven to Idle state  | X                                 | X  | X  | X  |
| Ethernet (Buffer Memory)            | Buffer memory corruption     | 4.          | When an even address is loaded to the ERXRPT registers, then the circular receive buffer may be corrupt  | X                                 | X  | X  | X  |
| Ethernet (MIIM)                     | PHY register corruption      | 5.          | MIWRL register written to PHY register through the MIIM interface can cause corruption                   | X                                 | X  | X  | X  |
| Ethernet (RX Filter)                | Receive Filter Pattern Match | 6.          | RX filter may allow some packets with an incorrect data pattern to be received                           | X                                 | X  | X  | X  |
| Ethernet (TX)                       | Timing collision             | 7.          | When operating in Half-Duplex mode, the transmit operation can encounter unusual collision timing        | X                                 | X  | X  | X  |
| Ethernet (DMA)                      | IP Checksum computation      | 8.          | DMA configured to compute an IP Checksum, incoming packet receive event can cause an internal deadlock   | X                                 | X  | X  | X  |
| I/O (PORTJ)                         | Weak pull-up on Port pins    | 9.          | RJ4 and RJ5 weak internal pull-up cannot be enabled  | X                                 | X  | X  | X  |
| Timer1/3                            | Timer1/3 Asynchronous mode   | 10.         | Timer 1/3 operation in Asynchronous External Input mode operation can cause an unexpected interrupt flag | X                                 | X  | X  | X  |

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

## Silicon Errata Issues

### 1. Module: Resets

MCLR and BOR Resets behave as a POR Reset. Special Function Registers' Reset values after a MCLR or BOR would have the same values as those after a POR. All other Resets behave as described in the data sheet.

#### Work around

None.

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

### 2. Module: I/O (PORTJ)

**Note:** This issue is only applicable to the 100-pin device.

When configured to operate in Microcontroller mode (CONFIG3L<EMB1:0> = 11), PORTJ pins do not go to a high-impedance state immediately after a POR Reset. Instead, PORTJ<4,0> are driven low, while all other PORTJ pins are driven high, until the device exits the Reset condition (refer to **Section 4.6.1 "Time-out Sequence"** of the Device Data Sheet for details on when the device exits the Reset condition) before transitioning to a high-impedance state. Note that since MCLR and BOR Resets are also treated as a POR Reset (see Errata Issue #1), PORTJ pins will also be driven as outputs until the device exits these Reset conditions.

#### Work around

If using a PORTJ pin as an input, make sure to check that your circuit will not create a short-circuit condition during a Reset. For example, if you need to have a direct pull-down to ground input, do this on PORTJ<4> or PORTJ<0>, since they are temporary driven low. If using a PORTJ pin as an output, then use a pin that will temporarily drive low for driving active-high loads, and use a pin that temporarily will drive high for driving active-low loads. This way, the temporary output signals are in the Idle state.

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

### 3. Module: I/O (PORTJ) and External Memory Bus

**Note:** This issue is only applicable to the 100-pin device.

In an Extended Microcontroller mode (CONFIG3L<EMB1:0> = 00, 01 or 10), each control signal on PORTJ is supposed to be driven to its Idle state. However, the control signals on PORTJ pins go to a high-impedance state for a brief interval after a MCLR Reset. The brief loss of control signals may cause the corruption of data in memory devices connected to the External Memory Bus (EMB).

#### Work around

To maintain the default states on the control lines, use pull-up or pull-down resistors on all PORTJ pins (pull-down on PORTJ<4,0>, pull-up on all others).

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

# PIC18F97J60 FAMILY

## 4. Module: Ethernet (Buffer Memory)

The receive hardware may corrupt the circular receive buffer (including the Next Packet Pointer and receive status vector fields) when an even value is programmed into the ERXRDPH:ERXRPTL registers.

### Work around

Ensure that only odd addresses are written to the ERXRDP registers. Assuming that ERXND contains an odd value, many applications can derive a suitable value to write to ERXRDP by subtracting 1 from the Next Packet Pointer (a value always ensured to be even because of hardware padding) and then compensating for a potential ERXST to ERXND wrap-around.

Assuming that the receive buffer area does not span the 1FFFh to 0000h memory boundary, the logic in [Example 1](#) will ensure that ERXRDP is programmed with an odd value.

### EXAMPLE 1: WRITING OLD ADDRESSES TO ERXRDP

```
if (Next Packet Pointer - 1 < ERXST) or
   (Next Packet Pointer - 1 > ERXND)
then:
  ERXRDP = ERXND
else:
  ERXRDP = Next Packet Pointer - 1
```

### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

## 5. Module: Ethernet (MIIM)

When writing to any PHY register through the MIIM interface's MIWRL and MIWRH registers, the low byte actually written to the PHY register may be corrupted. The corruption occurs when the following actions are taken:

- The application writes to MIWRL
- The PIC® MCU core executes any instruction that reads or writes to any memory address that has the Least Significant six address bits of 36h (`'b110110`)
- The application writes to MIWRH

For example, the following sequence will result in a corrupted write to a PHY register:

|       |              |
|-------|--------------|
| MOVFF | 0xCF5, MIWRL |
| NOP   |              |
| MOVFF | 0xCF6, MIWRH |

In this example, 0xCF5 and 0xCF6 are GPR memory locations that the application wishes to write to the current PHY register defined by the MIREGADR SFR. When the PIC MCU core reads from the GPR at address, 0xCF6 (`'b110011110110`), the value originally written to MIWRL will be corrupted.

### Work around 1

Ensure that following a write to MIWRL, the firmware does not access any of the problem memory locations prior to writing to MIWRH. After finished writing to MIWRH, normal operation can resume.

If interrupts are enabled, disable them prior to writing to MIWRL and MIWRH to prevent an Interrupt Service Routine (ISR) from performing any reads or writes to a problem memory address.

Special care must be taken to ensure that the source data to be written to MIWRH does not result in a problem memory access.

The following PHY write sequence avoids the problem:

1. Copy the low byte to be written to the PHY into the PRODL register.  
PRODL is at address, FF3h, and not subject to the memory address issue.
2. Copy the high byte to be written to the PHY into the PRODH register.  
PRODH is at address, FF4h, and not subject to the memory address issue.
3. Disable all interrupts by clearing GIEH and GIEL in the INTCON register.
4. Move PRODL into MIWRL.
5. Wait one instruction cycle as required by the MAC host interface logic.
6. Move PRODH into MIWRH.
7. Enable all interrupts that are needed by restoring GIEH and GIEL in INTCON.

### Work around 2

If you cannot disable interrupts, as specified in **Work around 1**, because the application cannot tolerate interrupt latency variations:

- Perform the write (with interrupts enabled), but
- Verify the correct values were written by reading the PHY register

If a corrupted value was written due to an interrupt occurring, perform the write again and reverify. The source data must be stored in a non-problem location.

The application should follow the following procedure:

1. Copy the low byte to be written to the PHY into the PRODL register.  
PRODL is at address, FF3h, and not subject to the memory address issue.
2. Copy the high byte to be written to the PHY into the PRODH register.  
PRODH is at address, FF4h, and not subject to the memory address issue.
3. Move PRODL into MIWRL.
4. Wait one instruction cycle as required by the MAC host interface logic.
5. Move PRODH into MIWRH.
6. Wait two T<sub>cy</sub> and then poll the BUSY bit (MISTAT<0>) until it is clear.
7. Perform a PHY register read of the same location.
8. Compare the read result with the original value copied to the PRODH:PRODL registers. If they do not match, return to step 1.

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

## 6. Module: Ethernet (RX Filter)

When enabled, the Pattern Match receive filter may allow some packets with an incorrect data pattern to be received. Also, in certain configurations, packets with a valid pattern may be incorrectly discarded.

#### Work around

Do not use the Pattern Match hardware filter. Instead, use the Unicast, Multicast, Broadcast and Hash Table receive filters to accept all needed packets and filter out unwanted ones in software.

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

## 7. Module: Ethernet (TX)

When configured for half duplex and a transmit operation encounters unusual collision timing, there is a small chance that the Ethernet transmit engine will internally deadlock. The PHY will stop transmitting the packet and normal RX operations will continue. However, the TXRTS bit (ECON1<3>) will stay set indefinitely. The TXIF (EIR<3>) and TXERIF (EIR<1>) bits will not become set.

This deadlock condition applies only to half-duplex operation and is most readily observable when the network has a duplex mismatch (i.e., PIC18F97J60 family device is configured for half duplex and the remote node is configured for full duplex). In most cases, high network utilization is needed to observe the issue.

#### Work around

To prevent most transmit deadlock conditions, issue a TX Logic Reset prior to transmitting each packet:

1. Set TXRST (ECON1<7>).
2. Clear TXRST.
3. Wait 1.6  $\mu$ s or longer.
4. Set TXRTS to start the transmission.

Issuing a TX Logic Reset may cause the Ethernet transmit error interrupt to occur and the associated TXERIF bit to become set, which can be ignored.

To detect and recover from any possible deadlock conditions, applications should implement a timer to poll the TXRTS bit. If the Ethernet hardware enters the deadlock state and fails to clear this bit by the time the timer expires, software should manually clear the TXRTS bit, issue a TX Logic Reset and then set the TXRTS bit to retry transmission. The timer should be cleared and restarted whenever the application sets TXRTS. The timer expiration time should be chosen to allow adequate time for ordinary packets to finish transmitting, after accounting for possible delays, due to the medium being occupied by other nodes. For example, a time-out value of 3 ms is suitable since it will allow a maximum length 1518-byte packet to be transmitted at 10Base-T speeds, while giving reasonable margin to account for potential collisions.

#### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

# PIC18F97J60 FAMILY

## 8. Module: Ethernet (DMA)

When the DMA is configured to compute an IP checksum, there is a small chance that an incoming packet receive event will cause the DMA to internally deadlock. In these cases, the DMAST bit (ECON1<5>) stays set indefinitely, and the DMA done interrupt never occurs.

### **Work around**

Perform checksum calculations in software. Use the DMA only for copy operations.

### **Affected Silicon Revisions**

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

## 9. Module: I/O (PORTJ)

**Note:** This issue is only applicable to the 80-pin device.

The weak internal pull-up resistors on pins, RJ4 and RJ5, cannot be enabled on the PIC18F86J60, PIC18F86J65 and PIC18F87J60 devices. Setting the RJPU bit (PORTA<7>) has no effect on the I/O pin state.

### **Work around**

Install external pull-up resistors on RJ4 and RJ5. Alternatively, use any of the PORTB, PORTD or PORTE pins, which all have weak internal pull ups.

### **Affected Silicon Revisions**

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

## 10. Module: Timer1/3

When Timer1 or Timer3 is operated in Asynchronous External Input mode, unexpected interrupt flag generation may occur if an external clock edge arrives too soon following a firmware write to the TMRxH:TMRxL registers. An unexpected interrupt flag event may also occur when enabling the module or switching from Synchronous to Asynchronous mode.

### **Work around**

This issue only applies when operating the timer in Asynchronous mode. Whenever possible, operate the timer module in Synchronous mode to avoid spurious timer interrupts.

If Asynchronous mode must be used in the application, potential strategies to mitigate the issue may include any of the following:

- Design the firmware so it does not rely on the TMRxIF flag or keep the respective interrupt disabled. The timer still counts normally and does not reset to 0x0000 when the spurious interrupt flag event is generated.
- Design the firmware so that it does not write to the TMRxH:TMRxL registers or does not periodically disable/enable the timer, or switch modes. Reading from the timer does not trigger the spurious interrupt flag events.
- If the firmware must use the timer interrupts and must write to the timer (or disable/enable, or mode switch the timer), implement code to suppress the spurious interrupt event, should it occur. This can be achieved by following the process shown in [Example 2](#).

## EXAMPLE 2: ASYNCHRONOUS TIMER MODE WORK AROUND TO AVOID SPURIOUS INTERRUPT

```
//Timer1 update procedure in asynchronous mode
//The code below uses Timer1 as example

T1CONbits.TMR1ON = 0;           //Stop timer from incrementing
PIE1bits.TMR1IE = 0;           //Temporarily disable Timer1 interrupt vectoring
TMR1H = 0x00;                   //Update timer value
TMR1L = 0x00;
T1CONbits.TMR1ON = 1;           //Turn on timer

//Now wait at least two full T1CKI periods + 2TCY before re-enabling Timer1 interrupts.
//Depending upon clock edge timing relative to TMR1H/TMR1L firmware write operation,
//a spurious TMR1IF flag event may sometimes assert. If this happens, to suppress
//the actual interrupt vectoring, the TMR1IE bit should be kept clear until
//after the "window of opportunity" (for the spurious interrupt flag event has passed).
//After the window is passed, no further spurious interrupts occur, at least
//until the next timer write (or mode switch/enable event).

while(TMR1L < 0x02);            //Wait for 2 timer increments more than the Updated Timer
                                //value (indicating more than 2 full T1CKI clock periods elapsed)
NOP();                          //Wait two more instruction cycles
NOP();

PIR1bits.TMR1IF = 0;            //Clear TMR1IF flag, in case it was spuriously set
PIE1bits.TMR1IE = 1;            //Now re-enable interrupt vectoring for timer 1
```

### Affected Silicon Revisions

| A0 | A1 | A2 | A3 |  |  |  |  |
|----|----|----|----|--|--|--|--|
| X  | X  | X  | X  |  |  |  |  |

# PIC18F97J60 FAMILY

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39762F).

**Note:** Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

## 1. Module: Thermal Packaging Characteristics

The thermal packaging characteristics are the following

**TABLE 3: THERMAL PACKAGING CHARACTERISTICS**

| Package | Pin Count | Package Body Size | Thermal Resistance Estimates (°C/W) <sup>(3)</sup> |  |
|---------|-----------|-------------------|--|--|
|         |           |                   | $\theta_{JA}$ (typical) <sup>(1)</sup>             | $\theta_{JC}$ (typical) <sup>(2)</sup> |
| TQFP    | 64        | 10x10x1           | 48.3   | 26.1                                   |
| TQFP    | 80        | 12x12x1           | 48.0   | 22.5                                   |
| TQFP    | 100       | 12x12x1           | 45   | 19.7                                   |
| TQFP    | 100       | 14x14x1           | 43   | 22.5                                   |

- Note 1:** Junction to ambient thermal resistance, Theta-JA ( $\theta_{JA}$ ) numbers are achieved by package simulations at 0m/s airflow (worst-case condition).
- 2:** Junction to case thermal resistance, Theta-JC ( $\theta_{JC}$ ) numbers are achieved by package simulations defined at the top center of the package (hottest point).
- 3:** Estimates only; dependent on many factors.
- 4:** Theta-JA ( $\theta_{JA}$ ) and Theta-JC ( $\theta_{JC}$ ) numbers is package specific and not device specific.

## 2. Module: Internal Voltage Regulator Specifications

In [Table 28-4](#), the minimum external filter capacitor should be 4.7  $\mu$ F:

**TABLE 28-4: INTERNAL VOLTAGE REGULATOR SPECIFICATIONS**

| Operating Conditions: $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ (unless otherwise stated) |        |                                 |            |      |      |         |  |
|---|--------|---------------------------------|------------|------|------|---------|--|
| Param No.   | Sym.   | Characteristics                 | Min.       | Typ. | Max. | Units   | Comments   |
|   | VRGOUT | Regulator Output Voltage        | —          | 2.5  | —    | V       |  |
|   | CF     | External Filter Capacitor Value | <b>4.7</b> | 10   | —    | $\mu$ F | <b>Capacitor must be low ESR, a low series resistance (&lt;5<math>\Omega</math>)</b> |



# PIC18F97J60 FAMILY

## 3. Module: Clock and I/O Timing Requirements

In Table 28-10, the values in 'Typ.' column for 164 and 166 parameters have modified as follows:

**TABLE 28-10: CLKO AND I/O TIMING REQUIREMENTS**

| Param. No | Symbol   | Characteristics  | Min.                | Typ.                            | Max.                | Units |
|-----------|----------|--|---------------------|---------------------------------|---------------------|-------|
| 150       | TadV2alL | Address Out Valid to ALE ↓<br>(address setup time)                         | $0.25 T_{CY} - 10$  | —                               | —                   | ns    |
| 151       | TalL2adI | ALE ↓ to Address Out Invalid<br>(address hold time)                        | 5                   | —                               | —                   | ns    |
| 155       | TalL2oeL | ALE ↓ to $\overline{OE}$ ↓   | 10                  | $0.125 T_{CY}$                  | —                   | ns    |
| 160       | TadZ2oeL | AD high-Z to $\overline{OE}$ ↓ (bus release to $\overline{OE}$ )           | 0                   | —                               | —                   | ns    |
| 161       | ToeH2adD | $\overline{OE}$ ↑ to AD Driven   | $0.125 T_{CY} - 5$  | —                               | —                   | ns    |
| 162       | TadV2oeH | Least Significant Data Valid before $\overline{OE}$ ↑<br>(data setup time) | 20                  | —                               | —                   | ns    |
| 163       | ToeH2adI | $\overline{OE}$ ↑ to Data In Invalid (data hold time)                      | 0                   | —                               | —                   | ns    |
| 164       | TalH2alL | ALE Pulse Width  | —                   | <b><math>0.25 T_{CY}</math></b> | —                   | ns    |
| 165       | ToeL2oeH | $\overline{OE}$ Pulse Width  | $0.5 T_{CY} - 5$    | $0.5 T_{CY}$                    | —                   | ns    |
| 166       | TalH2alH | ALE ↑ to ALE ↑ (cycle time)  | —                   | <b><math>T_{CY}</math></b>      | —                   | ns    |
| 167       | Tacc     | Address Valid to Data Valid  | $0.75 T_{CY} - 25$  | —                               | —                   | ns    |
| 168       | Toe      | $\overline{OE}$ ↓ to Data Valid  | —                   | —                               | $0.5 T_{CY} - 25$   | ns    |
| 169       | TalL2oeH | ALE ↓ to $\overline{OE}$ ↑   | $0.625 T_{CY} - 10$ | —                               | $0.625 T_{CY} + 10$ | ns    |
| 171       | TalH2csL | Chip Enable Active to ALE ↓  | $0.25 T_{CY} - 20$  | —                               | —                   | ns    |
| 171A      | TubL2oeH | AD Valid to Chip Enable Active   | —                   | —                               | 10                  | ns    |

# PIC18F97J60 FAMILY

## 4. Module: Brown-Out Reset Pulse Width

In [Table 28-12](#), the 35 parameter has been added as follows:

**TABLE 28-12: RESET, WATCHDOG TIMER, OSCILLATOR START-UP TIMER, POWER-UP TIMER AND BROWN-OUT RESET REQUIREMENTS**

| Param. No. | Symbol | Characteristic   | Min.                  | Typ. | Max.                  | Units | Conditions  |
|------------|--------|--|-----------------------|------|-----------------------|-------|---|
| 30         | TMCL   | MCLR Pulse Width (low)                                   | 2                     | —    | —                     | μs    |   |
| 31         | TWDT   | Watchdog Timer Time-out Period (no postscaler)           | 2.8                   | 4.1  | 5.4                   | ms    |   |
| 32         | TOST   | Oscillation Start-up Timer Period                        | 1024 T <sub>osc</sub> | —    | 1024 T <sub>osc</sub> | —     | T <sub>osc</sub> = OSC1 period                                  |
| 33         | TPWRT  | Power-up Timer Period                                    | 46.2                  | 66   | 85.8                  | ms    |   |
| 34         | TIOZ   | I/O High-Impedance from MCLR Low or Watchdog Timer Reset | —                     | —    | 3 T <sub>cy</sub> + 2 | μs    | System clock available  |
|            |        |  | —                     | —    | 415                   | μs    | System clock unavailable (Sleep mode or primary oscillator off) |
| 35         | TBOR   | Brown-out Reset Pulse Width                              | 200                   | —    | —                     | μs    | V <sub>DD</sub> ≤ Brown-out Reset voltage (see D005)            |
| 38         | TCSD   | CPU Start-up Time  | —                     | 200  | —                     | μs    |   |

# PIC18F97J60 FAMILY

## 5. Module: CCPxCON Register:0

In the CCPxCON Register, at CCPxM<3:0> bits,  
the 0011 should be read as 'Reserved mode',  
as follows:

**REGISTER 18-1: CCPxCON: ENHANCED CCPx CONTROL REGISTER (ECCP1/ECCP2/ECCP3)**

| R/W-0 | R/W-0 | R/W-0 | R/W-0 | R/W-0  | R/W-0  | R/W-0  | R/W-0  |
|-------|-------|-------|-------|--------|--------|--------|--------|
| PxM1  | PxM0  | DCxB1 | DCxB0 | CCPxM3 | CCPxM2 | CCPxM1 | CCPxM0 |
| bit 7 |       |       |       |        |        |        | bit 0  |

### Legend:

R = Readable bit

W = Writable bit

U = Unimplemented bit, read as '0'

-n = Value at POR

'1' = Bit is set

'0' = Bit is cleared

x = Bit is unknown

- bit 7-6 **PxM<1:0>**: Enhanced PWM Output Configuration bits  
If CCPxM<3:2> = 00, 01, 10:  
xx = PxA assigned as Capture/Compare input/output; PxB, PxC, PxD assigned as port pins  
If CCPxM<3:2> = 11:  
00 = Single output: PxA modulated; PxB, PxC, PxD assigned as port pins  
01 = Full-bridge output forward: P1D modulated; P1A active; P1B, P1C inactive  
10 = Half-bridge output: P1A, P1B modulated with dead-band control; P1C, P1D assigned as port pins  
11 = Full-bridge output reverse: P1B modulated; P1C active; P1A, P1D inactive
- bit 5-4 **DCxB<1:0>**: ECCPx Module PWM Duty Cycle Bit 1 and Bit 0  
Capture mode:  
Unused.  
Compare mode:  
Unused.  
PWM mode:  
These bits are the 2 LSBs of the 10-bit PWM duty cycle. The 8 MSBs of the duty cycle are found in CCPRxL.
- bit 3-0 **CCPxM<3:0>**: ECCPx Module Mode Select bits  
0000 = Capture/Compare/PWM disabled (resets ECCPx module)  
0001 = Reserved  
0010 = Compare mode; toggle output on match  
0011 = **Reserved mode**  
0100 = Capture mode; every falling edge  
0101 = Capture mode; every rising edge  
0110 = Capture mode; every 4th rising edge  
0111 = Capture mode; every 16th rising edge  
1000 = Compare mode; initialize ECCPx pin low; set output on compare match (set CCPxIF)  
1001 = Compare mode; initialize ECCPx pin high; clear output on compare match (set CCPxIF)  
1010 = Compare mode; generate software interrupt only, ECCPx pin reverts to I/O state)  
1011 = Compare mode; trigger special event (ECCPx resets TMR1 or TMR3, sets CCPxIF bit, ECCPx trigger also starts A/D conversion if A/D module is enabled)<sup>(1)</sup>  
1100 = PWM mode; PxA, PxC active-high; PxB, PxD active-high  
1101 = PWM mode; PxA, PxC active-high; PxB, PxD active-low  
1110 = PWM mode; PxA, PxC active-low; PxB, PxD active-high  
1111 = PWM mode; PxA, PxC active-low; PxB, PxD active-low

**Note 1:** Implemented only for ECCP1 and ECCP2; same as '1010' for ECCP3.

# PIC18F97J60 FAMILY

---

## APPENDIX A: REVISION HISTORY

### **Rev A Document (2/2009)**

Original version of this document. Includes silicon issues 1 (Resets), 2 (I/O – PORTJ), 3 (I/O (PORTJ) and External Memory Bus), 4 (Ethernet – Buffer Memory), 5 (Ethernet – MIIM), 6 (Ethernet – RX Filter), 7 (Ethernet – TX), 8 (Ethernet – DMA) and 9 (I/O – PORTJ).

### **Rev B Document (3/2010)**

Changed the title to A1/A2 as this document now also covers the A2 silicon. Updated the data sheet reference revision from “D” to “E”.

### **Rev C Document (10/2010)**

Merged silicon errata documents for Revision A0 and Revision A1/A2. Updated all affected silicon errata for each module to include Revision A3. Merged data sheet errata to create a single errata document for this part.

### **Rev D Document (7/2014)**

Added Module 10, Timer1/3, to Silicon Errata Issues section.

Data Sheet Clarifications: Removed Module 1.

### **Rev E Document (12/2014)**

Data Sheet Clarifications: Added Modules 1-5; Updated the Errata document to new format; Other minor corrections.

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, flexPWR, JukeBlox, KEELOQ, KEELOQ logo, Klear, LANCheck, MediaLB, MOST, MOST logo, MPLAB, OptoLyzer, PIC, PICSTART, PIC<sup>32</sup> logo, RightTouch, SpyNIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

The Embedded Control Solutions Company and mTouch are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, ECAN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, KlearNet, KlearNet logo, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, RightTouch logo, REAL ICE, SQI, Serial Quad I/O, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2009-2014, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-63276-852-0

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110

**Canada - Toronto**  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hangzhou**  
Tel: 86-571-8792-8115  
Fax: 86-571-8792-8116

**China - Hong Kong SAR**  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8864-2200  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-3019-1500

**Japan - Osaka**  
Tel: 81-6-6152-7160  
Fax: 81-6-6152-9310

**Japan - Tokyo**  
Tel: 81-3-6880-3770  
Fax: 81-3-6880-3771

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-5778-366  
Fax: 886-3-5770-955

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Dusseldorf**  
Tel: 49-2129-3766400

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Pforzheim**  
Tel: 49-7231-424750

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Venice**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Poland - Warsaw**  
Tel: 48-22-3325737

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820