

AD-4405, AD-4406, AD-4407 lb/kg Operation**AD-4405/06/07 C-Function**

NO.	ITEM	PARM.	DESCRIPTION	Remarks
** C00	Country	* 0	Universal	
		1	OIML (C01-C06 =0)	
		** 2	Canada/USA (C01-C06 =1)	
		3	Taiwan (C01=2-C06=0)	
		4	Singapore, HK (C01=2, C02-C06=0)	
** C01	Weighing Unit	* 0	kg, g, t	
		** 1	lb, oz available	
		2	tl available	
C02	ZERO indicator near GROSS 0	* 0	Turn on both GROSS or NET	
		1	Turn on only GROSS mode	
C03	ZERO indicator near NET 0	* 0	Turn on only NET 0	Not turn on when C05=1
		1	Not turn on	
C04	Zero suppress	* 0	0	d >= 10 (NTEP)
		1	00	
C05	TARE operation	* 0	Internal count	Preset tare operate DISPLAY count inspite of this setting
		1	Display count	
C06	ZERO key (TARE entered)	* 0	Display an NET, Enable in GROSS	TARE is cleared TARE is not cleared
		1	Enable both NET and GROSS	
C07	ZERO + TARE instead CAL (AD-4405/07)		Enable	
		*	Disable	
	Batch mode (AD-4406)	* 0	Enable	F22= 0 to 6
		1	Disable	
C08	Resolution limit	* 0	1/40000	
		1	1/10000	
C09	Reserved	* 0		
		1		

* Initial setting

PROCEDURE

Press NET/GROSS & Turn ON

Continue to hold NET/GROSS & Press CAL immediately when F00 is displayed

C00 will now be displayed.

To set up the indicator to operate in lb/kg mode, change the C setting above indicated with **.

The F1 or F2 key of the AD-4406 can be used to toggle between lb and kg. To use the F1 key, set F10 to 19.

Use CAL SET to enable lb/kg during calibration.

1. Press CAL key.
2. Press ZERO→ key 3 times to display CAL Set.
3. Press F2, "ENTER" key, to display SinGL.
4. Press ZERO→ key to toggle between the units. Display lb with kg flashing beneath lb.
5. Press F2, "ENTER" key, to display d=05.
6. Press TARE↑ to change the increment division.
7. Press ZERO→ to change decimal point position.
8. Press F2, "ENTER" key, to display the capacity in lb, CAP -XXXX.
9. Use ZERO→>/<TARE↑ to set the capacity.
10. Press F2, "ENTER" key, to start zero calibration, displays CAL O.
11. Press F2, "ENTER" key, to calibrate zero then displays span calibration weight in lb, CAL F XXXX.
12. Use ZERO→>/<TARE↑ to set the calibration weight in lb.
13. Press F2, "ENTER" key, to calibrate span, then displays CAL END.
14. Press the Cal key to display CAL Off.
15. Turn indicator off then on.