


UC-300 CALIBRATION



To calibrate, follow the procedure detailed in the UC 300_mm.pdf. However after pressing the right switch after the display test, just press the right switch several times to display “5”.

Make sure the scale has been sitting at a stable temperature for at least two hours and measure the temperature. This temperature must be input at this step as per the instructions before calibrating.

Whatever you do, DO NOT PRESS THE LEFT SWITCH IF THE DISPLAY SHOWS “6 or 7”!!!! It will destroy the pre-stored temperature offset level and will require the scale to be dismantled and the offset entered again.

Press the right switch to increment the display to read “9”. Follow the procedure to calibrate the zero point.

Increment the display to read “12” if you want to calibrate the scale with 100 kg instead of 136 kg, then follow the procedure to calibrate the span point.