

Statistical Techniques for Monitoring Industrial Processes



Lecture : PCA – Fault Detection

Module : PCA-based MSPM

Course TOC

❑ Introduction to Statistical Process Monitoring (SPM)


❑ Python Installation and basics (optional)

❑ Univariate SPM & Control Charts

- Shewhart Charts
- CUSUM Charts
- EWMA Charts


❑ Multivariate SPM

- Principal Component Analysis (PCA)-based MSPM
 - Dimensionality reduction
 - Fault detection & diagnosis (FDD) using PCA
 - Application to a Polymer Manufacturing process
- Partial Least Squares (PLS) regression-based MSPM
- Strategies for handling nonlinear, dynamic, multimode systems




❑ Deploying SPM solutions

PCA: Systematic Component and Noise




PCA-based Fault Detection Workflow



Importance of both T^2 and Q Statistics

- T^2 and Q are complementary metrics
- It is possible that an abnormal sample violates control limit of one metric, but not the other


Both T^2 and Q are important and should be monitored



Flow measurements across a valve (left) and mean-centered flow readings with two abnormal instances (samples a and b)

Computing (Statistical) Control Limits for T^2 and Q Statistics


T^2



$$T_{CL}^2 = \frac{k(N^2 - 1)}{N(N - k)} F_{k, N-k}(\alpha)$$

- α is false alert rate (usually 0.01 or 0.05)
- k = number of PCs retained
- N = number of training samples
- $F_{k, N-k}(\alpha)$ is $(1 - \alpha)$ percentile of a F distribution with k and $N - k$ degrees of freedom

Q




$$Q_{CL} = \theta_1 \left(\frac{z_\alpha \sqrt{2\theta_2 h_0^2}}{\theta_1} + 1 + \frac{\theta_2 h_0 (1 - h_0)}{\theta_1^2} \right)^2$$

$$h_0 = 1 - \frac{2\theta_1 \theta_3}{3\theta_2^2}; \quad \theta_r = \sum_{j=k+1}^m \lambda_j^r; r=1,2,3$$


- z_α is $(1 - \alpha)$ percentile of a standard Gaussian distribution

Computing (Statistical) Control Limits for T^2 and Q Statistics

T^2



Q



$$T_{CL}^2 = \frac{k(N^2 - 1)}{N(N - k)}$$

- α is false alarm rate
- k = number of variables
- N = number of training samples
- $F_{k, N-k}(\alpha)$ is $(1 - \alpha)$ percentile of a F distribution with k and $N - k$ degrees of freedom




These statistical expressions for control limits are valid only if the training data follow a multivariate Gaussian distribution

$$\left(\frac{\theta_2 h_0 (1 - h_0)}{\theta_1^2} \right)^2$$

- z_α is $(1 - \alpha)$ percentile of a standard Gaussian distribution

Computing (Empirical) Control Limits for T^2 and Q Statistics


T^2



$$T_{CL}^2 = \text{np.percentile}(T2_values, 99) \# \text{ alpha}=0.01$$

- Control limit is simply the 99th percentile of the T^2 values for the training samples

Q



$$Q_{CL} = \text{np.percentile}(Q_values, 99) \# \text{ alpha}=0.01$$

- Control limit is simply the 99th percentile of the Q values for the training samples

Statistical Techniques for Monitoring Industrial Processes



Next Lecture : PCA – Fault Detection Implementation

Module : PCA-based MSPM

