

# Applied Statistics and Data Analysis

## Part I

# Statistical Process and Quality Control

## Introduction

### Quality and Process Control

#### Definition of Quality

- Quality means fitness for use. and
- Quality is inversely proportional to variability.
- My definition: *Is* and *should* are the same.

#### Statistical Process Control (SPC)

- Statistical process control is, first and foremost, a way of thinking which happens to have some tools attached.

#### The Magnificent Seven

1. histogram
2. check sheet
3. Pareto chart
4. defect concentration diagram
5. cause-and-effect diagram
6. control chart
7. scatter diagram

## Control Charts

The basis of a control chart is a statistical hypothesis test.

### Hypothesis test

#### Question:

is  $|\bar{x} - \mu_0|$  significant?

- $\mu_0$  target value
- $\bar{x}$  Arithmetic mean of the measurements

#### Hypothesis

Two-sided statistical test to check the two alternative hypotheses:

$$\begin{aligned} H_0 : \mu_0 &= \bar{x} \text{ i.e. process is not disturbed} \\ H_1 : \mu_0 &\neq \bar{x} \text{ i.e. process is disturbed} \end{aligned} \quad (1)$$

#### Statistical test:

**Test statistic** (z-test, since  $\sigma$  is known)

$$z = \frac{\bar{x} - \mu_0}{\sigma} \sqrt{n} \quad (2)$$

**Critical value** i.e. q-quantile of the normal distribution

$$P(|z| \leq z_q) = q \quad (3)$$

with  $q = 1 - \frac{\alpha}{2}$ , where  $\alpha = 0.0027 \rightarrow z_q \approx 3$

#### Statistical conclusion

If  $\leq |z| z_q \rightarrow$  accept null hypothesis, i.e. process is not disturbed.

If  $< |z| z_q \rightarrow$  reject null hypothesis, i.e. process is disturbed.

Reverse it and determine acceptance and rejection limits of the test!

#### Control limits

$$UCL = \mu_0 + z_q \frac{\sigma}{\sqrt{n}} \quad LCL = \mu_0 - z_q \frac{\sigma}{\sqrt{n}} \quad (4)$$

#### Statistical conclusion

If  $LCL \leq \bar{x} \leq UCL \rightarrow$  process is not disturbed.

If  $\bar{x} < LCL$  or  $UCL < \bar{x} \rightarrow$  process is disturbed.

Problem: In general, process standard deviation is unknown.

- Monitoring the mean and the variation of a process.
- First, monitoring the variation, then (if variation under control) monitoring the mean.

Solution: Control charts! :)

## The Control Chart

No.	sample values						mean	sd	range
1	$x_{11}$	$x_{12}$	$\cdots$	$x_{1j}$	$\cdots$	$x_{1n}$	$\bar{x}_1$	$s_1$	$R_1$
2	$x_{21}$	$x_{22}$	$\cdots$	$x_{2j}$	$\cdots$	$x_{2n}$	$\bar{x}_2$	$s_2$	$R_2$
$\vdots$	$\vdots$	$\vdots$		$\vdots$		$\vdots$	$\vdots$	$\vdots$	$\vdots$
$i$	$x_{i1}$	$x_{i2}$	$\cdots$	$x_{ij}$	$\cdots$	$x_{in}$	$\bar{x}_i$	$s_i$	$R_i$
$\vdots$	$\vdots$	$\vdots$		$\vdots$		$\vdots$	$\vdots$	$\vdots$	$\vdots$
$k$	$x_{k1}$	$x_{k2}$	$\cdots$	$x_{kj}$	$\cdots$	$x_{kn}$	$\bar{x}_k$	$s_k$	$R_k$

Figure 1: Data Set with Mean, Standard Deviation and Range

#### Mean values

$$\bar{x}_i = \frac{1}{n} \sum_{j=1}^n x_{ij} \quad (5)$$

#### Standard deviations

$$s_i = \sqrt{\frac{1}{n-1} \sum_{j=1}^n (x_{ij} - \bar{x}_i)^2} \quad (6)$$

#### Ranges

$$R_i = \max \{x_{ij} | j \in \{1, \dots, n\}\} - \min \{x_{ij} | j \in \{1, \dots, n\}\} \quad (7)$$

for all  $i \in \{1, \dots, k\}$

### Control Chart for $\bar{x}$ and R

#### R Chart Centerline

$$\bar{R} = \frac{1}{k} \sum_{i=1}^k R_i \quad (8)$$

#### Control limits

$$UCL = D_4 \bar{R}; \quad LCL = D_3 \bar{R} \quad (9)$$

#### $\bar{x}$ Chart based on R chart

##### Control limits

$$UCL = \mu + 3 \frac{\sigma}{\sqrt{n}}; \quad LCL = \mu - 3 \frac{\sigma}{\sqrt{n}} \quad (10)$$

Problem:  $\mu$  and  $\sigma$  are in general unknown and must be estimated from the process data.

Two-stage process:

- Make sure that the process standard deviation (R chart) is under statistical control. That is, if some samples are out of bounds, it is recommended to omit these measurements and recalculate the limits.
- Use  $\bar{R}$  to estimate the process standard deviation.

#### Centerline

We know that for an independent sample  $x_1, \dots, x_n$  from a normal distribution with parameters  $\mu$  and  $\sigma$  the mean

$$\bar{x} = \frac{1}{n} \sum_{j=1}^n x_j \quad (11)$$

satisfies

$$E(\bar{x}) = \mu \quad \text{and} \quad \text{Var}(\bar{x}) = \frac{\sigma^2}{n} \quad (12)$$

The mean is an unbiased estimator with the standard error

$$SE(\bar{x}) = \frac{\sigma}{\sqrt{n}} \quad (13)$$

Assumption: R chart is under statistical control.

- The value  $\bar{R}$  is a reliable estimate for the mean range.

- The value  $\bar{R}$  is a reliable estimate for the process standard deviation

$$\hat{\sigma} = \frac{\bar{R}}{d_2} \quad (14)$$

Any samples excluded for construction of the R chart should also be disregarded for construction of the  $\bar{x}$  chart. This results in a sample of  $k^*$  valid samples, (where  $k^*$  denotes the reduced number of samples). Mean values of  $\bar{x}_1, \dots, \bar{x}_{k^*}$  provide an estimate of  $\mu$ , i.e

$$\bar{\bar{x}} = \frac{1}{k^*} \sum_{i=1}^{k^*} \bar{x}_i \quad (15)$$

#### Control limits

$$UCL = \bar{\bar{x}} + 3 \frac{\bar{R}}{d_2} \frac{1}{\sqrt{n}} \approx \bar{\bar{x}} + A_2 \bar{R} \quad (16)$$

$$LCL = \bar{\bar{x}} - 3 \frac{\bar{R}}{d_2} \frac{1}{\sqrt{n}} \approx \bar{\bar{x}} - A_2 \bar{R}$$

### Control Chart with $\bar{x}$ and s

## s Chart

**Centerline** The centreline of the s chart is denoted by  $\bar{s}$  and is calculated from the arithmetic mean of the standard deviations

$$\bar{s} = \frac{1}{k} \sum_{i=1}^k s_i \quad (17)$$

### Control limits

$$UCL = B_4 \bar{s}; \quad LCL = B_3 \bar{s} \quad (18)$$

## $\bar{x}$ Chart based on s chart

Using an s chart of a process that is under control, the process standard deviation can be estimated by

$$\hat{\sigma} = \frac{\bar{s}}{c_4} \quad (19)$$

Any samples excluded for construction of the s chart should also be disregarded for construction of the  $\bar{x}$  chart. This results in a sample of  $k^*$  valid samples, (where  $k^*$  denotes the reduced number of samples). Mean values of  $\bar{x}_1, \dots, \bar{x}_{k^*}$  provide an estimate of  $\mu$ , i.e

$$\hat{\mu} = \bar{\bar{x}} = \frac{1}{k^*} \sum_{i=1}^{k^*} \bar{x}_i \quad (20)$$

### Control limits

$$UCL = \bar{\bar{x}} + 3 \frac{\bar{s}}{c_4} \frac{1}{\sqrt{n}} \approx \bar{\bar{x}} + A_3 \bar{s} \quad (21)$$

$$LCL = \bar{\bar{x}} - 3 \frac{\bar{s}}{c_4} \frac{1}{\sqrt{n}} \approx \bar{\bar{x}} - A_3 \bar{s}$$

## Individual Control Charts

Individual control charts have exactly one measurement per sample. Problem: You cannot estimate variability from a single measurement. Idea: Use variation of two adjacent measurements.

### Moving ranges

$$MR_i = |x_{i+1} - x_i| \quad (22)$$

for all  $i \in \{1, \dots, n-1\}$ .

### Arithmetic mean of the moving ranges

$$\overline{MR} = \frac{1}{n-1} \sum_{i=1}^{n-1} MR_i \quad (23)$$

### Estimated process standard deviation

$$\hat{\sigma} = \frac{\overline{MR}}{d_2} = \frac{\overline{MR}}{1.128} \quad (24)$$

Since two neighboring measurements were used to calculate the moving ranges we have  $d_2 = 1.128$ .

### Centerline

The centerline for the individuals control chart is the arithmetic mean of the measured values.

$$\bar{\bar{x}} = \frac{1}{k} \sum_{i=1}^k x_i \quad (25)$$

### Control limits

$$UCL = \bar{\bar{x}} + 3 \frac{\overline{MR}}{1.128}; \quad LCL = \bar{\bar{x}} - 3 \frac{\overline{MR}}{1.128} \quad (26)$$

## Control Charts for Attributes Data – p Chart

Number of defectives under number tested is a discrete random variable.

Given: Random sample of size n, of which D parts are defective We know: The number of defective D under n examined parts follows a binomial distribution with the unknown probability p of success.

### Estimated probability

$$\hat{p} = \frac{D}{n} \quad (27)$$

### Variance

$$Var(\hat{p}) = \frac{p(1-p)}{n} \quad (28)$$

### Given:

- k random samples with  $n_1, \dots, n_k$  values.
- Each of these samples contains  $d_1, \dots, d_k$  defective products.

## k relative frequencies

$$p_1 = \frac{d_1}{n_1}, \dots, p_k = \frac{d_k}{n_k} \quad (29)$$

### Centerline

The centreline and the control limits of a p chart are again determined from a stable trial run with  $k^*$  valid samples.

Again  $k^* \leq k$  is the reduced number of samples.

Distinguish 2 cases:

1. The sample sizes  $n_1, \dots, n_k$  are all equal to n.
2. The sample sizes are not all equal.

### Case 1

#### Centerline

$$\bar{p} = \frac{1}{k^*} \sum_{i=1}^{k^*} p_i \quad (30)$$

#### Control limits

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}; \quad LSL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \quad (31)$$

### Case 2

#### Centerline

$$\bar{p} = \frac{d_1 + \dots + d_{k^*}}{n_1 + \dots + n_{k^*}} \quad (32)$$

#### Control limits

$$UCL_i = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n_i}}; \quad LSL_i = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n_i}} \quad (33)$$

The control limits now depend on the index i.


## Statistical Properties of Control Charts

Aim of process control using control charts: Keep the process under statistical control. Or, if it is not at the beginning, to put it into statistical control by improving production conditions.

## Interpretation of Control Charts


### Western Electric Rules

1. Any single data point falls outside the limit defined by UCL and LCL (beyond the  $3\sigma$ -limit).
2. Two out of three consecutive points fall beyond the limit defined by  $\frac{2}{3}$  UCL and  $\frac{2}{3}$  LCL on the same side of the centreline (beyond the  $2\sigma$ -limit).
3. Four out of five consecutive points fall beyond the limit defined by  $\frac{1}{3}$  UCL and  $\frac{1}{3}$  LCL on the same side of the centreline (beyond the  $2\sigma$ -limit).
4. Nine consecutive points fall on the same side of the centreline (so-called run).



Rule 1: Any point beyond zone A.

Rule 2: Two out of three consecutive points fall on the same side in zone A or beyond.



Rule 3: Four out of five consecutive points fall on the same side in zone B or beyond.

Rule 4: Nine consecutive points fall on the same side of the centreline.

## Type I Error and Type II Error

When monitoring a production process with a control chart, as with any statistical test, there are two wrong decisions possible.

$$\begin{aligned} H_0 : \mu_0 = \mu \text{ i.e. process is not disturbed} \\ H_1 : \mu_0 \neq \mu \text{ i.e. process is disturbed, } \mu_1 \text{ is true} \end{aligned} \quad (34)$$


Denoted by:

- $\mu_0$  the target value of the process
- $\mu$  the considered statistic, eg.  $\mu = \bar{x}$  or  $\mu = R$
- $\mu_1$  the true value of the considered statistic.

### Two wrong decisions possible:

- If a true null hypothesis  $H_0$  is rejected we make a type I error. An intervention in the process is necessary, because the control limits are exceeded, although the process is not disturbed. This is called a false alarm.
- If a false null hypothesis  $H_0$  is accepted we make a type II error. There is no intervention, since the control limits are not exceeded, although the process is disturbed. This is called an omitted alarm


### Type I Error



Let  $h_0$  be true: Since  $z < z_{1-\alpha}$  the null hypothesis is accepted. This is the right decision, which is made with probability  $1 - \alpha$ .

Let  $h_0$  be true: Since  $z \geq z_{1-\alpha}$  the null hypothesis is rejected. This is the wrong decision (type I error), which is made with probability  $\alpha$ .

### Type II Error



Let  $H_0$  be false,  $H_1$  true, i.e. the dashed density is true: Since  $z < z_{1-\alpha}$  the null hypothesis is accepted. This is the wrong decision (type II error), which is made with probability  $\beta$ .

Let  $H_0$  be false,  $H_1$  true, i.e. the dashed density is true: Since  $z \geq z_{1-\alpha}$  the null hypothesis is rejected. This is the correct decision, which is made with probability  $1 - \beta$  (power).

## Power Function and Operating Characteristic

The power of a hypothesis test is the probability  $1 - \beta$  that the test correctly rejects the null hypothesis when the alternative hypothesis is true, i.e.

$$\text{power} = P(\text{reject } H_0 | H_1 \text{ is true}) = 1 - \beta \quad (35)$$

### Power function

Probability to reject the null hypothesis  $H_0$  if  $\mu_1$  is true.

$$\delta = \frac{\mu_1 - \mu_0}{\sigma}, \quad (36)$$

or  $\mu_1 = \delta\sigma + \mu_0$ .

The variable  $\delta$  is a normalized measure for the deviation of the disturbed from the undisturbed process in units of  $\sigma$ .

In statistical process control the power function is denoted by

$$g(\mu_1) = g(\delta\sigma + \mu_0) = \tilde{g}(\delta). \quad (37)$$

It is a measure for the probability of an intervention in the process.

### Undisturbed Process

For an undisturbed process, i.e.  $\mu = \mu_0$ , we have

$$g(\mu_1) = \tilde{g}(0) = \alpha. \quad (38)$$

### Disturbed Process

For a disturbed process we have

$$\tilde{g}(\delta) = \Phi(\delta\sqrt{n} - z_q, 0, 1) + \Phi(-\delta\sqrt{n} - z_q, 0, 1) \quad (39)$$

with  $\Phi$  being

$$\Phi(x, \mu, \sigma^2) = \frac{1}{\sqrt{2\pi\sigma^2}} \int_{-\infty}^x e^{-\frac{(z-\mu)^2}{2\sigma^2}} dz \quad (40)$$

## Average Run Length

If the  $i_{RL}$ -th sample is the first to result in an intervention, i.e. this sample is beyond the control limits, then  $i_{RL}$  is called the run length of the control chart.

The ARL is the expected value of the probability i.e. the likelihood of exceeding the control limits when performing a test.

$$ARL(\delta) = \frac{1}{p(\mu)} = \frac{1}{g(\mu_1)} = \frac{1}{\tilde{g}(\delta)} \quad (41)$$

### Undisturbed Process

If we have an undisturbed process with  $\mu_1 = \mu_0$ , i.e. with  $\delta = 0$ , then it follows from equation 38 that

$$ARL(0) = \frac{1}{\alpha}. \quad (42)$$

### Disturbed Process

To determine the average run length of a disturbed process with  $\mu = \mu_1$ , i.e.  $\sigma = \frac{\mu_1 - \mu_0}{\sigma}$  we use the power function  $\tilde{g}(\delta)$  from equation 39.

## Process Capability

The specification limit (SL) is defined by

$$SL = \frac{USL + LSL}{2} \quad (43)$$

This performance is measured with so-called capability process ratios (PCR). The simplest process capability index is

$$C_p = \frac{USL - LSL}{6\sigma} \quad (44)$$

The capability process ratio  $C_p$  expresses the ratio of the width of the tolerance range to the width of the process range.

- $C_p = 1$  implies a reject rate of  $\alpha \cdot 100\% = 0.27\%$ .
- $C_p < 1$  implies a reject rate of more than  $\alpha \cdot 100\% = 0.27\%$ , i.e. the process capability is not guaranteed.
- $C_p > 1$  implies a reject rate of less than  $\alpha \cdot 100\% = 0.27\%$ , i.e. the process capability is guaranteed.

## Control Charts with Memory

### Classical Shewhart control charts

- Decision to interfere with the manufacturing process is based on the result of the current sample.
- No consideration of the development of the manufacturing process in the past (except with western electric rules).

### Modern control charts

- have a memory.

### Idea

Linear combination of mean values  $\bar{x}_j$  of samples from the past

$$y_i = \alpha_i + \sum_{j=1}^i \beta_j \bar{x}_j, \quad (45)$$

where  $\alpha_i$  and the weights  $\beta_1, \dots, \beta_i$  can be arbitrary real numbers where the sum of all  $\beta_s = 1$ .

Depending on how the weights are chosen, we get another type of control chart.

## CUSUM - Cumulative Sum Control Chart

The CUSUM chart plots the cumulative sums of deviations of measurement values from the target value.

### Recursive procedure

Using two statistics  $C^+$ , resp.  $C^-$  the CUSUM chart sums up deviations above, resp. below the target value

$$\begin{aligned} C_i^+ &= \max\{0, \bar{x}_i - (\mu_0 + K) + C_{i-1}^+\}, \\ C_i^- &= \max\{0, (\mu_0 - K) - \bar{x}_i + C_{i-1}^-\}. \end{aligned} \quad (46)$$

$C^+$  and  $C^-$  only sum up deviations from the target value, which are greater than the reference value  $K$ . The starting values of the recursion are  $C^+ = 0$  and  $C^- = 0$ .

If a shift of  $\Delta$  is to be detected then set

$$K = \frac{\Delta}{2}. \quad (47)$$

The constant  $K$  is called reference value.

If the process is under control the expected values of the statistic are both 0.

If the process is not under control, then the statistic sums up the deviations. If the sum of deviations ( $C^+$  and  $C^-$ ) exceed the decision interval  $H$ , then we should stop the process and look for the cause.

Rule of thumb for choosing the constants  $K$  and  $H$ : Let  $\hat{\sigma}$  be an estimate for the process standard deviation. - reference value =  $K \frac{\hat{\sigma}}{2}$  - decision interval  $H = 5\hat{\sigma}$




Figure 2: CUSUM-Chart

## EWMA - Exponentially Weighted Moving Average

### Idea

- Monitoring means.
- Weights  $\beta_j$  decay exponentially.

### Smoothing parameter $\lambda$

Lambda lays between 0 and 1. The smoothing parameter  $\lambda$  determines the influence of the previous sample mean  $\bar{x}_j$  on the statistic. The smaller  $\lambda$ , the more values  $\bar{x}_j$  are used for the decision. For  $\lambda = 1$  only one sample is used and we get the well-known Shewhart  $\bar{x}$  chart.

### Weights

$$\begin{aligned} \alpha_i &= (1 - \lambda)^1 \mu_0 \\ \beta_j &= \lambda(1 - \lambda)^{i-j} \text{ with } j \in \{1, 2, \dots, i\}. \end{aligned} \quad (48)$$

### Statistics

$$y_i = (1 - \lambda)^i \mu_0 + \lambda \sum_{j=1}^i (1 - \lambda)^{i-j} \bar{x}_j \quad (49)$$

Start:  $y_0 = \mu_0$

### The same with recursion

$$y_i = (1 - \lambda)y_{i-1} + \lambda \bar{x}_i \quad (50)$$

### Assumptions

If the process is under control, then  $\bar{x}_i$  comes from a normal distribution with the expected value  $\mu_0$  and the standard deviation  $\frac{\sigma}{\sqrt{n}}$ .

The standard deviation is either known or can be estimated from data. The statistic  $y_i$  is then also normally distributed with  $E(y_i) = \mu_0$  and

$$\text{Var}(y_i) = \frac{\lambda}{2 - \lambda} (1 - (1 - \lambda)^{2i}) \frac{\sigma^2}{n} \quad (51)$$

### Control limits

These assumptions lead to the  $3\sigma$  control limits:

$$\begin{aligned} UCL_i &= \mu_0 + 3\sqrt{\frac{\lambda}{2 - \lambda} (1 - (1 - \lambda)^{2i})} \frac{\sigma}{\sqrt{n}} \\ LCL_i &= \mu_0 - 3\sqrt{\frac{\lambda}{2 - \lambda} (1 - (1 - \lambda)^{2i})} \frac{\sigma}{\sqrt{n}} \end{aligned} \quad (52)$$

The asymptotic control limits are:

$$\begin{aligned} UCL_i &= \mu_0 + 3\sqrt{\frac{\lambda}{2 - \lambda}} \frac{\sigma}{\sqrt{n}} \\ LCL_i &= \mu_0 - 3\sqrt{\frac{\lambda}{2 - \lambda}} \frac{\sigma}{\sqrt{n}} \end{aligned} \quad (53)$$

### Estimate of process standard error

$$\hat{\sigma} = \frac{\bar{s}}{c_4} \quad (54)$$




Figure 3: EWMA-Chart

## Acceptance Sampling

Acceptance control is based on acceptance sampling plans, which contain instructions based on which the acceptance or return of a lot is decided. We should remember that the actual point of acceptance control is not to value quality, but to decide whether or not delivery will likely pass quality control.

**Idea:** Draw random samples from a lot and make a decision on the quality of the lot based on this information.

### Plans for Attributes

#### Percent defective

We have a lot of  $N$  parts (known). The number of defective parts  $m$  (unknown) with  $0 \leq m \leq N$  is observed. Thus, the percent defective is:

$$p = \frac{m}{N} \quad (55)$$

**Acceptance sampling plan** consist of:

- Sample size  $n$ ,
- the number of defective parts  $x$  in the sample, where  $0 \leq x < n$ ,
- the acceptance number  $c$ , where  $0 \leq c < n$  and
- the rule: if  $x \leq c$ , then the lot is accepted, if  $x > c$ , then the lot is rejected.

#### Hypothesis test

The rule above can also be formulated as a hypothesis test:

$$\begin{aligned} H_0 &: x \leq c, \text{ i.e. the lot is not rejected.} \\ H_1 &: x > c, \text{ i.e. the lot is rejected.} \end{aligned} \quad (56)$$

As with any hypothesis test the following two errors can be made.

### Type I Error

$H_0$  true, but rejected (Lot is good but is rejected)

Probability for this to happen (false negative):  $\alpha$ . (Producer's risk)

The producer wants to avoid type I error, i.e. does not want good lots to be returned.

### Type II Error

$H_0$  false, but accepted (Lot is bad but is accepted)

Probability for this to happen (false positive):  $\beta$ . (Consumer's risk)

The consumer wants to avoid type II error, i.e. does not want to accept bad lots.

In an agreement between a producer and a consumer the following parameter must be defined:

- $\alpha$ : The producer's acceptable probability of falsely rejecting a good lot,
- $\beta$ : The consumer's acceptable probability of falsely accepting a bad lot,
- $p_\alpha$  the producer's minimal percentage defective needed for a lot to be returned (The producer does not want to take back lots with  $p < p_\alpha$ ),
- $p_\beta$  the consumer's maximal percentage defective needed for a lot to be accepted (The consumer wants to reject lots with  $p_\beta < p$  whenever possible).

## Operating Characteristic

The operating characteristic, short OC, is the probability of accepting a lot as a function of the percent defective  $p$ .

The number of defective units  $X$  is a hypergeometric random variable. There are  $N$  parts in total, among which  $m$  defective and  $N - m$  are good parts. So a sample of size  $n$  is drawn at once. The probability that among these  $n$  parts are at most  $c$  parts defective is given by

$$OC(p) = P(X \leq c) = \sum_{k=0}^c P(X = k) = \sum_{k=0}^c \frac{\binom{pN}{k} \binom{N-pN}{n-k}}{\binom{N}{n}} \quad (57)$$

For a given lot size  $N$ , the parameters  $n$  and  $c$  of the acceptance sampling plan determine the form of the OC curve.

### Ideal OC Curve

If all parts of a lot get checked we get an ideal acceptance sampling plan:




Figure 4: OC curve of an ideal acceptance sampling plan




Figure 5: OC curve with fixed  $n$  and increasing  $c$




Figure 6: OC curve with increasing  $n$  and fixed  $c$

## Parameters of an Acceptance Sampling Plan

$n$  and  $c$  are to be chosen such that:

- $n$  is as small as possible,
- the producer risk is at most equal to  $\alpha$ , i.e.  $OC(p_\alpha) \leq 1 - \alpha$ , and
- the consumer risk is at most equal to  $\beta$ , i.e.  $OC(p_\beta) \geq \beta$

The pair  $(p_\alpha, 1 - \alpha)$  is called producer risk point and the pair  $(p_\beta, \beta)$  is called consumer risk point.

$n$  and  $c$  are calculated by brute force. The resulting OC curve is not a perfect fit since only integer values can be chosen.




Figure 7: OC curve of a real acceptance sampling plan.

## Acceptance Sampling Plans for Variables

It is always possible to reduce an acceptance sampling plan for variables to an acceptance sampling plan for attributes by saying:

- If  $LSL \leq x \leq USL$ , then the part is fit for use.
- If  $x < LSL$  or  $USL < x$ , then the part is rejected

By counting the number of rejected parts, we again have an acceptance sampling plan for attributes.

## Part II Multiple Regression

### Simple Linear Regression

One of the most important and widely used statistical technique is regression analysis. This is a statistical technique for investigating and modelling relationships between variables.

#### Simple Linear Regression Model

A simple linear regression model is a model with a single predictor variable that has a relationship with a response that is a straight line.

##### Model

$$y = \beta_0 + \beta_1 x + \varepsilon \quad (58)$$

where  $\beta_0$  and  $\beta_1$  are unknown and fixed parameters.

##### Variables and error

- Predictor / input / explanatory variable  $x$  (deterministic)
- Response / output variable  $y$  (random variable)
- Uncorrelated random error  $\varepsilon$  with

$$E(\varepsilon) = 0 \quad (59)$$

and unknown variance

$$Var(\varepsilon) = \sigma^2 \quad (60)$$

Since the error is a random value,  $y$  is also a random value.

##### Aim

Find Parameters  $\hat{\beta}_0, \hat{\beta}_1$  and  $\hat{\sigma}^2$  such that model fits data as well as possible.

##### Assumptions

The error  $\varepsilon$  is normally distributed:

$$E \approx N(0, \sigma^2) \Rightarrow E(y) = \beta_0 + \beta_1 x \quad (61)$$

### Estimation of the Parameters

#### Method of least square

Minimise:

$$S(\beta_0, \beta_1) = \sum_{i=1}^n (y_i - (\beta_0 + \beta_1 x_i))^2 \quad (62)$$

Calculating:

$$\hat{\beta}_0 = \bar{y} - \hat{\beta}_1 \bar{x} \text{ with } \hat{\beta}_1 = \frac{S_{xy}}{S_{xx}} \quad (63)$$

where

$$S_{xx} = \sum_{i=1}^n (x_i - \bar{x})^2 \text{ and } S_{xy} = \sum_{i=1}^n (x_i - \bar{x})(y_i - \bar{y}) \quad (64)$$

with

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x_i \text{ and } \bar{y} = \frac{1}{n} \sum_{i=1}^n y_i \quad (65)$$

#### Residual

The difference between the  $i$ th observed value  $y_i$  and its fitted value  $\hat{y}_i$  is the residual

$$e_i = y_i - \hat{y}_i = y_i - (\beta_0 + \beta_1 x_i) \quad (66)$$

#### Mean of residuals

$$\bar{e} = \frac{1}{n} \sum_{i=1}^n e_i = 0 \quad (67)$$

#### Unbiased estimator

An unbiased estimator  $\hat{\sigma}^2$  is obtained from the error sum of squares

$$\hat{\sigma}^2 = \frac{1}{n-2} \sum_{i=1}^n (e_i - \bar{e})^2 = \frac{1}{n-2} \sum_{i=1}^n e_i^2 \quad (68)$$

Notice that we have to divide by the degrees of freedom  $n-2$  to make the estimator unbiased. (2 because we have two parameters to find).

#### Distribution of the estimators

To be able to answer how well the model fits the data, whether the model can be used as a reliable predictor and whether the assumptions of constant variance and uncorrelated errors are met, we need to know the distributions of the estimators  $\beta_0$  and  $\beta_1$ .

Since the estimators  $\beta_0$  and  $\beta_1$  are calculated using the random variable  $y$ , the estimators themselves are random variables which follow the distributions

$$\hat{\beta}_0 \sim \mathcal{N}\left(\beta_0, \sigma^2 \left(\frac{1}{n} + \frac{\bar{x}^2}{S_{xx}}\right)\right) \quad (69)$$

and

$$\hat{\beta}_1 \sim \mathcal{N}\left(\beta_1, \frac{\sigma^2}{S_{xx}}\right). \quad (70)$$

### Tests and Confidence Intervals

In many cases we are not only interested in estimating the model parameters but also in testing hypothesis and constructing confidence intervals.

#### Statistical Test on the Slope Hypothesis

$$\begin{aligned} H_0 : \beta_1 &= \beta_{1,0} \\ H_1 : \beta_1 &\neq \beta_{1,0} \end{aligned} \quad (71)$$

The null hypothesis states that the observations follow the model of simple linear regression with  $\beta_1 = \beta_{1,0}$  and arbitrary  $\beta_0$  and  $\sigma$ . Where  $\beta_{1,0}$  is the slope we want to test.

**Estimated standard error** We can estimate the standard error with the error sum of squares.

$$se(\hat{\beta}_1) = \sqrt{\frac{\hat{\sigma}^2}{S_{xx}}} \text{ with } S_{xx} = \sum_{i=1}^n (x_i - \bar{x})^2 \quad (72)$$

#### Test statistic

$$T = \frac{\hat{\beta}_1 - \beta_{1,0}}{se(\hat{\beta}_1)} \quad (73)$$

Under the null hypothesis the test statistic  $T$  follows a Student's  $t$ -distribution with  $n-2$  degrees of freedom. Values of  $t$  are usually found in a table.

If  $T$  is smaller than  $t$  (from the table), we accept the null hypothesis and conclude that the data agrees also with a model with the slope  $\beta_{1,0}$ .

**P-Value** The probability, under the null hypothesis, of obtaining a result equal to or more extreme than what was actually estimated.

**Confidence Test**  
The test statistic

$$T = \frac{\hat{\beta}_1 - \beta_{1,0}}{se(\beta_1)}$$

is accepted on the significance level  $\alpha$  if

$$t_{\frac{\alpha}{2},n-2} \leq T \leq t_{-\frac{\alpha}{2},n-2}$$

**Confidence interval on the slope**

$$\hat{\beta}_1 - t_{\frac{\alpha}{2},n-2} \cdot se(\beta_1) \leq \beta_1 \leq \hat{\beta}_1 + t_{-\frac{\alpha}{2},n-2} \cdot se(\beta_1)$$

$$\left[ \hat{\beta}_1 - t_{\frac{\alpha}{2},n-2} \cdot se(\beta_1), \hat{\beta}_1 + t_{-\frac{\alpha}{2},n-2} \cdot se(\beta_1) \right] \tag{77}$$

(74) Interpretation: The true value lies in the confidence interval with high probability.

(75) **Part III**

(76) **Design of Experiment**