

A cursory analysis of @nitayart's Broadpwn bug (CVE-2017-9417)

This is part 1 of a two-part series on Broadpwn: part 2 is here: [Crashing phones with Wi-Fi: Exploiting nitayart's Broadpwn bug \(CVE-2017-9417\)](#)

Out of curiosity, I looked into [Nitay Artenstein's Broadpwn bug \(CVE-2017-9417\)](#), which was patched in the [July Android Security Bulletin](#).

TLDR

Broadpwn is a heap overflow on Broadcom Wi-Fi chips. It's triggered when a device receives a WME (Quality-of-Service) information element with a malformed length from a connected network. Scanning for networks without connecting doesn't seem to trigger the bug.

According to @nitayart, who discovered the bug, connecting to a malicious network [is not necessary](#), but I haven't figured out how that would work.

This supposedly affects many recent Android and iOS devices with Broadcom Wi-Fi, but I only experienced effects on a Nexus 6P with June 2017 firmware, and did not seem to affect any iOS devices I tested.

To protect a device, you might want to ensure that it only connects to known good networks, and disable auto connection on unsecured networks.

I don't know anything else about this bug - I was just curious. You should wait for @nitayart - who discovered the bug - to present the findings.

Bug Description

To analyze the bug, I compared the June 2017 firmware on a Nexus 6P (N2G47W) with the patched July 2017 firmware (N2G48B).

I followed [Project Zero's](#) and [Nexmon's](#) guide to extract the firmware. The BCM4358 has two parts to its firmware; the RAM, which is mapped at 0x180000, can be found at /vendor/firmware/fw_bcmdhd.bin. The ROM, which is mapped at 0x0 and is patched by the RAM at runtime, can be dumped from the device. To do that, I followed Nexmon's guide, obtained a copy of dhduutil from LineageOS, and ran on my rooted device

```
# ./dhduutil -i wlan0 membytes -r 0x0 0xA0000 > rom.bin
```

to dump the ROM.

I then installed the July firmware and repeated the steps. Then, I loaded the two firmwares into [BinDiff](#), which found changes in function 0x1b8ado.

An internet search identified this function as `wl_c_bss_parse_wme_ie`. This function is called to handle association, reassociation, and beacon packets. These packets contain information elements, which contains data for extensions to the Wi-Fi standard. The format of each information element (IE) is:

type (1 byte), **length** (1 byte), **data** of (length) bytes

This function processes WME information elements, which are used for the Quality of Service extension. Here's the format of a WME information element:

Element-ID 1-byte (221)	Length 1-byte (24)	OUI 3-bytes (00:50:f2)	OUI Type 1-byte (2)	OUI Sub-Type 1-byte (1)	Version 1-byte (1)	QoS Info Field 1-byte	Reserved 1-byte (0)	AC Parameters 16-byte
-------------------------------	--------------------------	------------------------------	------------------------------	----------------------------------	--------------------------	-----------------------------	---------------------------	-----------------------------

[\(Image Source\)](#)

The patched firmware verifies the length of the IE: if it's not 24 bytes, the firmware ignores the IE, fixing the bug.

This bug can easily be reproduced, as the latest version of [Hostapd](#), the standard software for setting up access points on a Linux computer, supports sending custom information elements.

Hostapd config:

[illegible]

Once the access point is setup, attempt to connect a vulnerable device to the new network. It should fail to connect, the wi-fi card should reset (the Wi-Fi config screen should go empty for a second), and in the device's `dmesg` should see:

```
[ 694.426930] CFG80211-ERROR) wl_cfg80211_disconnect : Reason 2
[ 694.926196] CFG80211-ERROR) wl_cfg80211_connect : timeout in waiting disconnect event
[ 694.933149] CFG80211-ERROR) wl_cfg80211_connect : Connecting to ff:ff:ff:ff:ff:ff with channel (1) ssid YourNetworkName
Here
[ 695.324023] wl_bss_connect_done succeeded with 41:41:41:41:41:41
[ 695.397981] PCIe shared addr read took 0 usec before dongle is ready
[ 695.398360] DMA RX offset from shared Area 0
[ 695.398377] bus->txmode_push is set to 0
[ 695.398575] ring_info_raw: 56
[ 695.326927] "!wf_chspec_malformed(chspec)": file "bcmwifi_channels.c", line "!wf_chspec_malformed(chspec)": file "bcmwifi_channels.c", line
[ 695.398592] 8c 97 23 00 5c 9a 23 00 04 9b 23 00 ac 9b 23 00
[ 695.398652] b8 9b 23 00 00 00 00 00 00 00 00 00 00 00 00
[ 695.398699] 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00
[ 695.398744] 00 00 00 00 2a 00 00 00
[ 695.398774] max H2D queues 42
[ 695.399363] CONSOLE: 37.4Mhz
[ 695.399379] CONSOLE: 000000.173 wl0: wlc_enable_probe_req: state down, deferring setting of host flags
[ 695.399388] CONSOLE: 000000.177 wl0: wl_open
[ 695.399394] CONSOLE: 000003.640 wl0: link up (wl0)
[ 695.399401] CONSOLE: 000003.645
[ 695.399412] CONSOLE: FWID 01-a2412ac4
[ 695.399420] CONSOLE: flags 60040005
[ 695.399425] CONSOLE: 000003.645
[ 695.399430] CONSOLE: TRAP 4(23fc30): pc 5550c, lr 2f697, sp 23fc88, cpsr 2000019f, spsr 200001bf
[ 695.399435] CONSOLE: 000003.645 dfsr 1, dfar 41414145
[ 695.399441] CONSOLE: 000003.645 r0 41414141, r1 2, r2 1, r3 0, r4 22cc00, r5 217634, r6 217048
[ 695.399449] CONSOLE: 000003.645 r7 2, r8 56, r9 1, r10 216120, r11 217224, r12 8848cb89
[ 695.399455] CONSOLE: 000003.645
```

```
[ 695.399460] CONSOLE:      sp+0 00000002 0022cc00 0022d974 00217634
[ 695.399465] CONSOLE: 000003.645      sp+10 00000004 0001aa83 0022d97f 00000168
[ 695.399471] CONSOLE:
[ 695.399476] CONSOLE: 000003.645 sp+14 0001aa83
[ 695.399481] CONSOLE: 000003.645 sp+38 000937eb
[ 695.399486] CONSOLE: 000003.645 sp+44 00003b15
[ 695.399492] CONSOLE: 000003.645 sp+4c 00088659
[ 695.399497] CONSOLE: 000003.645 sp+64 00008fc7
[ 695.399502] CONSOLE: 000003.645 sp+74 0000379b
[ 695.399507] CONSOLE: 000003.645 sp+94 00000a29
[ 695.399512] CONSOLE: 000003.645 sp+c4 0019a9e1
[ 695.399517] CONSOLE: 000003.645 sp+e4 00006a4d
[ 695.399523] CONSOLE: 000003.645 sp+11c 00188113
[ 695.399528] CONSOLE: 000003.645 sp+15c 000852ef
[ 695.399533] CONSOLE: 000003.645 sp+180 00019735
[ 695.399538] CONSOLE: 000003.645 sp+194 0001ec73
[ 695.399543] CONSOLE: 000003.645 sp+1bc 00018ba5
[ 695.399549] CONSOLE: 000003.645 sp+1dc 00018a75
[ 695.399554] CONSOLE: 000003.645 sp+1fc 0000656b
[ 695.399562] dhdpcie_checkdied: msgtrace address : 0x00000000
[ 695.399562] console address : 0x0023DEBC
[ 695.399562] Assrt not built in dongle
[ 695.399562] Dongle trap type 0x4 @ epc 0x5550c, cpsr 0x2000019f, spsr 0x200001bf, sp 0x23fc88, lp 0x2f697, rpc 0x5550c T
rap offset 0x23fc30, r0 0x41414141, r1 0x2, r2 0x1, r3 0x0, r4 0x22cc00, r5 0x217634, r6 0x217048, r7 0x2
```

Devices Tested

Surprisingly, not many devices are affected.

Affected:

- Nexus 6P - June security update - crashes wifi chip, wifi immediately restarts

Firmware version:

```
4358a3-rom1/pcie-ag-p2p-pno-aoe-pktfilter-keepalive-sr-mchan-pktctx-hostpp-
lpc-pwropt-txbf-wll1u-mfp-betdls-amsdtx5g-txpwr-rcc-wepso-sarctrl-btcdyn-
xorcsu-sum-proxd-gscan-linkstat-ndoe-hs20sta-oobrev-hchk-logtrace-rmon-apf-
d11status Version: 7.112.201.3 (r682908) CRC: 9e7ed84e Date: Fri 2017-02-03
11:21:56 PST Ucode Ver: 963.317 FWID: 01-a2412ac4
```

Unaffected:

- Nexus 6P - July security update - connects to the network without issue

Firmware version:

```
4358a3-rom1/pcie-ag-p2p-pno-aoe-pktfilter-keepalive-sr-mchan-pktctx-hostpp-
lpc-pwropt-txbf-wll1u-mfp-betdls-amsdtx5g-txpwr-rcc-wepso-sarctrl-btcdyn-
xorcsu-sum-proxd-gscan-linkstat-ndoe-hs20sta-oobrev-hchk-logtrace-rmon-apf-
d11status Version: 7.112.201.4 (r702727) CRC: 3454c05f Date: Fri 2017-06-02
17:32:42 PDT Ucode Ver: 963.317 FWID: 01-1c2706c3
```

- Nexus 7 (2012), CyanogenMod 12.1 Nightly - connects to the network without issue. It's probably too old to be affected?

Firmware version:

```
4330b2-rom1/sdio-g-p2p-idsup-idauth-pno Version: 5.90.195.114 CRC: 24b8f965
Date: wed 2013-01-23 17:48:37 PST FWID 01-f9e7e464
```

- iPad Air: connects to the network without issue. Also too old to be affected?
- Newer iOS devices: simply refuses to connect to network. Already patched?
- Any device using a different Wi-Fi chip. For example, all OnePlus devices use Qualcomm Atheros Wi-Fi.

I don't have any other devices using a recent Broadcom chip. Anybody want to test other devices?

Impact

The beacon code has the same issue, but is disabled until the first association response is processed, so just scanning for wi-fi shouldn't cause issues.

I wonder if one can spoof beacons or association responses from existing connected APs. There's [802.11w, Protected Management Frames](#) which sounds relevant. If it's possible to spoof beacons or association responses, then it's not enough to avoid connecting to suspicious Wi-Fi; one must disable Wi-Fi entirely. Anyone want to chime in on the feasibility?

According to @nitayart, this exploit can get code execution on the Wi-Fi chip, and then on the main processor. This seems difficult: [Project Zero's similar Broadcom Wi-Fi heap overflow](#) was very complicated to exploit, and they had allocate/free primitives through the TDLS request/responses. The buffer overflowed here is allocated at firmware startup and only deallocated at shutdown, I believe, so it may be harder to exploit. I'm very much looking forward to @nitayart's presentation.

Zhuowei Zhang (@zhuowei), 2017-07-06