

MCF5282 User's Manual Errata

by: Microcontroller Division

This errata document describes corrections to the *MCF5282 ColdFire Microcontroller User's Manual*, order number MCF5282UM. For convenience, the addenda items are grouped by revision. Please check our website at <http://www.freescale.com> for the latest updates.

Table of Contents

1	Errata for Revision 2.3	2
2	Errata for Revision 2.1 & 2.2	4
3	Errata for Revision 2.0	5
4	Errata for Revision 1.0	5
5	Revision History	15

1 Errata for Revision 2.3

Table 1. MCF5282UM Rev 2.3 Errata

Location	Description
Table 5-1/Page 5-2	The PRI1/PRI2 text description does not match the table below it. It should be: "If a bit is set, CPU has priority. If a bit is cleared, DMA has priority."
Chapter 8	Remove any references to the core watchdog timer being able to reset the device. It is only able to interrupt the processor. Use the peripheral watchdog timer described in Chapter 18 if needing a watchdog timer to reset the device.
Table 9-4/Page 9-7	In the table for MFD bit definition, footnote (1) equation should read: $f_{\text{sys}} = \frac{f_{\text{ref}} \times 2(\text{MFD} + 2)}{2^{\text{RFD}}}; f_{\text{ref}} \times 2(\text{MFD} + 2) \leq f_{\text{sys(max)}}; f_{\text{sys}} \leq f_{\text{sys(max)}}$ <p>Where $f_{\text{sys(max)}}$ is the maximum system frequency for the particular MCF5282 device (66MHz or 80MHz)</p>
Section 10.3.6/Page 10-11	Include the following text in the section description and as a note in Figure 10-9. "It is the responsibility of the software to program the ICR _n registers with unique and non-overlapping level and priority definitions. Failure to program the ICR _n registers in this manner can result in undefined behavior. If a specific interrupt request is completely unused, the ICR _n value can remain in its reset (and disabled) state."
Figure 10-6/Page 10-9	Interrupt Force Register Low (INTFRCL _n) is illustrated as read-only in the figure. However, this register should be read/write.
Table 10-14/Page 10-15	Change flag clearing mechanism for sources 24-26. They should read as follows: Write ERR_INT = 1 after reading ERR_INT = 1 Write BOFF_INT = 1 after reading BOFF_INT = 1 Write WAKE_INT = 1 after reading WAKE_INT = 1
Table 12-7/Page 12-7	BAM bit field description, the first example should read "So, if CSAR0 = 0x0000 and CSMR0[BAM] = 0x0001" instead of "So, if CSAR0 = 0x0000 and CSMR0[BAM] = 0x0008".
Table 15-1/Page 15-3	NOP command entry. Replace "SRAS asserted" with "SDRAM_CS[1:0] asserted"
Chapter 17	The maximum buffer size of the FEC is 2032 bytes. Replace any mention of the max size being 2047 bytes with 2032 bytes.
Table 17-11/Page 17-19	Add RMON_R_DROP with an IPSBAR Offset of 0x1280 and a description of 'Count of frames not counted correctly'.
Figure 17-26/Page 17-41	Change EMRBR register address from "IPSBAR + 0x11B8" to "IPSBAR + 0x1188".
Section 20.5.13/Page 20-12	Deleted reference to nonexistent CF bits in the figure and bit descriptions for the GPTFLG2 register.
Figure 23-18/Page 23-18	Remove the two 16-bit divider blocks from timer input, as the divider is not available using external clock sources.
Section 23.5.1.2.2/Page 23-19	Remove 16-bit divider from equation, as the divider is not available using external clock sources.
Section 25.5.8/Page 25-25	Change end of last sentence from "...and can be written by the host to '0'." to "...and can be written by the host to '1'."

Table 1. MCF5282UM Rev 2.3 Errata (continued)

Location	Description																																														
Table 25-17/Page 25-29	Remove the following information from the BITERR and ACKERR descriptions as these fields are read only: "To clear this bit, first read it as a one, then write it as a one. Writing zero has no effect." (This is a rescindment of a previous documentation errata.) Change last sentence in ERRINT description from: "To clear this bit, first read it as a one, then write as a zero. Writing a one has no effect." to "To clear this bit, first read it as a one, then write a one. Writing a zero has no effect." Add the following information to the BOFFINT and WAKEINT descriptions: "To clear this bit, first read it as a one, then write it as a one. Writing zero has no effect."																																														
Table 25-17/Page 25-27	Definition of bits ERRINT and BOFFINT are incorrect for register ESTAT: ERRINT should be bit 1, BOFFINT should be bit 2. They should be cleared by writing a one instead of a zero.																																														
Table 26-1/Page 26-5	Change description field for DTOUT1 from "DMA timer 1 output / Port TD[3]..." to "DMA timer 1 output / Port TD[2]..." Change description field for DTIN0 from "DMA timer 0 input / Port TD[3]..." to "DMA timer 1 output / Port TD[1]..." Change description field for DTOUT0 from "DMA timer 0 output / Port TD[3]..." to "DMA timer 1 output / Port TD[0]..."																																														
Chapter 33	Add the following note: "It is crucial during power-up that VDD never exceeds VDDH by more that ~0.3V. There are diode devices between the two voltage domains, and violating this rule can lead to a latch-up condition."																																														
Table 33-3/Page 33-3	In the V _{OH} and V _{OL} entries, change the respective I _{OH} and I _{OL} specs from "I _{OH} = -2.0mA" to "I _{OH} = -5.0mA" and "I _{OL} = +2.0mA" to "I _{OL} = +5.0mA"																																														
Table 33-8/Page 33-7	In the PLL Electrical Specifications table, only specs for the 80MHz MCF5282 device were listed. Insert specs for the 66MHz device in the first 2 rows and also declare symbol f _{sys(max)} , as shown below: <table><tr><th rowspan="2">Characteristic</th><th rowspan="2">Symbol</th><th rowspan="2">Min</th><th colspan="2">Max</th><th rowspan="2">Unit</th></tr><tr><th>66MHz</th><th>80MHz</th></tr><tr><td>PLL Reference Frequency Range</td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>Crystal reference</td><td>f_{ref_crystal}</td><td>2</td><td>8.33</td><td>10.0</td><td rowspan="3">MHz</td></tr><tr><td>External reference</td><td>f_{ref_ext}</td><td>2</td><td>8.33</td><td>10.0</td></tr><tr><td>1:1 Mode</td><td>f_{ref_1:1}</td><td>33.33</td><td>66.66</td><td>80</td></tr><tr><td>System Frequency ¹</td><td>f_{sys}</td><td></td><td>f_{sys(max)}</td><td>f_{sys(max)}</td><td rowspan="3">MHz</td></tr><tr><td>External Clock Mode</td><td></td><td>0</td><td>66.66</td><td>80</td></tr><tr><td>On-Chip PLL Frequency</td><td></td><td>f_{ref} / 32</td><td>66.66</td><td>80</td></tr></table>	Characteristic	Symbol	Min	Max		Unit	66MHz	80MHz	PLL Reference Frequency Range						Crystal reference	f _{ref_crystal}	2	8.33	10.0	MHz	External reference	f _{ref_ext}	2	8.33	10.0	1:1 Mode	f _{ref_1:1}	33.33	66.66	80	System Frequency ¹	f _{sys}		f _{sys(max)}	f _{sys(max)}	MHz	External Clock Mode		0	66.66	80	On-Chip PLL Frequency		f _{ref} / 32	66.66	80
Characteristic	Symbol				Min	Max		Unit																																							
		66MHz	80MHz																																												
PLL Reference Frequency Range																																															
Crystal reference	f _{ref_crystal}	2	8.33	10.0	MHz																																										
External reference	f _{ref_ext}	2	8.33	10.0																																											
1:1 Mode	f _{ref_1:1}	33.33	66.66	80																																											
System Frequency ¹	f _{sys}		f _{sys(max)}	f _{sys(max)}	MHz																																										
External Clock Mode		0	66.66	80																																											
On-Chip PLL Frequency		f _{ref} / 32	66.66	80																																											
Section 33.13.1/Page 33-21	Remove second sentence: "There is no minimum frequency requirement."																																														
Section 33.13.2/Page 33-22	Remove second sentence: "There is no minimum frequency requirement." Remove second paragraph as this feature is not supported on this device: "The transmit outputs (ETXD[3:0], ETXEN, ETXER) can be programmed to transition from either the rising or falling edge of ETXCLK, and the timing is the same in either case. This options allows the use of non-compliant MII PHYs. Refer to the Ethernet chapter for details of this option and how to enable it."																																														
Table A-3/Page A-4	The CSMR1 and CSCR1 register addresses are incorrect. They should be IPSBAR + 0x090 and IPSBAR + 0x096 respectively																																														

2 Errata for Revision 2.1 & 2.2

Table 2. MCF5282UM Rev 2.1 & 2.2 Errata

Location	Description
Figure 4-2/4-6	Changed bit 23 from DIDI to DISI
Table 4-6/4-9	Under 'Configuration' for 'Instruction Cache' the 'Operation' entry changed to "Invalidate 2 KByte data cache"
Table 4-6/4-9	Under 'Configuration' for 'Data Cache' the 'Operation' entry changed to "Invalidate 2 KByte instruction cache"
Figure 6-3/6-6	Changed bit 8 to write-only instead of read/write
Table 6-10/6-15	Removed "selected by BKSL[1:0]" as these are internal signal names not necessary for end-user.
Table 9-4/9-7	<p>In the table for MFD bit definition, footnote (1) equation should read:</p> $f_{\text{sys}} = \frac{f_{\text{ref}} \times 2(\text{MFD} + 2)}{2^{\text{RFD}}}; f_{\text{ref}} \times 2(\text{MFD} + 2) \leq f_{\text{sys}(\text{max})}; f_{\text{sys}} \leq f_{\text{sys}(\text{max})}$ <p>Where $f_{\text{sys}(\text{max})}$ is the maximum system frequency for the particular MCF5282 device (66MHz or 80MHz)</p>
10.3.2/10-8	Add the following note: 'If an interrupt source is being masked in the interrupt controller mask register (IMR) or a module's interrupt mask register while the interrupt mask in the status register (SR[I]) is set to a value lower than the interrupt's level, a spurious interrupt may occur. This is because by the time the status register acknowledges this interrupt, the interrupt has been masked. A spurious interrupt is generated because the CPU cannot determine the interrupt source. To avoid this situation for interrupts sources with levels 1-6, first write a higher level interrupt mask to the status register, before setting the mask in the IMR or the module's interrupt mask register. After the mask is set, return the interrupt mask in the status register to its previous value. Since level seven interrupts cannot be disabled in the status register prior to masking, use of the IMR or module interrupt mask registers to disable level seven interrupts is not recommended.'
Chapter 17	The maximum buffer size of the FEC is 2032 bytes. Replace any mention of the max size being 2047 bytes with 2032 bytes.
Table 17-2/17-5	In PALR/PAUR entry, delete "(only needed for full duplex flow control)"
Figure 17-23/17-39	Change FRSR to read/write instead of read-only.
25.4.10/25-16	Change CANICR to ICR _n .
Table 25-17/25-29	Add the following information to BITERR and ACKERR descriptions: "To clear this bit, first read it as a one, then write it as a one. Writing zero has no effect."
Table 25-17/25-30	Change bit ordering: ERRINT should be bit 2 and BOFFINT should be bit 1.
Table 25-19/25-32	Change BUF _n field description from "To clear an interrupt flag, first read the flag as a one, then write it as a zero" to "To clear an interrupt flag, first read the flag as a one, then write it as a one."

Table 2. MCF5282UM Rev 2.1 & 2.2 Errata (continued)

Location	Description																																														
Chapter 33	It is crucial during power-up that VDD never exceeds VDDH by more that ~0.3V. There are diode devices between the two voltage domains, and violating this rule can lead to a latch-up condition.																																														
Table 33-8/33-7	<p>In the PLL Electrical Specifications table, only specs for the 80MHz MCF5282 device were listed. Insert specs for the 66MHz device in the first 2 rows and also declare symbol $f_{\text{sys(max)}}$, as shown below:</p> <table><tr><th rowspan="2">Characteristic</th><th rowspan="2">Symbol</th><th rowspan="2">Min</th><th colspan="2">Max</th><th rowspan="2">Unit</th></tr><tr><th>66MHz</th><th>80MHz</th></tr><tr><td>PLL Reference Frequency Range</td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>Crystal reference</td><td>$f_{\text{ref_crystal}}$</td><td>2</td><td>8.33</td><td>10.0</td><td rowspan="3">MHz</td></tr><tr><td>External reference</td><td>$f_{\text{ref_ext}}$</td><td>2</td><td>8.33</td><td>10.0</td></tr><tr><td>1:1 Mode</td><td>$f_{\text{ref_1:1}}$</td><td>33.33</td><td>66.66</td><td>80</td></tr><tr><td>System Frequency ¹</td><td>f_{sys}</td><td></td><td>$f_{\text{sys(max)}}$</td><td>$f_{\text{sys(max)}}$</td><td rowspan="3">MHz</td></tr><tr><td>External Clock Mode</td><td></td><td>0</td><td>66.66</td><td>80</td></tr><tr><td>On-Chip PLL Frequency</td><td></td><td>$f_{\text{ref}} / 32$</td><td>66.66</td><td>80</td></tr></table>	Characteristic	Symbol	Min	Max		Unit	66MHz	80MHz	PLL Reference Frequency Range						Crystal reference	$f_{\text{ref_crystal}}$	2	8.33	10.0	MHz	External reference	$f_{\text{ref_ext}}$	2	8.33	10.0	1:1 Mode	$f_{\text{ref_1:1}}$	33.33	66.66	80	System Frequency ¹	f_{sys}		$f_{\text{sys(max)}}$	$f_{\text{sys(max)}}$	MHz	External Clock Mode		0	66.66	80	On-Chip PLL Frequency		$f_{\text{ref}} / 32$	66.66	80
Characteristic	Symbol				Min	Max		Unit																																							
		66MHz	80MHz																																												
PLL Reference Frequency Range																																															
Crystal reference	$f_{\text{ref_crystal}}$	2	8.33	10.0	MHz																																										
External reference	$f_{\text{ref_ext}}$	2	8.33	10.0																																											
1:1 Mode	$f_{\text{ref_1:1}}$	33.33	66.66	80																																											
System Frequency ¹	f_{sys}		$f_{\text{sys(max)}}$	$f_{\text{sys(max)}}$	MHz																																										
External Clock Mode		0	66.66	80																																											
On-Chip PLL Frequency		$f_{\text{ref}} / 32$	66.66	80																																											

3 Errata for Revision 2.0

Table 3. MCF5282UM Rev 2.0 Errata

Location	Description
Table 33-8/33-9	Reference to 'TA = TL to TH' was not deleted. Delete.

4 Errata for Revision 1.0

Table 4. MCF5282UM Rev 1.0 Errata

Location	Description
1.1/1-1	Change 'Real time debug support, with two user-visible hardware breakpoint registers' To 'Real time debug support, with one user-visible hardware breakpoint register'
Table 2-2/2-7	Change the I field description to read: "Interrupt level mask. Defines the current interrupt level. Interrupt requests are inhibited for all priority levels less than or equal to the current level, except the edge-sensitive level 7 request, which cannot be masked."

Table 4. MCF5282UM Rev 1.0 Errata (continued)

Location	Description																					
Table 5-1/5-2	<p>Replace the description of PRI1 and PRI2 with the following:</p> <table><tr><th colspan="3">Description</th></tr><tr><td colspan="3">Priority bit. PRI1 determines if DMA or CPU has priority in upper 32K bank of memory. PRI2 determines if DMA or CPU has priority in lower 32K bank of memory. If bit is set, DMA has priority. If bit is reset, CPU has priority. Priority is determined according to the following table.</td></tr><tr><th>PRI[1:2]</th><th>Upper Bank Priority</th><th>Lower Bank Priority</th></tr><tr><td>00</td><td>DMA Accesses</td><td>DMA Accesses</td></tr><tr><td>01</td><td>DMA Accesses</td><td>CPU Accesses</td></tr><tr><td>10</td><td>CPU Accesses</td><td>DMA Accesses</td></tr><tr><td>11</td><td>CPU Accesses</td><td>CPU Accesses</td></tr></table> <p>NOTE: The Motorola-recommended setting for the priority bits is 00.</p>	Description			Priority bit. PRI1 determines if DMA or CPU has priority in upper 32K bank of memory. PRI2 determines if DMA or CPU has priority in lower 32K bank of memory. If bit is set, DMA has priority. If bit is reset, CPU has priority. Priority is determined according to the following table.			PRI[1:2]	Upper Bank Priority	Lower Bank Priority	00	DMA Accesses	DMA Accesses	01	DMA Accesses	CPU Accesses	10	CPU Accesses	DMA Accesses	11	CPU Accesses	CPU Accesses
Description																						
Priority bit. PRI1 determines if DMA or CPU has priority in upper 32K bank of memory. PRI2 determines if DMA or CPU has priority in lower 32K bank of memory. If bit is set, DMA has priority. If bit is reset, CPU has priority. Priority is determined according to the following table.																						
PRI[1:2]	Upper Bank Priority	Lower Bank Priority																				
00	DMA Accesses	DMA Accesses																				
01	DMA Accesses	CPU Accesses																				
10	CPU Accesses	DMA Accesses																				
11	CPU Accesses	CPU Accesses																				
Table 5-1/5-3	<p>Add the following note to the SPV bit description: “The BDE bit in the second RAMBAR register must also be set to allow dual port access to the SRAM. For more information, see Section 8.4.2, ‘Memory Base Address Register (RAMBAR).’”</p>																					

Table 4. MCF5282UM Rev 1.0 Errata (continued)

Location	Description
Figure 6-2/6-4	<p>Replace Figure 6-2, “CFM 512K Array Memory Map,” with the figure below.</p> <p>Figure 6-2. CFM 512K Array Memory Map</p> <p>Each memory array = 64 Kbytes (16 bits wide × 32K) Each physical block = 128 Kbytes (32 bits wide × 32K)</p>
Table 6-12/6-16	Change value for page erase verify command to 0x06.
Table 6-13/6-20	Change value for page erase verify command to 0x06.
Table 8-3/8-5	Add the following note the BDE bit description: “The SPV bit in the CPU’s RAMBAR must also be set to allow dual port access to the SRAM. For more information, see Section 5.3.1, ‘SRAM Base Address Register (RAMBAR).’”
Figure 9-1/9-3	Remove ÷ 2 from CLKGEN block.
10.3.6/10-11	Add this text to the end of the first paragraph: “If a specific interrupt request is completely unused, the ICR _n x value can remain in its reset (and disabled) state.”
10.5/10-17	Add the following note: “The wakeup mask level taken from LPICR[6:4] is adjusted by hardware to allow a level 7 IRQ to generate a wakeup. That is, the wakeup mask value used by the interrupt controller must be in the range of 0–6.”
Figure 12-4/12-8	Change CSCR _n to reflect that AA is set to ‘1’ at reset.
13.5/13-15	Remove final paragraph. The paragraph incorrectly states that the MCF5282 does not have a bus monitor.

Table 4. MCF5282UM Rev 1.0 Errata (continued)

Location	Description																												
Table 17-13/17-26	Change encodings for bits 31–9 to: 0The corresponding interrupt source is masked. 1The corresponding interrupt source is not masked.																												
Chapter 19	Change PIT1–PIT4 to PIT0–PIT3 throughout chapter. When a timer is referenced individually, PIT1 should be PIT0, PIT2 should be PIT1, PIT3 should be PIT2, and PIT4 should be PIT3. Other chapters in the user’s manual use the correct nomenclature: PIT0–PIT3.																												
19.6.3/19-7	Change timeout period equation to the equation below. Timeout period = $\frac{\text{PRE}[3:0] \times (\text{PM}[15:0] + 1) \times 2}{\text{system clock}}$																												
Figure 23-11	Change UISR bits 5–3 to reserved bits																												
24.6.1/24-11	Change ‘I2CR = 0xA’ to ‘I2CR = 0xA0.’																												
27.2.1/27-2	Change ‘When interfacing to 16-bit ports, the port C and D pins and PJ[7:6] (BS[3:2]) can be configured as general-purpose input/output (I/O)’ To ‘When interfacing to 16-bit ports, the port C and D pins and PJ[5:4] (BS[1:0]) can be configured as general-purpose input/output (I/O)’																												
32.2/32-7	Added additional device number order information to Table 32-2.																												
<div>Table 32-2. Orderable Part Numbers</div> <table><tr><th>Motorola Part Number</th><th>Description</th><th>Speed</th><th>Temperature</th></tr><tr><td>MCF5280CVF66</td><td>MCF5280 RISC Microprocessor, 256 MAPBGA</td><td>66.67 MHz</td><td>-40° to +85° C</td></tr><tr><td>MCF5280CVF80</td><td>MCF5280 RISC Microprocessor, 256 MAPBGA</td><td>80 MHz</td><td>-40° to +85° C</td></tr><tr><td>MCF5281CVF66</td><td>MCF5281 RISC Microprocessor, 256 MAPBGA</td><td>66.67 MHz</td><td>-40° to +85° C</td></tr><tr><td>MCF5281CVF80</td><td>MCF5281 RISC Microprocessor, 256 MAPBGA</td><td>80 MHz</td><td>-40° to +85° C</td></tr><tr><td>MCF5282CVF66</td><td>MCF5282 RISC Microprocessor, 256 MAPBGA</td><td>66.67 MHz</td><td>-40° to +85° C</td></tr><tr><td>MCF5282CVF80</td><td>MCF5282 RISC Microprocessor, 256 MAPBGA</td><td>80 MHz</td><td>-40° to +85° C</td></tr></table>		Motorola Part Number	Description	Speed	Temperature	MCF5280CVF66	MCF5280 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C	MCF5280CVF80	MCF5280 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C	MCF5281CVF66	MCF5281 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C	MCF5281CVF80	MCF5281 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C	MCF5282CVF66	MCF5282 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C	MCF5282CVF80	MCF5282 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C
Motorola Part Number	Description	Speed	Temperature																										
MCF5280CVF66	MCF5280 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C																										
MCF5280CVF80	MCF5280 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C																										
MCF5281CVF66	MCF5281 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C																										
MCF5281CVF80	MCF5281 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C																										
MCF5282CVF66	MCF5282 RISC Microprocessor, 256 MAPBGA	66.67 MHz	-40° to +85° C																										
MCF5282CVF80	MCF5282 RISC Microprocessor, 256 MAPBGA	80 MHz	-40° to +85° C																										
Chapter 33	Delete references to ‘TA = TL to TH’.																												
Table 33-1/33-1	The Digital Input Voltage (V _{IN}) absolute maximum rating should be -0.3 to 6.0 V																												
Table 33-6/33-8	The normal operation analog supply current (I _{DDA}) maximum value has been changed to 5.0 mA.																												

Table 4. MCF5282UM Rev 1.0 Errata (continued)

Location	Description
Figure 33-5/33-16	<p>Replace Figure 33-5, 'SDRAM Read Cycle' with the figure below.</p> <p style="text-align: center;">Figure 33-5. SDRAM Read Cycle</p>
Table 14-3/14-11	Change 'Internal Pull-Up' column to pull-up indications in the table below.

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
Reset						
R11	$\overline{\text{RSTI}}$	—	—	Reset in	I	Yes
P11	$\overline{\text{RSTO}}$	—	—	Reset out	O	—
Clock						
T8	EXTAL	—	—	External clock/crystal in	I	—

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
R8	XTAL	—	—	Crystal drive	O	—
N7	CLKOUT	—	—	Clock out	O	—
Chip Configuration/Mode Selection						
R14	CLKMOD0	—	—	Clock mode select	I	Yes
T14	CLKMOD1	—	—	Clock mode select	I	Yes
T11	$\overline{\text{RCON}}$	—	—	Reset configuration enable	I	Yes
H1	D26	PA2	—	Chip mode	I/O	—
K2	D17	PB1	—	Chip mode	I/O	—
K3	D16	PB0	—	Chip mode	I/O	—
J4	D19	PB3	—	Boot device/data port size	I/O	—
K1	D18	PB2	—	Boot device/data port size	I/O	—
J2	D21	PB5	—	Output pad drive strength	I/O	—
External Memory Interface and Ports						
C6:B6:A5	A[23:21]	PF[7:5]	$\overline{\text{CS}}$ [6:4]	Address bus	O	Yes
C4:B4:A4:B3:A3	A[20:16]	PF[4:0]	—	Address bus	O	Yes
A2:B1:B2:C1: C2:C3:D1:D2	A[15:8]	PG[7:0]	—	Address bus	O	Yes
D3:D4:E1:E2: E3:E4:F1:F2	A[7:0]	PH[7:0]	—	Address bus	O	Yes
F3:G1:G2:G3: G4:H1:H2:H3	D[31:24]	PA[7:0]	—	Data bus	I/O	—
H4:J1:J2:J3: J4:K1:K2:K3	D[23:16]	PB[7:0]	—	Data bus	I/O	—
L1:L2:L3:L4: M1:M2:M3:M4	D[15:8]	PC[7:0]	—	Data bus	I/O	—
N1:N2:N3:P1: N5:T6:R6:P6	D[7:0]	PD[7:0]	—	Data bus	I/O	—
P14:T15:R15:R16	$\overline{\text{BS}}$ [3:0]	PJ[7:4]	—	Byte strobe	I/O	Yes
N16	$\overline{\text{OE}}$	PE7	—	Output enable	I/O	—
P16	$\overline{\text{TA}}$	PE6	—	Transfer acknowledge	I/O	Yes
P15	$\overline{\text{TEA}}$	PE5	—	Transfer error acknowledge	I/O	Yes
N15	$\text{R}/\overline{\text{W}}$	PE4	—	Read/write	I/O	Yes
N14	SIZ1	PE3	SYNCA	Transfer size	I/O	Yes ³

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
M16	SIZ0	PE2	SYNCB	Transfer size	I/O	Yes ⁴
M15	$\overline{\text{TS}}$	PE1	SYNCA	Transfer start	I/O	Yes
M14	$\overline{\text{TIP}}$	PE0	SYNCB	Transfer in progress	I/O	Yes
Chip Selects						
L16:L15:L14:L13	$\overline{\text{CS}}[3:0]$	PJ[3:0]	—	Chip selects 3-0	I/O	Yes
C6:B6:A5	A[23:21]	PF[7:5]	$\overline{\text{CS}}[6:4]$	Chip selects 6-4	O	Yes
SDRAM Controller						
H15	$\overline{\text{SRAS}}$	PSD5	—	SDRAM row address strobe	I/O	—
H16	$\overline{\text{SCAS}}$	PSD4	—	SDRAM column address strobe	I/O	—
G15	$\overline{\text{DRAMW}}$	PSD3	—	SDRAM write enable	I/O	—
H13:G16	$\overline{\text{SDRAM_CS}}[1:0]$	PSD[2:1]	—	SDRAM chip selects	I/O	—
H14	SCKE	PSD0	—	SDRAM clock enable	I/O	—
External Interrupts Port						
B15:B16:C14:C15: C16: D14:D15	$\overline{\text{IRQ}}[7:1]$	PNQ[7:1]	—	External interrupt request	I/O	—
Ethernet						
C10	EMDIO	PAS5	URXD2	Management channel serial data	I/O	—
B10	EMDC	PAS4	UTXD2	Management channel clock	I/O	—
A8	ETXCLK	PEH7	—	MAC Transmit clock	I/O	—
D6	ETXEN	PEH6	—	MAC Transmit enable	I/O	—
D7	ETXD0	PEH5	—	MAC Transmit data	I/O	—
B11	ECOL	PEH4	—	MAC Collision	I/O	—
A10	ERXCLK	PEH3	—	MAC Receive clock	I/O	—
C8	ERXDV	PEH2	—	MAC Receive enable	I/O	—
D9	ERXD0	PEH1	—	MAC Receive data	I/O	—
A11	ECRS	PEH0	—	MAC Carrier sense	I/O	—
A7:B7:C7	ETXD[3:1]	PEL[7:5]	—	MAC Transmit data	I/O	—
D10	ETXER	PEL4	—	MAC Transmit error	I/O	—
A9:B9:C9	ERXD[3:1]	PEL[3:1]	—	MAC Receive data	I/O	—
B8	ERXER	PEL0	—	MAC Receive error	I/O	—

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
FlexCAN						
D16	CANRX	PAS3	URXD2	FlexCAN Receive data	I/O	—
E13	CANTX	PAS2	UTXD2	FlexCAN Transmit data	I/O	—
I ² C						
E14	SDA	PAS1	URXD2	I ² C Serial data	I/O	Yes ⁵
E15	SCL	PAS0	UTXD2	I ² C Serial clock	I/O	Yes ⁶
QSPI						
F13	QSPI_DOUT	PQS0	—	QSPI data out	I/O	—
E16	QSPI_DIN	PQS1	—	QSPI data in	I/O	—
F14	QSPI_CLK	PQS2	—	QSPI clock	I/O	—
G14:G13:F16:F15	QSPI_CS[3:0]	PQS[6:3]	—	QSPI chip select	I/O	—
UARTs						
R7	URXD1	PUA3	—	U1 receive data	I/O	—
P7	UTXD1	PUA2	—	U1 transmit data	I/O	—
N6	URXD0	PUA1	—	U0 receive data	I/O	—
T7	UTXD0	PUA0	—	U0 transmit data	I/O	—
C10	EMDIO	PAS5	URXD2	U2 receive data	I/O	—
B10	EMDC	PAS4	UTXD2	U2 transmit data	I/O	—
D16	CANRX	PAS3	URXD2	U2 receive data	I/O	—
E13	CANTX	PAS2	UTXD2	U2 transmit data	I/O	—
E14	SDA	PAS1	URXD2	U2 receive data	I/O	Yes ⁵
E15	SCL	PAS0	UTXD2	U2 transmit data	I/O	Yes ⁶
K16	DTIN3	PTC3	$\overline{\text{URTS1}}/\overline{\text{URTS0}}$	U1/U0 Request to Send	I/O	—
K15	DTOUT3	PTC2	$\overline{\text{URTS1}}/\overline{\text{URTS0}}$	U1/U0 Request to Send	I/O	—
K14	DTIN2	PTC1	$\overline{\text{UCTS1}}/\overline{\text{UCTS0}}$	U1/U0 Clear to Send	I/O	—
K13	DTOUT2	PTC0	$\overline{\text{UCTS1}}/\overline{\text{UCTS0}}$	U1/U0 Clear to Send	I/O	—
J16	DTIN1	PTD3	$\overline{\text{URTS1}}/\overline{\text{URTS0}}$	U1/U0 Request to Send	I/O	—

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
J15	DTOUT1	PTD2	$\overline{\text{URTS1}}/\text{URTS0}$	U1/U0 Request to Send	I/O	—
J14	DTIN0	PTD1	$\overline{\text{UCTS1}}/\text{UCTS0}$	U1/U0 Clear to Send	I/O	—
J13	DTOUT0	PTD0	$\overline{\text{UCTS1}}/\text{UCTS0}$	U1/U0 Clear to Send	I/O	—
General Purpose Timers						
T13:R13:P13:N13	GPTA[3:0]	PTA[3:0]	—	Timer A IC/OC/PAI	I/O	Yes
T12:R12:P12:N12	GPTB[3:0]	PTB[3:0]	—	Timer B IC/OC/PAI	I/O	Yes
N14	SIZ1	PE3	SYNCA	Timer A synchronization input	I/O	Yes ³
M16	SIZ0	PE2	SYNCB	Timer B synchronization input	I/O	Yes ⁴
M15	$\overline{\text{TS}}$	PE1	SYNCA	Timer A synchronization input	I/O	Yes
M14	$\overline{\text{TIP}}$	PE0	SYNCB	Timer B synchronization input	I/O	Yes
DMA Timers						
K16	DTIN3	PTC3	$\overline{\text{URTS1}}/\text{URTS0}$	Timer 3 in	I/O	—
K15	DTOUT3	PTC2	$\overline{\text{URTS1}}/\text{URTS0}$	Timer 3 out	I/O	—
K14	DTIN2	PTC1	$\overline{\text{UCTS1}}/\text{UCTS0}$	Timer 2 in	I/O	—
K13	DTOUT2	PTC0	$\overline{\text{UCTS1}}/\text{UCTS0}$	Timer 2 out	I/O	—
J16	DTIN1	PTD3	$\overline{\text{URTS1}}/\text{URTS0}$	Timer 1 in	I/O	—
J15	DTOUT1	PTD2	$\overline{\text{URTS1}}/\text{URTS0}$	Timer 1 out	I/O	—
J14	DTIN0	PTD1	$\overline{\text{UCTS1}}/\text{UCTS0}$	Timer 0 in	I/O	—
J13	DTOUT0	PTD0	$\overline{\text{UCTS1}}/\text{UCTS0}$	Timer 0 out	I/O	—
Queued Analog-to-Digital Converter (QADC)						
T3	AN0	PQB0	ANW	Analog channel 0	I/O	—
R2	AN1	PQB1	ANX	Analog channel 1	I/O	—
T2	AN2	PQB2	ANY	Analog channel 2	I/O	—
R1	AN3	PQB3	ANZ	Analog channel 3	I/O	—

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
R4	AN52	PQA0	MA0	Analog channel 52	I/O	—
T4	AN53	PQA1	MA1	Analog channel 53	I/O	—
P3	AN55	PQA3	ETRIG1	Analog channel 55	I/O	—
R3	AN56	PQA4	ETRIG2	Analog channel 56	I/O	—
P4	VRH	—	—	High analog reference	I	—
T5	VRL	—	—	Low analog reference	I	—
Debug and JTAG Test Port Control						
R9	JTAG_EN	—	—	JTAG Enable	I	—
P9	DSCLK	$\overline{\text{TRST}}$	—	Debug clock / TAP reset	I	Yes ⁷
T9	TCLK	—	—	TAP clock	I	Yes ⁷
P10	$\overline{\text{BKPT}}$	TMS	—	Breakpoint/TAP test mode select	I	Yes ⁷
R10	DSI	TDI	—	Debug data in / TAP data in	I	Yes ⁷
T10	DSO	TDO	—	Debug data out / TAP data out	O	—
C12:D12:A13:B13	DDATA[3:0]	PDD[7:4]	—	Debug data	I/O	—
C13:A14:B14:A15	PST[3:0]	PDD[3:0]	—	Processor status data	I/O	—
Test						
N10	TEST	—	—	Test mode pin	I	—
Power Supplies						
R5	VDDA	—	—	Analog positive supply	I	—
P5:T1	VSSA	—	—	Analog ground	I	—
P2	VDDH	—	—	ESD positive supply	I	—
N8	VDDPLL	—	—	PLL positive supply	I	—
P8	VSSPLL	—	—	PLL ground	I	—
A6:C11	VPP	—	—	Flash (stress) programming voltage	I	—
A12:C5:D5:D11	VDDF	—	—	Flash positive supply	I	—
B5:B12:	VSSF	—	—	Flash module ground	I	—
N11	VSTBY	—	—	Standby power	I	—

Table 14-3. MCF5282 Signals and Pin Numbers Sorted by Function (continued)

MAPBGA Pin	Pin Functions			Description	Primary I/O	Internal Pull-up ¹
	Primary ²	Secondary	Tertiary			
E6-E11:F5:F7-F10: F12:G5:G6:G11: G12:H5:H6:H11: H12:J5:J6:J11:J12: K5:K6:K11:K12:L5: L7-L10:L12: M6-M11	VDD	—	—	Positive supply	I	—
A1:A16:E5:E12:F6: F11:G7-G10:H7-H10: J7-J10:K7-K10:L6: L11:M5:M12:T16	VSS	—	—	Ground	I	—

NOTES:

- ¹ Pull-ups are not active when GPIO functions are selected for the pins.
- ² The primary functionality of a pin is not necessarily its default functionality. Pins that have GPIO functionality will default to GPIO inputs.
- ³ Pull-up is active only with the SYNCA function.
- ⁴ Pull-up is active only with the SYNCA function.
- ⁵ Pull-up is active only with the SDA function.
- ⁶ Pull-up is active only with SCL function.
- ⁷ Pull-up is active when JTAG_EN is driven high.

5 Revision History

Table 5 provides a revision history for this document.

Table 5. Revision History Table

Rev. Number	Substantive Changes	Date of Release
0	Initial release.	07/2003
1	Added page erase verify errata for Chapter 6, "ColdFire Flash Module (CFM)."	09/2003
2	<ul style="list-style-type: none"> Added errata for UART interrupt status register. Added errata for PIT timer timeout equation. Added I2CR write errata. Added errata for 'Internal Pull-Up' column in 'MCF5282 Signals and Pin Numbers Sorted by Function' table. Added errata for "SDRAM Read Cycle" figure. 	11/2003
3	Added errata for Chapter 19. PIT1–PIT4 should be PIT0–PIT3.	01/2004
4	<ul style="list-style-type: none"> Added errata for spurious interrupt. Added errata for Table 33-8. Single instance of $T_A = T_L$ to T_H was overlooked in revision 2.0 of the manual. This instance has now been removed. 	03/2004
5	<ul style="list-style-type: none"> Added errata for Section 25.4.10: change CANICR to ICRn. Added errata for BITERR and ACKERR field descriptions. Added errata for BOFFINT and ERRINT bit sequence. Added errata for BUFnl field description. 	03/2004

Table 5. Revision History Table (continued)

Rev. Number	Substantive Changes	Date of Release
6	<ul style="list-style-type: none"> Added errata for Table 17-2 Added errata for FRSR register diagram 	11/2004
7	<ul style="list-style-type: none"> Added errata for Figure 4-2, Table 4-6, Figure 6-3, and Table 6-10 	11/2004
Added the below errata for MCF5282UM Rev 2.3		
8	<ul style="list-style-type: none"> Added FEC max buffer size errata. Added VDD/VDDH power-up requirement. Added MFD bit definition footnote errata. Added PLL spec table entries for 66MHz device. 	01/2005
9	<ul style="list-style-type: none"> Added INTRCLn figure errata. Added BAM bit field example errata. 	03/2005
10	<ul style="list-style-type: none"> Added SDRAM NOP command errata. Added UART clock source errata. 	07/2005
11	<ul style="list-style-type: none"> Added PRI1/PRI2 text description errata. Added CSMR1/CSCR1 register address errata. Removed Table 23-5 errata that was added in revision 10 of this document, as it was incorrect. Only the internal UART clock source is prescaled by the 16-bit divider. Added 2 UART external clock source errata, removing the 16-bit divider from a figure and equation. 	08/2005
12	<ul style="list-style-type: none"> Added core watchdog unable to reset the device errata. Added EMRBR register address errata. Added I_{OH} and I_{OL} errata. 	12/2005
13	<ul style="list-style-type: none"> Added FlexCAN flag clearing mechanism errata in interrupt controller. Added FlexCAN ESTAT register description errata for various bits. Added ICR_n note regarding unique and non-overlapping level and priority definitions. Added DTOUT1, DTIN0, DTOUT0 description field errata in GPIO chapter. Added FEC MII transmit and receive specification section errata. 	08/2006
14	<ul style="list-style-type: none"> Deleted reference to nonexistent CF bits in the figure and bit descriptions for the GPTFLG2 register. Added RMON_R_DROP counter errata. 	11/2006

THIS PAGE INTENTIONALLY LEFT BLANK

How to Reach Us:

Home Page:

www.freescale.com

E-mail:

support@freescale.com

USA/Europe or Locations Not Listed:

Freescale Semiconductor
Technical Information Center, CH370
1300 N. Alma School Road
Chandler, Arizona 85224
+1-800-521-6274 or +1-480-768-2130
support@freescale.com

Europe, Middle East, and Africa:

Freescale Halbleiter Deutschland GmbH
Technical Information Center
Schatzbogen 7
81829 Muenchen, Germany
+44 1296 380 456 (English)
+46 8 52200080 (English)
+49 89 92103 559 (German)
+33 1 69 35 48 48 (French)
support@freescale.com

Japan:

Freescale Semiconductor Japan Ltd.
Headquarters
ARCO Tower 15F
1-8-1, Shimo-Meguro, Meguro-ku,
Tokyo 153-0064, Japan
0120 191014 or +81 3 5437 9125
support.japan@freescale.com

Asia/Pacific:

Freescale Semiconductor Hong Kong Ltd.
Technical Information Center
2 Dai King Street
Tai Po Industrial Estate
Tai Po, N.T., Hong Kong
+800 2666 8080
support.asia@freescale.com

For Literature Requests Only:

Freescale Semiconductor Literature Distribution Center
P.O. Box 5405
Denver, Colorado 80217
1-800-441-2447 or 303-675-2140
Fax: 303-675-2150
LDCForFreescaleSemiconductor@hibbertgroup.com

Information in this document is provided solely to enable system and software implementers to use Freescale Semiconductor products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Freescale Semiconductor reserves the right to make changes without further notice to any products herein. Freescale Semiconductor makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale Semiconductor assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale Semiconductor data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals", must be validated for each customer application by customer's technical experts. Freescale Semiconductor does not convey any license under its patent rights nor the rights of others. Freescale Semiconductor products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Freescale Semiconductor product could create a situation where personal injury or death may occur. Should Buyer purchase or use Freescale Semiconductor products for any such unintended or unauthorized application, Buyer shall indemnify and hold Freescale Semiconductor and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Freescale Semiconductor was negligent regarding the design or manufacture of the part.



Freescale™ and the Freescale logo are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners. © Freescale Semiconductor, Inc. 2006. All rights reserved.