



**Service**  
Commercial Vehicles

TECHNICAL IMPROVEMENT  
No-SC/CV/TI/14-15\_390  
Dt.-29.01.2015

SUB GROUP: DSL FL  
Model : Maxima


To:  
All vehicle Dealer-CV  
All Authorized service centers-CV

**IMPROVEMENT: MODIFIED PINION DIFFERENTIAL-MAXIMA DSL**

**Reason for Change:** to address field issue of 'failure of differential pinion.'


**Modification details:**

Spline fillet radius and tip chamfer added to increase strength of pinion & mainshaft.



**Pinion differential damper**

Modified at splines



**Shaft main**

**Part Details:** Serviceable part nos remains same & are interchangeable

- 1) BB133098 -pinion differential damper
- 2) BB133061-shaft main Assly

**Implementation cut-off details:**

Model Name	Chassis/Engine No	Impl. date
RE Maxima DSL	BBZWFK00816	11.01.2015

Please bring this information to the notice of your concerned staff. Kindly make Copies as required for circulating to your branches spares division etc.  
Please confirm the improvement after modification appropriately.

Thanking You,

**SERVICE SUPPORT –CV  
BAJAJ AUTO LIMITED**

CC : All Area Service Managers  
: All Regional Training Heads / Technical Service/ All Area Sales Managers

**Ref ECR: - U14BBTRA0091**