

Lecture 32

Failure in materials- Creep


Prof. Divya Nayar
Department of Materials Science and Engineering
divyanayar@mse.iitd.ac.in

Recap...


- Surface defects: free surface, grain boundaries, stacking faults, twin boundary
- Lattice strains
- Strengthening mechanisms: grain size reduction

Strain hardening

Work hardening or cold working



(strained
unloaded
specimen)



$$\sigma_y' = K \epsilon^n$$

\rightarrow strain hardening exponent
 \hookrightarrow characteristic const. of metal

$$\sigma_y' > \sigma_y$$

Strain hardening

Dislocation-dislocation interactions

- **Strain hardening:** A ductile metal becomes harder and stronger as it is plastically deformed.
- The temperature at which deformation takes place is “cold” relative to the absolute melting temperature of the metal, **cold working**.
- Most metals strain harden at room temperature.

The dislocation density in a metal increases with deformation



The average distance of separation between dislocations decreases



Resistance to dislocation motion by other dislocations becomes more pronounced.




The imposed stress necessary to deform a metal increases with increasing cold work

Degree of plastic deformation as “percent cold work” (%CW)



$$\%CW = \left(\frac{A_0 - A_d}{A_0} \right) \times 100$$

where, A_0 : original cross-section area
 A_d : area after deformation



Solid solution hardening

Strengthen the metals by alloying with impurity atoms that go into either substitutional or interstitial solid solution




Alloys are stronger than the pure metals

-Alloys are stronger than pure metals because impurity atoms that go into solid solution ordinarily impose lattice strains on the surrounding host atoms.


- Lattice strain field interactions between dislocations and these impurity atoms result, and, consequently, dislocation movement is restricted.

Small-sized impurity



(a)



tensile lattice strains imposed on host atoms



Possible locations of smaller impurity atoms relative to an edge dislocation: cancellation of lattice strains

Large-sized impurity

Compressive lattice strains



Failure in materials

- Creep
- Fracture
- Fatigue

- Strengthening mechanisms
- Grain size reduction
 - Strain hardening
 - Solid solⁿ hardening
 - Precipitation hardening

Food for thought...

Wood bends by weight of fruit but steel bridges do not


Young's modulus of
timber : 150-200 GPa



Young's modulus of steel:
200 GPa



Similar Young's modulus!



?

Creep

Cold flow



Failure of Turbine rotors in jet engines



Creep in concrete bridges

High temperatures, static mechanical stresses

Creep

Materials are often placed in service at **elevated temperatures** and exposed to static mechanical stresses

- The stress in elastic deformation is time-independent.
- Creep is the **time-dependent** and permanent plastic deformation of materials when subjected to a constant load or stress.
- Amorphous polymers, which include plastics and rubbers, are especially sensitive to creep deformation
- **Creep test** consists of subjecting a specimen to a *constant load or stress* while maintaining the temperature constant; deformation or strain is measured and plotted as a function of elapsed time.
- Thermally activated process.


Creep is observed only at $T > 0.4T_m$
(T_m = melting point)

find $\frac{T}{T_m}$ and check!

eg. room T for Fe is $0.16T_m$, Cu is $0.22T_m$: No creep at room T
room T for Pb is $0.5T_m$: Creep observed at room T .

Creep Test

Creep strain vs. time: conducted in uniaxial tension using a specimen having the same geometry as for tensile tests




Three stages:

1. Primary
2. Secondary
3. Tertiary

Minimum creep rate: $\dot{\epsilon}_{ss} = \frac{d\epsilon}{dt}$ (slope) [Also, called steady-state creep rate]
Rupture lifetime, t_r : total time to rupture


Creep Test

1. **Primary or transient creep:** The creep rate continuously decreases i.e. the slope of the curve diminishes with time. Increase in creep resistance or strain hardening.
2. **Secondary creep or steady-state creep:** the rate is constant; the plot becomes linear. This is often the stage of creep that is of the longest duration. Balance between the competing processes of strain hardening and recovery. **Recovery** is the process whereby a material becomes softer and retains its ability to experience deformation.
3. **Tertiary creep:** there is an acceleration of the rate and ultimate failure. This failure is frequently termed **rupture** and results from microstructural and/or metallurgical changes; for example, grain boundary separation, and the formation of internal cracks, cavities, and voids.



Stress and temperature dependence on Creep

$$T_1 < T_2 < T_3, \sigma_1 < \sigma_2 < \sigma_3$$



$$\dot{\epsilon}_{ss}(T, \sigma) = C \sigma^n \exp\left(-\frac{Q}{RT}\right)$$

$\dot{\epsilon}_{ss}$ = steady-state strain rate at T and σ

T = test temperature



C = a constant

σ = test stress

n = stress exponent ($n \sim 1$ to 8)

Q = activation energy

Creep mechanisms




Dislocation Climb

- Vacancies move in response to the applied stress from surfaces of the specimen perpendicular to the stress axis to the surfaces that are parallel to the stress axis.
- Over a period of time, this movement would elongate the specimen in the direction of the stress axis and contract it in the transverse direction resulting in creep.

- Thus edge dislocations piled up against an immobile dislocation can move to other parallel slip planes by climb and continue their motion in response to the stress.
- *The rate controlling step in the climb process is the diffusion of vacancies.*
- The measured activation energy for creep agrees with the activation energy for self-diffusion by the vacancy mechanism in a number of materials.

Creep mechanisms



- Grain boundaries lose their strength at a lower temperature than the grains themselves.
- At temperatures above $0.5 T_m$, the viscosity of the grain boundaries is small enough for them to behave like a very viscous liquid separating the neighbouring grains and allowing them to slide against each other.
- At high temperatures, the grain boundaries facilitate the deformation process by sliding, whereas at low temperatures, they increase the yield strength by stopping the dislocations.

Grain boundary sliding

Creep resistant materials:

- *Cold working or strain hardening cannot be used* for creep resistance. At temperatures above $0.4T_m$, recrystallization will occur quite readily and the cold-worked strength will be lost on recrystallization. *Recrystallization* is the process of nucleation and growth of new, strain-free crystals, which replace all the deformed crystals of the worked material. It starts on heating to temperatures in the range of $0.3\text{--}0.5T_m$, which is above the recovery range.
- *Solid solution hardening can be used* for better creep resistance.
- *Fine-grained materials should be avoided* at high T as grain boundary sliding can add to creep deformation.
- Minimizing grain boundary sliding.
- Using high melting point material.