

Appendix P: Mathematics

Contents

Appendix P: Engineering Mathematics for CNC Design	2
P.1 Fundamentals: Units and Dimensional Analysis	2
P.1.1 SI Base Units	2
P.1.2 Common Derived Units	3
P.1.3 Dimensional Analysis	3
P.2 Algebra and Equation Manipulation	3
P.2.1 Linear Equations	3
P.2.2 Quadratic Equations	3
P.2.3 Simultaneous Linear Equations	4
P.2.4 Exponential and Logarithmic Equations	4
P.3 Trigonometry	4
P.3.1 Basic Trigonometric Functions	4
P.3.2 Inverse Trigonometric Functions	5
P.3.3 Angle Conversions	5
P.3.4 Practical CNC Applications	5
P.4 Vectors and Vector Operations	6
P.4.1 Vector Notation	6
P.4.2 Vector Magnitude	6
P.4.3 Dot Product (Scalar Product)	6
P.4.4 Cross Product (Vector Product)	6
P.5 Calculus: Differentiation	7
P.5.1 Basic Derivatives	7
P.5.2 Differentiation Rules	7
P.5.3 Applications in CNC	7
P.5.4 Optimization (Finding Maxima/Minima)	8
P.6 Calculus: Integration	8
P.6.1 Basic Integrals	8
P.6.2 Definite Integrals	8
P.6.3 Applications in CNC	8
P.7 Differential Equations for Dynamic Systems	9
P.7.1 First-Order Linear ODE	9
P.7.2 Second-Order Linear ODE (Vibration)	10
P.8 Matrix Algebra	10
P.8.1 Matrix Operations	10
P.8.2 Rotation Matrices	11
P.8.3 Transformation Matrices (Homogeneous Coordinates)	11

P.9 Statics and Force Analysis	11
P.9.1 Newton's Laws	11
P.9.2 Equilibrium Conditions	12
P.9.3 Free Body Diagrams (FBD)	12
P.9.4 Truss Analysis (Method of Joints)	12
P.10 Dynamics and Kinematics	12
P.10.1 Linear Motion Equations	12
P.10.2 Rotational Motion Equations	13
P.10.3 Newton's Second Law for Rotation	13
P.10.4 Work-Energy Theorem	14
P.11 Mechanics of Materials	14
P.11.1 Stress and Strain	14
P.11.2 Bending Stress	15
P.11.3 Beam Deflection	16
P.11.4 Torsional Stress and Deflection	16
P.12 Heat Transfer	17
P.12.1 Conduction (Fourier's Law)	17
P.12.2 Convection (Newton's Law of Cooling)	17
P.12.3 Radiation (Stefan-Boltzmann Law)	17
P.13 Control Systems Mathematics	17
P.13.1 Transfer Functions (Laplace Domain)	17
P.13.2 PID Controller	18
P.13.3 First-Order System	18
P.13.4 Second-Order System	19
P.14 Statistics and Uncertainty	19
P.14.1 Mean and Standard Deviation	19
P.14.2 Error Propagation	19
P.15 Fourier Analysis (Frequency Domain)	20
P.15.1 Fourier Series	20
P.15.2 Frequency Analysis Applications	20

Appendix P: Engineering Mathematics for CNC Design

P.1 Fundamentals: Units and Dimensional Analysis

P.1.1 SI Base Units

Quantity	Unit	Symbol
Length	meter	m
Mass	kilogram	kg
Time	second	s
Electric Current	ampere	A
Temperature	kelvin	K
Amount of Substance	mole	mol

Quantity	Unit	Symbol
Luminous Intensity	candela	cd

P1.2 Common Derived Units

Quantity	Unit	Symbol	Formula	SI Base
Force	newton	N	$F = ma$	$\text{kg}\cdot\text{m}/\text{s}^2$
Pressure/Stress	pascal	Pa	$P = F/A$	$\text{kg}/(\text{m}\cdot\text{s}^2)$ or N/m^2
Energy/Work	joule	J	$W = Fd$	$\text{kg}\cdot\text{m}^2/\text{s}^2$ or $\text{N}\cdot\text{m}$
Power	watt	W	$P = E/t$	$\text{kg}\cdot\text{m}^2/\text{s}^3$ or J/s
Frequency	hertz	Hz	$f = 1/T$	s^{-1}
Torque	newton-meter	$\text{N}\cdot\text{m}$	$\tau = F \times r$	$\text{kg}\cdot\text{m}^2/\text{s}^2$
Angle	radian	rad	$\theta = s/r$	dimensionless

P1.3 Dimensional Analysis

Rule: All terms in equation must have same dimensions.

Example: Beam deflection equation

$$\delta = \frac{FL^3}{3EI}$$

Dimensional check: - Left side: $[\delta] = \text{m}$ (length) - Right side: $\frac{[\text{N}] \cdot [\text{m}]^3}{[\text{Pa}] \cdot [\text{m}]^4} = \frac{\text{kg}\cdot\text{m}/\text{s}^2 \cdot \text{m}^3}{(\text{kg}/(\text{m}\cdot\text{s}^2)) \cdot \text{m}^4} = \frac{\text{m}^4}{\text{m}^3} = \text{m}$
[check]

P2 Algebra and Equation Manipulation

P2.1 Linear Equations

Standard form: $ax + b = 0$

Solution: $x = -\frac{b}{a}$

Example: Motor sizing requires torque $T = J\alpha$ where $J = 0.05 \text{ kg}\cdot\text{m}^2$, $\alpha = 100 \text{ rad}/\text{s}^2$. Find T :

$$T = 0.05 \times 100 = 5 \text{ N}\cdot\text{m}$$

P2.2 Quadratic Equations

Standard form: $ax^2 + bx + c = 0$

Quadratic formula:

$$x = \frac{-b \pm \sqrt{b^2 - 4ac}}{2a}$$

Example: Critical speed of ball screw: $N_{\text{crit}}^2 - 200N_{\text{crit}} - 10000 = 0$

$$N = \frac{200 \pm \sqrt{200^2 - 4(1)(-10000)}}{2(1)} = \frac{200 \pm \sqrt{80000}}{2} = \frac{200 \pm 283}{2}$$

Positive solution: $N = 241.5$ RPM

P2.3 Simultaneous Linear Equations

Matrix form: $\mathbf{Ax} = \mathbf{b}$

Example: Force balance on gantry

$$\begin{cases} F_1 + F_2 = 1000 \text{ N} \\ 2F_1 + F_2 = 1500 \text{ N} \end{cases}$$

Substitution method: - From equation 1: $F_2 = 1000 - F_1$ - Substitute into equation 2: $2F_1 + (1000 - F_1) = 1500$ - Solve: $F_1 = 500 \text{ N}$, $F_2 = 500 \text{ N}$

P2.4 Exponential and Logarithmic Equations

Exponential decay: $y = y_0 e^{-kt}$

Example: Vibration amplitude decay (damping):

$$A(t) = A_0 e^{-\zeta \omega_n t}$$

where ζ = damping ratio, ω_n = natural frequency (rad/s)

Logarithm rules: - $\log(ab) = \log a + \log b$ - $\log(a/b) = \log a - \log b$ - $\log(a^n) = n \log a$ - $\log_b(b^x) = x$

Example: Bearing life calculation involves cube root:

$$L_{10} = \left(\frac{C}{P}\right)^3 \text{ (million revolutions)}$$

Taking log: $\log L_{10} = 3 \log(C/P)$

P3 Trigonometry

P3.1 Basic Trigonometric Functions

Right triangle definitions:

$$\sin \theta = \frac{\text{opposite}}{\text{hypotenuse}}, \quad \cos \theta = \frac{\text{adjacent}}{\text{hypotenuse}}, \quad \tan \theta = \frac{\text{opposite}}{\text{adjacent}}$$

Pythagorean identity:

$$\sin^2 \theta + \cos^2 \theta = 1$$

Angle sum formulas:

$$\sin(A \pm B) = \sin A \cos B \pm \cos A \sin B$$

$$\cos(A \pm B) = \cos A \cos B \mp \sin A \sin B$$

P3.2 Inverse Trigonometric Functions

$$\theta = \arcsin(x), \quad \theta = \arccos(x), \quad \theta = \arctan(x)$$

Example: Gantry beam angle from deflection

$$\theta = \arctan\left(\frac{\delta}{L}\right) = \arctan\left(\frac{0.5 \text{ mm}}{1000 \text{ mm}}\right) = 0.0005 \text{ rad} = 0.029^\circ$$

P3.3 Angle Conversions

$$\text{radians} = \text{degrees} \times \frac{\pi}{180}$$

$$\text{degrees} = \text{radians} \times \frac{180}{\pi}$$

Example: Stepper motor 1.8° step

$$1.8^\circ = 1.8 \times \frac{\pi}{180} = 0.0314 \text{ rad}$$

Steps per revolution: $360^\circ/1.8^\circ = 200$ steps

P3.4 Practical CNC Applications

Arc interpolation (G02/G03):

Given start point (x_1, y_1) , end point (x_2, y_2) , radius R :

Center offset from start:

$$I = \pm \sqrt{R^2 - d^2/4}, \quad J = \pm \sqrt{R^2 - d^2/4}$$

where $d = \sqrt{(x_2 - x_1)^2 + (y_2 - y_1)^2}$

P4 Vectors and Vector Operations

P4.1 Vector Notation

2D vector: $\mathbf{v} = \begin{bmatrix} v_x \\ v_y \end{bmatrix}$ or $\mathbf{v} = v_x \mathbf{i} + v_y \mathbf{j}$

3D vector: $\mathbf{v} = \begin{bmatrix} v_x \\ v_y \\ v_z \end{bmatrix}$ or $\mathbf{v} = v_x \mathbf{i} + v_y \mathbf{j} + v_z \mathbf{k}$

P4.2 Vector Magnitude

$$|\mathbf{v}| = \sqrt{v_x^2 + v_y^2 + v_z^2}$$

Example: Gantry velocity components $v_x = 10$ m/min, $v_y = 15$ m/min

Resultant velocity:

$$|\mathbf{v}| = \sqrt{10^2 + 15^2} = \sqrt{325} = 18.03 \text{ m/min}$$

P4.3 Dot Product (Scalar Product)

$$\mathbf{a} \cdot \mathbf{b} = a_x b_x + a_y b_y + a_z b_z = |\mathbf{a}| |\mathbf{b}| \cos \theta$$

Applications: - Work: $W = \mathbf{F} \cdot \mathbf{d}$ - Power: $P = \mathbf{F} \cdot \mathbf{v}$ - Angle between vectors: $\theta = \arccos \left(\frac{\mathbf{a} \cdot \mathbf{b}}{|\mathbf{a}| |\mathbf{b}|} \right)$

Example: Cutting force $\mathbf{F} = (100, 50, 30)$ N, tool displacement $\mathbf{d} = (0, 0, -5)$ mm

Work done:

$$W = \mathbf{F} \cdot \mathbf{d} = 100(0) + 50(0) + 30(-5) = -150 \text{ N}\cdot\text{mm} = -0.15 \text{ J}$$

P4.4 Cross Product (Vector Product)

$$\mathbf{a} \times \mathbf{b} = \begin{vmatrix} \mathbf{i} & \mathbf{j} & \mathbf{k} \\ a_x & a_y & a_z \\ b_x & b_y & b_z \end{vmatrix} = (a_y b_z - a_z b_y) \mathbf{i} - (a_x b_z - a_z b_x) \mathbf{j} + (a_x b_y - a_y b_x) \mathbf{k}$$

Magnitude: $|\mathbf{a} \times \mathbf{b}| = |\mathbf{a}| |\mathbf{b}| \sin \theta$

Applications: - Torque: $\boldsymbol{\tau} = \mathbf{r} \times \mathbf{F}$ - Angular momentum: $\mathbf{L} = \mathbf{r} \times \mathbf{p}$

Example: Force $\mathbf{F} = (0, 100, 0)$ N at position $\mathbf{r} = (0.5, 0, 0)$ m

Torque about origin:

$$\boldsymbol{\tau} = \mathbf{r} \times \mathbf{F} = \begin{vmatrix} \mathbf{i} & \mathbf{j} & \mathbf{k} \\ 0.5 & 0 & 0 \\ 0 & 100 & 0 \end{vmatrix} = (0, 0, 50) \text{ N}\cdot\text{m}$$

Torque magnitude: 50 N·m about Z-axis

P.5 Calculus: Differentiation

P.5.1 Basic Derivatives

Function $f(x)$	Derivative $f'(x)$
c (constant)	0
x^n	nx^{n-1}
e^x	e^x
$\ln x$	$1/x$
$\sin x$	$\cos x$
$\cos x$	$-\sin x$

P.5.2 Differentiation Rules

Sum/Difference: $(f \pm g)' = f' \pm g'$

Product rule: $(fg)' = f'g + fg'$

Quotient rule: $\left(\frac{f}{g}\right)' = \frac{f'g - fg'}{g^2}$

Chain rule: $\frac{d}{dx}f(g(x)) = f'(g(x)) \cdot g'(x)$

P.5.3 Applications in CNC

Velocity from position:

$$v(t) = \frac{dx}{dt}$$

Acceleration from velocity:

$$a(t) = \frac{dv}{dt} = \frac{d^2x}{dt^2}$$

Example: Position profile during trapezoidal move:

Acceleration phase: $x(t) = \frac{1}{2}at^2$

Velocity: $v(t) = \frac{dx}{dt} = at$

Acceleration: $a(t) = \frac{dv}{dt} = a$ (constant)

Instantaneous power:

$$P = \frac{dE}{dt}$$

For motor: $P = \tau\omega$ where $\omega = \frac{d\theta}{dt}$ (angular velocity)

P5.4 Optimization (Finding Maxima/Minima)

Set $f'(x) = 0$ and solve for x .

Second derivative test: - $f''(x) > 0$: minimum - $f''(x) < 0$: maximum

Example: Minimize deflection by optimizing beam shape

For rectangular beam: $I = \frac{bh^3}{12}$

Given constant area $A = bh$, find h maximizing I :

$$b = A/h, \text{ so } I = \frac{Ah^2}{12}$$

$$\frac{dI}{dh} = \frac{Ah}{6} = 0 \quad \square \quad \text{No finite maximum (increase } h, \text{ decrease } b)$$

Practical constraint: buckling limits h/b ratio

P6 Calculus: Integration

P6.1 Basic Integrals

Function $f(x)$	Integral $\int f(x)dx$
x^n	$\frac{x^{n+1}}{n+1} + C$ ($n \neq -1$)
$1/x$	$\ln x + C$
e^x	$e^x + C$
$\sin x$	$-\cos x + C$
$\cos x$	$\sin x + C$

P6.2 Definite Integrals

$$\int_a^b f(x)dx = F(b) - F(a)$$

where $F(x)$ is antiderivative of $f(x)$

P6.3 Applications in CNC

Distance from velocity:

$$s = \int_0^t v(t)dt$$

Velocity from acceleration:

$$v = \int_0^t a(t)dt$$

Example: Trapezoidal velocity profile

Constant acceleration $a = 2 \text{ m/s}^2$ for $t = 3 \text{ s}$:

$$v(t) = \int_0^3 a \, dt = at \Big|_0^3 = 2(3) = 6 \text{ m/s}$$

Distance during acceleration:

$$s = \int_0^3 v(t) \, dt = \int_0^3 2t \, dt = t^2 \Big|_0^3 = 9 \text{ m}$$

Work from force:

$$W = \int_0^d F(x) \, dx$$

Average value:

$$f_{\text{avg}} = \frac{1}{b-a} \int_a^b f(x) \, dx$$

Example: Average motor torque over acceleration

$$\tau_{\text{avg}} = \frac{1}{T} \int_0^T \tau(t) \, dt$$

P.7 Differential Equations for Dynamic Systems

P.7.1 First-Order Linear ODE

Standard form: $\frac{dy}{dt} + p(t)y = q(t)$

Solution method: Integrating factor $\mu(t) = e^{\int p(t) \, dt}$

Example: RC circuit (similar to motor thermal model)

$$\frac{dT}{dt} + \frac{T}{\tau} = \frac{P}{\tau}$$

where T = temperature rise, τ = thermal time constant, P = power dissipation

Solution: $T(t) = P (1 - e^{-t/\tau})$ (heating from ambient)

P7.2 Second-Order Linear ODE (Vibration)

Standard form: $m \frac{d^2x}{dt^2} + c \frac{dx}{dt} + kx = F(t)$

Natural frequency: $\omega_n = \sqrt{\frac{k}{m}}$ rad/s

Damping ratio: $\zeta = \frac{c}{2\sqrt{km}}$

Solutions:

1. **Underdamped** ($\zeta < 1$): Oscillatory

$$x(t) = Ae^{-\zeta\omega_n t} \cos(\omega_d t + \phi)$$

where $\omega_d = \omega_n \sqrt{1 - \zeta^2}$ (damped frequency)

2. **Critically damped** ($\zeta = 1$): Fastest return without overshoot

$$x(t) = (A + Bt)e^{-\omega_n t}$$

3. **Overdamped** ($\zeta > 1$): Slow return, no oscillation

$$x(t) = Ae^{-(\zeta - \sqrt{\zeta^2 - 1})\omega_n t} + Be^{-(\zeta + \sqrt{\zeta^2 - 1})\omega_n t}$$

Example: Gantry vibration after step input

Given: $m = 50$ kg, $k = 100,000$ N/m, $c = 500$ N·s/m

$$\omega_n = \sqrt{\frac{100000}{50}} = 44.7 \text{ rad/s} = 7.1 \text{ Hz}$$

$$\zeta = \frac{500}{2\sqrt{50 \times 100000}} = 0.35$$

System is underdamped \square will oscillate at:

$$f_d = \frac{\omega_d}{2\pi} = \frac{44.7\sqrt{1 - 0.35^2}}{2\pi} = 6.6 \text{ Hz}$$

P8 Matrix Algebra

P8.1 Matrix Operations

Addition: $\mathbf{C} = \mathbf{A} + \mathbf{B}$ where $c_{ij} = a_{ij} + b_{ij}$

Multiplication: $\mathbf{C} = \mathbf{AB}$ where $c_{ij} = \sum_k a_{ik} b_{kj}$

Transpose: \mathbf{A}^T where $(A^T)_{ij} = A_{ji}$

Inverse: \mathbf{A}^{-1} where $\mathbf{A}\mathbf{A}^{-1} = \mathbf{I}$

2x2 inverse:

$$\mathbf{A}^{-1} = \frac{1}{\det \mathbf{A}} \begin{bmatrix} a_{22} & -a_{12} \\ -a_{21} & a_{11} \end{bmatrix}$$

where $\det \mathbf{A} = a_{11}a_{22} - a_{12}a_{21}$

P8.2 Rotation Matrices

2D rotation by angle θ :

$$\mathbf{R}(\theta) = \begin{bmatrix} \cos \theta & -\sin \theta \\ \sin \theta & \cos \theta \end{bmatrix}$$

3D rotation about Z-axis:

$$\mathbf{R}_z(\theta) = \begin{bmatrix} \cos \theta & -\sin \theta & 0 \\ \sin \theta & \cos \theta & 0 \\ 0 & 0 & 1 \end{bmatrix}$$

Example: Rotating coordinate system for angled tool approach

Point $(x, y) = (10, 0)$ mm rotated by $\theta = 45^\circ$:

$$\begin{bmatrix} x' \\ y' \end{bmatrix} = \begin{bmatrix} \cos 45^\circ & -\sin 45^\circ \\ \sin 45^\circ & \cos 45^\circ \end{bmatrix} \begin{bmatrix} 10 \\ 0 \end{bmatrix} = \begin{bmatrix} 7.07 \\ 7.07 \end{bmatrix} \text{ mm}$$

P8.3 Transformation Matrices (Homogeneous Coordinates)

Translation + Rotation in 2D:

$$\mathbf{T} = \begin{bmatrix} \cos \theta & -\sin \theta & t_x \\ \sin \theta & \cos \theta & t_y \\ 0 & 0 & 1 \end{bmatrix}$$

Point transformation:

$$\begin{bmatrix} x' \\ y' \\ 1 \end{bmatrix} = \mathbf{T} \begin{bmatrix} x \\ y \\ 1 \end{bmatrix}$$

Application: G-code coordinate transforms (G54-G59 work offsets, G68 rotation)

P9 Statics and Force Analysis

P9.1 Newton's Laws

First Law: Object at rest stays at rest unless acted upon by force (inertia)

Second Law: $\mathbf{F} = m\mathbf{a}$

Third Law: Action-reaction pairs (equal magnitude, opposite direction)

P9.2 Equilibrium Conditions

Static equilibrium:

$$\sum \mathbf{F} = 0 \quad (\text{no net force})$$
$$\sum \tau = 0 \quad (\text{no net torque})$$

2D equilibrium (3 equations):

$$\sum F_x = 0, \quad \sum F_y = 0, \quad \sum M_z = 0$$

3D equilibrium (6 equations):

$$\sum F_x = 0, \quad \sum F_y = 0, \quad \sum F_z = 0$$
$$\sum M_x = 0, \quad \sum M_y = 0, \quad \sum M_z = 0$$

P9.3 Free Body Diagrams (FBD)

Procedure: 1. Isolate body/component 2. Show all external forces (gravity, reactions, applied loads) 3. Choose coordinate system 4. Apply equilibrium equations

Example: Simply supported beam with center load

Given: Beam length $L = 1$ m, load $F = 1000$ N at center

FBD: Reactions R_A and R_B at ends

$$\text{Equilibrium: } -\sum F_y = R_A + R_B - F = 0 \quad -\sum M_A = R_B \cdot L - F \cdot (L/2) = 0$$

Solve: $R_B = F/2 = 500$ N, $R_A = 500$ N (symmetry)

P9.4 Truss Analysis (Method of Joints)

For each joint in equilibrium:

$$\sum F_x = 0, \quad \sum F_y = 0$$

Sign convention: Tension (+), Compression (-)

Example: Simple triangular truss supporting gantry beam

P10 Dynamics and Kinematics

P10.1 Linear Motion Equations

Constant acceleration:

$$v = v_0 + at$$
$$s = v_0 t + \frac{1}{2} at^2$$

$$v^2 = v_0^2 + 2as$$

Example: CNC rapid move (G00)

Acceleration phase: $a = 2 \text{ m/s}^2$, time $t_1 = 1 \text{ s}$

Final velocity: $v = 0 + 2(1) = 2 \text{ m/s}$

Distance: $s = 0 + \frac{1}{2}(2)(1)^2 = 1 \text{ m}$

P10.2 Rotational Motion Equations

Angular displacement: θ (rad)

Angular velocity: $\omega = \frac{d\theta}{dt}$ (rad/s)

Angular acceleration: $\alpha = \frac{d\omega}{dt}$ (rad/s²)

Constant angular acceleration:

$$\omega = \omega_0 + \alpha t$$

$$\theta = \omega_0 t + \frac{1}{2}\alpha t^2$$

$$\omega^2 = \omega_0^2 + 2\alpha\theta$$

Relationship to linear motion:

$$v = r\omega, \quad a_{\text{tangential}} = r\alpha, \quad a_{\text{centripetal}} = \frac{v^2}{r} = r\omega^2$$

Example: Spindle acceleration

From rest to $N = 3000 \text{ RPM}$ in $t = 0.5 \text{ s}$:

$$\omega = \frac{2\pi N}{60} = \frac{2\pi(3000)}{60} = 314 \text{ rad/s}$$

$$\alpha = \frac{\omega - 0}{t} = \frac{314}{0.5} = 628 \text{ rad/s}^2$$

P10.3 Newton's Second Law for Rotation

$$\tau = I\alpha$$

where I = moment of inertia (kg·m²), α = angular acceleration (rad/s²)

Moment of inertia (common shapes):

Shape	Axis	Moment of Inertia
Solid cylinder	Central axis	$I = \frac{1}{2}mR^2$
Hollow cylinder	Central axis	$I = \frac{1}{2}m(R_o^2 + R_i^2)$
Solid sphere	Diameter	$I = \frac{2}{5}mR^2$
Thin rod	Center, perpendicular	$I = \frac{1}{12}mL^2$
Point mass	Distance r	$I = mr^2$

Example: Motor torque for spindle acceleration

Spindle: $m = 5$ kg, $R = 0.05$ m (solid cylinder approximation)

$$I = \frac{1}{2}(5)(0.05)^2 = 0.00625 \text{ kg}\cdot\text{m}^2$$

From previous example: $\alpha = 628 \text{ rad/s}^2$

Required torque: $\tau = I\alpha = 0.00625 \times 628 = 3.93 \text{ N}\cdot\text{m}$

P.10.4 Work-Energy Theorem

$$W = \Delta KE = \frac{1}{2}m(v_f^2 - v_i^2)$$

Rotational kinetic energy:

$$KE_{\text{rot}} = \frac{1}{2}I\omega^2$$

Example: Energy to accelerate servo motor + ball screw

Motor rotor: $I_m = 0.001 \text{ kg}\cdot\text{m}^2$, final speed $\omega_m = 3000 \text{ RPM} = 314 \text{ rad/s}$

Ball screw: $I_s = 0.005 \text{ kg}\cdot\text{m}^2$, coupled 1:1

Total inertia (reflected to motor): $I_{\text{total}} = 0.001 + 0.005 = 0.006 \text{ kg}\cdot\text{m}^2$

Energy required:

$$E = \frac{1}{2}(0.006)(314)^2 = 296 \text{ J}$$

If accelerated in 0.5 s: $P_{\text{avg}} = 296/0.5 = 592 \text{ W}$

P.11 Mechanics of Materials

P.11.1 Stress and Strain

Normal stress: $\sigma = \frac{F}{A}$ (Pa or N/m²)

Shear stress: $\tau = \frac{F}{A}$ (Pa or N/m²)

Normal strain: $\epsilon = \frac{\Delta L}{L_0}$ (dimensionless or %)

Shear strain: $\gamma = \frac{\Delta x}{h}$ (rad, dimensionless)

Hooke's Law (elastic region):

$$\sigma = E\epsilon$$

where E = Young's modulus (Pa)

Example: Steel rod under tension

$F = 10,000 \text{ N}$, $A = 100 \text{ mm}^2$, $L_0 = 500 \text{ mm}$, $E = 200 \text{ GPa}$

$$\sigma = \frac{10000}{100 \times 10^{-6}} = 100 \times 10^6 \text{ Pa} = 100 \text{ MPa}$$

$$\epsilon = \frac{\sigma}{E} = \frac{100 \times 10^6}{200 \times 10^9} = 0.0005 = 0.05\%$$

$$\Delta L = \epsilon L_0 = 0.0005 \times 500 = 0.25 \text{ mm}$$

P.11.2 Bending Stress

Flexure formula:

$$\sigma = \frac{My}{I}$$

where: - M = bending moment (N·m) - y = distance from neutral axis (m) - I = second moment of area (m⁴)

Maximum stress (at outer fiber):

$$\sigma_{\max} = \frac{Mc}{I} = \frac{M}{S}$$

where $S = I/c$ = section modulus (m³)

Example: Gantry beam (rectangular cross-section)

$M = 500 \text{ N·m}$, $b = 100 \text{ mm}$, $h = 200 \text{ mm}$

$$I = \frac{bh^3}{12} = \frac{0.1 \times 0.2^3}{12} = 6.67 \times 10^{-5} \text{ m}^4$$

$$c = h/2 = 0.1 \text{ m}$$

$$\sigma_{\max} = \frac{500 \times 0.1}{6.67 \times 10^{-5}} = 75 \times 10^6 \text{ Pa} = 75 \text{ MPa}$$

P11.3 Beam Deflection

Cantilever beam (end load):

$$\delta = \frac{FL^3}{3EI}$$

Simply supported beam (center load):

$$\delta = \frac{FL^3}{48EI}$$

Example: Z-axis spindle head deflection (cantilever)

$$F = 1000 \text{ N}, L = 0.5 \text{ m}, E = 200 \text{ GPa}, I = 6.67 \times 10^{-5} \text{ m}^4$$

$$\delta = \frac{1000 \times 0.5^3}{3 \times 200 \times 10^9 \times 6.67 \times 10^{-5}} = 0.000313 \text{ m} = 0.313 \text{ mm}$$

P11.4 Torsional Stress and Deflection

Shear stress:

$$\tau = \frac{Tr}{J}$$

where: - T = torque (N·m) - r = radius (m) - J = polar moment of inertia (m⁴)

Solid circular shaft: $J = \frac{\pi d^4}{32}$

Hollow circular shaft: $J = \frac{\pi(d_o^4 - d_i^4)}{32}$

Angle of twist:

$$\phi = \frac{TL}{GJ}$$

where G = shear modulus (Pa)

Example: Ball screw torsional stiffness

$$d = 40 \text{ mm}, L = 1 \text{ m}, G = 80 \text{ GPa (steel)}$$

$$J = \frac{\pi(0.04)^4}{32} = 2.51 \times 10^{-7} \text{ m}^4$$

Torque $T = 50 \text{ N·m}$:

$$\phi = \frac{50 \times 1}{80 \times 10^9 \times 2.51 \times 10^{-7}} = 0.00249 \text{ rad} = 0.143^\circ$$

P.12 Heat Transfer

P.12.1 Conduction (Fourier's Law)

$$Q = -kA \frac{dT}{dx}$$

Steady-state through wall:

$$Q = \frac{kA\Delta T}{L}$$

where: - Q = heat transfer rate (W) - k = thermal conductivity (W/(m·K)) - A = area (m²) - ΔT = temperature difference (K) - L = thickness (m)

Thermal resistance: $R_{\text{thermal}} = \frac{L}{kA}$ (K/W)

Example: Motor cooling through aluminum housing

$k = 205$ W/(m·K), $A = 0.01$ m², $L = 5$ mm, $\Delta T = 50$ K

$$Q = \frac{205 \times 0.01 \times 50}{0.005} = 20,500 \text{ W}$$

P.12.2 Convection (Newton's Law of Cooling)

$$Q = hA(T_s - T_\infty)$$

where: - h = convection coefficient (W/(m²·K)) - T_s = surface temperature (K) - T_∞ = fluid temperature (K)

Typical values: - Natural air: $h = 5 - 25$ W/(m²·K) - Forced air: $h = 10 - 200$ W/(m²·K) - Water: $h = 500 - 10,000$ W/(m²·K)

P.12.3 Radiation (Stefan-Boltzmann Law)

$$Q = \epsilon \sigma A(T_s^4 - T_{\text{surr}}^4)$$

where: - ϵ = emissivity (0-1) - $\sigma = 5.67 \times 10^{-8}$ W/(m²·K⁴) (Stefan-Boltzmann constant) - T in Kelvin (absolute temperature)

P.13 Control Systems Mathematics

P.13.1 Transfer Functions (Laplace Domain)

Laplace transform:

$$\mathcal{L}\{f(t)\} = F(s) = \int_0^\infty f(t)e^{-st} dt$$

Common transforms:

Time Domain	Laplace Domain
$\delta(t)$ (impulse)	1
$u(t)$ (step)	$\frac{1}{s}$
e^{-at}	$\frac{1}{s+a}$
$\sin(\omega t)$	$\frac{\omega}{s^2+\omega^2}$
$\cos(\omega t)$	$\frac{s}{s^2+\omega^2}$

Differentiation: $\mathcal{L}\left\{\frac{df}{dt}\right\} = sF(s) - f(0)$

Integration: $\mathcal{L}\left\{\int_0^t f(\tau)d\tau\right\} = \frac{F(s)}{s}$

P.13.2 PID Controller

Time domain:

$$u(t) = K_p e(t) + K_i \int_0^t e(\tau)d\tau + K_d \frac{de}{dt}$$

Laplace domain:

$$U(s) = \left(K_p + \frac{K_i}{s} + K_d s \right) E(s)$$

Transfer function:

$$G_c(s) = K_p + \frac{K_i}{s} + K_d s = \frac{K_d s^2 + K_p s + K_i}{s}$$

Gains: - K_p : Proportional gain (immediate response to error) - K_i : Integral gain (eliminates steady-state error) - K_d : Derivative gain (damping, anticipates error)

P.13.3 First-Order System

Transfer function:

$$G(s) = \frac{K}{\tau s + 1}$$

Step response:

$$y(t) = K(1 - e^{-t/\tau})$$

where τ = time constant (63.2% of final value at $t = \tau$)

P13.4 Second-Order System

Transfer function:

$$G(s) = \frac{\omega_n^2}{s^2 + 2\zeta\omega_n s + \omega_n^2}$$

Step response characteristics: - Rise time: $t_r \approx \frac{1.8}{\omega_n}$ (underdamped) - Settling time: $t_s \approx \frac{4}{\zeta\omega_n}$ (2% criterion) - Peak overshoot: $M_p = e^{-\pi\zeta/\sqrt{1-\zeta^2}}$ (underdamped)

P.14 Statistics and Uncertainty

P14.1 Mean and Standard Deviation

Mean (average):

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x_i$$

Standard deviation:

$$\sigma = \sqrt{\frac{1}{n-1} \sum_{i=1}^n (x_i - \bar{x})^2}$$

Example: Measuring part dimension 10 times: Data: 50.01, 50.03, 49.98, 50.02, 50.00, 50.01, 49.99, 50.02, 50.00, 50.01 mm

$$\bar{x} = \frac{500.07}{10} = 50.007 \text{ mm}$$

$$\sigma = 0.015 \text{ mm}$$

P14.2 Error Propagation

Addition/Subtraction:

$$\sigma_z^2 = \sigma_x^2 + \sigma_y^2$$

Multiplication/Division:

$$\left(\frac{\sigma_z}{z}\right)^2 = \left(\frac{\sigma_x}{x}\right)^2 + \left(\frac{\sigma_y}{y}\right)^2$$

General function $z = f(x, y)$:

$$\sigma_z^2 = \left(\frac{\partial f}{\partial x}\right)^2 \sigma_x^2 + \left(\frac{\partial f}{\partial y}\right)^2 \sigma_y^2$$

P.15 Fourier Analysis (Frequency Domain)

P.15.1 Fourier Series

Periodic signal $f(t)$ with period T :

$$f(t) = a_0 + \sum_{n=1}^{\infty} \left[a_n \cos \left(\frac{2\pi nt}{T} \right) + b_n \sin \left(\frac{2\pi nt}{T} \right) \right]$$

Coefficients:

$$a_0 = \frac{1}{T} \int_0^T f(t) dt$$

$$a_n = \frac{2}{T} \int_0^T f(t) \cos \left(\frac{2\pi nt}{T} \right) dt$$

$$b_n = \frac{2}{T} \int_0^T f(t) \sin \left(\frac{2\pi nt}{T} \right) dt$$

P.15.2 Frequency Analysis Applications

Vibration analysis: Decompose vibration signal into frequency components

Modal testing: Identify natural frequencies and mode shapes

Chatter detection: Monitor cutting forces in frequency domain

End of Engineering Mathematics Appendix