

Problems

① A 6 pole lap wound dc shunt motor has 500 conductors in the armature. The resistance of the armature is 0.05Ω the resistance of the shunt field is 25Ω . Find the speed of the motor when it takes $120A$ from a $100V$ dc supply. ϕ per pole is $20mwb$

$$\rightarrow E_b = \frac{P\phi ZN}{60A}$$

$$P = 6$$

$$N \Rightarrow ?$$

$$R_a = 0.05$$

$$\phi = 20mwb$$

$$R_f = 25\Omega$$

$$I_a = 120A$$

$$A = 6$$

$$V = 100V$$

$$Z = 500$$

$$I_L = 120A$$

$$I_f = \frac{V_f}{R_f} = \frac{100}{25}$$

$$= 4A$$

$$V = I_a R_a + E_b$$

$$100 = 116(0.05) + E_b$$

$$E_b = 94.2V$$

$$I_L = I_f + I_a$$

$$I_a = I_L - I_f$$

$$= 120 - 4$$

$$= 116A$$

$$E_b = \frac{P\phi ZN}{60A}$$

$$N = \frac{E_b \times 60A}{P\phi Z} = \frac{94.2 \times 60 \times 6}{6 \times 20 \times 10^{-3} \times 500} = 565.2 \text{ rpm}$$

Calculate the speed when the load on the motor is reduced by 20%.

Soln → Load reduced by 20%

$$I_L = \frac{120 \times 20}{100} = 24 = I_L$$

∴ I_L is reduced by $120 - 24 = 96A$

$$N = \frac{94.5 \times 60 \times 6}{6 \times 50 \times 2}$$

$$I_a = I_L - I_f = 96 - 4 = 92A.$$

$$V = 92 \times (0.05) + E_b$$

$$100 - 4.6 = E_b$$

$$E_b = 95.4V$$

$$N = 95.4 = 572.48 \text{ rpm.}$$

ii) 50% of load

$$I_L = \frac{120 \times 50}{100} = 60A$$

$$I_a = I_L - I_f = 56A.$$

$$V = 56 \times (0.05) + E_b$$

$$100 - 2.8 = E_b$$

$$E_b = 97.2V$$


$$N = 583.2 \text{ rpm.}$$

iii) 25% of 120A.

$$I_L = 30 \quad I_a = 30 - 4 = 26A.$$

$$E_b = 100 - 1.3 = 98.7$$

$$N = 592.2$$



- ② A 230V motor has an armature circuit resistance of 0.6Ω if the full load armature current is 30A and no load armature current is 4A. Find the change in back emf. Find the % change in back emf from no load to full load.

Soln:

$$V = 230V$$

$$R_a = R_f$$

$$R_a = 0.6\Omega$$

$$I_{a_{FL}} = 30A$$

$$I_{a_{NL}} = 4A$$

$$E_b = V - I_a R_a$$

$$E_b = V - I_a R_a$$

$$E_b = 230 - 30(0.6)$$

$$= 212V$$

$$= 230 - 4(0.6)$$

$$E_b = 227.6$$

$$\text{Change in back emf} :- 227.6 - 212 = 15.6$$

$$\% \text{ change in back emf} : \frac{15.6}{227.6} \times 100 = 6.85\%$$

- ③ A 440V DC shunt motor has an armature resistance of 0.8Ω and field resistance of 200Ω . Determine E_b when giving an output 7.46 kW at 85% efficiency.

$$R_f = 200\Omega$$

$$P_{out} = 7.46 \text{ kW}$$

$$\eta = 0.85$$

$$R_a = 0.8\Omega$$

$$\frac{\text{Output}}{\text{Input}} = 0.85$$

$$V = I_a (R_f + R_a) + E_b$$

$$\eta = 0.85$$

$$\frac{\text{output}}{\text{input}} = 0.85$$

$$\frac{7.46 \times 100}{E_b} = \frac{85}{100}$$

$$\frac{7.46 \text{ kWatt}}{0.85} = \text{input}$$

$$\text{input} = 8.776 \times 10^3$$

output ~~hp~~ \rightarrow horsepower

$$1 \text{ hp} = 746 \text{ watt}$$

$$P_{out} = 7.46 \text{ kW}$$

$$\text{Input power: } 8.776 \times 10^3 = V \times I_L$$

$$I_L = \frac{8.776 \times 10^3}{440}$$

$$= 19.946 \text{ A}$$

$$\begin{aligned} \text{output} &= 7.46 \text{ kW} \\ &= 10 \text{ hp} \end{aligned}$$

$$\begin{aligned} \therefore I_a &= I_L - I_f \\ &= 17.746 \text{ A} \end{aligned}$$

$$I_f = \frac{V}{R_f} = 2.2 \text{ A}$$

$$\begin{aligned} E_b &= V - I_a R_a \\ &= 440 - (17.746)(0.8) \\ E_b &= 425.8 \text{ V} \end{aligned}$$

- Q) A 250V DC series motor has an armature resistance of 0.08Ω and field resistance of 0.02Ω and produces full load torque when running at 500rpm and taking the current of 40A. Calculate:
- Armature current
 - speed when producing half of the full load torque

$$\begin{aligned} V &= 250 \text{ V} & R_a &= 0.08 \Omega & R_f &= 0.02 \Omega \\ N &= 500 \text{ rpm} & I_L &= 40 \text{ A} \end{aligned}$$

$$I_a = I_L = 40 \text{ A}$$

$$\begin{aligned} E_b &= V - I_a (R_a + R_f) \\ 250 &= 40(0.08 + 0.02) + E_b \\ E_b &= 246 \text{ V} \end{aligned}$$

$$\cancel{P_L = P_{\phi} \times \omega}$$

$$T \propto I_a^2$$

$$T_1 \propto 40^2 \quad \text{--- (1)}$$

$$0.5 T_1 = T_2 \propto I_{a2}^2 \quad \text{--- (2)}$$

$$\frac{T_1}{0.5 T_1} = \frac{40^2}{I_{a2}^2}$$

$$I_{a2} = 28.28 \text{ A}$$

$$E_b \propto \phi N$$

$$E_b \propto I_a N$$

$$\phi \propto I_a$$

$$\frac{E_{b1}}{E_{b2}} = \frac{I_{a1} N_1}{I_{a2} N_2}$$

$$E_{b2} = V - I_{a2}(R_a + R_{se})$$

$$= 250 - 28.28(0.1)$$

$$E_{b2} = 247.172$$

$$\frac{246}{247.172} = \frac{40(500)}{28.28 N_2}$$


$$E_{b1} = V - I_{a1}(R_a + R_{se})$$

$$= 250 -$$

$$N_2 = \frac{40 \times 500 \times 247.172}{246 \times 28.28}$$

$$N_2 = 711.4 \text{ rpm.}$$

30/8/22
Lesson plan.



(3) $\phi = 30 \text{ mwb}$ $V = 220 \text{ V}$ $I_f = 1 \text{ A}$
 $A = 4$ $P = 5.6 \text{ kW}$ T $I_L = 32 \text{ A}$
 $Z = 540$ $R_a = 0.1 \Omega$
 $P = 4$

$$E_b = \frac{P \phi Z N}{60 A} = \frac{4 \times 30 \times 10^{-3} \times 540 \times N}{60 \times 4} = 216.9$$

$$N = \frac{216.9 \times 60 \times 4}{4 \times 30 \times 10^{-3} \times 540}$$

$$E_b = I_L = I_a + I_f \quad N = 803.33 \text{ rpm}$$

$$I_a = 31 \text{ A}$$

$$V = I_a R_a + E_b$$

$$220 = 31 \times 0.1 + E_b$$

$$E_b = 216.9$$

$$T = 0.159 \phi Z I_a \frac{P}{A}$$

$$= 0.159 \times 30 \times 10^{-3} \times 540 \times 31 \times \frac{4}{4}$$

$$= 79.84 \text{ Nm}$$

(4) $V = 220 \text{ V}$ $N = 700 \text{ rpm}$ $I_a = 100 \text{ A}$
 $R_a + R_{se} = 0.1 \Omega$ $T_2 = 0.7 T_1$
 Supply motor

$$V = I_a (R_{se} + R_a) + E_b$$

$$220 = 100 (0.1) + E_b$$

$$E_b = 210$$

$$\frac{T_1}{T_2} = \frac{I_{a1}^2}{I_{a2}^2}$$

$$\frac{T_1}{0.7 T_1} = \frac{(100)^2}{I_{a2}^2}$$

$$I_{a2}^2 = 7000$$

$$I_{a2} = 83.66 \text{ A}$$

$$\frac{N_1}{N_2} = \frac{I_2}{I_1}$$

$$\frac{700}{N_2} = \frac{83.66}{100}$$

$$N_2 = \frac{700 \times 100}{83.66}$$

$$N_2 = 836.72 \text{ rpm}$$

Torque is reduced by 30% = 70% of starting torque

PMDC motor
 $I_f = 0$
 permanent magnets
 are used

$$\frac{E_{b1}}{E_{b2}} = \frac{I_{a1} N_1}{I_{a2} N_2}$$

$$E_{b2} = V - I_{a2}(0.1)$$

$$= 220 - 0$$

$$= 211.63$$

$$\frac{210}{211.63} = \frac{100 \times 700}{83.66 \times N_2}$$

$$210 (83.66 \times N_2) = 100 \times 700 \times 211.63$$

$$N_2 = \frac{100 \times 700 \times 211.63}{83.66 \times 210}$$

$$= 843.21 \text{ rpm}$$

s) $R_a = 0.2 \Omega$ $V = 24 \text{ V}$ $I_f = 0$ $N_1 = 1200 \text{ rpm}$
 $I_a = 0.5 \text{ A}$ $N_2 = 1120 \text{ rpm}$ $P = ?$

$$E_{b1} = V - I_{a1} R_a$$

$$= 24 - 0.5 \times 0.2$$

$$E_{b1} = 23.9 \text{ V}$$

$$E_b = \frac{V \phi Z N}{60 A}$$

$$\frac{23.9}{E_{b2}} = \frac{1200}{1120}$$

$$E_{b2} = 22.3 \text{ V}$$

$$E_b = V - I_{a2} R_a$$

$$22.3 = 24 - I_{a2}(0.2)$$

$$I_{a2} = 8.5 \text{ A}$$

$$P = V \times I_{a2}$$

$$= 24 \times 8.5$$

$$= 204 \text{ watt}$$

ut7/22

Three phase Induction Motor

- It is widely used for all industrial application

- i) It has a rugged construction.
- ii) it is self starting
- iii) it has higher efficiency & less maintenance
- iv) it can cater to both constant speed & high starting torque application.

Three phase induction motor:

i) stator ii) Rotor

in 3 ϕ induction motor, stator receives 3 ϕ AC input voltage

- 3 ϕ AC voltage as input
- AC voltage is given to stator
- Armature RYB together will form one pole.
- flux is produced in stator.

• DC motor

- DC input voltage is given as input
- DC voltage is supplied to rotatory part i.e. rotor

• flux is produced in yoke (DC flux)

• Outer periphery

Induction Motor

• 3 ϕ AC voltage

• AC voltage is supplied to stationary part i.e. stator

• flux is produced in stator itself (AC flux)

• Armature RYB will together form one pole.

• Inner periphery

$$\Phi_R = \Phi_m \sin \omega t$$

$$\Phi_Y = \Phi_m \sin(\omega t - 120^\circ)$$

$$\Phi_B = \Phi_m \sin(\omega t - 240^\circ)$$

Stator - 3 ϕ input voltage



Rotor \div SRIM : slip ring induction motor

SCIM

Squirrel cage induction motor

SRIM:


The rotor is made up of high silicon content steel stamping which are cut on the outer periphery.



- func of $R_{starting}$ is: It increases the starting torque.
- during motor running condition slip rings slip on each other thereby disconnecting starting resistance.
- This type of motors are used in high torque.

SCIM


Thick copper plates are inserted in rotor slots and are permanently welded on to the end rings. It is used at constant speed application.



In SCIM, the rotor circuit comprises of thick Cu plates which are permanently welded on to end rings.

Explain how a rotating magnetic field (RMF) by phasor dia. taking two cases for ωt .

- There is no provision to connect resistances to cut cut
- It's outer periphery is cut into slots.



i) $\omega t = 0$

$$\phi_R = 0$$


$$\phi_Y = \phi_m \sin(0 - 120^\circ) = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_B = \phi_m \sin(0 - 240^\circ) = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_m = \phi_R - \phi_B$$

$$\phi_m =$$

$$\phi_{resultant} = 1.5 \phi_m$$



ii) $\omega t = 0$

$$\phi_R = \phi_m \sin \omega t$$

$$\phi_R = \phi_m \sin 60^\circ = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_R = \phi_m \sin(-120^\circ)$$

$$= \phi_m \sin(60 - 120)$$

$$= -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_B = \phi_m \sin(60 - 240)$$

$$= \phi_m \sin(-180)$$

$$= 0$$

- Hence the resultant of fluxes has a constant magnitude of $1.5 \phi_m$ & is continuously changing its direction
- which means a rotating magnetic field of speed is called as synchronous speed is established & is denoted by N_s .

$$\text{Now, } N_s = \frac{120f}{P}$$

$\therefore f$ is frequency of 3ϕ supply voltage
 P is no. of poles of induction motor

WORKING OF A 3ΦIM

i) 3 ϕ supply is given to the stator windings which produce three phase fluxes, whose resultant Φ_r is equal to $1.5\Phi_m$ & rotating at a speed called as synchronous speed.

given by $N_s = 120 f/p$.

ii) This RMF cuts the rotor conductors thereby inducing emf in them.

iii) The rotor winding is a closed ckt, hence induced currents are set up. As a result each rotor conductor has its own magnetic field.

iv) The resultant effect of the two fields makes the rotor ~~to~~ rotate at a speed N .

v) The rotor speed N is always less than N_s .
(Because (synchronous speed))

→ The rotor sp If $N = N_s$ then relative speed becomes zero, hence no induced emf in the rotor so the rotor stops rotating.

This difference in speed is called as the slip speed
 $= N_s - N$

$$s = \frac{N_s - N}{N_s}$$

$$\% \text{ Slip} = \frac{N_s - N}{N_s} \times 100$$

Slip is 1 at the instant of rotation $\because N=0$.

N is \perp at start

Relation between f , f' and s .

$f \rightarrow$ supply frequency
 $f' \rightarrow$ frequency of the rotor induced emf.

$$f \propto N_s \quad \text{--- (1)}$$

$$f' \propto N_s - N \quad \text{--- (2)}$$

$$\frac{f'}{f} = \frac{N_s - N}{N_s} = s \rightarrow \text{slip}$$

$$f' = sf$$

Input to the induction motor : $P = \sqrt{3} V_L I_L \cos \phi$

$$N_s = \frac{120f}{P}$$

$$s = \frac{N_s - N}{N_s}$$

$$f' = sf$$

⑥ $V = 440V$ $f = 50Hz$ $P = 4$
 $P.F. = 0.85$ $P = 10 \times 7.56$
 $\cos \phi = 0.85$ $N = 1450 \text{ rpm}$ $\eta = 90\%$

$$ii) N_s = \frac{120 \times 50}{4} = 1500$$

$$s = \frac{1500 - 1450}{1500}$$

$$= 0.03333$$

$$s\% = 3.33\%$$

$$\eta = \frac{\text{o/p}}{\text{i/p}}$$

$$I_L = \frac{\text{o/p}}{V_L \sqrt{3} \cos \phi}$$

$$= \frac{7460}{440 \times \sqrt{3} \times 0.85}$$

$$iii) f' = sf$$

$$\frac{\text{o/p}}{\eta} = \frac{\text{o/p}}{\eta}$$

$$= \frac{7460}{647.78} = \frac{8288.88}{647.78}$$

$$f' = 0.03333 \times 50 = 1.666 \text{ Hz}$$

$$= \frac{7460}{0.90}$$

$$= 12.79A$$

$$= 8288.88$$