

# TRAVEO™ T2G family AUTOSAR MCAL FLS release notes

**SRN223408 version 1.17**

## About this document

### Scope and purpose

Thank you for your interest in the TRAVEO™ T2G family AUTOSAR MCAL FLS driver version 1.17. This document lists the installation requirements, software changes, limitations, and known issues.

### Intended audience

This document is intended for anyone who uses the FLS driver of the TRAVEO™ T2G family.

## Table of contents

<b>About this document.....</b>	<b>1</b>
<b>Table of contents.....</b>	<b>1</b>
<b>1 System requirements and recommendations .....</b>	<b>3</b>
1.1 Supported compilers .....	3
1.2 Compiler options.....	3
1.3 Library compiler options.....	4
1.4 Memory consumption .....	4
1.5 Stack consumption .....	6
1.5.1 Green Hills Software.....	6
1.5.2 IAR Embedded Workbench .....	7
1.6 Note on "_Bswmd.arxml" .....	7
1.7 Release details.....	8
<b>2 Installation.....</b>	<b>9</b>
<b>3 Deviations from AUTOSAR .....</b>	<b>10</b>
<b>4 Limitations.....</b>	<b>17</b>
<b>5 Known defects .....</b>	<b>25</b>
<b>6 Documentation .....</b>	<b>26</b>
<b>7 Technical support .....</b>	<b>27</b>
<b>8 Version history.....</b>	<b>28</b>
8.1 Module SW-Version 1.3.....	28
8.2 Module SW-Version 1.4.....	28
8.3 Module SW-Version 1.5.....	29
8.4 Module SW-Version 1.6.....	30
8.5 Module SW-Version 1.7.....	32
8.6 Module SW-Version 1.8.....	33
8.7 Module SW-Version 1.9.....	33
8.8 Module SW-Version 1.10.....	34
8.9 Module SW-Version 1.11.....	34

**Table of contents**

8.10	Module SW-Version 1.12.....	36
8.11	Module SW-Version 1.13.....	36
8.12	Module SW-Version 1.14.....	37
8.13	Module SW-Version 1.15.....	38
8.14	Module SW-Version 1.16.....	38
8.15	Module SW-Version 1.17.....	40

## System requirements and recommendations

# 1 System requirements and recommendations

Software prerequisites	Supported version
EB tresos Studio package for Infineon	26.2.0

## 1.1 Supported compilers

Green Hills Software, compiler v2017.1.4

IAR Embedded Workbench 8.0 EWARM FS 8.22.3

## 1.2 Compiler options

This section summarizes the compiler options used to build and test the module. When changing the compiler options, the module must be considered untested.

Compiler	Option (Cortex®-M4F core)
Green Hills Software, compiler v2017.1.4	<code>-cpu=cortexm4f -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsingle</code>

Compiler	Option (Cortex®-M7 core)
Green Hills Software, compiler v2017.1.4	<code>-cpu=cortexm7 -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fhard</code>

Compiler	Option (Cortex®-M4F core)
IAR Embedded Workbench 8.0 EWARM FS 8.22.3	<code>--debug --endian=little --cpu=Cortex-M4 -e --fpu=VFPv4_sp -Ohs --no_size_constraints</code>

Compiler	Option (Cortex®-M7 core)
IAR Embedded Workbench 8.0 EWARM FS 8.22.3	<code>--debug --endian=little --cpu=Cortex-M7 -e --fpu=VFPv5_d16 -Ohs --no_size_constraints</code>

## System requirements and recommendations

## 1.3 Library compiler options

If a binary library has been delivered with this module, it has been built using the following options:

Compiler	Option (Cortex®-M4F core)
Green Hills Software, compiler v2017.1.4	<code>-cpu=cortexm4f -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsingle</code>

Compiler	Option (Cortex®-M7 core)
Green Hills Software, compiler v2017.1.4	<code>-cpu=cortexm7 -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fhard</code>

Compiler	Option (Cortex®-M4F core)
IAR Embedded Workbench 8.0 EWARM FS 8.22.3	<code>--debug --endian=little --cpu=Cortex-M4 -e --fpu=VFPv4_sp -Ohs --no_size_constraints</code>

Compiler	Option (Cortex®-M7 core)
IAR Embedded Workbench 8.0 EWARM FS 8.22.3	<code>--debug --endian=little --cpu=Cortex-M7 -e --fpu=VFPv5_d16 -Ohs --no_size_constraints</code>

## 1.4 Memory consumption

GHS (Fls_lib) section	Size (in bytes)
.text	7724
.bss	120
Combined	7844

GHS (Fls_src) section	Size (in bytes)
.text	1254
.bss	160
.rodata	435
Combined	1849

## System requirements and recommendations

GHS (Fls_sub) section	Size (in bytes)
.text	6900
.bss	76
.rodata	3
Combined	6979

IAR (Fls_lib) section	Size (in bytes)
.text	7604
.bss	117
Combined	7721

IAR (Fls_src) section	Size (in bytes)
.text	1162
.bss	161
.rodata	444
Combined	1767

IAR (Fls_sub) section	Size (in bytes)
.text	6708
.bss	71
Combined	6779

Note: The memory consumption of \*\_src.lib depends on the configuration.

Note: The listed memory consumption will vary depending on customer configuration.

## Explanatory notes for this section

Section	Description
.text	Program code
.data	Variables with explicitly initialized values
.bss	Variables that are not explicitly initialized
.rodata	Read-only data

## System requirements and recommendations

## 1.5 Stack consumption

## 1.5.1 Green Hills Software

Function	Max stack usage (in bytes)
Fls_Init	28
Fls_Erase	116
Fls_Write	112
Fls_Cancel	88
Fls_GetStatus	0
Fls_GetJobResult	24
Fls_MainFunction	196
Fls_Read	100
Fls_Compare	92
Fls_SetMode	28
Fls_GetVersionInfo	28
Fls_GetStatusSub	64
Fls_BlankCheck	104
Fls_ReadImmediate	100
Fls_Suspend	108
Fls_Resume	104
Fls_SetCycleMode	28
Fls_Isr_Ipc_Cat1	84
Fls_Isr_Ipc_Cat2	84
Fls_Isr_Flash_Cat1	92
Fls_Isr_Flash_Cat2	92
Fls_Fault_Handling	0
Fls_Isr_FlsIpc_Cat1	20
Fls_Isr_FlsIpc_Cat2	20

**Note:** Stack consumption has been evaluated using the *gstack* utility program, which is part of the Green Hills release package. To enable the measurement of stack consumption in your project, build the source code according to the instructions given in the "Measuring the Stack Consumption" section of the module's user guide.

**Note:** The listed stack consumption will vary depending on customer configuration.

**Note:** The GHS stack consumption listed in the release notes was measured using the additional compile option "*-gs*". The GHS compiler cannot measure stack consumption for the selected optimization level (see compilation options). Green Hills cannot exclude possible effects of "*-gs*" on optimization and stack consumption. Therefore, Infineon cannot guarantee the accuracy of these values. For more information on measuring GHS stack consumption, see the section *gstack* utility program in *Build\_arm.pdf*.

## System requirements and recommendations

## 1.5.2 IAR Embedded Workbench

Function	Max stack usage (in bytes)
Fls_Init	48
Fls_Erase	144
Fls_Write	144
Fls_Cancel	112
Fls_GetStatus	0
Fls_GetJobResult	32
Fls_MainFunction	216
Fls_Read	128
Fls_Compare	128
Fls_SetMode	24
Fls_GetVersionInfo	32
Fls_GetStatusSub	88
Fls_BlankCheck	136
Fls_ReadImmediate	128
Fls_Suspend	144
Fls_Resume	144
Fls_SetCycleMode	40
Fls_Isr_Ipc_Cat1	88
Fls_Isr_Ipc_Cat2	88
Fls_Isr_Flash_Cat1	96
Fls_Isr_Flash_Cat2	96
Fls_Fault_Handling	0
Fls_Isr_FlsIpc_Cat1	24
Fls_Isr_FlsIpc_Cat2	24

**Note:** To enable the measurement of stack consumption in your project, build the source code with the linker option "`--enable_stack_usage --log call_graph`". See stack usage analysis of the IAR C/C++ development guide for details.

**Note:** The listed stack consumption will vary depending on customer configuration.

## 1.6 Note on "\*\_Bswmd.arxml"

Note that the `<Module>_Bswmd.arxml` files are templates that can be freely modified by the customer or RTE vendor.

These are in the `output\generated\swcd` subfolder of your *project* folder.

Named files are not tested.

## System requirements and recommendations

## 1.7 Release details

---

**Module software version**

---

1.17.x

(x=software patch version; see the delivery notes for details)

---

---

**AUTOSAR specification version (ASR)**

---

4.2.2

---

---

**Target**

---

MXS40

---

---

**MCAL configuration settings**

See the resource release notes

---

**Supported derivatives**See the resource release notes

---

---

**Corresponding Fls\_MemMap.h stub file version**

---

1.0.1

---



## Installation

## 2 Installation

See the installation manual for EB tresos Studio for INFINEON AUTOSAR software products and installation manual for MCAL42-TRAVEO.

### 3 Deviations from AUTOSAR

T2MC-6734 - [ECUC\_Fls\_00310]

**Title:** [ECUC\_Fls\_00310]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00310: (Obsolete)</b>
<b>Container Name</b>	FlsDemEventParameterRefs
<b>Description</b>	<p>Container for the references to <code>DemEventParameter</code> elements which shall be invoked using the <code>Dem_ReportErrorStatus</code> API in case the corresponding error occurs. The <code>EventId</code> is taken from the referenced <code>DemEventParameter</code>'s <code>DemEventId</code> value. The standardized errors are provided in the container and can be extended by vendor specific error references.</p> <p><b>Tags:</b>  <code>atp.Status=obsolete</code>  <code>atp.StatusComment=This container is set to obsolete and will be removed in release 4.3.</code>  <code>atp.StatusRevisionBegin=4.2.2</code></p>

#### Configuration Parameters

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

T2MC-6736 - [ECUC\_Fls\_00311]

**Title:** [ECUC\_Fls\_00311]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00311: (Obsolete)</b>		
<b>Name</b>	FLS_E_ERASE_FAILED		
<b>Description</b>	<p>Reference to the <code>DemEventParameter</code> which shall be issued when the error "Flash erase failed (HW)" has occurred.</p> <p><b>Tags:</b>  <code>atp.Status=obsolete</code>  <code>atp.StatusComment=This reference is set to obsolete and will be removed in release 4.3.</code>  <code>atp.StatusRevisionBegin=4.2.2</code></p>		
<b>Multiplicity</b>	0..1		
<b>Type</b>	Symbolic name reference to [ <code>DemEventParameter</code> ]		
<b>Post-Build Multiplicity</b>	<b>Variant</b>	true	
<b>Post-Build Variant Value</b>		true	
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Value Configuration Class</b>		<b>Pre-compile time</b>	X VARIANT-PRE-COMPILE

## Deviations from AUTOSAR

	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

T2MC-6739 - [ECUC\_Fls\_00312]

**Title:** [ECUC\_Fls\_00312]

**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00312: (Obsolete)</b>		
<b>Name</b>	FLS_E_WRITE_FAILED		
<b>Description</b>	Reference to the <code>DemEventParameter</code> which shall be issued when the error "Flash write failed (HW)" has occurred. <b>Tags:</b> atp.Status=obsolete atp.StatusComment=This reference is set to obsolete and will be removed in release 4.3. atp.StatusRevisionBegin=4.2.2		
<b>Multiplicity</b>	0..1		
<b>Type</b>	Symbolic name reference to [ <code>DemEventParameter</code> ]		
<b>Post-Build Variant Multiplicity</b>	true		
<b>Post-Build Variant Value</b>	true		
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

T2MC-6737 - [ECUC\_Fls\_00313]

**Title:** [ECUC\_Fls\_00313]

**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00313: (Obsolete)</b>		
<b>Name</b>	FLS_E_READ_FAILED		
<b>Description</b>	Reference to the <code>DemEventParameter</code> which shall be issued when the error "Flash read failed (HW)" has occurred. <b>Tags:</b> atp.Status=obsolete atp.StatusComment=This reference is set to obsolete and will be		

## Deviations from AUTOSAR

	removed in release 4.3. atp.StatusRevisionBegin=4.2.2		
<b>Multiplicity</b>	0..1		
<b>Type</b>	Symbolic name reference to [ DemEventParameter ]		
<b>Post-Build Variant Multiplicity</b>	true		
<b>Post-Build Variant Value</b>	true		
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

T2MC-6735 - [ECUC\_Fls\_00314]

**Title:** [ECUC\_Fls\_00314]

**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00314: (Obsolete)</b>		
<b>Name</b>	FLS_E_COMPARE_FAILED		
<b>Description</b>	Reference to the DemEventParameter which shall be issued when the error "Flash compare failed (HW)" has occurred. <b>Tags:</b> atp.Status=obsolete atp.StatusComment=This reference is set to obsolete and will be removed in release 4.3. atp.StatusRevisionBegin=4.2.2		
<b>Multiplicity</b>	0..1		
<b>Type</b>	Symbolic name reference to [ DemEventParameter ]		
<b>Post-Build Variant Multiplicity</b>	true		
<b>Post-Build Variant Value</b>	true		
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

## Deviations from AUTOSAR

T2MC-6738 - [ECUC\_Fls\_00315]

**Title:** [ECUC\_Fls\_00315]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00315: (Obsolete)</b>		
<b>Name</b>	FLS_E_UNEXPECTED_FLASH_ID		
<b>Description</b>	Reference to the <code>DemEventParameter</code> which shall be issued when the error "Expected hardware ID not matched" has occurred. <b>Tags:</b> atp.Status=obsolete atp.StatusComment=This reference is set to obsolete and will be removed in release 4.3. atp.StatusRevisionBegin=4.2.2		
<b>Multiplicity</b>	0..1		
<b>Type</b>	Symbolic name reference to [ <code>DemEventParameter</code> ]		
<b>Post-Build Variant Multiplicity</b>	true		
<b>Post-Build Variant Value</b>	true		
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

T2MC-6542 - [SWS\_Fls\_00048]

**Title:** [SWS\_Fls\_00048]**Description:** If supported by hardware, the function `Fls_Init` shall set the flash memory erase/write protection as provided in the configuration set. (SRS\_Fls\_12132)**Reason for rejection:** Protection is not within the scope of the flash driver.

T2MC-6466 - [SWS\_Fls\_00088]

**Title:** [SWS\_Fls\_00088]**Description:** The functional requirements and the functional scope are the same for both internal and external drivers. Hence the API is semantically identical. (SRS\_Fls\_12147, SRS\_Fls\_12148)**Reason for rejection:** The external flash device is not supported. Only internal work flash is supported.

Deviations from AUTOSAR

---

T2MC-6512 - [SWS\_Fls\_00140]

**Title:** [SWS\_Fls\_00140]

**Description:** The FLS module's erase routine shall load the flash access code for erasing the flash memory to the location in RAM pointed to by the erase function pointer contained in the flash drivers configuration set if the FLS module is configured to load the flash access code to RAM on job start. (SRS\_Fls\_12193)

**Reason for rejection:** The code flash is not supported, so loading the code into RAM is unnecessary.

---

T2MC-6513 - [SWS\_Fls\_00141]

**Title:** [SWS\_Fls\_00141]

**Description:** The FLS module's write routine shall load the flash access code for writing the flash memory to the location in RAM pointed to by the write function pointer contained in the flash drivers configuration set if the FLS module is configured to load the flash access code to RAM on job start. (SRS\_Fls\_12193)

**Reason for rejection:** The code flash is not supported, so loading the code into RAM is unnecessary.

---

T2MC-6516 - [SWS\_Fls\_00143]

**Title:** [SWS\_Fls\_00143]

**Description:** After an erase or write job has been finished or canceled, the FLS module's main processing routine shall unload (i.e. overwrite) the flash access code (internal erase/write routines) from RAM if they have been loaded to RAM by the flash driver. (SRS\_Fls\_13300)

**Reason for rejection:** The code flash is not supported, so loading the code into RAM is unnecessary.

---

T2MC-6507 - [SWS\_Fls\_00144]

**Title:** [SWS\_Fls\_00144]

**Description:** During the initialization of the external flash driver, the FLS module shall check the hardware ID of the external flash device against the corresponding published parameter. If a hardware ID mismatch occurs, the FLS module shall report the error code FLS\_E\_UNEXPECTED\_FLASH\_ID to the Default Error Tracer (DET), set the FLS module status to FLS\_E\_UNINIT and shall not initialize itself. (SRS\_Fls\_12107)

A complete list of required parameters is specified in the SPI Handler/Driver Software Specification (Chapter "Configuration Specification", marked as "SPI User").

**Reason for rejection:** The external flash device is not supported. Only internal work flash is supported.

---

T2MC-6556 - [SWS\_Fls\_00145]

**Title:** [SWS\_Fls\_00145]

**Description:** If possible, e.g. with interrupt controlled implementations, the FLS module shall start the first round of the erase job directly within the function `Fls_Erase` to reduce overall runtime. (SRS\_Fls\_12136)

**Reason for rejection:** This requirement is not mandatory and the rejection is due to simplification of the implementation.

---

Deviations from AUTOSAR

---

T2MC-6571 - [SWS\_Fls\_00146]

**Title:** [SWS\_Fls\_00146]**Description:** If possible, e.g. with interrupt controlled implementations, the FLS module shall start the first round of the write job directly within the function `Fls_Write` to reduce overall runtime. (SRS\_Fls\_12135)**Reason for rejection:** This requirement is not mandatory and the rejection is due to simplification of the implementation.

---

T2MC-6515 - [SWS\_Fls\_00213]

**Title:** [SWS\_Fls\_00213]**Description:** The FLS module's main processing routine shall access the flash access code routines by means of the respective function pointer contained in the FLS module's configuration set (post-compile parameters) regardless whether the flash access code routines have been loaded to RAM or whether they can be executed directly from (flash) ROM. (SRS\_Fls\_12194)**Reason for rejection:** The code flash is not supported, so loading the code into RAM is not necessary.

---

T2MC-6517 - [SWS\_Fls\_00214]

**Title:** [SWS\_Fls\_00214]**Description:** The FLS module shall only load the access code to the RAM if the access code cannot be executed out of flash ROM. (SRS\_Fls\_12193)**Reason for rejection:** The access code can be executed out of flash ROM.

---

T2MC-6510 - [SWS\_Fls\_00215]

**Title:** [SWS\_Fls\_00215]**Description:** The FLS module's flash access routines shall only disable interrupts and wait for the completion of the erase/write command if necessary (that is if it has to be ensured that no other code is executed in the meantime). (SRS\_Fls\_12194)**Reason for rejection:** The code flash is not supported, therefore disabling interrupts and waiting is unnecessary. Writing to the work flash does not disturb code execution.

---

T2MC-6519 - [SWS\_Fls\_00302]

**Title:** [SWS\_Fls\_00302]**Description:** **{Obsolete}** The module's status, mode and the job result shall be made available for debugging (reading). (RS\_BRF\_02240)**Reason for rejection:** This requirement is obsolete in the AUTOSAR specification.

---

---

**Deviations from AUTOSAR**

---

T2MC-6505 - [SWS\_Fls\_00319]

**Title:** [SWS\_Fls\_00319]

**Description:** The runtime error code `FLS_E_UNEXPECTED_FLASH_ID` shall be reported when the expected flash ID is not matched (see SWS\_Fls\_00144). (SRS\_BSW\_00337, SRS\_BSW\_00385, SRS\_BSW\_00327, SRS\_BSW\_00331)

**Reason for rejection:** Flash ID is not used because only internal flash memory is supported.

---



## Limitations

## 4 Limitations

T2MC-6704 - [ECUC\_Fls\_00169]

**Title:** [ECUC\_Fls\_00169]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00169:</b>		
<b>Name</b>	FlsBaseAddress		
<b>Description</b>	The flash memory start address (see also SWS_Fls_00208 and SWS_Fls_00209). This parameter defines the lower boundary for read / write / erase and compare jobs.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: local		

**Limitation:** The flash memory address ("virtual" addresses) always starts from 0 in this implementation, so the configuration parameter `FlsBaseAddress` is fixed at 0.

T2MC-6718 - [ECUC\_Fls\_00270]

**Title:** [ECUC\_Fls\_00270]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00270:</b>		
<b>Name</b>	FlsAcErase		
<b>Description</b>	Address offset in RAM to which the erase flash access code shall be loaded. Used as function pointer to access the erase flash access code.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	true		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

## Limitations

**Limitation:** This implementation does not need to load the flash access code to RAM since code flash is out of scope. So, the configuration parameter `FlsAcErase` cannot be configured.

T2MC-6728 - [ECUC\_Fls\_00279]

**Title:** [ECUC\_Fls\_00279]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00279:</b>		
<b>Name</b>	FlsProtection		
<b>Description</b>	Erase/write protection settings. Only relevant if supported by hardware.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	true		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local dependency: Only relevant if supported by hardware.		

**Limitation:** The protection by the FLS driver is out of scope, the configuration parameter `FlsProtection` cannot be configured.

T2MC-6748 - [ECUC\_Fls\_00281]

**Title:** [ECUC\_Fls\_00281]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00281:</b>		
<b>Name</b>	FlsPageSize		
<b>Description</b>	Size of one page of this sector. Implementation Type: <code>Fls_LengthType</code> .		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: local dependency: The sector size has to be an integer multiple of the page size.		

**Limitation:** This parameter value is only four.

## Limitations

T2MC-6703 - [ECUC\_Fls\_00284]

**Title:** [ECUC\_Fls\_00284]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00284:</b>		
<b>Name</b>	FlsAcLoadOnJobStart		
<b>Description</b>	<p>The flash driver shall load the flash access code to RAM whenever an erase or write job is started and unload (overwrite) it after that job has been finished or canceled.</p> <p>true: Flash access code loaded on job start /unloaded on job end or error. false: Flash access code not loaded to / unloaded from RAM at all.</p>		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucBooleanParamDef		
<b>Default value</b>	false		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM since code flash is out of scope. So, the configuration parameter `FlsAcLoadOnJobStart` cannot be configured and is always false.

T2MC-6708 - [ECUC\_Fls\_00287]

**Title:** [ECUC\_Fls\_00287]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00287:</b>		
<b>Name</b>	FlsDevErrorDetect		
<b>Description</b>	<p>Switches the Default Error Tracer (Det) detection and notification ON or OFF.</p> <p>true: enabled (ON). false: disabled (OFF).</p>		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucBooleanParamDef		
<b>Default value</b>	true		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: local		

## Limitations

**Limitation:** The configuration parameter `FlsDevErrorDetect` can be set as false and notification is defined as OFF, but `ErrorCallOutFunction` is called for functional safety point of view.

T2MC-6709 - [ECUC\_Fls\_00288]

**Title:** [ECUC\_Fls\_00288]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00288:</b>		
<b>Name</b>	FlsDriverIndex		
<b>Description</b>	Index of the driver, used by FEE.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef (Symbolic Name generated for this parameter)		
<b>Range</b>	0 .. 254		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: ECU		

**Limitation:** Only one flash driver is provided, so the configuration parameter `FlsDriverIndex` cannot be configured and is fixed at 0.

T2MC-6754 - [ECUC\_Fls\_00294]

**Title:** [ECUC\_Fls\_00294]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00294:</b>		
<b>Name</b>	FlsAcLocationErase		
<b>Description</b>	Position in RAM, to which the erase flash access code has to be loaded. Only relevant if the erase flash access code is not position independent. If this information is not provided it is assumed that the erase flash access code is position independent and that therefore the RAM position can be freely configured.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Published Information</b>	X	All Variants
<b>Scope / Dependency</b>	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM, since code flash is out of scope. So, the configuration parameter `FlsAcLocationErase` is not used.

## Limitations

T2MC-6755 - [ECUC\_Fls\_00295]

**Title:** [ECUC\_Fls\_00295]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00295:</b>		
<b>Name</b>	FlsAcLocationWrite		
<b>Description</b>	Position in RAM, to which the write flash access code has to be loaded. Only relevant if the write flash access code is not position independent. If this information is not provided it is assumed that the write flash access code is position independent and that therefore the RAM position can be freely configured.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Published Information</b>	X	All Variants
<b>Scope / Dependency</b>	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM, since code flash is out of scope. So, the configuration parameter `FlsAcLocationWrite` is not used.

T2MC-6756 - [ECUC\_Fls\_00296]

**Title:** [ECUC\_Fls\_00296]**Description:**

<b>SWS Item</b>	<b>ECUC_Fls_00296:</b>		
<b>Name</b>	FlsAcSizeErase		
<b>Description</b>	Number of bytes in RAM needed for the erase flash access code.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	false		
<b>Value Configuration Class</b>	<b>Published Information</b>	X	All Variants
<b>Scope / Dependency</b>	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM, since code flash is out of scope. So, the configuration parameter `FlsAcSizeErase` is not used.

## Limitations

T2MC-6757 - [ECUC\_Fls\_00297]

**Title:** [ECUC\_Fls\_00297]

### Description:

SWS Item	ECUC_Fls_00297:		
Name	FlsAcSizeWrite		
Description	Number of bytes in RAM needed for the write flash access code.		
Multiplicity	1		
Type	EcucIntegerParamDef		
Range	0 .. 4294967295		
Default value	--		
Post-Build Variant Value	false		
Value Configuration Class	Published Information	X	All Variants
Scope / Dependency	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM, since code flash is out of scope. So, the configuration parameter `FlsAcSizeWrite` is not used.

T2MC-6760 - [ECUC\_Fls\_00300]

**Title:** [ECUC\_Fls\_00300]

### Description:

SWS Item	ECUC_Fls_00300:		
Name	FlsExpectedHwId		
Description	Unique identifier of the hardware device that is expected by this driver (the device for which this driver has been implemented). Only relevant for external flash drivers.		
Multiplicity	1		
Type	EcucStringParamDef		
Default value	--		
maxLength	--		
minLength	--		
regularExpression	--		
Post-Build Variant Value	false		
Value Configuration Class	Published Information	X	All Variants
Scope / Dependency	scope: local		

**Limitation:** The external flash device is not supported, so the configuration parameter `FlsExpectedHwId` is not used.

## Limitations

T2MC-6719 - [ECUC\_Fls\_00305]

**Title:** [ECUC\_Fls\_00305]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00305:</b>		
<b>Name</b>	FlsAcWrite		
<b>Description</b>	Address offset in RAM to which the write flash access code shall be loaded. Used as function pointer to access the write flash access code.		
<b>Multiplicity</b>	1		
<b>Type</b>	EcucIntegerParamDef		
<b>Range</b>	0 .. 4294967295		
<b>Default value</b>	--		
<b>Post-Build Variant Value</b>	true		
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	VARIANT-PRE-COMPILE
	<b>Link time</b>	--	
	<b>Post-build time</b>	X	VARIANT-POST-BUILD
<b>Scope / Dependency</b>	scope: local		

**Limitation:** This implementation does not need to load the flash access code to RAM, since code flash is out of scope. So, the configuration parameter `FlsAcWrite` cannot be configured.

T2MC-6741 - [ECUC\_Fls\_00316]

**Title:** [ECUC\_Fls\_00316]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00316:</b>
<b>Container Name</b>	FlsExternalDriver
<b>Description</b>	This container is present for external Flash drivers only. Internal Flash drivers do not use the parameter listed in this container, hence its multiplicity is 0 for internal drivers.

### Configuration Parameters

**Limitation:** The external flash device is not supported, so the container `FlsExternalDriver` cannot be configured.

T2MC-6742 - [ECUC\_Fls\_00317]

**Title:** [ECUC\_Fls\_00317]

### Description:

<b>SWS Item</b>	<b>ECUC_Fls_00317:</b>
<b>Name</b>	FlsSpiReference
<b>Description</b>	Reference to SPI sequence (required for external Flash drivers).
<b>Multiplicity</b>	1..*
<b>Type</b>	Symbolic name reference to [ SpiSequence ]

## Limitations

<b>Post-Build Variant Multiplicity</b>	false		
<b>Post-Build Variant Value</b>	false		
<b>Multiplicity Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Value Configuration Class</b>	<b>Pre-compile time</b>	X	All Variants
	<b>Link time</b>	--	
	<b>Post-build time</b>	--	
<b>Scope / Dependency</b>	scope: local		

**Limitation:** The external flash device is not supported, so the configuration parameter `FlsSpiReference` cannot be configured.

T2MC-43889 - [FLS] AUTOSAR C implementation rules

**Title:** [FLS] AUTOSAR C implementation rules

**Description:** The MCAL modules shall fulfill all design and implementation guidelines as described in specification of C implementation rules AUTOSAR\_TR\_CImplementationRules.pdf.

**Limitation:** Out of scope: keyword macros 'CONST' and 'VAR' are not required for declaration/definition of the local variable, function parameter, and structure/union fields.

T2MC-6509 - [SWS\_Fls\_00137]

**Title:** [SWS\_Fls\_00137]

**Description:** The FLS module's implementer shall place the code of the flash access routines into a *separate C-module* `Fls_ac.c`. (SRS\_Fls\_12193)

**Limitation:** `Fls_ac.c` is replaced by `Fls_Sub` module, which is provided as hardware abstraction layer (HAL) part.

T2MC-6665 - [SWS\_Fls\_00234]

**Title:** [SWS\_Fls\_00234]

**Description:** If interrupt controlled job processing is supported and enabled with the configuration parameter `FlsUseInterrupts`, the interrupt service routine shall reset the interrupt flag, check for errors reported by the underlying hardware, reload the hardware finite state machine for the next round of the pending job or call the appropriate notification routine if the job is finished or aborted. (RS\_BRF\_01144)

**Limitation:** The notification routine is called by `Fls_MainFunction` or `Fls_Cancel` in this implementation.



**Known defects**

## **5 Known defects**

The listed issues were known at the day this release note was generated. Further problems may have been discovered in the meantime. For an up-to-date list of known issues, contact your Infineon sales representative.

This release has no known issues at the time of release.

## 6 Documentation

All user guides for MCAL drivers are in the `\doc` subdirectory of the *installation* directory. The default location is:

C:\INFINEON\_ESDB\Tresos26\_2\_0\doc

## **7 Technical support**

If you have questions related to the driver, contact the local support application engineer.

## Version history

## 8 Version history

### 8.1 Module SW-Version 1.3

Initial module setup.

### 8.2 Module SW-Version 1.4

T2MC-39176 - [All] Correcting vendor-specific module definition

**Title:** [All] Correcting vendor-specific module definition

**Description:** The following rules should be followed in the vendor-specific module definition.

- The multiplicity of each AUTOSAR parameter, reference and container is not correctly derived.
- The DEFAULT-VALUE of each parameter is not valid.
- If the target of DESTINATION-REF is not the standard AUTOSAR container, the reference should not start with '/AUTOSAR/EcucDefs/'.

T2MC-38134 - [FLS] FLS module sets the wait states for all flash that MCU module configures.

**Title:** [FLS] FLS module sets the wait states for all flash that MCU module configures.

**Description:** FLS and MCU write to the same registers (flash wait states).

The following are the problems:

1. If MCU and FLS are used in the same project, then the configuration of one module (usually MCU) is overwritten and ignored.
2. FLS configures the wait states for all flash, including code flash. This has negative impact on system performance.
3. Requirement SWS\_Fls\_00086 is violated.

The registers should be written by MCU module only. FLS settings should be removed.

T2MC-38069 - [FLS] The durations of interrupt service routine for erase job and exclusive areas in Fls\_Suspend / Fls\_Resume are too long.

**Title:** [FLS] The durations of interrupt service routine for erase job and exclusive areas in Fls\_Suspend / Fls\_Resume are too long.

**Description:** The durations of interrupt service routine for erase job and exclusive areas in Fls\_Suspend / Fls\_Resume are too long.

- Measurement condition  
Source oscillation: 8MHz  
PLL clock multiplier: x10 (80MHz)
- Measurement result  
Fls\_Suspend exclusive areas: 96usec (maybe depending on timing)  
Fls\_Resume exclusive areas: 62usec (maybe depending on timing)  
erase ISR: 67.0 us
- Workaround  
The erase ISR would not been fixed because there is workaround which Fls\_Erase should be called for erase every one sector when the configuration parameter *FlsGeneral/FlsUseInterrupts* is TRUE.

## Version history

---

T2MC-38074 - File extension should be changed from .bmd to .arxml

**Title:** File extension should be changed from .bmd to .arxml

**Description:** The file extension should be changed from \*.bmd to \*.arxml.  
Each module still has an autosar/<module>.bmd file.

---

## 8.3 Module SW-Version 1.5

---

T2MC-39747 - [All] Checking for valid C function name and including filename in configuration parameters

**Title:** [All] Checking for valid C function name and including filename in configuration parameters

**Description:** Checking for valid C function name:

Check all configuration parameters related to the function name to see if it is a valid C function name.

A part of parameters are not checked.

If an invalid function name is set, a compile error will occur during the build process, which is inconvenient for users.

Therefore, it is better to check whether the configured function names are valid C function names in advance (i.e. during configuration phase).

Checking for valid filename:

Check all configuration parameters related to the file name to see if it is valid.

A part of parameters cannot check the fact that empty file name (i.e. ".h") is wrong.

If an invalid file name is set, a compile error will occur during the build process, which is inconvenient for users.

Therefore, it is better, to check in advance, whether the configured file names are valid.

This CR is intended to solve the inconvenience.

---

T2MC-47850 - [FLS] When SourceAddressPtr of Fls\_Write is not a multiple of FlsPageSize, the writing would not run normally

**Title:** [FLS] When SourceAddressPtr of Fls\_Write is not a multiple of FlsPageSize, the writing would not run normally

**Description:** According to hardware specification, the address of programmed data passed to system call of ProgramRow is allowed only 32-bit aligned address.  
It has not yet been considered.

---

T2MC-50581 - [FLS]: Dummy read is needed after erase operation in non-blocking mode is finished

**Title:** [FLS]: Dummy read is needed after erase operation in non-blocking mode is finished

**Description:** According to the latest hardware specification, requirement for a user to perform a dummy read in non-blocking mode was added by CDT 307046.

Dummy read is required to make the logical bank of work flash ready for read operation after a program or erase operation. (This is not applicable if EraseSector is invoked in blocking mode.)

- If dummy read is not done, the first read from the work flash logical bank which was programmed/erased will give error.
-

## Version history

- Moreover, if you read from logical bank which completed program/erase operation, then FLASH\_CTL.WORK\_ERR\_SILENT must be set to 1 in advance.

In current implementation, FLS invokes EraseSector in non-blocking mode, but has not done the dummy read after completion of erase operation. It has already set FLASH\_CTL.WORK\_ERR\_SILENT.

Therefore, FLS must only do a dummy read after erase sector operation is finished.

---

T2MC-41850 - [General] <CODE-DESCRIPTORS> Node should be added to the *arxml* files of all modules

**Title:** [General] <CODE-DESCRIPTORS> Node should be added to the *arxml* files of all modules

**Description:** For all modules, the <CODE-DESCRIPTORS> Node needs to be added for the RTE within the BSWMD *arxml* file.

---

T2MC-39411 - [FLS]: Support TRAVEO™ T2G-B-H-8M.

**Title:** [FLS]: Support TRAVEO™ T2G-B-H-8M

**Description:** AUTOSAR MCAL supports the TRAVEO™ T2G-B-H-8M.

FLS is modified for the following change.

- Switch of the IPC structure No. for SROM API, the flash interface status register address and internal information for each core  
Because the above-mentioned items are separated by cores, FLS needs to switch them by referring the CPUSS.IDENTITY register.
- WorkFlash size  
It is required for BMD file to be added additional sectors for maximum size of TRAVEO™ T2G products.

## 8.4 Module SW-Version 1.6

---

T2MC-52843 - [FLS] Appearance of function interface is not unified between definition and declaration

**Title:** [FLS] Appearance of function interface is not unified between definition and declaration

**Description:** Appearances of function interfaces in some functions are not unified between definition and declaration.

---

T2MC-54374 - [FLS] Fls.h does not include Fls\_Cfg.h

**Title:** [FLS] Fls.h does not include Fls\_Cfg.h

**Description:** Fls.h does not include Fls\_Cfg.h. So, the Fls module does not comply with the file structure represented in [SWS\_Fls\_00107] of AUTOSAR specification.

---

T2MC-55313 - [FLS] The mclass is missing in Fls.xdm

**Title:** [FLS] The mclass is missing in Fls.xdm

**Description:** The mclass in xdm file corresponds to ECUC-MULTIPLICITY-CONFIGURATION-CLASS in *arxml* file.

## Version history

---

There are some configuration parameters that have ECUC-MULTIPLICITY-CONFIGURATION-CLASS in Fls.arxml and do not have mclass in Fls.xdm.

However, to avoid issuing many warning messages, the mclass is added for only two containers.

- FlsConfigSet
- FlsSector

---

T2MC-54377 - [FLS] The ptrclass of pointer to const variable is not FLS\_APPL\_CONST

**Title:** [FLS] The ptrclass of pointer to const variable is not FLS\_APPL\_CONST

**Description:** The ptrclass of pointer to const variable is FLS\_APPL\_DATA. It should be FLS\_APPL\_CONST.

---

T2MC-54375 - [FLS] There are some internal types whose prefix are not Fls

**Title:** [FLS] There are some internal types whose prefix are not Fls

**Description:** Following internal types have a prefix which is not Fls. The prefix should be Fls.

- FeeJobEndNotificationFctPtr

---

T2MC-50612 - [General] Delete device-dependent information from the user guide

**Title:** [General] Delete device-dependent information from the user guide

**Description:** Any device-dependent information should not be included in the user guide.

Therefore, delete the datasheet name from the related documentation in the user guide.

---

T2MC-50519 - [General] Export issue with MCAL ES10\_20180308

**Title:** [General] Export issue with MCAL ES10\_20180308

**Description:** An example of the issue is described below.

The configuration exported from Tresos does not correspond to the real configuration shown in Tresos. See the attached example.

The issue concerns other modules too, not only the port described in attached pdf file.

---

T2MC-56129 - [FLS]: Target name is changed from CYT2 to MXS40

**Title:** [FLS]: Target name is changed from CYT2 to MXS40

**Description:** Target name is changed from CYT2 to MXS40. Therefore, followings are modified.

- The makefile names are changed from Fls\_defs\_CYT2.mak and Fls\_rules\_CYT2.mak to Fls\_defs\_der.mak and Fls\_rules\_der.mak, respectively, to avoid depending on target name.
  - The macro names are changed from FLS\_CYT2 and FLS\_CYT2XXXXXX to FLS\_MXS40.
-

## Version history

## 8.5 Module SW-Version 1.7

T2MC-59563 - [FLS] The description regarding registers in access register table of user guide is wrong

**Title:** [FLS] The description regarding registers in access register table of user guide is wrong

**Description:** The description regarding FLASHC FLASH\_CTL register in access register table of user guide has the following mistakes:

(Wrong) Value: 0x00510000, Monitoring Value: 0x0051000F | MAIN\_WS[3:0]

(Correct) Value: 0x00510000 | MAIN\_WS[3:0], Monitoring Value: 0x00510000 | MAIN\_WS[3:0]

The description regarding FAULT MASK1 register in access register table of user guide has following mistakes.

(Wrong) Value: 0x03380000, Mask Value: 0x03380000, Monitoring Value: 0x03380000

(Correct) Value: 0x00380000, Mask Value: 0x00380000, Monitoring Value: 0x00380000

T2MC-63150 - [FLS] Memory access order of IPC register writing and SRAM\_SCRATCH writing must be ensured

**Title:** [FLS] Memory access order of IPC register writing and SRAM\_SCRATCH writing must be ensured

**Description:** FLS design must consider the following characteristics of the Arm® architecture:

- SRAM\_SCRATCH is in an area which has "Normal" memory attributes.
- IPC registers (like NOTIFY) are of course located in an area with "Device" memory attributes.

Therefore, memory access order of IPC register writing and SRAM\_SCRATCH writing must be ensured by use of a memory barrier instruction.

T2MC-61562 - [FLS] Problem in FLS BSWMD file

**Title:** [FLS] Problem in FLS BSWMD file

**Description:** FLS BSWMD file (Fls\_Bswmd.xml) has some errors.

- The interrupt service routines are implemented in FLS, but BSW-INTERRUPT-ENTITY node does not exist in Fls\_Bswmd.xml.
- The nodes regarding the interrupt service routines are generated in Fls\_Bswmd.xml whether or not FlsUseInterrupts is true.
- Although Fls\_Init has exclusive area, there is no CAN-ENTER-EXCLUSIVE-AREA-REFS node (in BSW-CALLED-ENTITY) for Fls\_Init in Fls\_Bswmd.xml.

T2MC-63151 - [FLS] When a compare job fails due to hardware error, the job result is not MEMIF\_JOB\_FAILED

**Title:** [FLS] When a compare job fails due to hardware error, the job result is not MEMIF\_JOB\_FAILED

**Description:** When a compare job fails due to hardware error, the job result is not MEMIF\_JOB\_FAILED.

It is because the job result is replaced with MEMIF\_BLOCK\_INCONSISTENT in Fls\_MainFunction.

There is similar error of processing for read job in Fls\_MainFunction.



## Version history

---

## 8.6 Module SW-Version 1.8

---

T2MC-65904 - [FLS] Non-cacheable setting in enabling data cache is not documented

**Title:** [FLS] Non-cacheable setting in enabling data cache is not documented

**Description:** When data cache is enabled, for erasing/writing to Flash memory, following area must be in non-cacheable area by use of MPU.

- Work flash region
- A section FLS\_START\_SEC\_VAR\_NO\_INIT\_UNSPECIFIED / FLS\_STOP\_SEC\_VAR\_NO\_INIT\_UNSPECIFIED (in Fls\_MemMap.h)

Flash driver user guide does not describe the non-cacheable setting in enabling data cache.

---

T2MC-65997 - [FLS] The parameter FlsMaxWriteNormalMode should be configured in units of page size

**Title:** [FLS] The parameter FlsMaxWriteNormalMode should be configured in units of page size

**Description:** The minimum number is defined by the size of one flash page and therefore, depends on the underlying flash device.

In that case, the minimum number should be 4 bytes as the page size is 4.

---

T2MC-65903 - [FLS] Uninitialized variable is referred

**Title:** [FLS] Uninitialized variable is referred

**Description:** Following variables can be referred before setting:

1. Fls\_FMAPIIpcStruct
  2. Fls\_ConfigPtr
- 

The following is supported in release V1.2.4.

---

T2MC-77594 – Support IAR compiler

**Title:** Support IAR compiler

**Description:** Support IAR compiler (IAR EWARM FS 8.22.3.15992).

---

---

## 8.7 Module SW-Version 1.9

---

T2MC-88178 - [FLS] When the configuration FlsUseInterrupts is true, writing job rarely leads to the FLS\_E\_VERIFY\_WRITE\_FAILED error

**Title:** [FLS] When the configuration FlsUseInterrupts is true, writing job rarely leads to the FLS\_E\_VERIFY\_WRITE\_FAILED error

**Description:** In the FLS module, when the configuration “FlsUseInterrupts” is true (enabled) and writing on hardware is very fast (or software is slow), data writing job by Fls\_Write() is not correctly performed occasionally on to few areas of Work Flash memory. As a result, the writing job leads to the FLS\_E\_VERIFY\_WRITE\_FAILED error.

---

## Version history

---

## 8.8 Module SW-Version 1.10

---

T2MC-91144 - [FLS] The description for Fls\_MainFunction shall not be generated in Fls\_Bswmd.arxml file if "FlsCallCycle" is 0

**Title:** [FLS] The description for Fls\_MainFunction shall not be generated in Fls\_Bswmd.arxml file if "FlsCallCycle" is 0

**Description:** This requirement from customer is that the description for Fls\_MainFunction shall not be generated in Fls\_Bswmd.arxml file if the configuration parameter "FlsCallCycle" is set to 0.

---

T2MC-91523 - [FLS] Fls.xdm is inconsistent with Fls.arxml

**Title:** [FLS] Fls.xdm is inconsistent with Fls.arxml

**Description:** Fls.xdm is inconsistent with Fls.arxml.

Fls.arxml uses unnecessary tags.

Fls.arxml and Fls.xdm lack some essential tags.

---

T2MC-91800 - [FLS] The system call in user guide should be updated to match the new HW Spec

**Title:** [FLS] The system call in user guide should be updated to match the new HW Spec

**Description:** The system call described in "6.5 System Call" of the user guide does not match with the new hardware specification.

For example, "the last available SRAM is the allocated stack for system call and calling NMI Handler."

- SRAM area for system call is newly changed from last to first.
- The interrupt which triggers system call is no longer NMI handler.

The description should be modified.

---

## 8.9 Module SW-Version 1.11

---

T2MC-97037 - [FLS] Minimum time from resume to suspend for erase job should be described in user guide

**Title:** [FLS] Minimum time from resume to suspend for erase job should be described in user guide

**Description:** For TRAVEO™ T2G, minimum 250 µs must be ensured between an erase/erase resume to erase suspend operation.

This time should be described as the FLS specification in FLS user guide.

In addition, a missing limitation (SWS\_Fls\_00226) should be added in FLS release notes.

---

T2MC-97131 - Different macros are used for setting and checking the value

**Title:** Different macros are used for setting and checking the value

**Description:** Some modules differ in the macro names defined and the macro names used in the processing.

For example, when the macro set to TRUE is judged as STD\_ON, the definition value is 1 for both, but the same macro must be used.

---

## Version history

---

```
#define MACRO_DEFINE (TRUE)
```

```
-
```

```
#if MACRO_DEFINE == STD_ON
```

```
xxx
```

```
#endif
```

In Platform\_Types.h of the base module

```
#define TRUE 1U
```

```
#define FALSE 0U
```

In Std\_Types.h of the base module

```
#define STD_ON 0x01U
```

```
#define STD_OFF 0x00U
```

---

T2MC-97382 - Macro definition at variable declaration is missing and the limitation is not mentioned in release notes

**Title:** Macro definition at variable declaration is missing and the limitation is not mentioned in release notes

**Description:** Macro definitions are not used when declaring some variables and pointers (in FLS, MCU, PORT, SPI, and WDG).

According to AUTOSAR specification:

[SWS\_COMPILER\_00026]

```
#define VAR(vartype, memclass)
```

True:

```
volatile P2VAR(Spi_DmaChannelRegsType, AUTOMATIC, REGSPACE) retPtr;
```

False:

```
volatile Spi_DmaChannelRegsType * retPtr;
```

This issue is present in the following cases:

All types of pointer declaration/definition are defined without macros.

These contain the function parameter/global variable/local variable/structure field/union field.

All types of function declaration/definition are defined without macros.

When there is nested macro usage in function macros.

Raw pointer is used in the function macro:

e.g., FUNC(int \*, memclass) function(void);

Global variable or static variable in the function is not defined with macros.

To fully comply with these cases, change the variable and function definitions in FLS, MCU, PORT, SPI, and WDG.

In requirements, keyword macros 'CONST' and 'VAR' are not required for declaration/definition of the local variable, function parameter, and structure/union fields.

The information must be described in all release notes.

---

T2MC-39519 - Support EB tresos V26.2.0

**Title:** Support EB tresos V26.2.0

**Description:** Support EB tresos V26.2.0

[Impact]

Strict AUTOSAR specification and check for parameter configuration errors are implemented in EB tresos V26.2.0.

---

---

**Version history**

In addition, handling of reference paths (relative paths) such as system description file (ARXML) is changed in EB tresos V26.2.0.

Therefore, if the current ECUC configuration definitions XML file contains deviations or errors, you may find errors during import to EB tresos V26.2.0. In that case, the ECUC configuration definitions XML file must be modified appropriately.

In addition, if the current ARXML file contains unresolvable paths, you may find errors during import to EB tresos V26.2.0. In that case, ARXML file must be modified.

The SW has been tested; no risks except for the low-level risk listed above were found.

---

## **8.10           Module SW-Version 1.12**

---

T2MC-98286 - [FLS] Main flash dual bank register to be free control.

**Title:** [FLS] Main flash dual bank register to be free control.

**Description:** There are some requests regarding register settings and configuration.

- Main flash dual bank (FLASHC\_FLASH\_CTL) register to be free control
- FLASHC\_WORK\_FLASH\_SAFETY register to be free control
- When CCR:UNALIGN\_TRP is set, Fls\_Write can be used with odd source address
- Watchdog clear routine can be removed from FLS
- Fault structure selection

[Impact]

When new configuration parameters are added, if an existing (old) project is applied for this version, you will find some warnings in “Load results” window during import to EB tresos V26.2.0. In that case, click OK button in the window to accept the default values for the new configuration parameters. FLS will be configured as before.

---

## **8.11           Module SW-Version 1.13**

---

T2MC-164778 - Support MISRA C:2012 coding rule

**Title:** Support MISRA C:2012 coding rule

**Description:** Support MISRA C:2012 coding rule.

The MISRA C:2012 coding rule checks the source code.

If a deviation from the rules is required, add the deviation comment to the code and report the result.

If a deviation is for MISRA-C:2004 only, remove the deviation comment.

---

## Version history

---

8.12 Module SW-Version 1.14

---

T2MC-164831 - [ALL] Misleading comment in Module\_MemMap.h

**Title:** [ALL] Misleading comment in Module\_MemMap.h

**Description:** {Mip}\_MemMap.h files are provided as sample template files. But, the file header comment cannot be modified, which is a contradiction. To resolve this contradiction, change the file header comment to allow user modification.

Also, to make sure that the file is not a part of the commercial product, move the {Mip}\_MemMap.h files to the MemMap stub folder.

---

T2MC-159174 - [FLS] C/NC ECC error on 32 bits read from CM7

**Title:** [FLS] C/NC ECC error on 32 bits read from CM7

**Description:** Read access of 32 bits on a Work Flash from CM7 causes C/NC ECC error on the next 32-bit address. Work Flash is always accessed 64-bit-wide when it is read by AXI. Therefore, FLS / FEE may not work properly on CM7; FLS must use DMA transfer to read the data from the work flash memory.

New configuration parameters of FLS are added:

- FlsDmaChannel: Specifies the DMA channel that is used for reading from Work Flash.
- FlsAuxiliaryBufferSize: The size of the auxiliary buffer that stores the data read from Work Flash through DMA transfer at a time, on reading, verifying, or comparing process.

[Impact]

When new configuration parameters are added, if an existing (old) project is applied for this version, you will find some warnings in the “Load results” window during import to EB tresos V26.2.0. In that case, click **OK** in the window to accept the default values for the new configuration parameters. FLS will be configured as before.

---

T2MC-165859 - [FLS] Support of writing with non-blocking mode

**Title:** [FLS] Support of writing with non-blocking mode

**Description:** With FLS, you can select either blocking mode or non-blocking mode for the system call for programming the data to flash memory; a new MCAL FLS configuration parameter is added for the selection.

- FlsUseNonBlockingWrite

[Impact]

When new configuration parameters are added, if an existing (old) project is applied for this version, you will find some warnings in “Load results” window during import to EB tresos V26.2.0. In that case, click **OK** in the window to accept the default values for the new configuration parameters. FLS will be configured as before.

---

T2MC-97198 - [FLS][HSM support] Support of CY HSM library

**Title:** [FLS][HSM support] Support of CY HSM library

**Description:** FLS supports multicore for FEE used by an AUTOSAR application and HSM.

- Multicore support is needed between main application (CM4/CM7) and HSM (CM0+). The two have separate builds

with different instruction sets.

## Version history

- 
- The flash is a shared resource. The concept of channel instances is not applicable.
- 

### 8.13 Module SW-Version 1.15

---

T2MC-169023 - [FLS][HSM support] Issues with read from blank area and register setting

**Title:** [FLS][HSM support] Issues with read from blank area and register setting

**Description:** In HSM support, the following defects are fixed:

- A read job by Fls\_Read API may return data other than all 0xF for blank area.
  - The FLASHC.FLASH\_CMD register is not set correctly by the HSM side.
- 

T2MC-169020 - [FLS] Support for new API that disables timeout monitoring

**Title:** [FLS] Support for new API that disables timeout monitoring

**Description:** FLS supports a selectable specification for enabling or disabling timeout monitoring for asynchronous jobs.

A new MCAL FLS API is added.

- Fls\_SetCycleMode: The parameter is MEMIF\_MODE\_SLOW (enabling) or MEMIF\_MODE\_FAST (disabling).

A new MCAL FLS configuration parameter is added.

- FlsSetCycleModeApi: Specifies whether the Fls\_SetCycleMode is enabled (true) or disabled (false).

[Impact]

When new configuration parameters are added, if an existing (old) project is applied for this version, you will find some warnings in “Load results” window during import to tresos26. In that case, click OK in the window to accept the default values for the new configuration parameters. FLS will be configured as before.

---

T2MC-169021 - [FLS] Specification to select whether to use DMA usage in reading from flash memory

**Title:** [FLS] Specification to select whether to use DMA in reading from flash memory

**Description:** FLS supports a specification that determines whether to use DMA for reading data from flash memory on read/comparison/write(verification) job . A new MCAL FLS configuration parameter is added.

- FlsUseDmaForRead

[Impact]

When new configuration parameters are added, if an existing (old) project is applied for this version, you will find some warnings in “Load results” window during import to tresos26. In that case, click OK in the window to accept the default values for the new configuration parameters. FLS will be configured as before.

---

### 8.14 Module SW-Version 1.16

---

T2MC-170666 - [FLS] Code description improvement

**Title:** T2MC-170666 - [FLS] Code description improvement

**Description:**

1. Modified the two external variables declared in *Fls\_LibInterface.h* so that they are declared between the start and stop symbols of the specified memory section to comply with the AUTOSAR specification.
-

## Version history

---

2. Fixed the incorrect code comment.

- Incorrect: /\* call Fls\_MainFinish() and finish an erase job \*/
  - Correct: /\* call Fls\_MainFinish() and finish a write job \*/
- 

T2MC-170667 - [FLS] [HSM support] Register control improvement

**Title:** T2MC-170667 - [FLS] [HSM support] Register control improvement

**Description:** FLS supports selectable specification to indicate whether FLS sets fault mask register for work flash, and therefore a new MCAL FLS configuration parameter is added.

- FlsSetWorkFlashFaultMaskRegister

If you use HSM together with FLS, you may not want FLS to set the fault mask register for work flash. In that case, set the configuration parameter to FALSE.

The explanation on fault handling for such cases is also added in the user guide.

Moreover, FLS does not enable/disable DMA controller. You can enable using either of the following:

- Using the MCU module (i.e. McuDmaEnable=true)
  - Setting the DMA register (without MCU module)
- 

T2MC-170842 - [FLS] Support of configuration for not reporting to error callout

**Title:** T2MC-170842 - [FLS] Support of configuration for not reporting to error callout

**Description:** FLS supports selectable specification to indicate whether FLS calls error callout functions (i.e. Det\_ReportError function and error callout handler) when a blank check job (started by Fls\_BlankCheck()) detects FLS\_E\_VERIFY\_ERASE\_FAILED error, which means non-blank. Therefore, a new MCAL FLS configuration parameter is added.

- FlsReportErrorIfNotBlank

If you would not like FLS to call the error callout functions, set the configuration parameter to FALSE.

---

T2MC-170789 - [FLS] Some parameters are inconsistent between XDM and ARXML

**Title:** T2MC-170789 - [FLS] Some parameters are inconsistent between XDM and ARXML

**Description:** The default values of the following configuration parameters were mentioned in *Fls.arxml* and not in *Fls.xdm*, and this has been fixed:

- FlsJobEndNotification
  - FlsJobErrorNotification
  - FlsDedErrorNotification
  - FlsSedErrorNotification
- 

T2MC-172524 - [FLS] Modify description in the user guide

**Title:** T2MC-172524 - [FLS] Modify description in the user guide

**Description:** Modify the sections 5.1.12 Suspending a Jobs and 5.1.13 Resuming a Suspended Job of the user guide as follows.

Current description:

Note: This function should not be used for the Flash driver for HSM (Fls\_TS\_T40D13M2I0R0).

---

---

**Version history**

---

Updated description:

Note: This function can be called for Flash drivers for application (Fls\_TS\_T40D13M1I0R0) and HSM (Fls\_TS\_T40D13M2I0R0). However, make sure that arbitration is taken care, for example, make sure that one core does not start an erase job while the other core is suspending the erase operation.

---

The following is supported in release V1.12.0.

---

T2MC-178688 - Addition of the notice for Arm® errata and workaround in the user guide

**Title:** Addition of the notice for Arm® errata and workaround in the user guide

**Description:** Add a notice for Arm® Cortex®-M4 errata 838869 and software workaround in the user guide.

---

## 8.15 Module SW-Version 1.17

---

T2MC-181015 - [FLS] Robustness improvement for SROM status handling

**Title:** T2MC-181015 - [FLS] Robustness improvement for SROM status handling

**Description:** The FLS driver supports all defined results returned from the SROM BlankCheck API. The driver's behavior when undefined results are returned is not consistent. Add the handling for undefined SROM status to make the FLS driver more robust.

---

The following is supported in release V1.15.0.

---

T2MC-183983 - Update copyright notice and disclaimer statement

**Title:** Update copyright notice and disclaimer statement

**Description:** Copyright notice and disclaimer statement in the file header comment are updated to follow the up-to-date specifications.

---

The following is supported in release V1.16.0.

---

T2MC-184093 - [FLS] Inaccurate description for FlsTotalSize

**Title:** [FLS] Inaccurate description for FlsTotalSize

**Description:** It describes that the configuration parameter FlsTotalSize calculates from the configured sector list. However, the sector list configured by the user is not related to the value of FlsTotalSize. Configure this parameter to the available total size of Work Flash on the target device.

---

T2MC-184107 - [FLS] Add a definition of the data buffer to the user guide

**Title:** [FLS] Add a definition of the data buffer to the user guide

**Description:** The data buffer definition used in the user guide is missing and may cause user misunderstanding. It is necessary to clarify the definition in the user guide.

---



## Trademarks

All referenced product or service names and trademarks are the property of their respective owners.

**Edition 2022-09-27**

**Published by**

**Infineon Technologies AG**

**81726 Munich, Germany**

**© 2022 Infineon Technologies AG.**

**All Rights Reserved.**

**Do you have a question about this document?**

**Go to [www.infineon.com/support](http://www.infineon.com/support)**

**Document reference**

**002-23408 Rev. \*R**

## IMPORTANT NOTICE

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffenheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

For further information on the product, technology, delivery terms and conditions and prices please contact your nearest Infineon Technologies office ([www.infineon.com](http://www.infineon.com)).

## WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.