


Chapter 4

Field Oriented Control (FOC) for PMSM

Professor Min-Fu Hsieh

Fall Semester - 2022



https://www.eetimes.com/author.asp?section_id=36&doc_id=1326133&image_number=6




成功大學

National Cheng Kung University²

Modeling and Equivalent Circuit of PMSM

Modelling and Reference Frames of PMSM

3




a-b-c: 3 phase stationary frame

α - β : 2 phase stationary frame

d-q: rotating frame

Rotor position angle θ_e is defined in term of the angle between the magnetic axis of α -axis and d -axis

Assuming a balanced 3-phase system, the equivalent circuit of PMSM



Three-phase voltages of the stator winding in three-phase (a-b-c) reference frame are expressed as the following

$$\begin{bmatrix} V_a \\ V_b \\ V_c \end{bmatrix} = \begin{bmatrix} R_s & 0 & 0 \\ 0 & R_s & 0 \\ 0 & 0 & R_s \end{bmatrix} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} + \frac{d}{dt} \begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix}$$

where i_a, i_b, i_c are 3-phase currents
and R_s is resistance of stator windings

Relationship of three-phase stator flux linkage and three-phase current can be expressed as follows


$$\begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix} = L_s \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} + \Psi_f$$

where Ψ_f is permanent magnet flux linkage
and L_s is stator inductance matrix

The electromotive forces E_a, E_b, E_c can be obtained

$$\begin{bmatrix} E_a \\ E_b \\ E_c \end{bmatrix} = |\Psi_f| \omega_e \begin{bmatrix} \sin \theta_e \\ \sin \left(\theta_e - \frac{2}{3} \pi \right) \\ \sin \left(\theta_e + \frac{2}{3} \pi \right) \end{bmatrix}$$

where ω_e is electrical velocity



L_s is **stator inductance** matrix, as follows

$$L_s = \begin{bmatrix} L_{aa} & L_{ab} & L_{ac} \\ L_{ba} & L_{bb} & L_{bc} \\ L_{ca} & L_{cb} & L_{cc} \end{bmatrix}$$

where L_{aa}, L_{bb}, L_{cc} are the **self-inductances** of three-phase stator winding,
 $L_{ab}, L_{ac}, L_{ba}, L_{bc}, L_{cb}, L_{ca}$ are the **mutual-inductances** of three-phase stator winding

Assuming that the air gap of the motor is **uniform**, relations can be obtained, as follows


$$L_{aa} = L_{bb} = L_{cc} = \underline{L_{ss} + L_{sl}}$$

$$L_{ab} = L_{ac} = L_{ba} = L_{bc} = L_{cb} = L_{ca}$$

where L_{sl} is stator leakage inductance and L_{ss} is the magnetizing inductance.

漏電感

磁化電感



$$\begin{bmatrix} V_a \\ V_b \\ V_c \end{bmatrix} = \begin{bmatrix} R_s & 0 & 0 \\ 0 & R_s & 0 \\ 0 & 0 & R_s \end{bmatrix} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} + \frac{d}{dt} \begin{bmatrix} \Psi_a \\ \Psi_b \\ \Psi_c \end{bmatrix}$$

Clarke Transform

$$\begin{bmatrix} V_\alpha \\ V_\beta \\ V_0 \end{bmatrix} = \begin{bmatrix} \frac{2}{3} & -\frac{1}{3} & -\frac{1}{3} \\ 0 & \frac{1}{\sqrt{3}} & -\frac{1}{\sqrt{3}} \\ \frac{1}{3} & \frac{1}{3} & \frac{1}{3} \end{bmatrix} \begin{bmatrix} V_a \\ V_b \\ V_c \end{bmatrix}$$

Park Transform


$$\begin{bmatrix} V_d \\ V_q \end{bmatrix} = \begin{bmatrix} \cos(\theta_e) & \sin(\theta_e) \\ -\sin(\theta_e) & \cos(\theta_e) \end{bmatrix} \begin{bmatrix} V_\alpha \\ V_\beta \end{bmatrix}$$

$$\begin{cases} V_d = R_s i_d + \frac{d\psi_d}{dt} - \omega_e \psi_q \\ V_q = R_s i_q + \frac{d\psi_q}{dt} + \omega_e \psi_d \end{cases}$$

Equivalent Circuit of PMSM

7

The **dynamic equivalent circuit** of a PMSM based on the d-q frame can be drawn:



After Clark and Park's transformation, **stator voltages in d-q frame** are obtained in the following:

$$v_d = R_s i_d + \frac{d\psi_d}{dt} - \omega_e \psi_q \quad v_q = R_s i_q + \frac{d\psi_q}{dt} + \omega_e \psi_d$$

Assuming that variation of the stator resistance R_s is neglected, **d-q axis flux linkages** is defined as follows:


$$\underline{\Psi_d = L_d i_d + \Psi_f}$$

$$\underline{\Psi_q = L_q i_q} \quad \leftarrow \text{假設 PM 沒有供獻任何磁通給 q 軸}$$

where L_d and L_q are corresponding to d-axis and q-axis inductances

Actual Equivalent Circuit of PMSM

The **actual dynamic equivalent circuit** of a PMSM based on the d-q frame including iron loss resistor R_s



Considering iron losses , **stator voltages in d-q frame** becomes

$$v_d = R_s i_d + \frac{d\psi_d}{dt} - \omega_e \psi_q$$

$$\Psi_q = L_q i_{oq}$$

$$v_q = R_s i_q + \frac{d\psi_q}{dt} + \omega_e \psi_d$$

$$\Psi_d = L_d i_{od} + \Psi_f$$


$$\frac{d\psi_d}{dt} = L_d \frac{di_{od}}{dt}$$

$$\frac{d\psi_q}{dt} = L_q \frac{di_{oq}}{dt}$$

Phasor Diagram of PMSM

9

$I_d < 0$ (flux weakening)




$$\psi_d = L_d i_d + \psi_f$$

$$E_{emf} = \psi_f \omega_e$$

$$|\psi_d| < |\psi_f|$$


$I_d = 0$



$$\psi_d = \psi_f$$

$$E_{emf} = \psi_f \omega_e$$

$I_d > 0$ (flux intensifying)




$$\psi_d = L_d i_d + \psi_f$$

$$E_{emf} = \psi_f \omega_e$$

$$|\psi_d| > |\psi_f|$$

Phasor Diagram of PMSM

10



In the d-q reference frame, electromotive force can be represented as follows:

$$E_d = -\omega_e L_q i_q \quad E_q = \omega_e \psi_d = \omega_e (L_d i_d + \psi_f)$$

Assuming that the motor losses are negligible, the input power equals the output power, power P of motor as:

$$P = \frac{3}{2} (E_d i_d + E_q i_q)$$

Assuming that the motor losses are negligible, the input power equals the output power, power P of motor as:


$$\omega_e = \frac{p}{2} \omega_m \quad \longrightarrow \quad P = \frac{3}{2} \frac{p}{2} \omega_m \left[\psi_f i_q + (L_d - L_q) i_d i_q \right]$$

Motor electromagnetic torque can be obtained as the following equation:


$$T_e = \frac{3}{2} \frac{p}{2} \left[\psi_f i_q + (L_d - L_q) i_d i_q \right] \quad \text{where } p \text{ is number of poles in motor}$$

Torque Characteristic of PMSM

12



Separately Excited DC Motor



$$T_e = K_t \cdot \psi_a \cdot \psi_f = K'_t \cdot i_a \cdot i_f$$

Flux Component


Torque Component

Simplified Motor Flux Diagram

13

$$\psi = N\phi = Li$$

$$L = \frac{\psi}{i}$$



saliency ratio

$$\xi = \frac{L_q}{L_d}$$

inductance big



inductance small

磁鐵導磁率很差


Reluctance Torque

電流不能直接打在 d 或 q 軸上
否則無 reluctance torque

($i_d = 0$ or $i_q = 0$)



$$T_e = \frac{3P}{4} \frac{1}{\omega} \dot{i}_g$$



phase advance \Rightarrow reluctance torque angle

$$i_s = \sqrt{i_d^2 + i_g^2}$$

- 1



The equation for the **motor mechanical dynamics** is shown as follows.

$$T_e = T_L + B_m \omega_r + J_m \frac{d\omega_r}{dt}$$

where T_L is **load torque**, B_m is **damping coefficient**, ω_r is **mechanical rotor speed**

and J_m is **moment of inertia** of the motor.


The equation for the **motor mechanical dynamics** is shown as follows.

$$CPSR = \frac{\omega_r}{\omega_L}$$


$$FW, I_{ch} = \frac{\psi_f}{L_d}$$

$$\psi_d = \psi_f + L_d i_d$$

I_{ch} 特徵電流
加在 d 軸上
FW、



Industry



Electric Vehicle



Control of PMSM

The concept of FOC was first invented in the beginning of 1970s. This method brought forward intensive efforts in investigating high performance control of ac drives because of the fact that an **induction motor** controlled by an **FOC algorithm** can be controlled in a similar manner to the control of a separately **excited dc motor**.

FOC is also known as **vector control**, decoupling control, and orthogonal control. In general, the principle of **FOC schemes implies independent (decoupled) control** of **flux – current (i_d)** and **torque – current (i_q) components** of a stator current through a coordinated change in the supply voltage amplitude, phase angle and frequency.

- In the real case, the current and voltage are subject to real constraints:

Current limit equation: $\underline{i_d^2 + i_q^2 = i_s^2 \leq i_{max}^2} \rightarrow \text{a continuous circle form}$

Voltage limit equation: $v_d^2 + v_q^2 = v_s^2 \leq v_{max}^2 \rightarrow \text{difference of SPM and IPM}$

- Assume that motor runs at high speed mode (and sufficiently high), so **the phase resistance R_s is neglected** because its voltage drop is much smaller than X_L , we have voltage on d-q axis as:

$$v_d = \omega_e L_q i_q$$

$$v_q = \omega_e L_d i_d + \omega_e \psi_f$$

$$\Rightarrow \frac{\left(i_d + \frac{\psi_f}{L_d}\right)^2}{\left(\frac{V_s}{\omega_e L_d}\right)^2} + \frac{(i_q)^2}{\left(\frac{V_s}{\omega_e L_q}\right)^2} = 1 \quad (A)$$

$$V_{dL} = V_R + V_L + E$$

↑

高速下可略

$$Z = R + jX$$

↓
 $\omega_e L$

$\omega_e L \gg R$

→ Taking into account (A) in case of SPM and IPM


Current limit and Voltage limit

SPM: $L_d = L_q = L_s$

Circle equation

$$\frac{(i_d + \frac{\psi_f}{L_s})^2}{(\frac{V_s}{\omega_e L_s})^2} + \frac{(i_q)^2}{(\frac{V_s}{\omega_e L_s})^2} = 1$$

V_s is under circles




IPM: $L_d < L_q$

Ellipse equation

$$\frac{\left(i_d + \frac{\psi_f}{L_d}\right)^2}{\left(\frac{V_s}{\omega_e L_d}\right)^2} + \frac{(i_q)^2}{\left(\frac{V_s}{\omega_e L_q}\right)^2} = 1$$

V_s is under ellipses



The operable region of the motor drive system

motor
↑
generator

i_d
 i_q

Direct Field Oriented Control is a basic control method which can be easily applied either in IPM or SPM. The direct axis(d-axis) current is controlled to zero to make sure no field intensify or weakening effect while q-axis current is controlled according to torque demand similar to DC motor.

Advantage : Output torque is ^{easily controlled} ~~easy to control~~ due to the linear relationship to q-axis current.


★ Drawback : Reluctance torque cannot be produced.

SPM no reluctance torque

IPM 用此控制有些浪费

Direct FOC has no field intensify or weakening effect($i_d = 0$), Magnetomotive force (MMF) is only established by permanent magnets mounted on rotor.


$I_d < 0$ (demagnetizing)



$$\psi_d = -L_d i_d + \psi_f$$

$$E = \psi_f \omega_e$$


$I_d = 0$



$$\psi_d = \psi_f$$

$$E = \psi_f \omega_e$$

$I_d > 0$ (magnetizing)



$$\psi_d = L_d i_d + \psi_f$$

$$E = \psi_f \omega_e$$

IPM

相位落後

磁阻轉矩為負


$$T_e = \frac{3}{4} P [\psi_f i_q + (L_d - L_q) i_d i_q]$$

(-) (+)

use in SynRM

FI-IPM

Torque expression for PM motors for direct FOC .



phase advance angle start from φ

With **current angle $\beta = 90^\circ$** , we have:

$$i_s = i_d + j i_q$$

$$i_d = i_s \sin(90^\circ - \beta) = i_s \cos \beta = 0$$

$$i_q = i_s \cos(90^\circ - \beta) = i_s \sin \beta = i_s$$

For SPM, no saliency ($L_d = L_q$)
 \rightarrow reluctance torque is zero

Magnet torque (due to PM)

$$T_{e_SPM} = \frac{3}{2} \frac{P}{2} \psi_f i_q$$

No reluctance torque is produced in direct FOC

For IPM, ($L_d < L_q$)

Magnet torque (due to PM)

$$T_{e_IPM} = \frac{3}{2} \frac{P}{2} \left[\underbrace{\psi_f i_q}_{\text{Magnet torque}} + \underbrace{(L_d - L_q) i_d i_q}_{\text{Reluctance torque}} \right] = \frac{3}{2} \frac{P}{2} (\psi_f i_q)$$

Reluctance torque


$$i_d = 0$$

$$T_{e_IPM} = T_{e_SPM} = \frac{3}{2} \frac{p}{2} (\psi_f i_s \sin \beta) = T_{\text{magnet}}$$


Either IPM or SPM, only magnet torque can be produced in Direct FOC.

To find the maximum torque, $\frac{\partial T_e}{\partial \beta} = \frac{3}{2} \frac{p}{2} (\psi_f i_s \cos \beta) = 0$


Maximum torque can only be obtained when β equal to 90°




The operating region of Direct FOC is a simple straight line. Without the effect of i_d , output torque $T_e = \frac{3p}{2} \psi_f i_q$ can be easily controlled by i_q due to the linear relation.



Control block diagram for Direct FOC






Specification	Value
Rated Torque T_{rated} (N.m)	11.78
Max. Torque T_{max} (N.m)	29.4
Rated Voltage V_{rated} (V_{pk})	220
Rated Current I_{rated} (A_{rms})	18.5
Max. Current I_{max} (A_{rms})	45
Rated Speed N_{rated} (RPM)	3000
Rated Power P_{rated} (kW)	3.7
Pole	8
Torque Constant K_T ($N \cdot m / A_{pk}$, FOC $i_d = 0$)	0.48
Voltage Constant K_e ($V_{pk} \cdot s / rad$)	0.08
Inertia J_m ($kg \cdot m^2$)	0.00633
resolution	128
Parameter	Value
D Axis Inductance L_d (mH)	0.76
Q Axis Inductance L_q (mH)	1.61
Resistance of Stator Windings R_s (mΩ)	141.6
Flux Linkage λ_m (mWb)	80

Direct FOC simulation result

Test condition:

Accelerating to 2000rpm unloaded and then loading 10Nm at 0.2s





Direct FOC Simulation Result

29

Test condition : Speed up to 2000rpm with unload from 0 to 0.2 sec
Adding 10Nm load at t=0.2s

i_q dominates the torque output , so when accelerating or loading , i_q rises significantly for high torque demand.

Torque(Nm)	i_q (A)
21.6	45
19.2	40
16.8	35
14.4	30
12	25
9.6	20
7.2	15
4.8	10
2.4	5
0	0




i_q current feedback (red line)
 i_q current reference (blue line)




Controller Design of FOC

Control Architecture of FOC for PMSM


31



- The I_d reference controls **rotor magnetizing flux**, I_q reference controls the **torque** output of the motor
- I_d and I_q are only time-invariant under steady-state load conditions



(a)



(b)

The equivalent circuit of PMSM
under the d-q axis
(a) d axis (b) q axis

Voltage equation

$$\begin{cases} V_d = R_s i_d + \frac{d}{dt} \psi_d - \omega_e \psi_q \\ V_q = R_s i_q + \frac{d}{dt} \psi_q + \omega_e \psi_d \end{cases} \quad (1)$$

$$\begin{cases} \psi_d = L_d i_d + \psi_f \\ \psi_q = L_q i_q \end{cases} \quad (2)$$

Electromagnetic torque equation

$$T_e = \frac{3}{2} \frac{p}{2} (\psi_d i_q - \psi_q i_d) = \frac{3}{2} \frac{p}{2} [\lambda_m i_q + (L_d - L_q) i_d i_q] \quad (3)$$

(p=number of pole)

Dynamic equation

$$T_e - T_L = J_m \frac{d\omega_m}{dt} + B_m \omega_m \quad (4)$$

(T_L : Load Torque , B_m : Friction Torque , J_m : Inertia Torque ,
 $\omega_e = \omega_m * p/2$)

t-domain

According to voltage equations (1) & (2)


$$\begin{cases} \frac{di_d}{dt} = \frac{-R_s}{L_d} i_d + \frac{1}{L_d} V_d + \frac{\omega_e L_q}{L_d} i_q \\ \frac{di_q}{dt} = \frac{-R_s}{L_q} i_q + \frac{1}{L_q} V_q - \frac{\omega_e L_d}{L_q} i_d - \frac{\omega_e \psi_f}{L_q} \end{cases} \quad (5)$$

s-domain


Laplace Transform (5)

$$\begin{cases} si_d(s) = \frac{-R_s}{L_d} i_d(s) + \frac{1}{L_d} V_d(s) + \frac{\omega_e(s) L_q}{L_d} i_q(s) \\ si_q(s) = \frac{-R_s}{L_q} i_q(s) + \frac{1}{L_q} V_q(s) - \frac{\omega_e(s) L_d}{L_q} i_d(s) - \frac{\omega_e(s) \psi_f}{L_q} \end{cases} \quad (6)$$

Yields:



PMSM d-axis current




PMSM q-axis current


According to torque and dynamic equation (3) & (4)

$$\begin{cases} T_e(s) = \frac{3}{4}p[\psi_f i_q(s) + (L_d - L_q)i_d(s)i_q(s)] \\ T_e(s) - T_L(s) = sJ_m\omega_m(s) + B_m\omega_m(s) \end{cases} \quad (7)$$


Yields:



PMSM Speed diagram




PMSM Dynamic Model



PMSM Dynamic Model including speed and current controllers


PI controller - D-axis current loop PI

37




PI controller - Q-axis current loop PI

38



Design PI controller- Q-axis speed loop PI

39



Design PI controller - D-axis current loop PI

From above PI introduction, we can set transfer function $G_d(s)$:

$$G_d(s) = k_{pd} + \frac{k_{id}}{s} \quad k_{pd} \text{ is Proportional constant, } k_{id} \text{ is intergral constant}$$

Transfer function of d-axis current closed loop is :

$$\frac{i_d(s)}{i_d^*(s)} = \frac{(k_{pd} + \frac{k_{id}}{s}) \cdot \frac{1}{sL_d + R_s}}{1 + (k_{pd} + \frac{k_{id}}{s}) \cdot \frac{1}{sL_d + R_s}} \quad \text{Using zero pole canceling, we set } \frac{k_{pd}}{k_{id}} = \frac{L_d}{R_s}$$

Then we can get

$$\frac{i_d(s)}{i_d^*(s)} = \frac{1}{\frac{R_s}{k_{id}}s + 1} = \frac{1}{\frac{1}{2\pi f_{BWd}}s + 1}$$

Generally, the bandwidth f_{BWd} is equal to 0.1^*f_{sw} (switching frequency)

As a result,

$$k_{pd} = 2\pi f_{BWd} L_d$$

$$k_{id} = 2\pi f_{BWd} R_s$$

Design PI controller - Q-axis current loop PI

From above PI introduction, we can set transfer function $G_q(s)$:

$$G_q(s) = k_{pq} + \frac{k_{iq}}{s} \quad k_{pq} \text{ is Proportional constant, } k_{iq} \text{ is intergral constant}$$

Transfer function of q-axis current closed loop is :

$$\frac{i_q(s)}{i_q^*(s)} = \frac{(k_{pq} + \frac{k_{iq}}{s}) \cdot \frac{1}{sL_q + R_s}}{1 + (k_{pq} + \frac{k_{iq}}{s}) \cdot \frac{1}{sL_q + R_s}}$$

Using zero pole canceling, we set $\frac{k_{pq}}{k_{iq}} = \frac{L_q}{R_s}$

Then we can get

$$\frac{i_q(s)}{i_q^*(s)} = \frac{1}{\frac{R_s}{k_{iq}}s + 1} = \frac{1}{\frac{1}{2\pi f_{BWq}}s + 1}$$

Generally, the bandwidth f_{BWd} is equal to $0.1 * f_{sw}$ (switching frequency)

As a result,

$$k_{pq} = 2\pi f_{BWq} L_q$$

$$k_{iq} = 2\pi f_{BWq} R_s$$

Design PI controller speed loop PI

From above PI introduction, we can set transfer function $G_m(s)$:

$$G_m(s) = k_{pm} + \frac{k_{im}}{s} \quad k_{pm} \text{ is Proportional constant, } k_{im} \text{ is intergral constant}$$

Transfer function of speed closed loop is :

$$\frac{\omega_m(s)}{\omega_m^*(s)} = \frac{(k_{pm} + \frac{k_{im}}{s}) \cdot \frac{1}{sJ_m + B_m} \cdot k_t}{1 + (k_{pm} + \frac{k_{im}}{s}) \cdot \frac{1}{sJ_m + B_m} \cdot k_t} \quad \text{Using zero pole canceling, we set } \frac{k_{pm}}{k_{im}} = \frac{J_m}{B_m}$$

Then we can get

$$\frac{\omega_m(s)}{\omega_m^*(s)} = \frac{1}{\frac{B_m}{k_{im}k_t}s + 1} = \frac{1}{\frac{1}{2\pi f_{BWm}}s + 1} \quad \text{Generally, the bandwidth } f_{BWd} \text{ is equal to } 0.01 \cdot f_{sw} \text{ (switching frequency)}$$

As a result,

$$k_{pm} = \frac{2\pi f_{BWm} J_m}{k_t} \quad k_{im} = \frac{2\pi f_{BWm} B_m}{k_t}$$