



# PIC24F16KM204 FAMILY

## PIC24F16KM204 Family Silicon Errata and Data Sheet Clarification

The PIC24F16KM204 family devices that you have received conform functionally to the current Device Data Sheet (DS30003030B), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC24F16KM204 family silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A0).

Data Sheet clarifications and corrections start on [Page 5](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
  - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24F16KM204 family silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>	Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>
		A0			A0
PIC24FV16KM204	551Fh	0000h	PIC24F16KM204	551Eh	0000h
PIC24FV08KM204	5517h		PIC24F08KM204	5516h	
PIC24FV16KM104	550Fh		PIC24F16KM104	550Eh	
PIC24FV16KM202	551Bh		PIC24F16KM202	551Ah	
PIC24FV08KM202	5513h		PIC24F08KM202	5512h	
PIC24FV16KM102	550Bh		PIC24F16KM102	550Ah	
PIC24FV08KM102	5503h		PIC24F08KM102	5502h	
PIC24FV08KM101	5501h		PIC24F08KM101	5500h	

**Note 1:** The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

**2:** Refer to the "PIC24FXXKMXXX/KLXXX Flash Programming Specification" (DS30625) for detailed information on Device and Revision IDs for your specific device.

# PIC24F16KM204 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>
				A0
A/D	—	1.	Excessive current consumption under certain conditions.	X
A/D	—	2.	Device Reset when sampling upper guardband input.	X
MCCP and SCCP	Triggered Operation	3.	TRSET bit does not function in retrigger operations.	X
MCCP and SCCP	Compare Mode	4.	Extra compare event in One-Shot mode under certain conditions.	X
MCCP and SCCP	Compare Mode	5.	Output compare synchronization does not occur correctly for the first event.	X
MCCP and SCCP	Compare Mode	6.	Special Event Trigger postscaler does not work.	X
MCCP and SCCP	—	7.	Unexpected 32-bit timer rollover under certain conditions.	X
Op Amp	—	8.	Op amp output and digital output drivers may cause bus conflict.	X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

# PIC24F16KM204 FAMILY

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A0).

### 1. Module: A/D Converter

When low-power operation is enabled (LPEN bit is set), the module may still consume high current (approximately 90  $\mu$ A) when the device is in Sleep mode and after the conversion is completed.

#### Work around

After conversions in Sleep mode are complete, wake the device and disable the module.

#### Affected Silicon Revisions

A0							
X							

### 2. Module: A/D Converter

Sampling and converting the upper VDD guard-band rail input (AD1CHS<12:8> = 11100) may cause a device Reset. This can occur without regard to any other operating conditions.

#### Work around

Do not use the upper guardband input.

#### Affected Silicon Revisions

A0							
X							

### 3. Module: MCCP and SCCP

In retrigger operation, setting the TRSET bit (CCPxSTATL<6>) may not properly cause a retrigger event. All other available trigger sources will cause a retrigger event as described.

#### Work around

If the TRSET bit must be used for retrigger operation, set the TRCLR bit (CCPxSTATL<5>) prior to setting the TRSET bit.

#### Affected Silicon Revisions

A0							
X							

### 4. Module: MCCP and SCCP

In One-Shot Output Compare mode, an additional compare event may occur, causing an extra toggling of the OCx pin and an additional interrupt event. This occurs whenever the value of CCPxRA is 0000h, and after the trigger has been cleared and the CCPxTMR is reset.

#### Work around

A non-zero value of CCPxRA (e.g., 0001h) prevents the additional compare event.

#### Affected Silicon Revisions

A0							
X							

### 5. Module: MCCP and SCCP

Output compare synchronization of the OCx pin to the module's selected time base (enabled when OENSYNC (CCPxCON2H<15>) = 1) may prevent output on the pin on the first time base period after enabling the module. After the first period, OCx pin events will appear correctly.

#### Work around

None.

#### Affected Silicon Revisions

A0							
X							

### 6. Module: MCCP and SCCP

When the Special Event Trigger output is selected (CCPxCON1H = 1), the interrupt post-scaler setting, selected by CCPxCON1H<11:8>, has no effect. A Special Event Trigger will output on each compare match event.

#### Work around

None.

#### Affected Silicon Revisions

A0							
X							

# PIC24F16KM204 FAMILY

## 7. Module: M CCP and S CCP

The M CCP module may rollover at an incorrect time when all of the following conditions are met:

- The module is configured in 32-bit operation (T32 (CCPxCON1L<5>) = 1)
- The CCPxTMRH and CCPxPRH registers are initialized with the same value;
- The CCPxTMRL register is initialized with a value higher than CCPxPRL
- The module is configured for a timer match with no external synchronization source (SYNC<4:0> (CCPxCON1H<4:0>) = 00000)

With the module configured this way, the M CCP module will clear the CCPxTMRH/L register pair and generate a timer rollover interrupt when CCPxTMRL rolls over from FFFFh to 0000h, regardless of the value of CCPxTMRH. The expected behavior would be to roll over only after reaching the expected timer rollover value of FFFFFFFFh.

For example, if the module is initialized with the following settings:

- CCPxTMRH = CCPxPRH = 1000h
- CCPxPRL = 0000h
- CCPxTMRL = 0001h

When the module is enabled, it will run until CCPxTMR = 1000FFFFh, then roll over to zero and generate an M CCP timer rollover interrupt.

### Work around

None.

### Affected Silicon Revisions

A0							
X							

## 8. Module: Op Amp

When op amp modules are enabled, a bus conflict between the module's analog driver and the digital I/O driver may result, causing an unexpected voltage level and high-current consumption.

This is only seen when the TRISx bit associated with the OAxOUT pin is cleared. This results in the digital output driver being enabled and conflicting with the op amp's analog output driver.

### Work around

When using an op amp module, ensure that the TRISx bit associated with the OAxOUT pin is set as an input (TRISx = 1) to disable the digital output driver.

### Affected Silicon Revisions

A0							
X							

# PIC24F16KM204 FAMILY

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS30003030B):

**Note:** Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

### 1. Module: Memory Organization

In Table 4-25 and on Registers 19-6, 19-8 and 19-10, the AD1CHITH, AD1CSSH and AD1CTMENH registers, respectively, incorrectly note that bits 3 and 4 are not implemented on 20-pin devices. These bits are implemented on 20-pin parts and instead, this note should apply to bits 1 and 2.

### 2. Module: Electrical Characteristics

Table 27-17, Operational Amplifier Specifications, has had the Input Offset Voltage Max value and Common-Mode Input Voltage Range Max value updated, as shown below in **bold**.

**TABLE 27-17: OPERATIONAL AMPLIFIER SPECIFICATIONS**

DC CHARACTERISTICS			Standard Operating Conditions: 1.8V to 3.6V (PIC24F16KM204) 2.0V to 5.5V (PIC24FV16KM204) Operating temperature -40°C ≤ TA ≤ +85°C for Industrial -40°C ≤ TA ≤ +125°C for Extended				
Param No.	Sym	Characteristic	Min	Typ <sup>(1)</sup>	Max	Units	Comments
	VIOFF	Input Offset Voltage	—	±2	<b>±50</b>	mV	
	VICM	Common-Mode Input Voltage Range	AVSS	—	<b>AVDD – 850</b>	<b>mV</b>	

Note 1: Data in “Typ” column is at 3.3V, +25°C unless otherwise stated.

### 3. Module: 12-Bit A/D Converter with Threshold Detect

The Note 2 references in Register 19-6: AD1CHITH moved from CHH19 and CHH20 to CHH17 and CHH18. The Table Footnote 2 now reads “The CHH<18:17> bits are not implemented in 20-pin devices.”

The Note 2 references in Register 19-8: AD1CSSH moved from CSS19 and CSS20 to CSS17 and CSS18. The Table Footnote 2 now reads “The CSS<18:17> bits are not implemented in 20-pin devices.”

The Note 2 reference in Register 19-10: AD1CTMENH moved from CTMEN19 and CTMEN20 to CTMEN17 and CTMEN18. The Table Footnote 2 now reads “The CTMEN<18:17> bits are not implemented in 20-pin devices.”

### 4. Module: Timer1

The first sentence in the Timer1 introduction has changed to the following:

The Timer1 module is a 16-bit timer which operates as a free-running, interval timer/counter.

# PIC24F16KM204 FAMILY

---

## APPENDIX A: DOCUMENT REVISION HISTORY

### Rev A Document (2/2013)

Initial release of this document; issued for Revision A0. Includes silicon issues 1-2 (A/D Converter) and 3-6 (MCCP and SCCP).

### Rev B Document (9/2013)

Adds silicon issues 7 (MCCP and SCCP) and 8 (Op Amp) to Silicon Revision A0.

Adds data sheet clarification 1 (Memory Organization).

### Rev C Document (3/2014)

Adds data sheet clarifications 2 (Electrical Characteristics), 3 (12-Bit A/D Converter with Threshold Detect) and 4 (Timer1).

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.


Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rLAB, Select Mode, SQL, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2013-2014, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-62077-962-0

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC<sup>®</sup> MCUs and dsPIC<sup>®</sup> DSCs, KEELOQ<sup>®</sup> code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110

**Canada - Toronto**  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hangzhou**  
Tel: 86-571-2819-3187  
Fax: 86-571-2819-3189

**China - Hong Kong SAR**  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8864-2200  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-3019-1500

**Japan - Osaka**  
Tel: 81-6-6152-7160  
Fax: 81-6-6152-9310

**Japan - Tokyo**  
Tel: 81-3-6880-3770  
Fax: 81-3-6880-3771

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-5778-366  
Fax: 886-3-5770-955

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Dusseldorf**  
Tel: 49-2129-3766400

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Pforzheim**  
Tel: 49-7231-424750

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Venice**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Poland - Warsaw**  
Tel: 48-22-3325737

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820

10/28/13