



## Accuracy, precision & resolution

Last Modification: December 18, 2017

Quantities can't be determined with absolute certainty. Measurement tools and systems have always some tolerance and disturbances that will introduce a degree of uncertainty. In addition, also the distinctiveness is a limiting factor.

The following terminology are often used in relation to the measurement uncertainty:

- **Accuracy:** The error between the real and measured value.
- **Precision:** The random spread of measured values around the average measured values.
- **Resolution:** The smallest to be distinguished magnitude from the measured value.

In practice these terms are often confused. This article discusses these concepts.

### Measurement uncertainty

Measurement uncertainties can be divided into systematic and random measurement errors. The systematic errors are caused by abnormalities in gain and zero settings of the measuring equipment and tools. The random errors caused by noise and induced voltages and/or currents.

### Definition accuracy and precision

Often the concepts accuracy and precision are used interchangeably; they are regarded as synonymous. These two terms, however, have an entirely different meaning. The accuracy indicates how close the measured value is from its actual value, i.e. the deviation between the measured and actual values. Precision refers to the random spread of the measured values.

When a number of measurements is done to a stable voltage or other parameter, the measured values will show a certain variation. This is caused by thermal noise in the measuring circuit of the measuring equipment and the measurement set-up. The left graph in Figure 1 shows these variations.

### Histogram

The measured values can be plotted in a histogram as shown in Figure 1. The histogram shows how often a measured value occurs. The highest point of the histogram, this is the measured value that has been most frequently measured, indicates the mean value. This is indicated by the blue line in both graphs. The black line represents the real value of the parameter. The difference between the average measured value and real value is the accuracy. The width of the histogram indicates the spread of individual measurements. This distribution of measurements is called accuracy.

### Use the correct definition

Accuracy and precision thus have a different meaning. It is therefore quite possible that a measurement is very precise but not accurate. Or conversely, a very accurate measurement, but not precise. In general, a measurement is considered valid if both the measurement is precise as well accurate.

### Accuracy

Accuracy is an indication of the correctness of a measurement. Because at a single measurement the precision affects also the accuracy, an average of a series of measurements will be taken.

The uncertainty of measuring instruments is usually given by two values: uncertainty of reading and uncertainty over the full scale. These two specifications together determine the total measurement uncertainty.

These values for the measurement uncertainty is specified in percent or in ppm (parts per million) relative to the current national standard. 1 % corresponds to 10000 ppm.

The specified uncertainty is quoted for specified temperature ranges and for certain time period after calibration. Please also note that at different ranges other uncertainties may apply.

### Uncertainty relative to reading

An indication of a percentage deviation without further specification also refers to the reading. Tolerances of voltage dividers, the exact gain and absolute deviation of the readout and digitization cause this inaccuracy.

A voltmeter which reads 70,00 V and has a "±5 % reading" specification, will have an uncertainty of 3,5 V (5 % of 70 V) above and below. The actual voltage will be between 66,5 en 73,5 volt.

### In this article:

- » [Measurement uncertainty](#)
- » [Accuracy](#)
- » [Cumulative uncertainty](#)
- » [Precision](#)
- » [Resolution](#)

[Deze pagina in het Nederlands](#)

### Highlights

#### Build your own wattmeter



[Learn how wattmeters work by building your own with an Arduino.](#)




Fig. 1: Definitions uncertainties. On the left a series of measurements. On the right the values are plotted in a histogram.

Squarespace  
Website  
Builder

Make an  
you  
professio  
with Squ  
all-in-one

#### Measuring with an Arduino

[Learn more about the usage and properties of the Arduino analog to digital converter.](#)

#### Fast Lux meter

[A DIY lux meter for measuring light intensity with a bandwidth from DC to 350 kHz.](#)




Fig. 2: Uncertainty of 5 % reading and a read value of 70 V.




Fig. 3: Uncertainty of 3 % full scale in the 100 V range.

### Uncertainty relative to full scale

This type of inaccuracy is caused by offset errors and linearity errors of amplifiers. And with instruments that digitizes signals, by the non-linearity of the conversion and the uncertainty in AD converters. This specification refers to the full-scale range that is used.

A voltmeter may have a specification "3 % full scale". If during a measurement the 100 V range is selected (= full scale), then the uncertainty is 3 % of 100 V = 3 V regardless of the voltage measured.

If the readout in this range 70 V, then the real voltage is between 67 and 73 volts.

Figure 3 makes clear that this type of tolerance is independent of the reading. Would a value of 0 V being read; in this case would the voltage in reality between -3 and +3 volts.

### Full scale uncertainty in digits

Often give digital multimeters the full-scale uncertainty in digits instead of a percentage value.

A digital multimeter with a 3½ digit display (range -1999 t / m 1999), the specification can read "+ 2 digits". This means that the uncertainty of the display is 2 units. For example: if a 20 volt range is chosen (± 19.99), then the full scale uncertainty is ±0.02 V. The display shows a value of 10.00 then the actual value shall be between 9.98 and 10.02 volts.




Fig. 4: Total uncertainty of 5 % reading and 3 % full-scale on a 100 V range and a reading of 70 V.

### Calculation of measurement uncertainty

The specification of the tolerance of the reading and the full scale together determine the total measurement uncertainty of an instrument. In the following calculation example the same values are used as in the examples above:

Accuracy: ±5 % reading (3 % full scale)  
Range: 100 V, Reading: 70 V

The total measurement uncertainty is now calculated as follows:

$$\begin{aligned} \frac{\% \text{reading}}{100 \%} \cdot \text{reading} &= \frac{5 \%}{100 \%} \cdot 70 \text{ V} = 3.5 \text{ V} \\ \frac{\% \text{fullscale}}{100 \%} \cdot \text{range} &= \frac{3 \%}{100 \%} \cdot 100 \text{ V} = 3.0 \text{ V} \\ &+ 7.5 \text{ V} \end{aligned} \quad [\text{equ. 1}]$$

In this situation, a total uncertainty of 7.5 V up and down. The real value should be between 62.5 and 77.5 volts. Figure 4 shows this graphically.

The percentage uncertainty is the relationship between reading and uncertainty. In the given situation this is:

$$\frac{\text{uncertainty}}{\text{reading}} \cdot 100 \% = \frac{7.5 \text{ V}}{70 \text{ V}} \cdot 100 \% = 10.7 \% \quad [\text{equ. 2}]$$

### Digits

A digital multimeters can hold a specification of "±2.0 % rdg, + 4 digits. This means that 4 digits have to be added to the reading uncertainty of 2 %. As an example again a 3½ digit digital readout. This will read 5.00 V in while the 20 V range is selected. 2 % of the reading would mean an uncertainty of 0.1 V. Add to this the inaccuracy of the digits (= 0.04 V). The total

### Multimeters

The assumption that multimeters always measure the correct value isn't so obvious as we wish. See here what the issues are

TOP



uncertainty is therefore 0.14 V. The real value should be between 4.86 and 5.14 volts.

### Cumulative uncertainty

Often only the uncertainty of the measuring instrument is taken into account. But also must be looked after the additional measurement uncertainty of the measurement accessories if these are used. Here are a couple of examples:

#### Increased uncertainty when using probe 1:10

When a 1:10 is used, not only the measurement uncertainty of the instrument must take into account. Also the input impedance of the used instrument and the resistance of the probe, who make together a voltage divider, shall influence the uncertainty.




Fig. 5: A 1:1 probe attached to an oscilloscope.

Figure 5 shows schematically an oscilloscope with a 1:1 probe. If we consider this probe as ideal (no series resistance), the voltage applied to the probe is offered directly at the input of the oscilloscope. The measurement uncertainty is now only determined by the tolerances in the attenuator, amplifier and further processing, and is specified by the manufacturer.

(The uncertainty is also influenced by the resistance network that forms the internal resistance  $R_i$ . This is included in the

specified tolerances.)




Fig. 6: A 1:10 probe connected to an oscilloscope introduces an additional uncertainty.

Figure 6 shows the same scope, but now a 1:10 probe is connected to the input. This probe has an internal series resistance  $R_p$  and together with the input resistance of the oscilloscope  $R_i$  will form a voltage divider. The tolerance of the resistors in the voltage divider will cause its own uncertainty.

The tolerance of the input resistance of the oscilloscope can be found into the specifications. The tolerance of the series resistance  $R_p$  of the probe is not always given. However, the system uncertainty stated by the combination of the

oscilloscope probe with a specified type oscilloscope will be known. If the probe is used with another type than the prescribed oscilloscope, the measurement uncertainty is undetermined. This must always be avoided.

#### Summation in quadrature

To get the resulting measurement uncertainty, all the relevant tolerances must be summed in quadrature. In the following example an oscilloscope has a tolerance of 1.5 % and a 1:10 probe is used with a system uncertainty of 2.5 %. These two specifications must be summation in quadrature to obtain total reading uncertainty:

$$\%total = \sqrt{\%reading^2 + \%system^2} = \sqrt{1.5^2 + 2.5^2} = 2.915\% \quad [\text{equ. 3}]$$

#### Measuring with a shunt resistor




Fig. 7: Increases of uncertainty when using a shunt resistor.

To measure currents an external shunt resistor is sometimes used. The shunt has a certain tolerance that affects the measurement.

The specified tolerance of the shunt resistor refers to the reading uncertainty. To find the total uncertainty, the tolerance of the shunt and the reading uncertainty of the measuring instrument are added in quadrature:

$$\%total = \sqrt{\%reading^2 + \%shunt^2} = \sqrt{1.5^2 + 2^2} = 2.5\% \quad [\text{equ. 4}]$$

In this example, the total reading uncertainty is 2.5 %.

The resistance of the shunt is temperature dependent. The resistance value is specified for a given temperature. The temperature dependence is often expressed in ppm/°C.

As an example the calculating of the resistance value at ambient temperature ( $T_{amb}$ ) of 30 °C. The shunt has a specification:  $R=100 \Omega$  @ 22 °C (respectively  $R_{nom}$  &  $T_{nom}$ ), and a temperature dependence of 20 ppm/°C.

$$\left[ 1 + (T_{amb} - T_{nom}) \cdot \frac{\text{ppm}}{1000000} \right] \cdot R_{nom} =$$

$$\left[ 1 + (30^\circ\text{C} - 22^\circ\text{C}) \cdot \frac{20}{1000000} \right] \cdot 100 \Omega = 100.016 \Omega \quad [\text{equ. 5}]$$

The current flowing through the shunt causes dissipation of energy in the shunt and this will result in rising of the temperature and therefore a change in resistance value. The change in resistance value due to the current flow is dependent on several factors. For very accurate measurements the shunt must be calibrated at a flow resistance and environmental conditions in which these will be used.

### Precision

The term precision is used to express the random measurement error. The random nature of the deviations of the measured value is mostly of thermal origin. Because of the arbitrary nature of this noise it's not possible to give an absolute error. The

TOP



precision gives only the probability that the measurement value is between given limits.

Gaussian distribution

Thermal noise has a Gaussian or normal distribution. This is described by the following equation:

$$f(x) := \frac{1}{\sigma \cdot \sqrt{2 \cdot \pi}} \cdot \exp \left[ \frac{-(x - \mu)^2}{2 \cdot \sigma^2} \right]$$

[equ. 6]

Here is  $\mu$  the mean value and  $\sigma$  indicates the degree of dispersion and corresponds to the RMS value of the noise signal. The function provides a probability distribution curve as shown in Figure 8 where the mean value  $\mu$  2 is and the effective noise amplitude  $\sigma$  1.




Fig. 8: Probability distribution for  $\mu=2$  en  $\sigma=1$ .

Tabel 1:  
Probability Values

Border	Chance
0,5 · σ	38.3 %
0,674 · σ	50.0 %
1 · σ	68.3 %
2 · σ	95.4 %
3 · σ	99.7 %

Probability table

Table 1 lists some chance values expressed at a certain limit. As seen, the probability that a measured value is within  $\pm 3 \cdot \sigma$  is 99.7 %.

Improving precision

The precision of a measurement can be improved by oversampling or filtering. The individual measurements are averaged out so that the noise quantity is greatly reduced. The spread of the measured values is hereby also reduced. With oversampling or filtering must be taken into account that this may reduce the bandwidth.

Resolution

The resolution of a measurement system is the smallest yet to distinguish different in values. The specified resolution of an instrument has no relation to the accuracy of measurement.

Digital measuring systems

A digital system converts an analog signal to a digital equivalent with an AD converter. The difference between two values, the resolution, is therefore always equal to one bit. Or in the case of a digital multimeter, this is 1 digit.

It's also possible to express the resolution in other units than bits. As an example a digital oscilloscope which has an 8 bit AD converter. If the vertical sensitivity is set to 100 mV/div and the number of divisions is 8, the total range will be 800 mV. The 8 bits represent  $2^8 = 256$  different values. The resolution in volts is then  $800 \text{ mV} / 256 = 3125 \text{ mV}$ .

Analog measuring systems

In the case of analog measuring instruments where the measured value is displayed in a mechanical way, such as a moving-coil meter, it's difficult to give an exact number for the resolution. Firstly, the resolution is limited by the mechanical hysteresis caused by friction of the bearings of the needle. On the other hand, resolution is determined by the observer, making this a subjective evaluation.

Con SCEGLI TU SPECIAL 3 di Enel Energia  
hai un'offerta 100% rinnovabile e per i primi  
TRE MESI la componente energia è GRATIS.

10 from 13 comments loaded.

↓↓ Click here to load older comments ↓↓

- At 18 feb 2015, 12:50:17 wrote [Freddy](#)

The terminology in the article is correct. Accuracy means how close your measured (averaged) values are compared with the true value. And precision is the spread of measured values around the average measured values.
- At 09 jul 2015, 19:25:10 wrote [John McGaughey](#)

In the example shown for total measurement uncertainty I believe the sum of 3.5 V and 3.0 V is 6.5 V , not 7.5 V.
- At 10 jul 2015, 20:45:58 wrote [Freddy](#)

Thanks, you're right. This article will be rewritten in the future. There are more incorrectness. For example the way how multiple uncertainties are added is not correct.
- At 14 jul 2015, 16:23:39 wrote [A.J.x](#)

Thank you for this article.
- At 26 nov 2015, 03:29:00 wrote [Rhys](#)

This is a really useful article but I am slightly confused as how to work out the uncertainty of the system I have. In particular the probe (PKT 520A-RO). The probe has a Attenuation ratio 10:1 +/- 2% at DC (connected to a scope with an input of 1Mohm +/-1%) and an input resistance (system) of 10Mohm +/- 1%. Which am I suppose to use?

TOP

Note: the scope I am using has an impedance gain of 1Mohm +/-1% and a measurement uncertainty of 1.9% with the scale I'm using.

At 30 nov 2015, 12:05:14 wrote [Freddy](#)

The given resistive error from the probe and the input of the scope have both influence on the total error. So include both errors to the total error equation.

At 18 apr 2017, 11:54:48 wrote [Peter van der Burgt](#)

Because of uncertainty in measurements the true/real value of a physical quantity can never be known exactly. Therefore your definition "Accuracy: The error between the real and measured value" is incorrect.

A measured value is called accurate if we have good reasons to argue that it is close to the true value. For instance, if different measurements of the same quantity performed at different laboratories using different methods yield very similar results, then we are confident that these measurements are close to the true value of the quantity.

An accurate result does not necessarily imply that the experimental error is small: a measurement with a large estimated error can still be close to the true value. A measured value is called precise if it has a small error, but this does not necessarily imply that it is close to the true value.

At 03 maa 2018, 20:11:53 wrote [Siddiq M. Hamza](#)

I appreciate the efforts done in this site, I would like to join and stay in touch, though I cannot see "sign up link".  
Thanks alot.

At 11 aug 2018, 22:02:48 wrote [MAHMOUD ALQSAS](#)

Very Very thanks for yours

At 17 aug 2018, 09:54:32 wrote [arnel ruiz](#)

% of reading plus 5 counts what does it means

***Responding to articles is temporarily disabled.***

[Contact](#) • [Sitemap](#) • [Links](#) • [Rules](#) • [Login](#) • 

All texts and images on this site are the intellectual property of Freddy Alferink.

TOP

