

SECTION-D

Note: Long Answer type question. Attempt any two questions. (2x10=20)

Q.36 What do you mean by heat treatment furnace? What are its different types? Explain any two. (CO-1)

Q.37 Explain the electric furnace with neat sketch.(CO-4)

Q.38 Explain T.T.T. Diagrams. (CO-5)

Note : Course Outcome (CO) mentioned in the question paper is for official purpose only.

No. of Printed Pages : 4

181856/121856/031851

Roll No.....

5th Sem / Mechanical Engineering

Subject : Heat Treatment

Time : 3 Hrs.

M.M. : 100

SECTION-A

Note: Multiple choice questions. All questions are compulsory. (10x1=10)

Q.1 While hardening of steel, the component is cooled in (CO-1)

- a) Still Air b) Water or Oil
- c) Furnace d) All of the above

Q.2 Fatigue crack normally start at (CO-1)

- a) Centre of specimen b) Core of specimen
- c) Surface of specimen d) All of the above

Q.3 The ability of the material to resist fracture due to high impact loads is. (CO-2)

- a) Toughness b) Hardness
- c) Brittleness d) None of these

Q.4 Eutectic mixture of austenite and cementite is called. (CO-2)

- a) Troostite b) Leadburite
- c) Martensite d) None of these

Q.5 Sorbite is obtained when. (CO-2)

- a) Steel is quenched b) Steel is annealed
- c) Steel is hardened d) None of these

- Q.6 Fatigue results in (CO-3)
 a) Brittle fracture b) Ductile fracture
 c) Elongation d) None of these
- Q.7 Nitriding is a process for. (CO-3)
 a) Annealing b) Normalizing
 c) Case hardening d) None of these
- Q.8 A thermal equilibrium diagram is also known as. (CO-4)
 a) Phase diagram
 b) Constitutional diagram
 c) Both A & B
 d) None of these
- Q.9 Corrosion resistance of steel is increased by the addition of. (CO-4)
 a) Sulphur b) Tungsten
 c) Chromium d) None of these
- Q.10 If steel is quenched in oil, the structure obtained will be. (CO-5)
 a) Pearlite b) Troostite
 c) Sorbite d) Bauxite

SECTION-B

Note: Objective type questions. All questions are compulsory. (10x1=10)

- Q.11 The object of annealing is _____ (CO-1)
 Q.12 Nitriding is a process for _____ (CO-1)
 Q.13 Name any two semi-conductors. (CO-1)

- Q.14 Define heat treatment. (CO-2)
 Q.15 Define tempering. (CO-2)
 Q.16 Name two types of annealing. (CO-2)
 Q.17 Pearlite is a combination of _____. (CO-3)
 Q.18 Name the purest form of iron. (CO-3)
 Q.19 Give the full form of T.T.T. (CO-5)
 Q.20 Define hardening. (CO-6)

SECTION-C

Note: Short answer type questions. Attempt any twelve questions out of fifteen questions. (12x5=60)

- Q.21 Define Ferrous metals with one example. (CO-1)
 Q.22 Define creep. (CO-1)
 Q.23 Define ductility of a material. (CO-1)
 Q.24 Name four types of annealing. (CO-2)
 Q.25 Define process of annealing. (CO-2)
 Q.26 Differentiate between annealing and hardening. (CO-1)
 Q.27 Write the advantages of heat treatment. (CO-1)
 Q.28 Differentiate between slip and twinning. (CO-2)
 Q.29 Explain lead bath furnace. (CO-2)
 Q.30 What austenite? (CO-2)
 Q.31 Write the characteristics of carburizing. (CO-3)
 Q.32 Write the uses of nitriding. (Any five) (CO-3)
 Q.33 Write purpose of tempering. (CO-4)
 Q.34 What is martensite? (CO-5)
 Q.35 Write any five application of heat treatment. (CO-6)