



Entergy Operations, Inc.
P. O. Box 756
Port Gibson, MS 39150

Thomas Coutu
Director, Regulatory and
Performance Improvement
Grand Gulf Nuclear Station
Tel. (601) 437-7511

GNRO-2014/00070

October 07, 2014

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Revised Licensee Event Report for Reactor Pressure Vessel steam pressure less than 0 psig during six plant startups resulting in a violation of Technical Specification 3.4.11, Reactor Coolant System (RCS) Pressure and Temperature (P/T) Limits.
Grand Gulf Nuclear Station, Unit 1
Docket No. 50-416
License No. NPF-29

REFERENCE: Entergy Letter, "Reactor Pressure Vessel steam pressure less than 0 psig during six plant startups resulting in a violation of Technical Specification 3.4.11, RCS Pressure and Temperature (P/T) Limits," GNRO-2014/00008, dated February 5, 2014 (ADAMS Accession No. ML14037A459)

Dear Sir or Madam:

Attached is Licensee Event Report (LER) 2013-005-01 which is a final report. This is a revision to LER 2013-005-00 provided in the Reference above. The revision changes the corrective action from revising the Pressure and Temperature (P/T) curve to revising the Integrated Operating Instruction (IOI) 03-1-01-1. IOI 03-1-01-1 will be revised to have instruction to prevent drawing a vacuum on the Reactor Vessel. Also, some editorial changes were made for clarification purposes. This report is being submitted in accordance with Title 10 *Code of Federal Regulations* 50.73(a)(2)(i)(B).

This letter contains no new commitments. If you have any questions or require additional information, please contact James Nadeau at 601-437-2103.

Sincerely,

A handwritten signature in cursive script, appearing to read "Thomas Coutu".

TC/tmc

Attachment: License Event Report (LER) 2013-005-01
cc: (see next page)

cc: with Attachment

U.S. Nuclear Regulatory Commission
ATTN: Mr. Marc L. Dapas (w/2)
Regional Administrator, Region IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511

U.S. Nuclear Regulatory Commission
ATTN: Mr. Alan Wang, NRR/DORL
Mail Stop OWFN 8 B1
Washington, DC 20555-0001

NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

Attachment to
GNRO-2014/00070
License Event Report (LER) 2013-005-01

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Grand Gulf Nuclear Station, Unit 1

2. DOCKET NUMBER**05000 416****3. PAGE****1 OF 3****4. TITLE**

Reactor Pressure Vessel steam pressure less than 0 psig during six plant startups resulting in a violation of Technical Specification 3.4.11, RCS Pressure and Temperature (P/T) Limits.

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
12	12	2013	2013 - 005 - 01			10	06	2014	N/A	05000 N/A

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

10. POWER LEVEL	
100	

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME

James Nadeau / Manager, Regulatory Assurance

TELEPHONE NUMBER (Include Area Code)

(601) 437-2103

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
D	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

14. SUPPLEMENTAL REPORT EXPECTED☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR
N/A	N/A	N/A

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On December 12, 2013, with the plant operating in Mode 1 at 100 percent thermal power, Grand Gulf Nuclear Station (GGNS) discovered that during six past startups, the Reactor Pressure Vessel (RPV) steam pressure was below zero (0) pounds per square inch gage (psig) with the Main Steam Isolation Valves (MSIVs) open and the Mechanical Vacuum Pumps (MVPs) running without entering LCO 3.4.11 RCS Pressure and Temperature (P/T) Limits. From 12/12/10 through 12/12/13 there were six occurrences of reactor pressure being < 0 psig. The Reactor Pressure/Temperature curves in the GGNS Pressure and Temperature Limit Report (PTLR) have a minimum pressure value of 0 psig referenced on the curve. The lowest pressure noted in the six occurrences was approximately -9.9 psig on December 13, 2012. All systems performed per design during the reactor startups with RPV pressure below 0 psig during the past 3 years. The cause of not entering LCO 3.4.11 was the condition was procedurally allowed and aligned with Operations training. There were no adverse effects on the health or safety of the public as a result of these events.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Grand Gulf Nuclear Station, Unit 1	05000 416	YEAR	SEQUENTIAL NUMBER	REV. NO.	2 OF 3
		2013 -- 005 -- 01			

NARRATIVE

A. REPORTABLE OCCURRENCE

This Licensee Event Report (LER) is being submitted pursuant to Title 10 Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B) for an operation or condition which was prohibited by Technical Specifications by not entering Limiting Condition of Operation (LCO) 3.4.11, RCS Pressure and Temperature (P/T) Limits during six Reactor startups with Reactor Pressure Vessel (EIS:RPV) steam pressure below zero (0) pounds per square inch gage (psig).

B. INITIAL CONDITIONS

At the time of discovery of the issue, the reactor was in operational mode one with reactor power at 100 percent and normal operating pressure. There were no additional inoperable structures, systems, or components at the time of discovery that contributed to this event. This event is considered a discovery of an existing but previously unrecognized condition.

C. DESCRIPTION OF OCCURRENCE

On December 12, 2013, Grand Gulf Nuclear Station discovered a previously unrecognized failure to enter LCO 3.4.11 when Reactor Pressure Vessel (RPV) pressure dropped below zero psig during six reactor startups. The plant was operating in Mode 1 at 100 percent thermal power during discovery. All systems performed per design.

D. APPARENT CAUSE

The cause of the failure to enter the LCO was the condition was procedurally allowed and aligned with training Operations personnel had received. Therefore, RPV being below 0 psig was not recognized to be a condition that required entry into the LCO. Integrated Operating Instruction (IOI) 03-1-01-1 was revised in 1994 to allow startup with a vacuum in the reactor vessel because opening Main Steam Isolation Valves (MSIVs) with pressure in the reactor vessel can cause a rapid drop in level.

E. CORRECTIVE ACTIONS

A corrective action has been issued to revise the IOI 03-1-01-1 to have instruction to prevent drawing a vacuum on the RPV. Interim corrective action of MSIVs remaining closed during start-up until a slight pressure (~5-10 psig) is observed in the reactor was issued to ensure negative pressure is not applied to the RPV until IOI 03-1-01-1 is revised. A corrective action has also been issued for training to update all applicable training materials related to changes to the IOI 03-1-01-1.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Grand Gulf Nuclear Station, Unit 1	05000 416	YEAR	SEQUENTIAL NUMBER	REV. NO.	3 OF 3
		2013 -- 005 -- 01			

NARRATIVE

F. SAFETY ASSESSMENT

The six events posed no threat to public health and safety as the RPV performed as designed. All safety systems performed as designed.

The six events did not challenge any design or safety limit. Nuclear safety was not significantly compromised because the negative (vacuum) internal pressures identified do not cause any concerns with applicable material stresses or analysis for the GGNS RPV. GGNS remained in an analyzed condition and within established margins in regards to brittle fracture of the RPV ferritic materials. There are no known or understood safety significance issues created by allowing the RPV to have a relatively small vacuum of approximately -9.9 to -6 psig during startup with the RPV metal temperatures being at approximately 160 degrees Fahrenheit (°F) to 170°F. There is reasonable assurance that operating below 0 psig on the pressure/temperature (P/T) curves is acceptable. The PTLR is set for the limiting components which are nozzle welds for the RPV inlet. These locations get compressive and tensile stresses during startup and shutdown, but the vacuum in the steam region had an immeasurable effect on these limiting locations. The locations were still under pressure from the static fluid head (just less pressure due to being at vacuum). Therefore, margin remained.

During the six events, no Technical Specification defined Safety Limits were challenged. Radiological Safety was not affected since there was no radiological release to the public during the events.

There was no impact to the safety of the public, industrial safety or radiological safety as a result of these events.

G. ADDITIONAL INFORMATION

There have been no indications of RPV brittle fracture in the past 3 years due to the cause documented in this LER. There have been no identified failures to enter LCO 3.4.11 due to inadequate procedure or training documented in an LER in the past 3 years.