



Entergy Nuclear South
Entergy Operations, Inc.
17265 River Road
Killona, LA 70057-3093
Tel 504 739 6685
Fax 504 739 6698
wsteelm@entergy.com

William J. Steelman
Acting Licensing Manager
Waterford 3

W3F1-2010-0030

April 29, 2010

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Subject: Licensee Event Report 2009-003-01
Waterford Steam Electric Station, Unit 3 (Waterford 3)
Docket No. 50-382
License No. NPF-38

Dear Sir or Madam:

Entergy is hereby submitting Licensee Event Report (LER) 09-003-01 for Waterford Steam Electric Station Unit 3. This report provides a revision to the details associated with higher than expected failure rates of normally energized Tyco model E7024PB electro pneumatic time delay relays. This report contains no new commitments. Please contact William J. Steelman at (504) 739-6685 if you have questions regarding this information.

Sincerely,

A handwritten signature in black ink, appearing to read "William J. Steelman", with a long, sweeping horizontal stroke extending to the right.

WJS

Attachment: Licensee Event Report 2009-003-01

IE22
NRR

cc: Mr. Elmo E. Collins, Jr.
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
612 E. Lamar Blvd., Suite 400
Arlington, TX 76011-4125

NRC Senior Resident Inspector
Waterford Steam Electric Station Unit 3
P.O. Box 822
Killona, LA 70066-0751

U. S. Nuclear Regulatory Commission
Attn: Mr. N. Kalyanam
Mail Stop O-07D1
Washington, DC 20555-0001

Wise, Carter, Child & Caraway
ATTN: J. Smith
P.O. Box 651
Jackson, MS 39205

Winston & Strawn
ATTN: N.S. Reynolds
1700 K Street, NW
Washington, DC 20006-3817

Morgan, Lewis & Bockius LLP
ATTN: T.C. Poindexter
1111 Pennsylvania Avenue, NW
Washington, DC 20004

Louisiana Department of Environmental Quality
Office of Environmental Compliance
Surveillance Division
P. O. Box 4312
Baton Rouge, LA 70821-4312

R.K. West, lerevents@inpo.org - INPO Records Center

Attachment

W3F1-2010-0030

Licensee Event Report 2009-003-01

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (9-2007)				APPROVED BY OMB NO. 3150-0104				EXPIRES 8/31/2010											
LICENSEE EVENT REPORT (LER)										Estimated burden per response to comply with this mandatory information collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME Waterford 3 Steam Electric Station						2. DOCKET NUMBER 05000382				3. PAGE 1 OF 6									
4. TITLE Multiple Tyco Relay Failures																			
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	FACILITY NAME		DOCKET NUMBER								
02	22	2010	2009	003	01	04	29	2010	NA		05000								
									FACILITY NAME		DOCKET NUMBER								
									NA		NA								
9. OPERATING MODE 1			11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																
			<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(ix)(A) <input type="checkbox"/> 50.73(a)(2)(x) <input type="checkbox"/> 73.71(a)(4) <input type="checkbox"/> 73.71(a)(5) <input checked="" type="checkbox"/> OTHER Specify in Abstract below or in NRC Form 366A													
10. POWER LEVEL 100																			
12. LICENSEE CONTACT FOR THIS LER																			
FACILITY NAME								TELEPHONE NUMBER (Include Area Code)											
Waterford 3 Steam Electric Station William Steelman								504-739-6685											
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																			
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX									
B	JE	2	TYCO	Y															
14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO										15. EXPECTED SUBMISSION DATE									
										MONTH	DAY	YEAR							
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)																			
This is a Licensing Event Report (LER) to identify a 10CFR21 issue of generic interest. There have been two additional failures of Tyco relay model E7024PB with date codes that had not previously failed since LER 2009-003-00 was submitted.																			
Waterford 3 has observed a higher than expected failure rate of normally energized Tyco model E7024PB electro-pneumatic time delay relays produced since 2007. Seven of the eight failures were observed on 2007 or newer date code relays and one was observed on a 2004 date code relay. The early-in-life failures have been observed on Tyco model E7024PB relays designed as an Off-Delay, 4 pole double throw, 125VDC operating coil, with a time delay range of 0.5 to 5 seconds.																			
All failed relays were replaced. Post failure bench testing at Waterford 3, Tyco, or independent Failure Analysis has not consistently repeated the failures.																			

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Waterford 3 Steam Electric Station	05000382	2009	- 003	- 01	2 OF 6

NARRATIVE**REPORTABLE OCCURRENCE**

This condition is a Licensee Event Report (LER) to report a 10CFR21 issue of generic interest. This condition meets the reporting criteria of 10CFR21 because reduced reliability of Tyco model E7024PB relays has been established in Waterford 3 Corrective Action Program, the root cause was determined to be manufacturer fabrication less than adequate, and Waterford 3 has Tyco model E7024PB relays in the warehouse.

The 10CFR21 two day report was made on 4/21/10 at 1035 EDT under notification number EN45862. This is the follow up 30 day written notification.

INITIAL CONDITIONS

This LER identifies multiple Tyco model E7024PB electro-pneumatic time delay relay failures that have occurred at different initial conditions. Of interest, four of the eight failures resulted in Waterford 3 entering into Unplanned Shutdown Limiting Conditions of Operation (LCO) of 72 hours (one additional was a 7 day LCO).

EVENT DESCRIPTION

Waterford 3 has observed a higher than expected failure rate of normally energized Tyco model E7024PB electro-pneumatic time delay relays produced since 2007. Seven of the eight failures were observed on 2007 or newer date code relays and one was observed on a 2004 date code relay. Waterford 3 had 33 Tyco model E7024PB time delay relays installed in the plant. The Agastat E7000 series timing relay consists of two basic operating types, On-Delay and Off-Delay. The On-Delay models provide a delay period of contact re-positioning on energization and no time delay upon de-energization. The Off-Delay models provide a delay period of contact re-positioning on de-energization and no time delay upon energization. These relays may be ordered with various electrical characteristics suitable for use specific to each application. The early-in-life failures have been observed on Tyco model E7024PB relays designed as an Off-Delay, 4 pole double throw, 125VDC operating coil, with a time delay range of 0.5 to 5 seconds.

All failed relays were replaced. Post failure bench testing at Waterford 3, Tyco, and independent Failure Analysis has not consistently repeated the failures.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 6
		2009	- 003	- 01	

NARRATIVE**CAUSAL FACTORS**

A Root Cause Analysis was completed using multiple investigative techniques (Kepner-Tregoe Problem Solving Analysis and Failure Modes Analysis). The root cause of the early in life relay failures is manufacturer fabrication less than adequate. No common specific fabrication issue was identified that would encompass all the relay failures, but the Root Cause Analysis identified eight potential fabrication issues that could not be eliminated during the analysis process. These include:

- Cracked contact blocks on relays 09150078, 09030683, and 08350005
- Resistance change to contacts due to clamping force on terminal block
- Incorrect recycle spring installed causing 10 CFR Part 21 notification
- Contact block force spring adjustments (Allen set screw) out of tolerance
- Loose terminal points discovered on two spare relays
- Screw inside the lower contact block assembly (contact set 8-12) is not tight / backed out from stationary contact 0921
- Foreign Material in contact block most likely from manufacturing
- Mechanical binding of armature and plunger due to foreign material

The eight early-in-life normally energized Tyco model E7024PB electro-pneumatic time delay relay failures with serial numbers 04030244, 08040634, 08040636, 08270633, 09030683, 08350005, 07160240, and 09150078 can be grouped as follows:

- Date code 0804
High Pressure Safety Injection (HPSI) Pump B (09/11/2008) and Chemical Volume Control (CVC) Charging Pump A (10/13/2008)
Tyco indicated the failures were due to worker error in fabrication and testing (force balance).
An additional failure occurred during a bench test. This Tyco Relay 08040635 bench test failure (04/13/2009) cause was indeterminate.
- Date code 0903
CVC Charging Pump B (03/13/2009)
Southwest Research Institute (SwRI) performed failure analysis and found foreign material in relay.
- Date code 0827
Battery Exhaust Fan A (06/01/2009)
Date codes 0808-0835 were identified by the Tyco 10CFR Part 21 Notification dated 11/21/08 as potentially having an incorrect spring installed during fabrication. The 08270633 relay was returned to Tyco per 10CFR21 and Tyco reported the correct springs were installed. Tyco could not duplicate the failure.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 6
		2009	- 003	- 01	

NARRATIVE**CAUSAL FACTORS CONTINUED**

- Date code 0835
HPSI Pump B (06/22/2009)
The date code 0808 through 0835 relays that were sent back to the vendor per the Part 21 notification, re-certified by the vendor, and returned to Waterford 3 as new relays and the 0835 date code relay failed subsequently. The 08350005 Relay was sent to SwRI for failure analysis with result that the failure could not be duplicated, but minor foreign material was identified.
- Date code 0403
Train B Integrated Emergency Diesel Generator/Engineering Safety Features Test multiple components (05/15/2008)
Bench testing of the failed relay by Electrical Maintenance determined that this normally energized relay would change state if actuated shortly after being energized; however, after an extended period of time (~1 hour) the relay would not change state. This was evaluated as evidence of a heat related failure mechanism specific to this relay. This relay was inadvertently disposed and a formal failure analysis could not be performed.
- Date code 0915
Low Pressure Safety Injection (LPSI) Pump B (2/22/10)
Tyco witnessed relay test at Waterford 3, which confirmed failure mechanism. Tyco returned to manufacturing facility with relay (09150078) to perform failure analysis. This is in the Waterford 3 corrective action process.
- Date code 0716
Battery Exhaust Fans B (2/27/10).
The relay failure mechanism could not be confirmed at Waterford 3. Relay (07160240) was returned to Tyco to perform failure analysis. This is in the Waterford 3 corrective action process.

CORRECTIVE ACTIONS

The Root Cause Analysis has identified multiple required corrective actions. The most pertinent are as follows:

- Revised Tyco relay pre-installation testing to include a 24 hour burn in time and cycling the relay 10 times.
- For installed Tyco relays of specific date codes and risk significance, the testing frequency has been increased to proactively assess reliability.
- Implementing modification to replace all Tyco E7024PB relays in safety related applications.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 6
		2009	- 003	- 01	

NARRATIVE**SAFETY SIGNIFICANCE**

The Waterford 3 EOOS model was used to calculate the risk using the Waterford 3 Revision 4 Change 1 Probabilistic Risk Analysis (PRA). The zero maintenance risk for the Revision 4 Change 1 PRA is 2.292E-06/year.

The 2007-2009 Tyco date coded model E7024PB relays installed have 293 successful actuations out of a total of 300 actuations or 97.67% successful actuations. This results in a failure rate of 2.33E-2. A risk analysis was performed using this 2.33E-2 failure rate. The analysis shows that the only relays having potential risk significance are those associated with the HPSI pumps A and B, Emergency Feedwater (EFW) pump B, and Chilled Water (CHW) pump A.

If these relays were to fail, the failure to start would be readily detected by the operators, who are trained and frequently practice in training where the pumps would be started manually using the switches on the main control room panels. Existing procedures require verifying these pumps start and direct manually starting the pumps if they did not start automatically. The operator actions for manually starting these pumps were conservatively assumed to have a 1.1E-2 or 2.8E-3 failure probability, depending on the accident sequence. Using these manual actions, the internal events Core Damage Frequency (CDF) is 2.885E-6/yr, which is an increase of 5.93E-7/yr with respect to the baseline CDF of 2.292E-6/yr. The risk impact for external events is 2.30E-7/yr for a total risk impact of 8.23E-7/yr. All the Tyco model E7024PB relays have been reviewed to confirm that the potential relay failures can be mitigated by simple manual action. Thus, the potential reduced reliability of the relays is not risk significant.

The Public Health and Safety was not adversely affected by this condition. The relay failures were identified during surveillance or bench testing with the redundant train operable. There were no system or train actuations or initiations resulting from these relay failures. There was not a common mode failure mechanism identified for the relay failures. This condition had no impact on industrial safety or radiological safety. No personnel were injured during these events. The relays are installed outside the radiological controlled areas. No dose was received as a result of these failures.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Waterford 3 Steam Electric Station	05000382	2009	- 003	- 01	6 OF 6

NARRATIVE

SIMILAR EVENTS

As stated in the event description, Waterford 3 has observed a higher than expected failure rate of normally energized Tyco model E7024PB electro-pneumatic time delay relays produced since 2007. Seven of the eight failures were observed on 2007 or newer date code relays and one 2004 date code relay. This LER is an outcome of multiple similar events.

ADDITIONAL INFORMATION

None