



Entergy Operations, Inc.  
River Bend Station  
5485 U.S. Highway 61N  
St. Francisville, LA 70775  
Tel 225 381 4157  
Fax 225 635 5068  
dlorfin@entergy.com

David N. Lorfing  
Manager-Licensing

RBG-47127

March 2, 2011

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Subject: Licensee Event Report 50-458 / 10-004-01  
River Bend Station – Unit 1  
Docket No. 50-458  
License No. NPF-47

File No. G9.5

RBF1-11-0044

Dear Sir or Madam:

In accordance with 10CFR50.73, enclosed is the subject Licensee Event Report.  
This document contains no commitments. If you have any questions, please contact  
me at 225-381-4157.

Sincerely,

  
David N. Lorfing  
Manager – Licensing

Enclosure

JE22  
NRL

Licensee Event Report 50-458 / 10-004-01  
March 2, 2011  
RBG-47127  
RBF1-11-0044  
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission  
Region IV  
612 East Lamar Blvd., Suite 400  
Arlington, TX 76011-4125

NRC Sr. Resident Inspector  
P. O. Box 1050  
St. Francisville, LA 70775

INPO Records Center  
E-Mail (MS Word format)

Mr. Jim Calloway  
Public Utility Commission of Texas  
1701 N. Congress Ave.  
Austin, TX 78711-3326

Mr. Jeffrey P. Meyers  
Louisiana Department of Environmental Quality  
Attn: OEC-ERSD  
P.O. Box 4312  
Baton Rouge, LA 70821-4312

**LICENSEE EVENT REPORT (LER)**(See reverse for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects.resource@nrc.gov](mailto:infocollects.resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

**1. FACILITY NAME**

River Bend Station – Unit 1

**2. DOCKET NUMBER**

05000 - 458

**3. PAGE**

1 OF 4

**4. TITLE**

High Pressure Core Spray System Inoperable Due to Failed Motor Oil Reservoir Drain Plug

**5. EVENT DATE**

MONTH	DAY	YEAR
11	07	2010

**6. LER NUMBER**

YEAR	SEQUENTIAL NUMBER	REV NO.
2010	004	01

**7. REPORT DATE**

MONTH	DAY	YEAR
03	02	2011

**8. OTHER FACILITIES INVOLVED**

FACILITY NAME	DOCKET NUMBER
	05000
FACILITY NAME	DOCKET NUMBER
	05000

**9. OPERATING MODE**

1

**11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)**

- |   |   |   |  |
|---|---|---|--|
| <input type="checkbox"/> 20.2201(b)         | <input type="checkbox"/> 20.2203(a)(3)(i)   | <input type="checkbox"/> 50.73(a)(2)(i)(C)            | <input type="checkbox"/> 50.73(a)(2)(vii)        |
| <input type="checkbox"/> 20.2201(d)         | <input type="checkbox"/> 20.2203(a)(3)(ii)  | <input type="checkbox"/> 50.73(a)(2)(ii)(A)           | <input type="checkbox"/> 50.73(a)(2)(viii)(A)    |
| <input type="checkbox"/> 20.2203(a)(1)      | <input type="checkbox"/> 20.2203(a)(4)      | <input type="checkbox"/> 50.73(a)(2)(ii)(B)           | <input type="checkbox"/> 50.73(a)(2)(viii)(B)    |
| <input type="checkbox"/> 20.2203(a)(2)(i)   | <input type="checkbox"/> 50.36(c)(1)(i)(A)  | <input type="checkbox"/> 50.73(a)(2)(iii)             | <input type="checkbox"/> 50.73(a)(2)(ix)(A)      |
| <input type="checkbox"/> 20.2203(a)(2)(ii)  | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(iv)(A)           | <input type="checkbox"/> 50.73(a)(2)(x)          |
| <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2)        | <input type="checkbox"/> 50.73(a)(2)(v)(A)            | <input type="checkbox"/> 73.71(a)(4)             |
| <input type="checkbox"/> 20.2203(a)(2)(iv)  | <input type="checkbox"/> 50.46(a)(3)(ii)    | <input type="checkbox"/> 50.73(a)(2)(v)(B)            | <input type="checkbox"/> 73.71(a)(5)             |
| <input type="checkbox"/> 20.2203(a)(2)(v)   | <input type="checkbox"/> 50.73(a)(2)(i)(A)  | <input type="checkbox"/> 50.73(a)(2)(v)(C)            | <input type="checkbox"/> OTHER                   |
| <input type="checkbox"/> 20.2203(a)(2)(vi)  | <input type="checkbox"/> 50.73(a)(2)(i)(B)  | <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D) | Specify in Abstract below<br>or in NRC Form 366A |

**10. POWER LEVEL**  
100**12. LICENSEE CONTACT FOR THIS LER**

## FACILITY NAME

David N. Lorfing, Manager – Licensing

## TELEPHONE NUMBER (Include Area Code)

225-381-4157

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX
E	BG	(see text)	(see text)	YES					

**14. SUPPLEMENTAL REPORT EXPECTED**☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO**15. EXPECTED  
SUBMISSION  
DATE**

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On November 7, 2010, at 10:23 a.m. CDT, with the plant operating at 100 percent power, the high pressure core spray (HPCS) pump was declared inoperable following the discovery of an oil leak on the pump motor. The source of the oil leak was found to be a cracked drain plug on the lower motor bearing oil reservoir. The oil plug was replaced, and the HPCS system was restored to its standby condition at 7:40 p.m. CDT that same day. The investigation of this event determined that the oil plug cracked due to application of torque to correct an oil leak. The oil leak had been caused by age-related degradation of the O-ring on the plug, attributable to the lack of a preventative maintenance task to provide for its periodic replacement. A new oil plug was installed on the motor, and the system was returned to service. The preventative maintenance program is being updated to include this plug and O-ring.

This condition is being reported in accordance with 10CFR50.73(a)(2)(v)(D) as the loss of a system needed to mitigate the consequences of an accident. No other safety-related systems were out of service during the time that the HPCS system was inoperable. This event was of minimal significance with respect to the health and safety of the public.

# **LICENSEE EVENT REPORT (LER) CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station – Unit 1	05000 -458	YEAR	SEQUENTIAL NUMBER	REV. NO.	2 OF 4
		2010 -- 004 -- 01			

## **REPORTED CONDITION**

On November 7, 2010, at 10:23 a.m. CDT, with the plant operating at 100 percent power, the high pressure core spray (HPCS) (BG) pump was declared inoperable following the discovery of an oil leak on the pump motor (\*\*MO\*\*). This condition is being reported in accordance with 10CFR50.73(a)(2)(v)(D) as the loss of a system needed to mitigate the consequences of an accident.

The oil plug was replaced, and the HPCS system was restored to its standby condition at 7:40 p.m. CDT that same day. No other safety-related systems were out of service during the time that the HPCS system was inoperable.

## **INVESTIGATION**

On July 14, 2010, a minor, unquantifiable oil leak was found on the lower reservoir drain plug of the HPCS pump. The leak appeared only as oil sheen around the drain plug. On August 7, the leak was quantified as approximately 1 drop every 3 minutes. A maintenance technician tightened the plug approximately one-quarter turn that day, which had no apparent effect. The leakage rate was determined to be stable, and it was concluded that the pump remained capable of performing its safety function.

The approximate timeline of subsequent activities concerning this event, developed from documentation and from interviews with the operators and maintenance technicians, is as follows. Oil was added to the reservoir on September 13. The HPCS system was operated on September 20 for scheduled surveillance testing, and no increase in the leakage rate was seen. Oil was again added to the reservoir on October 26. No further oil additions were made until November 7. Twice-weekly inspections of the pump by the operators confirmed that the leakage had not increased. (Operators also perform a general inspection of the pump room each shift, checking for oil accumulation on equipment and other conditions. Those inspections continued to be satisfactory.) On October 29, the operators wrapped an absorbent pad around the plug to eliminate the need to clean up oil around the pump pedestal, and to eliminate the potential slipping hazard. These pads were subsequently replaced three times prior to November 7 (the last replacement was on November 5), and on each occasion, the oil leak rate had not increased.

On November 7, the operator removed the absorbent pad, and found that the leak had increased to a small stream approximately one-tenth of an inch in diameter. The HPCS pump was removed from service, and the oil drain plug was replaced with a new part.

# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station – Unit 1	05000 -458	YEAR	SEQUENTIAL NUMBER	REV. NO.	3 OF 4
		2010 -- 004 -- 01			

## IMMEDIATE CORRECTIVE ACTIONS

The failed drain plug was replaced, and the HPCS pump was restored to service at 7:40 p.m. CDT on the same day. At the time of this event, no similar leaks existed on the other emergency core cooling system (ECCS) pumps, which share a common drain plug design with the HPCS pump.

## CAUSAL ANALYSIS

Visual inspection of the removed drain plug assembly identified a circumferential fracture on the threaded portion of the drain plug. The drain plug assembly and O-ring were then sent to an independent laboratory for analysis.

Laboratory analysis found that the plug fracture surface exhibited a purely ductile failure of a low tensile strength material with significant porosity. The lab postulated that the initial leakage of the drain plug was the result of O-ring failure. The O-ring exhibited surface cracks and chips and had developed a permanent set in the radial direction due to its more than 24 years of service. It appeared that an attempt to mitigate the leakage was made by further tightening of the drain plug. The fracture along the head of the plug caused the markedly higher leak rate discovered on November 7.

The pump motor vendor (General Electric) was contacted to provide detailed information about the drain plug material and design of the drain plug assembly and O-ring. The laboratory analysis determined that the failed drain plug material was zinc alloy die casting, which is consistent with one of the specified materials by GE.

GE also provided service information recommending that low nitrile Buna O-rings be replaced with medium Buna-N O-rings containing at least 27 percent nitrile to improve seal reliability and increase the life of the seals. It was also recommended that the O-rings should be replaced at every other oil change. The laboratory analysis found that the drain plug O-ring was the recommended 27 percent nitrile material.

That same service information was reviewed by RBS in 1991, and it was agreed to replace the drain plug O-rings and sight glass O-rings. The review stated that "A [preventative maintenance] task or multiple tasks will be initiated to track work which will be performed in accordance with the GE SIL." This investigation found that no such tasks were ever initiated.

## CORRECTIVE ACTIONS TO PREVENT RECURRENCE

The failed drain plug assembly and O-ring are common to the upper and lower motor bearing reservoirs of the five emergency core cooling pump motors (i.e., low pressure core spray, three residual heat removal subsystems, and high pressure core spray). The remaining drain plug assemblies are also originally installed components. A schedule has been set for replacing all

# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station – Unit 1	05000 -458	YEAR	SEQUENTIAL NUMBER	REV. NO.	4 OF 4
		2010 -- 004 -- 01			

those plugs with new stainless steel parts. In the interim, the maintenance technicians were informed not to apply torque to the currently installed plugs in an attempt to stop any future leakage.

Preventative maintenance tasks will be developed to replace the drain plug O-rings on a schedule consistent with vendor recommendations.

## PREVIOUS OCCURRENCE EVALUATION

There have been no similar events reported by RBS since January 1, 2005.

## SAFETY SIGNIFICANCE

Two of three divisions of ECCS are required for the RBS loss of coolant accident analyses. While HPCS was out of service, Division 1 and Division 2 ECCS systems and the automatic depressurization system were available, and would have met the ECCS performance criteria of 10CFR50.46. The HPCS system was returned to service within the time limit of the Required Action in the plant's Technical Specifications. This event was of minimal safety significance with respect to the health and safety of the public.

(NOTE: Energy Industry Component Identification codes are annotated as (\*\*XX\*\*).)