



A subsidiary of Pinnacle West Capital Corporation

10 CFR 50.73

Palo Verde Nuclear
Generating Station

Dwight C. Mims
Senior Vice President
Nuclear Regulatory and Oversight

Tel. 623-393-5403
Fax 623-393-6077

Mail Station 7605
P. O. Box 52034
Phoenix, Arizona 85072-2034

102-06521-DCM/TNW/MAM/DFH
May 4, 2012

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Dear Sirs:


Subject: Palo Verde Nuclear Generating Station (PVNGS) Units 1, 2, and 3
Docket No. STN 50-528, STN 50-529, and STN 50-530
License No. NPF-41, NPF-51, and NPF-79
Licensee Event Report 2012-001-00

Enclosed, please find Licensee Event Report (LER) 50-528/2012-001-00 that has been prepared and submitted pursuant to 10 CFR 50.73. This LER reports a condition prohibited by Technical Specification (TS) 3.1.7, Regulating Control Element Assembly (CEA) Insertion Limits, when the power dependent insertion limit alarm circuit was determined to be inoperable for a period greater than allowed by TS.

In accordance with 10 CFR 50.4, copies of this LER are being forwarded to the Nuclear Regulatory Commission (NRC) Regional Office, NRC Region IV and the Senior Resident Inspector. If you have questions regarding this submittal, please contact Mark McGhee, Operations Support Manager, Regulatory Affairs, at (623) 393-4972.

Arizona Public Service Company makes no commitments in this letter.

Sincerely,



FOR D.C. MIMS

DCM/TNW/MAM/DFH/hsc

Enclosure

cc:	E. E. Collins Jr.	NRC Region IV Regional Administrator
	B. K. Singal	NRC NRR Project Manager for PVNGS (electronic / paper)
	L. K. Gibson	NRC NRR Project Manager for PVNGS (electronic)
	J. R. Hall	NRC NRR Senior Project Manager (electronic)
	M. A. Brown	NRC Senior Resident Inspector for PVNGS

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • San Onofre • South Texas • Wolf Creek

TE22
NRR

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Palo Verde Nuclear Generating Station (PVNGS) Unit 1

2. DOCKET NUMBER

05000528

3. PAGE

1 OF 5

4. TITLE

Technical Specification LCO 3.1.7 Incorrect PDIL Setpoint Values

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
04	19	2005	2012	- 001 -	00	05	7	2012	(PVNGS) Unit 2	05000529
									(PVNGS) Unit 3	05000530

9. OPERATING MODE
1/1/1

10. POWER LEVEL
100/100/95

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME

Mark McGhee, Operations Support Manager, Regulatory Affairs

TELEPHONE NUMBER (Include Area Code)

623-393-4972

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On March 8, 2012, at approximately 1752 Mountain Standard Time, all Palo Verde units entered Technical Specification (TS) Limiting Condition for Operation (LCO) 3.1.7 Regulating Control Element Assembly (CEA) Insertion Limits, Condition D, when the power dependent insertion limit (PDIL) alarm setpoint was determined to be non-conservative. The value for the PDIL alarm setpoint had been incorrect since April 19, 2005, when the specified regulating group CEAs fully withdrawn position was raised from greater than or equal to (\geq) 144.47 inches to \geq 147.75 inches, and the PDIL alarm setpoint remained at 144 inches.

As an immediate corrective action, the PDIL alarm setpoint for all three units was changed to 147 inches. This corrective action allowed each unit to exit TS LCO 3.1.7 on March 11, 2012.

The cause of this event was determined to be the implementation of a change that was made to the specified CEA fully withdrawn position in the Core Operating Limits Report (COLR) without making the corresponding change to the PDIL alarm setpoint.

No similar events have been reported to the NRC in the prior three years.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station (PVNGS) Unit 1	05000528	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 5
		2012 --	001 --	00	

NARRATIVE

All times are Mountain Standard Time and approximate unless otherwise indicated.

1. REPORTING REQUIREMENT(S):

This LER is being submitted pursuant to 10 CFR 50.73 (a)(2)(i)(B) as an operation prohibited by Technical Specification (TS) 3.1.7, Regulating Control Element Assembly (CEA) Insertion Limits. The Limiting Condition for Operation (LCO) for this TS requires that the power dependent insertion limit (PDIL) alarm circuit to be OPERABLE. If the Required Action and associated Completion Time are not met for LCO 3.1.7 Condition D, then LCO 3.1.7 Condition E requires that the plant be in Mode 3 within 6 hours. The PDIL alarm setpoint was incorrectly set and the PDIL alarm circuit was determined to be inoperable since April 19, 2005, which exceeds the required action completion time.

2. DESCRIPTION OF STRUCTURE(S), SYSTEM(S) AND COMPONENT(S):

The control element drive mechanism control system (CEDMCS) (EIS: AA) provides control signals and motive power to the coils of the magnetic jacks in the 89 control element drive mechanisms (CEDMs) (EIS: AA) which move, hold, and release the CEAs (EIS: AA). The CEAs absorb neutrons to control reactivity.

CEAs are grouped in shutdown, regulating, and part-strength groups. Shutdown CEA groups remain fully withdrawn during reactor operation to ensure the capability to rapidly shutdown the reactor during anticipated operational occurrences evaluated in the plant safety analysis. Regulating and part-strength CEA groups are positioned to control core flux distribution and reactivity and are normally fully withdrawn during power operations. Limits on regulating CEA group insertion have been established and all CEA positions are monitored and controlled during power operation to ensure that power distribution and reactivity limits related to power peaking, ejected CEA worth, reactivity insertion rate, and shutdown margin are preserved. These insertion limits are referred to as the PDILs.

Core operating limits for each reload cycle are established and documented in the Core Operating Limits Report (COLR) as required by TS 5.6.5. PDIL Alarm circuits are provided to ensure the operating limits on allowable CEA insertion as a function of reactor power are maintained consistent with the requirements of the COLR. The PDIL alarm circuit alerts operators to CEAs that are outside required insertion limits. In response, operators ensure either CEA positions are restored or actions are taken to limit thermal power or thermal power increases as specified in TSs. The PDIL alarm circuit is not credited in the safety analysis and it does not directly control any of the safety functions in the safety analysis.

For an inoperable PDIL alarm circuit, TS LCO 3.1.7 Condition D requires verification that each regulating CEA group position is within its insertion limits within one hour of discovery and every four hours thereafter, until the PDIL alarm circuit is restored.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station (PVNGS) Unit 1	05000528	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 5
		2012 --	001 --	00	

NARRATIVE

The PDIL alarms are generated using the PDIL alarm setpoint programmed into the software of the plant monitoring system (PMS) computers. The PMS is comprised of two independent computer systems designated as the plant computer (PC) and the core monitoring computer (CMC). The PC and CMC functions related to the PDIL alarm circuits are fully redundant and each provides the same alarm capabilities.

CEA position indication is provided by three separate instruments for each of the CEAs. Two safety-related reed switch position transmitter (RSPT) indications and one computer generated pulse counter position indication are provided for each CEA. The RSPTs measure CEA position via magnetically actuated reed switches located on the CEDM housing and input to the plant protection system to provide safety related reactor protection system functions and CEA position indications in the Control Room. The PMS computers generate pulse counter CEA position indications by counting CEDM coil movement electrical pulses at the CEDMCS cabinets and provide indications and alarms in the control room and CEA positions for use in the core operating limit supervisory system (COLSS) calculations. Each pulse that is counted indicates 0.75 inches of CEA travel. The pulse counted CEA positions are used as inputs for the PDIL alarm circuits.

3. INITIAL PLANT CONDITIONS:

On March 8, 2012, all three units were in Mode 1, with Units 1 and 2 operating at 100 percent power and Unit 3 at 95 percent power during power coast down for a scheduled refueling outage. There were no structures, systems, or components inoperable at the time of the event that contributed to the event.

4. EVENT DESCRIPTION:

On March 8, 2012, at 1752, all Palo Verde units entered TS LCO 3.1.7, Regulating CEA Insertion Limits, Condition D, when the PDIL alarm setpoint for each unit was determined to be non-conservative.

During an investigation of an event described in LER 2-2012-001, Palo Verde personnel determined that the Regulating CEA PDIL alarm setpoint was incorrectly set at 144 inches since April 19, 2005, when the specified CEA fully withdrawn position was changed from greater than or equal to (\geq) 144.75 inches to \geq 147.75 inches.

Changes which altered the fuel configuration began in 1993, when the fuel inconel spacer grid assembly was replaced with a redesigned inconel spacer grid assembly called the Guardian grid. The Guardian grid fuel assembly was installed in Unit 1 during Cycle 5, Unit 2 during Cycle 6 and Unit 3 during Cycle 5. The Guardian grid raised the active fuel region by 1.589 inches. The reload analysis report (RAR) for those fuel cycles concluded that the

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station (PVNGS) Unit 1	05000528	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 5
		2012 --	001 --	00	

NARRATIVE

change in the location of the active fuel region relative to the core internals would not impact the results for the various accident analyses and no changes to the CEA Insertion Limits were required with the installation of the new Guardian grid fuel assembly.

On April 19, 2005, changes were made to the COLR figures for CEA Insertion Limits versus Thermal Power to revise the CEA Group insertion limits by changing the fully withdrawn position to ≥ 147.75 inches. The change added a note to the COLR figures which specified the fully withdrawn CEA position as ≥ 147.75 inches. Corresponding changes should have been made to the PDIL alarm setpoint; however, the PDIL alarm setpoint remained at 144 inches. Since the PDIL alarm setpoint remained unchanged, the PDIL alarm circuit would not provide operators with an alarm when the limit was exceeded.

Corrective actions were performed in all three units to change the PDIL alarm setpoint to 147 inches, which allowed each unit to exit TS LCO 3.1.7 Condition D, on March 11, 2012.

5. ASSESSMENT OF SAFETY CONSEQUENCES:

This condition did not adversely affect plant safety or the health and safety of the public. The condition did not result in any challenges to the fission product barriers or result in any releases of radioactive materials. The safety limits for Departure from Nucleate Boiling Ratio (DNBR) and fuel peak centerline temperature were not exceeded as a result of this event.

An engineering evaluation was performed with the minimum PDIL alarm setpoint of 144 inches to determine the impact on CEA scram worth and the potential impact to the safety analysis, as well as the impact to flux distribution on core power peaking. The evaluation determined that the impact of the incorrect PDIL alarm setpoint was bounded by the assumptions made in the safety analyses with respect to CEA positions at 144.75 inches vs. the specified COLR limit of 147.75 inches and did not impact the safe operation of the units. Therefore, there were no actual adverse safety consequences as a result of this condition.

Additionally, the condition did not impact the safety related plant protection system functions performed by the core protection calculators (CPCs) and CEA Calculators (CEACs) which provide the Linear Heat Rate and DNBR reactor trip functions. Based upon these conclusions, the incorrect PDIL alarm setpoint did not adversely affect plant safety or the health and safety of the public.

The CEA safety functions were not affected by the inoperable PDIL alarm circuits. The circuits provide an alarm function only and do not fulfill a safety function credited in the safety analysis. Therefore, this event would not have prevented the fulfillment of a safety function to safely shutdown the reactor and did not result in a safety system functional failure as described by 10 CFR 50.73(a)(2)(v).

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station (PVNGS) Unit 1	05000528	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5
		2012 --	001 --	00	

NARRATIVE

6. CAUSE OF THE EVENT:

The cause of the event was a failure to revise the PDIL alarm setpoint in the software for the CMC and PC computers following changes to the COLR requirements which specified the fully withdrawn position for regulating CEAs.

The root cause for failing to change the PDIL alarm setpoint was determined to be the figures for the Core Operating Limits Report (COLR) were not directly tied to any basis document.

Contributing to this event was the lack of clear procedural guidance for making COLR changes.

7. CORRECTIVE ACTIONS:

As an immediate corrective action, PDIL alarm setpoint in the software for the CMC and PC for all three units were changed to 147 inches for the PDIL. This corrective action allowed each unit to exit TS LCO 3.1.7 on March 11, 2012.

Additionally, the following corrective actions are planned:

- Develop and institute a Safety Analysis Basis Document (SABD) for the COLR.
- Revise Setpoint Checklist SABD (SABD-5.04.06) to include the checks on PMS PDIL files.
- Enhance procedural guidance for COLR changes.

8. PREVIOUS SIMILAR EVENTS:

No prior similar events were identified in which PDIL alarm circuits were inoperable because changes to the COLR were not incorporated into the PDIL alarm setpoint.