



**Entergy Operations, Inc.**  
River Bend Station  
5485 U.S. Highway 61N  
St. Francisville, LA 70775  
Tel 225 381 4157  
Fax 225 635 5068  
dlorfin@entergy.com

**David N. Lorfing**  
Manager-Licensing

RBG-47104

January 5, 2011

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Subject: Licensee Event Report 50-458 / 10-004-00  
River Bend Station – Unit 1  
Docket No. 50-458  
License No. NPF-47

File No. G9.5

RBF1-10-0192

Dear Sir or Madam:

In accordance with 10CFR50.73, enclosed is the subject Licensee Event Report.  
This document contains no commitments. If you have any questions, please contact  
me at 225-381-4157.

Sincerely,

A handwritten signature in cursive script, appearing to read "David N. Lorfing".

David N. Lorfing  
Manager – Licensing

Enclosure

IE22  
NRR

Licensee Event Report 50-458 / 10-004-00  
January 5, 2011  
RBG-47104  
RBF1-10-0192  
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission  
Region IV  
612 East Lamar Blvd., Suite 400  
Arlington, TX 76011-4125

NRC Sr. Resident Inspector  
P. O. Box 1050  
St. Francisville, LA 70775

INPO Records Center  
E-Mail (MS Word format)

Mr. Jim Calloway  
Public Utility Commission of Texas  
1701 N. Congress Ave.  
Austin, TX 78711-3326

Mr. Jeffrey P. Meyers  
Louisiana Department of Environmental Quality  
Attn: OEC-ERSD  
P.O. Box 4312  
Baton Rouge, LA 70821-4312

**LICENSEE EVENT REPORT (LER)**(See reverse for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects.resource@nrc.gov](mailto:infocollects.resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

**1. FACILITY NAME**

River Bend Station – Unit 1

**2. DOCKET NUMBER**

05000 - 458

**3. PAGE**

1 OF 3

**4. TITLE**

High Pressure Core Spray System Inoperable Due to Failed Motor Oil Reservoir Drain Plug

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	07	2010	2010-004-00			01	05	2011	FACILITY NAME	DOCKET NUMBER <b>05000</b>
									FACILITY NAME	DOCKET NUMBER <b>05000</b>

**9. OPERATING MODE**

1

**11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)**

- |   |   |   |  |
|---|---|---|--|
| <input type="checkbox"/> 20.2201(b)         | <input type="checkbox"/> 20.2203(a)(3)(i)   | <input type="checkbox"/> 50.73(a)(2)(i)(C)            | <input type="checkbox"/> 50.73(a)(2)(vii)        |
| <input type="checkbox"/> 20.2201(d)         | <input type="checkbox"/> 20.2203(a)(3)(ii)  | <input type="checkbox"/> 50.73(a)(2)(ii)(A)           | <input type="checkbox"/> 50.73(a)(2)(viii)(A)    |
| <input type="checkbox"/> 20.2203(a)(1)      | <input type="checkbox"/> 20.2203(a)(4)      | <input type="checkbox"/> 50.73(a)(2)(ii)(B)           | <input type="checkbox"/> 50.73(a)(2)(viii)(B)    |
| <input type="checkbox"/> 20.2203(a)(2)(i)   | <input type="checkbox"/> 50.36(c)(1)(i)(A)  | <input type="checkbox"/> 50.73(a)(2)(iii)             | <input type="checkbox"/> 50.73(a)(2)(ix)(A)      |
| <input type="checkbox"/> 20.2203(a)(2)(ii)  | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(iv)(A)           | <input type="checkbox"/> 50.73(a)(2)(x)          |
| <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2)        | <input type="checkbox"/> 50.73(a)(2)(v)(A)            | <input type="checkbox"/> 73.71(a)(4)             |
| <input type="checkbox"/> 20.2203(a)(2)(iv)  | <input type="checkbox"/> 50.46(a)(3)(ii)    | <input type="checkbox"/> 50.73(a)(2)(v)(B)            | <input type="checkbox"/> 73.71(a)(5)             |
| <input type="checkbox"/> 20.2203(a)(2)(v)   | <input type="checkbox"/> 50.73(a)(2)(i)(A)  | <input type="checkbox"/> 50.73(a)(2)(v)(C)            | <input type="checkbox"/> OTHER                   |
| <input type="checkbox"/> 20.2203(a)(2)(vi)  | <input type="checkbox"/> 50.73(a)(2)(i)(B)  | <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D) | Specify in Abstract below<br>or in NRC Form 366A |

**10. POWER LEVEL**

100

**12. LICENSEE CONTACT FOR THIS LER**

## FACILITY NAME

David N. Lorfing, Manager – Licensing

## TELEPHONE NUMBER (Include Area Code)

225-381-4157

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
E	BG	(see text)	(see text)	YES					

**14. SUPPLEMENTAL REPORT EXPECTED**☒ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☐ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR
03	03	2011

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On November 7, 2010, at 10:23 a.m. CDT, with the plant operating at 100 percent power, the high pressure core spray (HPCS) (BG) pump was declared inoperable following the discovery of an oil leak on the pump motor (\*\*MO\*\*). The source of the oil leak was found to be a cracked drain plug on the lower motor bearing oil reservoir. The oil plug was replaced, and the HPCS system was restored to its standby condition at 7:40 p.m. CDT that same day. This is a preliminary report, as the causal analysis of this event is not yet complete. A supplement to this report will be provided by March 3, 2011.

This condition is being reported in accordance with 10CFR50.73(a)(2)(v)(D) as the loss of a system needed to mitigate the consequences of an accident. No other safety-related systems were out of service during the time that the HPCS system was inoperable. This event was of minimal significance with respect to the health and safety of the public.

# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station – Unit 1	05000 -458	YEAR	SEQUENTIAL NUMBER	REV. NO.	2 OF 3
		2010 -- 004 -- 00			

## REPORTED CONDITION

On November 7, 2010, at 10:23 a.m. CDT, with the plant operating at 100 percent power, the high pressure core spray (HPCS) (BG) pump was declared inoperable following the discovery of an oil leak on the pump motor (\*\*MO\*\*). This condition is being reported in accordance with 10CFR50.73(a)(2)(v)(D) as the loss of a system needed to mitigate the consequences of an accident.

The source of the oil leak was found to be a cracked drain plug on the lower motor bearing oil reservoir. The oil plug was replaced, and the HPCS system was restored to its standby condition at 7:40 p.m. CDT that same day. No other safety-related systems were out of service during the time that the HPCS system was inoperable.

## INVESTIGATION

On July 14, 2010, a minor, unquantifiable oil leak was found on the lower reservoir drain plug of the HPCS pump. The leak appeared only as oil sheen around the drain plug. On August 7, the leak was quantified as approximately 1 drop every 3 minutes. The leakage rate was determined to be stable, and it was concluded that the pump remained capable of performing its safety function.

The approximate timeline of subsequent activities concerning this event, developed from documentation and from interviews with the operators and maintenance technicians, is as follows. Oil was added to the reservoir on September 13. The HPCS system was operated on September 20 for scheduled surveillance testing, and no increase in the leakage rate was seen. Oil was again added to the reservoir on October 26. No further oil additions were made until November 7. Twice-weekly inspections of the pump by the operators confirmed that the leakage had not increased. (Operators also perform a general inspection of the pump room each shift, checking for oil accumulation on equipment and other conditions. Those inspections continued to be satisfactory.) On October 29, the operators wrapped an absorbent pad around the plug to eliminate the need to clean up oil around the pump pedestal, and to eliminate the potential slipping hazard. These pads were subsequently replaced three times prior to November 7 (the last replacement was on November 5), and on each occasion, the oil leak rate had not increased.

On November 7, the operator removed the absorbent pad, and found that the leak had increased to a small stream approximately one-tenth of an inch in diameter. The HPCS pump was removed from service, and the oil drain plug was replaced with a new part.

## IMMEDIATE CORRECTIVE ACTIONS

The failed drain plug was replaced, and the HPCS pump was restored to service at 7:40 p.m. CDT on the same day. At the time of this event, no similar leaks had been reported on the other

**LICENSEE EVENT REPORT (LER)**  
**CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
River Bend Station – Unit 1	05000 -458	YEAR	SEQUENTIAL NUMBER	REV. NO.	3 OF 3
		2010 -- 004 -- 00			

emergency core cooling system (ECCS) pumps, which share a common drain plug design with the HPCS pump.

**CAUSAL ANALYSIS and CORRECTIVE ACTIONS TO PREVENT RECURRENCE**

The investigation of this event is ongoing. The final results of the causal analysis will be provided in a supplement to this report.

**PREVIOUS OCCURRENCE EVALUATION**

There have been no similar events reported by RBS since January 1, 2005.

**SAFETY SIGNIFICANCE**

Two of three divisions of ECCS are required for the RBS loss of coolant accident analyses. While HPCS was out of service, Division 1 and Division 2 ECCS systems and the automatic depressurization system were available, and would have met the ECCS performance criteria of 10CFR50.46. The HPCS system was returned to service within the time limit of the Required Action in the plant's Technical Specifications. This event was of minimal safety significance with respect to the health and safety of the public.

(NOTE: Energy Industry Component Identification codes are annotated as (\*\*XX\*\*).)