



**ENERGY
NORTHWEST**

W. Grover Hettel
Columbia Generating Station
P.O. Box 968, PE23
Richland, WA 99352-0968
Ph. 509.377.8311 | F. 509.377.4150
wghettel@energy-northwest.com

May 2, 2014
GO2-14-072

10 CFR 50.73

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Subject: **COLUMBIA GENERATING STATION, DOCKET NO. 50-397
LICENSEE EVENT REPORT NO. 2014-002-00**

Dear Sir or Madam:

Transmitted herewith is Licensee Event Report No. 2014-002-00 for Columbia Generating Station. This report is submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B).

There are no commitments being made to the NRC by this letter. If you have any questions or require additional information, please contact Mr. J. R. Trautvetter, Regulatory Compliance Supervisor, at (509) 377-4337.

Respectfully,

W. G. Hettel
Vice President, Operations

Enclosure: Licensee Event Report 2014-002-00

cc: NRC Region IV Administrator
NRC NRR Project Manager
NRC Senior Resident Inspector/988C
M.A. Jones – BPA/1399
W.A. Horin – Winston & Strawn

IE22
NRR

LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of
digits/characters for each block).

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NE08-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Columbia Generating Station

2. DOCKET NUMBER

05000 397

3. PAGE

1 OF 4

4. TITLE

Unanalyzed Condition Resulting from Direct Current (DC) Ammeter Circuits Without Overcurrent Protection

5. EVENT DATE

MONTH	DAY	YEAR
03	11	2014

6. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2014	002	00

7. REPORT DATE

MONTH	DAY	YEAR
05	02	2014

8. OTHER FACILITIES INVOLVED

FACILITY NAME	DOCKET NUMBER
	05000

9. OPERATING MODE

1

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

10. POWER LEVEL

100

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME

Diego Suarez

TELEPHONE NUMBER (Include Area Code)

509-377-8652

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO15. EXPECTED
SUBMISSION
DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On March 11, 2014, with the plant operating in Mode 1 at 100 percent power, an extent of condition evaluation, resulting from a review of nuclear industry operational experience, identified areas in the plant that may be susceptible to secondary fires due to hot shorts from unfused ammeters in the Direct Current distribution system. In the postulated event, a fire in the station cable raceway, cable spreading room, or Control Room could cause a ground loop through unprotected ammeter wiring or control circuit wiring and potentially result in excessive current flow and heating to the point of causing a secondary fire. The postulated secondary fire could affect the availability of equipment needed to place the plant in a safe shutdown condition. This scenario has not been analyzed in accordance with 10 CFR 50 Appendix R commitments. Compensatory hourly fire watch measures have been put in place and will remain in place for the affected areas of the plant until analyses are completed and modifications are put in place to eliminate the concern. The condition affects 14 Class 1E DC ammeters and 2 non-Class 1E DC ammeters in 3 plant divisions. The cause of the unfused DC ammeter circuits is that the original plant design did not include overcurrent protection features to isolate fault current in the current flow path from the shunts for each direct current battery or charger to the remote ammeter circuits in the Control Room. The corrective action plant modification will provide fuses to the unprotected ammeters.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocoll@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Columbia Generating Station	2. DOCKET 05000 397	6. LER NUMBER <table border="1"><tr><td data-bbox="860 386 987 449">YEAR</td><td data-bbox="987 386 1115 449">SEQUENTIAL NUMBER</td><td data-bbox="1115 386 1235 449">REV NO.</td></tr><tr><td data-bbox="860 449 987 497">2014</td><td data-bbox="987 449 1115 497">- 002</td><td data-bbox="1115 449 1235 497">- 00</td></tr></table>	YEAR	SEQUENTIAL NUMBER	REV NO.	2014	- 002	- 00	3. PAGE 2 OF 4
YEAR	SEQUENTIAL NUMBER	REV NO.							
2014	- 002	- 00							

NARRATIVE**Background Information**

Operational experience available from INPO on December 10, 2013 through report IER-L4-13-54, "Unprotected Direct Current Ammeters Result in Unanalyzed Conditions," involved Control Room direct current (DC) ammeters [II] lacking overcurrent protection in their original plant wiring designs, which significantly degraded plant safety. Specifically, wiring designs for the DC ammeter circuits in the Control Room often included a shunt [17] in the current flow path from each DC battery [BTRY] or charger [BYC]. Overcurrent protective devices were not used to isolate fault current in the ammeter wiring attached to the shunts at stations that reported this condition. A postulated fire in the station cable raceway, cable spreading room, or Control Room could cause an ammeter wire short to ground. If another DC wire from the opposite polarity on the same DC source shorted to ground, fault current would flow through the unprotected ammeter cable with the potential for overheating and initiating a secondary fire. Either the secondary fire or the ground condition could adversely affect safe shutdown equipment and hinder the ability of the plant to safely shut down as committed to 10 CFR 50 Appendix R.

Identification of Occurrence and Plant Conditions Prior to Occurrence

The identification of specific applicability to Columbia of the unfused DC ammeters condition occurred on February 27, 2014 after issuance of an extent of condition report; however, analysis to determine impact to safety systems was not completed until March 11, 2014. The NRC was notified through Event Notification 49898 on the same date, in accordance with 10 CFR 50.72(b)(3)(ii)(B) reporting requirements for the unanalyzed condition. The plant was operating in Mode 1 at 100 percent power, within design temperature and pressure conditions, and there were no structures, systems, or components that were inoperable at the start of the event and that contributed to the event.

Event Analysis and Extent of Condition

Plant wiring design drawings for the DC Electrical System ammeter circuits that utilize a shunt in the current flow path for each DC battery or charger were analyzed to determine affected components.

The extent of condition analysis identified the following Columbia components that provide remote monitoring or Control Room indication associated with 24 VDC, 125 VDC, or 250 VDC circuits as being vulnerable to the condition:

- Division 1: a total of six ammeters that provide operator indication for associated battery or battery charger current output, and remote monitoring of current flow.
- Division 2: a total of six ammeters that provide operator indication for associated battery or battery charger current output, and remote monitoring of current flow.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Columbia Generating Station	05000 397	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 4
		2014 -	002	- 00	

NARRATIVE

- Division 3: a total of two ammeters that provide operator indication for associated battery or battery charger current output, and remote monitoring of current flow.

DC ammeter circuitry cables for two of the Division 2 ammeters are non-safety related feeding their corresponding non-safety related DC ammeter. All other DC ammeter circuitry divisional cables referenced above are safety-related in class 1E raceways feeding their respective safety-related DC ammeters.

Failures and Errors

There were no safety system or safety component failures or errors resulting from this condition.

Safety System Responses

The plant's safety systems that could have been affected by this condition have not experienced a condition-related abnormal response. The condition has not resulted in declarations of system inoperabilities at the plant.

Cause of Occurrence

This condition occurred because the original plant wiring design did not include overcurrent protection features to isolate fault current in the current flow path from the shunts for each DC station battery and/or charger to the remote ammeter circuits in the Control Room. The postulated event requires two concurrent extremely low resistance (hard) grounds; one on the positive side of the battery through the ammeter circuit wiring routed to the Control Room and one on the negative side of the battery. Because this is a very low probability event, it was likely not considered in the original design.

Assessment of Safety Consequences

The discovered condition is being reported under criterion in 10 CFR 50.73(a)(2)(ii)(B) – Any event or condition that results in the nuclear plant being in an unanalyzed condition that significantly degraded plant safety.

There have been no actual adverse nuclear, radiological, or industrial safety consequences resulting from the reported condition. The administrative controls of the Fire Protection Program, the availability of fire detection and suppression systems, the established compensatory measures, and a trained on-site fire brigade all combine to mitigate the event postulated in the scenario until permanent corrective actions described below are implemented.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Columbia Generating Station	05000 397	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 4
		2014 -	002	- 00	

NARRATIVE

Corrective Actions

Due to the complexity of the engineering review that is being conducted towards mitigation of this condition, a conservative decision was made to establish hourly fire tours for the fire areas of concern. Barrier Impairment measures have been implemented per established station procedures.

In addition to the immediate compensatory action consisting of hourly fire watches and establishment of barrier impairments in the affected areas, an engineering change is being developed to modify the affected DC electrical circuits to comply with the commitments of 10 CFR 50 Appendix R. Specifically, the scope of the engineering change will modify the existing DC ammeter circuits to include fuses, credited as overcurrent protective devices, to ensure that the postulated fire scenario does not impact the plant safety systems. Ensuing corrective action implementation work orders will include design changes, analysis updates, and physical work orders to bring affected DC circuits in full compliance with Columbia commitments to 10 CFR 50 Appendix R.

Previous Occurrences

Columbia has not experienced similar occurrences in the past, based on a review of LER historical records.