



**ENERGY  
NORTHWEST**

W. Grover Hettel  
Columbia Generating Station  
P.O. Box 968, PE23  
Richland, WA 99352-0968  
Ph. 509.377.8311 | F. 509.377.4150  
whettel@energy-northwest.com

November 19, 2012  
GO2-12-170

10 CFR 50.73

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555-0001

Subject: **COLUMBIA GENERATING STATION, DOCKET NO. 50-397  
LICENSEE EVENT REPORT NO. 2012-006-00**

Dear Sir or Madam:

Transmitted herewith is Licensee Event Report No. 2012-006-00 for Columbia Generating Station. This report is submitted pursuant to 10 CFR 50.73(a)(2)(v). The attached report discusses being in a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident.

There are no commitments being made to the NRC by this letter. If you have any questions or require additional information, please contact Mr. ZK Dunham at (509) 377-4735.

Respectfully,

WG Hettel  
Vice President, Operations

Attachment: Licensee Event Report 2012-006-00

cc: NRC Region IV Administrator  
NRC NRR Project Manager  
NRC Senior Resident Inspector/988C  
AJ Rapacz – BPA/1399  
WA Horin – Winston & Strawn

IE22  
NRR

<b>NRC FORM 366</b> <b>U.S. NUCLEAR REGULATORY COMMISSION</b> (10-2010)		<b>APPROVED BY OMB NO. 3150-0104</b> <b>EXPIRES 10/31/2013</b> Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to <a href="mailto:infocollects.resource@nrc.gov">infocollects.resource@nrc.gov</a> , and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.													
<b>LICENSEE EVENT REPORT (LER)</b> (See reverse for required number of digits/characters for each block)															
<b>1. FACILITY NAME</b> Columbia Generating Station		<b>2. DOCKET NUMBER</b> <b>05000397</b>	<b>3. PAGE</b> <b>1 OF 3</b>												
<b>4. TITLE</b> Both Divisions of SDC Isolation Valves Made Inoperable															
<b>5. EVENT DATE</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th style="width:33%;">MONTH</th> <th style="width:33%;">DAY</th> <th style="width:33%;">YEAR</th> </tr> <tr> <td style="text-align: center;">09</td> <td style="text-align: center;">19</td> <td style="text-align: center;">2012</td> </tr> </table>		MONTH	DAY	YEAR	09	19	2012	<b>6. LER NUMBER</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th style="width:33%;">YEAR</th> <th style="width:33%;">SEQUENTIAL NUMBER</th> <th style="width:33%;">REV NO.</th> </tr> <tr> <td colspan="3" style="text-align: center;">2012 - 006 - 0</td> </tr> </table>		YEAR	SEQUENTIAL NUMBER	REV NO.	2012 - 006 - 0		
MONTH	DAY	YEAR													
09	19	2012													
YEAR	SEQUENTIAL NUMBER	REV NO.													
2012 - 006 - 0															
		<b>7. REPORT DATE</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th style="width:33%;">MONTH</th> <th style="width:33%;">DAY</th> <th style="width:33%;">YEAR</th> </tr> <tr> <td style="text-align: center;">11</td> <td style="text-align: center;">19</td> <td style="text-align: center;">2012</td> </tr> </table>		MONTH	DAY	YEAR	11	19	2012						
MONTH	DAY	YEAR													
11	19	2012													
		<b>8. OTHER FACILITIES INVOLVED</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th style="width:60%;">FACILITY NAME</th> <th style="width:40%;">DOCKET NUMBER</th> </tr> <tr> <td></td> <td style="text-align: center;"><b>05000</b></td> </tr> <tr> <td></td> <td style="text-align: center;"><b>05000</b></td> </tr> </table>		FACILITY NAME	DOCKET NUMBER		<b>05000</b>		<b>05000</b>						
FACILITY NAME	DOCKET NUMBER														
	<b>05000</b>														
	<b>05000</b>														
<b>9. OPERATING MODE</b> 1		<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §:</b> <i>(Check all that apply)</i>													
<b>10. POWER LEVEL</b> 100		<table style="width:100%;"> <tr> <td style="width:25%; vertical-align: top;"> <input type="checkbox"/> 20.2201(b)  <input type="checkbox"/> 20.2201(d)  <input type="checkbox"/> 20.2203(a)(1)  <input type="checkbox"/> 20.2203(a)(2)(i)  <input type="checkbox"/> 20.2203(a)(2)(ii)  <input type="checkbox"/> 20.2203(a)(2)(iii)  <input type="checkbox"/> 20.2203(a)(2)(iv)  <input type="checkbox"/> 20.2203(a)(2)(v)  <input type="checkbox"/> 20.2203(a)(2)(vi)         </td> <td style="width:25%; vertical-align: top;"> <input type="checkbox"/> 20.2203(a)(3)(i)  <input type="checkbox"/> 20.2203(a)(3)(ii)  <input type="checkbox"/> 20.2203(a)(4)  <input type="checkbox"/> 50.36(c)(1)(i)(A)  <input type="checkbox"/> 50.36(c)(1)(ii)(A)  <input type="checkbox"/> 50.36(c)(2)  <input type="checkbox"/> 50.46(a)(3)(ii)  <input type="checkbox"/> 50.73(a)(2)(i)(A)  <input type="checkbox"/> 50.73(a)(2)(i)(B)         </td> <td style="width:25%; vertical-align: top;"> <input type="checkbox"/> 50.73(a)(2)(i)(C)  <input type="checkbox"/> 50.73(a)(2)(ii)(A)  <input type="checkbox"/> 50.73(a)(2)(ii)(B)  <input type="checkbox"/> 50.73(a)(2)(iii)  <input type="checkbox"/> 50.73(a)(2)(iv)(A)  <input type="checkbox"/> 50.73(a)(2)(v)(A)  <input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)  <input type="checkbox"/> 50.73(a)(2)(v)(C)  <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)         </td> <td style="width:25%; vertical-align: top;"> <input type="checkbox"/> 50.73(a)(2)(vii)  <input type="checkbox"/> 50.73(a)(2)(viii)(A)  <input type="checkbox"/> 50.73(a)(2)(viii)(B)  <input type="checkbox"/> 50.73(a)(2)(ix)(A)  <input type="checkbox"/> 50.73(a)(2)(x)  <input type="checkbox"/> 73.71(a)(4)  <input type="checkbox"/> 73.71(a)(5)  <input type="checkbox"/> OTHER  <i>Specify in Abstract below or in NRC Form 366A</i> </td> </tr> </table>		<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input checked="" type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(ix)(A) <input type="checkbox"/> 50.73(a)(2)(x) <input type="checkbox"/> 73.71(a)(4) <input type="checkbox"/> 73.71(a)(5) <input type="checkbox"/> OTHER <i>Specify in Abstract below or in NRC Form 366A</i>								
<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input checked="" type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(ix)(A) <input type="checkbox"/> 50.73(a)(2)(x) <input type="checkbox"/> 73.71(a)(4) <input type="checkbox"/> 73.71(a)(5) <input type="checkbox"/> OTHER <i>Specify in Abstract below or in NRC Form 366A</i>												
<b>12. LICENSEE CONTACT FOR THIS LER</b>															
FACILITY NAME Motley Hedges		TELEPHONE NUMBER <i>(Include Area Code)</i> 509-377-8277													
<b>13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT</b>															
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX		CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX					
<b>14. SUPPLEMENTAL REPORT EXPECTED</b>						<b>15. EXPECTED SUBMISSION DATE</b>									
<input checked="" type="checkbox"/> <b>YES</b> <i>(If yes, complete 15. EXPECTED SUBMISSION DATE)</i>						<input type="checkbox"/> <b>NO</b>									
						MONTH		DAY		YEAR					
						01		21		2013					
<b>ABSTRACT</b> <i>(Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)</i> <p>On September 19, 2012, Energy Northwest (EN) identified that both divisions of Residual Heat Removal (RHR) Shutdown Cooling (SDC) Reactor Vessel isolation valves were inappropriately made inoperable at the same time on multiple occasions in support of maintenance and surveillance testing during the 2011 refueling outage (R-20). This planned inoperability of the SDC isolation valves was performed using procedure SOP-RHR-SDC-BYPASS. SOP-RHR-SDC-BYPASS contains the specific steps for preventing the closure of each of the SDC isolation valves and the subsequent restoration steps. SOP-RHR-SDC-BYPASS did not contain guidance to allow both divisions SDC isolation valves to be inoperable at the same time. Since both divisions of SDC isolation valves were made inoperable without procedural guidance, this is being reported as a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident.</p> <p>An evaluation in accordance with the corrective action program is currently in progress. A supplemental report will be submitted to add additional details concerning the evaluation's conclusions and corrective actions.</p>															

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Columbia Generating Station	05000397	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3
		2012 - 006 - 0			

**NARRATIVE**

**Plant Conditions:**

**Event Description:**

On September 19, 2012, Energy Northwest (EN) identified that both divisions of Residual Heat Removal (RHR) Shutdown Cooling (SDC) Reactor Vessel isolation valves were inappropriately made inoperable at the same time on multiple occasions in support of maintenance and surveillance testing during the 2011 refueling outage (R-20). This issue was identified and entered into the Columbia Generating Station (Columbia) corrective action program following review of the NRC Operating Experience Smart Sample (OpESS) 2012/02, Revision 1. All required technical specification conditions for inoperable primary containment isolation valves were entered when the valves were made inoperable, and compliance with actions was maintained. No operations with a potential to drain the reactor vessel were in progress. Columbia was in Mode 5 with the vessel flooded up. During R-20, EN implemented a plant modification to change the Group 1 isolation valves reactor water level signal from level 2 to level 1. The NRC granted permission for this change to technical specifications (TS) in a letter dated August 18, 2009 (TAC NO. MD9598). This planned inoperability of the SDC isolation valves, in support of the maintenance and surveillance activities associated with the modification to change the isolation signal from level 2 to level 1, was performed using procedure SOP-RHR-SDC-BYPASS. SOP-RHR-SDC-BYPASS contains the specific steps for preventing the closure of each of the SDC isolation valves and the subsequent restoration steps. SOP-RHR-SDC-BYPASS did not contain guidance to allow both divisions of SDC isolation valves to be inoperable at the same time. Since both divisions of the SDC isolation valves were made inoperable and the approved procedure did not provide specific guidance for removal of both divisions at the same time, this is being reported as a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident. This condition is reportable under 10 CFR 50.73(a)(2)(v)(B) and 50.73(a)(2)(v)(D).

**Extent of Condition:**

An extent of condition review was performed. The only instances of both divisions of RHR SDC isolation valves being inoperable at the same time was during R-20. There were multiple instances in which this occurred in R-20.

**Immediate Corrective Action:**

No immediate corrective action was required.

**Cause:**

The correction action process to determine a cause is still in progress. This information will be provided in the supplemental report.

**Operating Experience & Previous Occurrences:**

This had not previously occurred at Columbia.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Columbia Generating Station	05000397	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3
		2012 - 006 - 0			

**NARRATIVE**

**Further Corrective Actions:**

The correction action process to determine corrective actions is still in progress. This information will be provided in the supplemental report.

**Assessment of Safety Consequences:**

Each occurrence took place when the plant was in Mode 5 with the reactor vessel in a flooded condition. No operations with a potential to drain the vessel were in progress. The inoperability of the RHR SDC isolation valves was not due to equipment failure. If a loss of reactor level was detected, the isolation valves could be quickly restored to an operable condition. All required TS conditions were entered. Compliance with all TS actions was maintained. There was no significant impact on safety consequences.

**Energy Industry Identification System (EIIIS) Information**

EIIS codes are bracketed [] where applicable in the narrative.