

Omaha Public Power District
444 South 16th Street Mall
Omaha, NE 68102-2247

LIC-12-0149
October 15, 2012

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Reference: Docket No. 50-285

Subject: Licensee Event Report 2012-019, Revision 0, for the Fort Calhoun Station

Please find attached Licensee Event Report 2012-019, Revision 0, dated October 15, 2012. This report is being submitted pursuant to 10 CFR 50.73(a)(2)(v)(B).

No commitments are being made in this letter.

If you should have any questions, please contact me.

Sincerely,

Louis P. Cortopassi
Site Vice President and CNO

LPC/EPM /rjr

Attachment

c: E. E. Collins, Jr., NRC Regional Administrator, Region IV
L. E. Wilkins, NRC Project Manager
J. C. Kirkland, NRC Senior Resident Inspector

Employment with Equal Opportunity

IE22
NRK

LICENSEE EVENT REPORT (LER)(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimates to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollect@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

Fort Calhoun Station

2. DOCKET NUMBER

05000285

3. PAGE

1 OF 4

4. TITLE

Traveling Screen Sluice Gates Found with Dual Indication

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
08	14	2012	2012	019	0	10	15	2012		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																																							
5	<table border="0"><tr><td><input type="checkbox"/> 20.2201(b)</td><td><input type="checkbox"/> 20.2203(a)(3)(i)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td><td><input type="checkbox"/> 50.73(a)(2)(vii)</td></tr><tr><td><input type="checkbox"/> 20.2201(d)</td><td><input type="checkbox"/> 20.2203(a)(3)(ii)</td><td><input type="checkbox"/> 50.73(a)(2)(ii)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(1)</td><td><input type="checkbox"/> 20.2203(a)(4)</td><td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td><td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(i)</td><td><input type="checkbox"/> 50.38(c)(1)(i)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(iii)</td><td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(ii)</td><td><input type="checkbox"/> 50.38(c)(1)(ii)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(iv)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(x)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(iii)</td><td><input type="checkbox"/> 50.38(c)(2)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td><td><input type="checkbox"/> 73.71(a)(4)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(iv)</td><td><input type="checkbox"/> 50.48(a)(3)(ii)</td><td><input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)</td><td><input type="checkbox"/> 73.71(a)(5)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(v)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td><td><input type="checkbox"/> OTHER</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(vi)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(B)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td><td>Specify in Abstract below or in NRC Form 368A</td></tr></table>				<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.38(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.38(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.38(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.48(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 368A
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																					
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																					
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																					
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.38(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																					
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.38(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																					
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.38(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																					
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.48(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																					
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																					
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 368A																																					

12. LICENSEE CONTACT FOR THIS LER	
FACILITY NAME	TELEPHONE NUMBER (Include Area Code)
Erick Matzke	402-533-6855

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED		15. EXPECTED SUBMISSION DATE	
<input checked="" type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	MONTH	DAY
		02	15

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On August 14, 2012, at approximately 2100 hours Central Daylight Time, Operations was cycling all 6 traveling screen sluice gates when it was identified that traveling screen sluice gate CW-14E motor was stopping on high torque and provided indication that the gate was approximately 8 inches open. Traveling screen sluice gate CW-14C was also stopping on high torque and providing indication the gate was not fully closed. During a flooding event, these sluice gates are credited to fully close allowing control of the intake structure cell level with the raw water pumps. Cell level is maintained below elevation 1007-foot 6-inches. This is the point at which the raw water pump bay could become flooded causing a loss of raw water to the component cooling water heat exchangers. On August 25, 2012, divers removed the sediment and debris from all sluice gate bottoms returning the sluice gates' capability to be fully closed in the event of a design basis flood.

The apparent cause of the failure of the sluice gates to fully close was debris under the gates. A cause analysis is in process and when completed, this LER will be supplemented.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET	3. LER NUMBER			4. PAGE
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 4
		2012	- 019 -	0	

NARRATIVE


BACKGROUND

Fort Calhoun Station (FCS) is a two-loop reactor coolant system of Combustion Engineering (CE) design.

Four raw water pumps are installed in the intake structure pump house to provide screened river water to the component cooling heat exchangers.

Protection for the raw water pumps and their drives against floods is provided at three elevations. The pumps are permanently protected against any water level up to elevation 1,007.5 feet by the Class I concrete substructure of the intake building. Protection against the 1,009.5-foot and 1,014-foot floods is provided by gasketed steel closures at exterior doorway openings and the screen wash discharge trough. The water level inside the intake cells can be controlled by pre-positioning the exterior sluice gates (i.e., before floodwater reaches the elevation that prevents access to the sluice gate manual actuators) to severely restrict the inflow into the cells. Intake cell level is then controlled by varying the raw water pump(s) output to remove the inlet flow.

USAR Figure 9.8-1 is provided below for reference.



The basic safety related function of the raw water system is to provide a cooling medium for the component cooling water system. The raw water system also provides direct cooling for the following safety related components in the event that the component cooling water system is unavailable: the shutdown cooling heat exchangers, the high/low pressure safety injection pump bearing oil and seal coolers, the containment spray pump bearing oil and seal coolers, and the control room air conditioners.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 4
		2012	- 019	- 0	

NARRATIVE

The circulating water pumps, which take suction from the intake cells, have been secured for approximately 18 months, in part, creating a low flow condition and may be causing additional sediment to build-up.

Technical Specification (TS), Limiting Condition for Operation (LCO) 2.4, Containment Cooling, defines the minimum requirements for reactor criticality (except for low-temperature physics tests). The reactor may be made critical with one inoperable raw water pump; however, LCO action statements shall apply.

TS LCO, 2.16, River Level, provides the maximum river level, as measured at the intake structure, as 1009 feet for reactor shutdown and 1004.2 feet and rising as the level to institute the emergency plan to protect the plant.

EVENT DESCRIPTION

On August 14, 2012, at approximately 2100 hours Central Daylight Time, Operations was cycling all 6 traveling screen sluice gates when it was identified that traveling screen sluice gate (CW-14E) motor was stopping on high torque and provided indication that the gate was approximately 8 inches open. Traveling screen sluice gate (CW-14C) was also stopping on high torque and providing indication the gate was not fully closed. During a flooding event, these sluice gates are credited to fully close allowing control of the intake structure cell level with the raw water pumps. Cell level is maintained below elevation 1007-foot 6-inches. This is the point at which the raw water pump bay could become flooded causing a loss of raw water to the component cooling water heat exchangers. At the time of discovery, FCS was shutdown in Mode 5. In addition to the raw water pumps, the circulating water pumps take suction from the intake cells. These pumps have been secured for approximately 18 months, creating a low flow condition which may, in-part, be causing additional sediment to build-up where the sluice gates rest when closed.

On August 15, 2012, FCS engineers provided reasonable assurance that the indication was incorrect and that the sluice gates were closed. FCS does not have a TS delineating sluice gate operability. The functionality determination required that divers confirm that the sluice gates were closed. On August 25, 2012, divers documented the following gaps between the sluice gate bottom edge and the concrete resting floor:

- CW-14A: 1.5 inches
- CW-14B: 1 inch
- CW-14C: 1 inch
- CW-14D: 1 inch
- CW-14E: 3 inches
- CW-14F: 2.5 inches

On August 25, 2012, divers removed the sediment from all sluice gate bottoms and a 3-inch tree branch from CW-14E, returning the sluice gates' capability to be fully closed in the event of a design basis flood.

On September 17, 2012, this event was determined to be reportable under 10 CFR 70.73(a)(2)(v)(B), any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to remove residual heat.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 4
		2012	- 019	- 0	

NARRATIVE

CONCLUSION

The apparent cause of the failure of the sluice gates to fully close was debris under the gates. A cause analysis is in-process and when completed, this LER will be supplemented to include any additional causes that are identified.

CORRECTIVE ACTIONS

A preventive maintenance activity was previously created to cycle CW-14A/B/C/D/E/F through their full range of travel in ensure availability for flood mitigation. This activity is currently performed monthly and is performed to ensure the sluice gates perform their safety function.

A flood impairment has been placed in the control room to provide direction for verifying full closure and flushing sediment and debris that could prevent the gates from fully closing during a design flooding event.

A cause analysis is in-process and when completed, this LER will be supplemented to include any additional corrective actions.

SAFETY SIGNIFICANCE

The loss of the ability to close the intake structure sluice gates during flood conditions could lead to the loss of the raw water pumps which supply cooling water component cooling water heat exchangers. The raw water system also provides direct cooling for the following safety related components in the event that the component cooling water system is unavailable: the shutdown cooling heat exchangers, the high/low pressure safety injection pump bearing oil and seal coolers, the containment spray pump bearing oil and seal coolers, and the control room air conditioners.

In the event of a DBA, the component cooling water system is designed to provide sufficient cooling water to the engineered safeguards equipment.

SAFETY SYSTEM FUNCTIONAL FAILURE

This event does result in a safety system functional failure in accordance with NEI-99-02.

PREVIOUS EVENTS

A cause analysis is in-process and when completed, this LER will be supplemented to include any previous events that are identified.

[Handwritten signature]
NRC
Public
Date