



Stephen E. Hedges
Site Vice President

October 7, 2011

WO 11-0076

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Subject: Docket No. 50-482: Licensee Event Report 2011-009-00, "Inadequate Oil Analysis Caused Inoperable Auxiliary Feedwater Pump Longer Than Required Action Completion Time"


Gentlemen:

The enclosed Licensee Event Report (LER) is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B) to report exceeding the Technical Specification Required Action Completion Time for the turbine driven auxiliary feedwater pump at the Wolf Creek Generating Station.

Commitments made by Wolf Creek Nuclear Operating Corporation in the enclosed LER are identified in the Attachment to this letter.

If you have any questions concerning this matter, please contact me at (620) 364-4190, or Mr. Gautam Sen at (620) 364-4175.

Sincerely,



Stephen E. Hedges

SEH/rlt

Attachment	List of Commitments
Enclosure	LER

cc: E. E. Collins (NRC), w/a, w/e
J. R. Hall (NRC), w/a, w/e
G. B. Miller (NRC), w/a, w/e
Senior Resident Inspector (NRC), w/a, w/e

IE22
NRR

LIST OF COMMITMENTS

The following table identifies those actions committed to by Wolf Creek Nuclear Operating Corporation in this document. Any other statements in this letter are provided for information purposes and are not considered regulatory commitments. Please direct questions regarding these commitments to Mr. Gautam Sen, Manager Regulatory Affairs at Wolf Creek Generating Station, (620) 364-4175.

REGULATORY COMMITMENT	DUE DATE
Procedure I-ENG-004, "Lubricating Oil Analysis," will be revised to specify the actions to take when oil sample results reach alert levels and to strengthen oil sample processing controls.	December 18, 2011

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (10-2010)		APPROVED BY OMB: NO. 3150-0104 EXPIRES: 10/31/2013 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.																																					
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)																																							
1. FACILITY NAME WOLF CREEK GENERATING STATION		2. DOCKET NUMBER 05000 482	3. PAGE 1 OF 4																																				
4. TITLE Inadequate Oil Analysis Caused Inoperable Auxiliary Feedwater Pump Longer Than Required Action Completion Time																																							
5. EVENT DATE <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td>08</td> <td>14</td> <td>2011</td> </tr> </table>		MONTH	DAY	YEAR	08	14	2011	6. LER NUMBER <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>YEAR</th> <th>SEQUENTIAL NUMBER</th> <th>REV NO.</th> </tr> <tr> <td>2011</td> <td>- 009 -</td> <td>00</td> </tr> </table>	YEAR	SEQUENTIAL NUMBER	REV NO.	2011	- 009 -	00	7. REPORT DATE <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td>10</td> <td>07</td> <td>2011</td> </tr> </table>	MONTH	DAY	YEAR	10	07	2011	8. OTHER FACILITIES INVOLVED <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>FACILITY NAME</th> <th>DOCKET NUMBER</th> </tr> <tr> <td></td> <td>05000</td> </tr> </table>	FACILITY NAME	DOCKET NUMBER		05000													
MONTH	DAY	YEAR																																					
08	14	2011																																					
YEAR	SEQUENTIAL NUMBER	REV NO.																																					
2011	- 009 -	00																																					
MONTH	DAY	YEAR																																					
10	07	2011																																					
FACILITY NAME	DOCKET NUMBER																																						
	05000																																						
9. OPERATING MODE Mode 1		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)																																					
10. POWER LEVEL 100%		<table style="width:100%;"> <tr> <td><input type="checkbox"/> 20.2201(b)</td> <td><input type="checkbox"/> 20.2203(a)(3)(i)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td> <td><input type="checkbox"/> 50.73(a)(2)(vii)</td> </tr> <tr> <td><input type="checkbox"/> 20.2201(d)</td> <td><input type="checkbox"/> 20.2203(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(1)</td> <td><input type="checkbox"/> 20.2203(a)(4)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(i)</td> <td><input type="checkbox"/> 50.36(c)(1)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(ii)</td> <td><input type="checkbox"/> 50.36(c)(1)(ii)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iv)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(x)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iii)</td> <td><input type="checkbox"/> 50.36(c)(2)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td> <td><input type="checkbox"/> 73.71(a)(4)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iv)</td> <td><input type="checkbox"/> 50.46(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(B)</td> <td><input type="checkbox"/> 73.71(a)(5)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(v)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td> <td><input type="checkbox"/> OTHER</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(vi)</td> <td><input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td> <td></td> </tr> </table>		<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																				
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																				
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																				
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																				
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																				
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																				
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																				
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																				
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)																																					
12. LICENSEE CONTACT FOR THIS LER																																							
FACILITY NAME Gautam Sen, Manager Regulatory Affairs		TELEPHONE NUMBER (Include Area Code) (620) 364-4175																																					
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																																							
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX																														
A	BA	P	I075	Y																																			
14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO					15. EXPECTED SUBMISSION DATE <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>MONTH</th> <th>DAY</th> <th>YEAR</th> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>					MONTH	DAY	YEAR																											
MONTH	DAY	YEAR																																					
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)																																							
<p>On 8/11/2011 at 1145 CDT the turbine driven Auxiliary Feedwater (AFW) pump was declared inoperable due to oil sample results that indicated a high particulate count in the turbine lube oil system. The cause of the condition was determined to be residual quantities of Fyrquel remaining in the system after an inadvertent addition of Fyrquel to the system in March 2011, in addition to water, dirt, wear and oxide particles. The lube oil system was drained, flushed and filled multiple times followed by oil sample testing to determine particulate content.</p> <p>On 8/14/2011, Wolf Creek Nuclear Operating Corporation requested a Notice of Enforcement Discretion (NOED) to extend the Completion Time for the turbine driven AFW pump an additional 24 hours. The NRC granted the approval of the NOED on 8/14/2011. A Technical Specification required shutdown was initiated on 8/15/2011. The turbine driven AFW pump was returned to operable status on 8/15/2011 and the plant was returned to full power.</p> <p>Procedure I-ENG-004, "Lubricating Oil Analysis," will be revised to specify the actions to take when oil sample results reach alert levels and to strengthen oil sample processing controls.</p>																																							

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 4
		2011	-- 009 --	00	

PLANT CONDITIONS AT THE TIME OF THE EVENT

Mode 1
100% power

DESCRIPTION OF THE EVENT

On 8/11/2011 at 1145 CDT the turbine driven Auxiliary Feedwater (AFW) pump [EIS Code: BA-P] was declared inoperable due to oil sample results that indicated a high particulate count in the turbine lube oil system. The results exceeded the International Organization for Standardization (ISO) Solid Contamination Code action limit provided in procedure I-ENG-004, "Lubricating Oil Analysis." Technical Specification (TS) 3.7.5 Condition B was entered with a Completion Time of 72 hours to restore the pump to operable status. At the time of the event, no systems, structures, or components other than the turbine driven AFW pump were inoperable that contributed to the event.

Work was immediately started to drain and flush the oil from the turbine driven AFW pump and replace it with new oil. The turbine lube oil system was drained and flushed multiple times.

Following the third drain and fill of the turbine driven AFW pump oil, surveillance test procedure STS-AL-103, "TDAFW Pump Inservice Test," was performed satisfactorily. However, oil sample results continued to indicate elevated particulate levels.

Additional effort to correct this condition involved cleaning bearing housings where particulates have a high potential of being located followed by re-circulating the oil in the system through an in line re-circulation skid with a fine (2 micron) filter until the particulate limit was met. This method of filtering process proved effective. However, the time required to perform the pump post maintenance surveillance, take an additional oil sample, and perform additional filtering, would have resulted in exceeding the 72-hour Completion Time of TS 3.7.5, Required Action B.1.

On 8/14/2011, Wolf Creek Nuclear Operating Corporation (WCNOC) requested a Notice of Enforcement Discretion (NOED) to not enforce compliance with the actions required in TS 3.7.5 Required Actions C.1 and C.2 for a period of 24 hours. The NRC gave verbal approval of the NOED on 8/14/2011 at 0945 CDT.

On 8/15/2011 at 1145 CDT, an evaluation of the oil sample results had not been completed and the unit began a TS required shutdown in accordance with TS 3.7.5, Required Actions C.1 and C.2. On 8/15/2011 at 1203 CDT, the turbine oil was determined to be acceptable and the turbine driven AFW pump was declared operable. The TS required shutdown was terminated with the unit at 81% power. The unit was returned to full power on 8/15/2011 at 1425 CDT.

The cause of the condition was determined to be residual quantities of Fyrquel remaining in the turbine lube oil system after an inadvertent addition of 8 ounces of Fyrquel to the system in March 2011, in addition to water, dirt, wear and oxide particles. Immediately following the addition of Fyrquel and prior to operating the turbine driven AFW pump in March 2011, the system was flushed, cleaned and the proper lubricant added. The turbine driven AFW pump was operated for a sufficient period of time to demonstrate that it would fulfill its safety function.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 4
		2011	-- 009 --	00	

BASIS FOR REPORTABILITY

WCNOC requested and received a NOED from the NRC to not enforce compliance with the actions required in TS 3.7.5 Required Actions C.1 and C.2 for a period of 24 hours. The turbine driven AFW pump was inoperable for longer than allowed by the Completion Time of TS 3.7.5, Required Action B.1. The event is reportable pursuant to 10 CFR 50.73(a)(2)(i)(B) for any operation or condition which was prohibited by the plant's TS.

ROOT CAUSE

The direct cause of the turbine driven AFW pump inoperability was lube oil analysis controls were less than adequate.

Monitoring of oil sample results is included in procedure I-ENG-004, "Lubricating Oil Analysis." On 3/11/2011, an oil sample analysis was taken and sent to an offsite laboratory for analysis. The oil analysis did not include a particulate count. On 7/8/2011, another oil sample was taken and sent offsite for analysis. A particulate count was provided and showed the turbine driven AFW pump oil failed to meet the oil particulate action level specified in procedure I-ENG-004. Procedure I-ENG-004 did not provide specific guidance on the type of testing to perform on the oil sample or specify that additional testing should be requested if an action limit was exceeded.

The primary contributor to exceeding the 72-hour TS Completion Time and NOED allowed extension of 24 hours is a lack of knowledge of the variation in particulate counting test methods and test results. The turbine lube oil system was drained multiple times, an in-line filtration method was used, new oil was being tested for cleanliness, and new oil was circulated through the system by running the turbine, yet particulate count results continued to exceed the I-ENG-004 acceptance criteria. The reliability of particulate count testing is now known to fluctuate by as much as two ISO codes values depending on testing method practices and instruments. Sources of variation can occur from air bubbles, water, and additives or incompatible fluids entrapped in the oil, and these soft particles generate some of the largest spikes in ISO cleanliness values.

Residual Fyrquel would be expected to act like an interfering soft particle and contribute to inaccurate particle counts when a sample is tested. Per the ASTM D7657 standard, interfering soft particles are an undissolved, dispersed material (such as an additive) within an oil blend or substance that is formed during the service life of an oil blend. When these substances are present in a sample and not completely solubilized, they are likely to be counted by an optical particle counter in a similar manner to dirt and wear metal particles, air bubbles, and free water droplets.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 4
		2011	-- 009	-- 00	

CORRECTIVE ACTIONS

The lube oil system was drained, flushed and filled multiple times followed by oil sample testing to determine particulate content.

Procedure I-ENG-004, "Lubricating Oil Analysis," will be revised by 12/18/2011 to include the following:

1. Specify the actions to take when oil sample results are at the ISO Solid Contamination Code action limit. Specify the additional testing that will be performed if the ISO Alert Limit is reached.
2. Critical components that require the ISO Code for oil analysis will be specified.
3. Oil sample processing controls will be strengthened by formalizing an oil sample tracking method to provide consistent testing methods and trending for critical components.
4. A process for testing new oil prior to use will be developed to establish a baseline.

SAFETY SIGNIFICANCE

The WCNOG final quantitative risk analysis indicated that the incremental conditional core damage probability (ICCDP) for the 24-hour extension was 1.20E-07, and the incremental conditional large early release probability (ICLERP) for the 24-hour extension was 5.18E-09. The calculated value for ICCDP and ICLERP met the Regulatory Issue Summary 2005-01, "Changes to Notice of Enforcement Discretion (NOED) Process and Staff Guidance," guidance thresholds.

To further mitigate the risk impact, WCNOG implemented a series of compensatory actions for the duration of the enforcement period and continued until the turbine driven AFW pump was restored to operable status.

OPERATING EXPERIENCE/PREVIOUS SIMILAR OCCURRENCES

None.