



GUIDE

# Designing for Moldability


VOLUME 1: A RAPID INJECTION MOLDING  
REFERENCE GUIDE FOR PRODUCT  
DESIGNERS AND ENGINEERS

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## What is injection molding?

- 1 The hopper is loaded with the plastic stock material.
- 2 A heated barrel is used to melt the beads into a molten form.
- 3 A screw apparatus is used to inject the polymer into a mold.
- 4 The part cools and solidifies.
- 5 The mold is opened and the part ejected.



## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## What is Rapid Injection Molding?

### Rapid mold fabrication

- Molds are made from aluminum
- They are 3-axis CNC milled
- Selective use of electrical discharge machining (EDM)
- Parts in 1 to 15 business days
- Side-action and hand-load insert capabilities
- Simple overmolding capabilities



## Applications of Rapid Injection Molding

- Refine your design with real molded prototype parts
- Functional testing in product development cycle
- Test multiple materials
- Try multiple versions
- Make quick iterations
- Bridge tooling
- Low-volume production
- 25 to 10,000 parts
- Support for production line shutdowns
- Crash development projects

### Markets that use Rapid Injection Molding


- Medical
- Automotive
- Electronics
- Aerospace
- Consumer Products
- Appliance
- Lighting
- Marine

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Up Against the Wall (Thickness)


The most important design requirement for getting good molded parts: maintain constant wall thickness.



**Tip:** Good injection-molded part design relies on consistent wall thickness to minimize the potential for warped or distorted parts.

## A Core Issue

Core out parts to eliminate thick walls. You get the same functionality in a good molded part.



**Tip:** Unnecessary thickness can alter part dimensions, reduce strength and necessitate post-process machining.

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Let's Get Absolute

### Recommended wall thickness by resin.


Resin	Recommended Wall Thickness (Inches)
ABS	0.045 – 0.140
Acetal	0.030 – 0.120
Acrylic	0.025 – 0.150
Liquid crystal polymer	0.030 – 0.120
Long-fiber reinforced plastics	0.075 – 1.000
Nylon	0.030 – 0.115
Polycarbonate	0.040 – 0.150
Polyester	0.025 – 0.125
Polyethylene	0.030 – 0.200
Polyphenylene sulfide	0.020 – 0.180
Polypropylene	0.025 – 0.150
Polystyrene	0.035 – 0.150

**Note:** These are general guidelines, subject to part geometry and molded construction. Larger parts shouldn't be designed with the minimum wall thickness.


**Tip:** Protolabs' general rule for wall thickness is 0.040–0.140 inches.

## A Warped Personality

Eliminate sharp transitions that cause molded-in stress.



Design 3D structures that support themselves.




## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Get the Stress Out


**Sharp corners weaken parts.**

- They cause molded-in stress from resin flow.
- They form a stress riser in your application.



## Give 'Em a Good Ribbing

To prevent sink, ribs should be no more than 60% of the wall's thickness.




**Tip:** If Protolabs asks for greater wall thickness on your 40–60% T-wall, consider increasing your T-wall to compensate for this increased thickness to reduce the risk of sink.

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14


## Good and Bad Bosses

- Don't create thick sections with screw bosses.
- Thick sections can cause sink and voids in your part.



## Don't Be a Draft Dodger

Draft (slope the vertical walls) as much as possible — this makes it easier to eject parts without drag marks or ejector punch marks. You get better parts, faster.




## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Core-cavity

When you draft, use core-cavity instead of ribs if you can. It allows you to have constant wall thickness rather than walls with a thick base. We can mill molds with better surface finish and deliver better parts faster.



**Tip:** This option is faster and less expensive to manufacture.

## Deep (Milling) Impact

Draft the part as much as possible. This allows us to make deeper features for you. Draft allows us to reduce tool chatter and cosmetic defects when milling deep walls. If you can fit it in, use 1 degree of draft or more. On core-cavity designs, try to use 2 degrees or more. A rough rule of thumb is 1 degree of draft for each of the first 2 inches of depth. From 2 to 4 inches of depth, either 3 degrees of draft or a minimum of 1/8 in. thickness may be required.

## Texture

Protolabs can add bead-blast texture to the mold for your parts. Light texture requires 3 degrees of draft minimum on vertical walls. Medium texture requires 5 degrees.





## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14


## Straight (Pull) Shooter

Sliding shutoffs are your friend — these features can be made in a straight-pull mold. They do require 3 degrees of draft, but save significant money over side-actions.



## Side-Action for Undercuts

Side-actions can form undercuts on the outside of your part. Undercuts must be on or connected to the parting line. They must be in the plane of the parting line. Undercuts must be connected and perpendicular to the direction the mold is opening.




## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Bumpoffs

A bumpoff is a small undercut in a part design that can be safely removed from a straight-pull mold without the use of side-actions. Bumpoffs can be used to solve some simple slight undercuts, but are sensitive to geometry, material type and orientation.



**Tip:** Molds can be made core-cavity, allowing room for the part to “bumpoff” after the mold opens.

## Pickouts

A pickout is a separate piece of metal that is inserted into the mold to create an undercut. It is ejected with the part, then removed by the operator and re-inserted in the mold.

**Tip:** Using a pickout overcomes many shape and positioning restrictions, but is more costly than sliding shutoffs, or using a side-action.

## High-Aspect-Ratio, Small Diameter Holes

These holes can be made with steel core pins in the mold. A steel pin is strong enough to handle the stress of ejection and its surface is smooth enough to release cleanly from the part without draft. There shouldn't be any cosmetic effect on the resulting part; if there is, it will be inside the hole where it won't be seen.


## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Watch Your Penmanship


Choose a sans serif font where the smallest feature is at least 0.020 in. thick. Serif fonts have small tails which are often too small. Text that is raised above the part is better. We cannot polish around it if the text is cut into your part.

- In SolidWorks, Century Gothic 26 point regular font and **16 point bold** create millable text.
- **Comic Sans MS 24 point** also creates millable text.
- For small text, a depth of 0.010–0.015 in. often works well to reduce milling cost and improve ejection.



## Open the Floodgates

Thin edges restrict flow and can break during gate trimming. We need somewhere thick to gate into your part. There may be alternatives, so please contact one of our customer service engineers at 877.479.3680 or [customerservice@protolabs.com](mailto:customerservice@protolabs.com).



## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14


## Self-Mating Parts

Identical parts that flip over and mate to themselves are possible and save the cost of a second mold.


### Elements include:

- Peg and hole
- Interlocking rim
- Hooks and latches

### Peg and hole/interlocking rim



### Hooks and latches



## Be Tolerant

- Protolabs can hold about  $\pm 0.003$  in. machining accuracy.
- Shrink tolerance depends mainly on part design and resin choice. It varies from 0.002 in./in. for stable resins like ABS and polycarbonate to 0.025 in./in. for unstable resins like TPE.
- There are techniques for getting the most accuracy out of our process. Please contact a customer service engineer at 877.479.3680 or [customerservice@protolabs.com](mailto:customerservice@protolabs.com).

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## It's a Material World

When choosing a material for your part, relevant properties might include mechanical, physical, chemical resistance, heat, electrical, flammability or UV resistance. Resin manufacturers, compounders and independent resin search engines have data online. For resin links, visit [protolabs.com/resources#materials](https://protolabs.com/resources#materials).

### Commodity Resins

#### Polypropylene

- Soft
- Tough
- Cheap
- Chemical resistant
- Makes good living hinges

#### Polyethylene

- Soft
- Tough
- Cheap
- Chemical resistant
- High Density
- Low Density

#### Polystyrene

- Hard
- Clear
- Cheap
- Brittle but can be toughened

#### Colors

No color-matching, salt/pepper 3% mixture for most stocked colorants, re-compounded material/colorants or customer supplied colorants.

### Engineering Resins

#### ABS

- Inexpensive
- Impact Resistant
- Equipment and handheld housings
- Susceptible to sink

#### Acetal

- More expensive
- Strong
- Good lubricity and machinability
- Very sensitive to excess wall thickness

#### LCP

- Very expensive
- Very strong
- Fills very thin parts
- Weak knit lines

#### Nylon

- Reasonable cost
- Very strong
- Susceptible to shrink and warp, particularly glass-filled
- Absorbs water — dimensional and property change

#### Polycarbonate

- Moderate cost
- Very tough
- Good dimensional accuracy
- Susceptible to chemical stress cracking, voids

#### PBT, PET, PPS, PSU, PES, PEI and many others

## TABLE OF CONTENTS

What is Injection Molding?	2
What is Rapid Injection Molding?	3
Applications of Rapid Injection Molding	3
Wall Thickness	4
Cored Geometry	4
Recommended Wall Thickness	5
Warp	5
Sharp Corners	6
Ribs	6
Bosses	7
Draft	7
Core-cavity	8
Deep (Milling) Impact	8
Texture	8
Straight-Pull Mold	9
Side-Actions	9
Bumpoff	10
Pickouts	10
Steel Core Pins	10
Text	11
Tab Gate	11
Self-Mating Parts	12
Tolerance	12
Choosing a Material	13
Select Colors	14
Resin Additives	14

## Select Colors

Stock colors from the resin vendor are typically black and natural. Natural might be white, beige, amber or another color. Semi-custom colors are created when colorant pellets are added to natural resins. For available colors, visit [protolabs.com/resources/molding-materials](https://protolabs.com/resources/molding-materials). There is no added charge for our inventory colors. They may not be an exact match and may create streaks or swirls in parts. Custom colors that need to match an exact Pantone or color chip need to be compounded with a resin supplier. This process is slower and more expensive, but produces a more accurate match.

## Resin Additives

**Short glass fibers** are used to strengthen a composite and reduce creep, especially at higher temperatures. They make the resin stronger, stiffer, and more brittle. They can cause warp due to the difference in cooling shrink between the resin and the fibers.

**Carbon fiber** is used to strengthen and/or stiffen a composite and also to aid in static dissipation. It has the same limitations as glass fibers. Carbon fiber can make plastic very stiff.

**Minerals** such as talc and clay are often used as fillers to reduce the cost or increase the hardness of finished parts. Since they do not shrink as much as resins do when cooled, they can reduce warping.

**PTFE (Teflon) and molybdenum disulfide** are used to make parts self lubricating in bearing applications.

**Long glass fibers** are used like short glass fibers to strengthen and reduce creep, but make the resin much stronger and stiffer. The downside is that they can be particularly challenging to mold parts with thin walls and/or long resin flows.

**Aramid (Kevlar) fibers** are like less-abrasive glass fibers only not as strong.

**Glass beads and mica flakes** are used to stiffen a composite and reduce warping and shrinkage. With high loading, they can be challenging to inject.

**Stainless steel fibers** are used to control EMI (electromagnetic interference) and RFI (radio frequency interference) typically in housings for electronic components. They are more conductive than carbon fiber.

**UV inhibitor** for outdoor applications.

**Static treatments** make resins dissipate static.

## Questions?

Call your account manager or a customer service engineer at **877-479-3680**.

Protolabs is the world's fastest digital manufacturing source for custom prototypes and low-volume production parts. Our automated quoting system and proprietary software translate 3D CAD models into instructions for high-speed manufacturing equipment. This enables advanced 3D printing, CNC machining and injection molding technologies to produce plastic and metal parts within days. The result is an unprecedented speed-to-market value for product designers and engineers worldwide.

**protolabs.com**  
**877-479-3680**

### **Protolabs**

5540 Pioneer Creek Drive  
Maple Plain, MN 55359

