

ISSUE/VIOLATION	RECOMMENDED ACTION	ESTIMATED CAPITAL EXPENDITURES												
BRANCH CIRCUIT BREAKERS IN PANELS SERVING FIRE ALARM SYSTEM LOADS ARE NOT PROPERLY MARKED	IDENTIFY AND MARK CIRCUIT BREAKERS PER CODE													
COMINGLED CIRCUITS	TRACE EACH OF THE PANELS CIRCUITS AND RELOCATE THE COMINGLED CIRCUITS TO PANELS ON THE PROPER SYSTEM TO SERVE RELOCATED CIRCUIT.	<table><tr><td>ACTIVITY</td><td>GUESTIMATE</td></tr><tr><td>TEST ACTIVITY 1</td><td>\$1,000</td></tr><tr><td>TEST ACTIVITY 2</td><td>\$1,050</td></tr><tr><td>Sub-Total:</td><td>\$2,050</td></tr><tr><td>Engineering Design Fee(10% of project cost):</td><td>\$205</td></tr><tr><td>TOTAL:</td><td>\$0</td></tr></table>	ACTIVITY	GUESTIMATE	TEST ACTIVITY 1	\$1,000	TEST ACTIVITY 2	\$1,050	Sub-Total:	\$2,050	Engineering Design Fee(10% of project cost):	\$205	TOTAL:	\$0
ACTIVITY	GUESTIMATE													
TEST ACTIVITY 1	\$1,000													
TEST ACTIVITY 2	\$1,050													
Sub-Total:	\$2,050													
Engineering Design Fee(10% of project cost):	\$205													
TOTAL:	\$0													
LIQUID ABSORBING MATERIAL WAS LEFT ON THE FLOOR WHICH CREATES A TRIPPING HAZARD.	CLEAN UP MATERIAL OFF THE FLOOR.	<table><tr><td>ACTIVITY</td><td>GUESTIMATE</td></tr><tr><td>TEST ACTIVITY 1</td><td>\$1,000</td></tr><tr><td>TEST ACTIVITY 2</td><td>\$1,050</td></tr><tr><td>Sub-Total:</td><td>\$2,050</td></tr><tr><td>Engineering Design Fee(10% of project cost):</td><td></td></tr><tr><td>TOTAL:</td><td>\$2,050</td></tr></table>	ACTIVITY	GUESTIMATE	TEST ACTIVITY 1	\$1,000	TEST ACTIVITY 2	\$1,050	Sub-Total:	\$2,050	Engineering Design Fee(10% of project cost):		TOTAL:	\$2,050
ACTIVITY	GUESTIMATE													
TEST ACTIVITY 1	\$1,000													
TEST ACTIVITY 2	\$1,050													
Sub-Total:	\$2,050													
Engineering Design Fee(10% of project cost):														
TOTAL:	\$2,050													
FIRE STOP SEALS DO NOT APPEAR TO BE PROPERLY INSTALLED AND SEAL LABEL APPEARS TO BE MISSING.	PROPERLY MARK AND FIRE PACK THE CONDUIT WALL PENETRATION.													
JUNCTION BOX WAS LEFT OPEN.	PROPERLY INSTALL THE JUNCTION BOX COVER													
EXISTING TRANSFORMER HAS SOME LIQUID DAMAGE	INSPECT EQUIPMENT IS STILL IN PROPER WORKING ORDER AND CLEAN. OTHER WISE REPLACE THE EQUIPMENT.													
DISCONNECT AND PANEL IS INSTALLED OVER A TRANSFORMER	RELOCATE EQUIPMENT SO THAT CODE REQUIRED CLEARANCES ARE MET.													
COMMUNICATIONS CABLING IS LEFT UNSUPPORTED.	PROVIDE PROPER SUPPORTS FOR LOOSE CABLES.													
ELECTRICAL DISCONNECT CLEARANCE HAS BEEN INFRINGED	RELOCATE EQUIPMENT SO THAT CODE REQUIRED CLEARANCES ARE MET.													

ISSUE/VIOLATION	RECOMMENDED ACTION	ESTIMATED CAPITAL EXPENDITURES
PANEL IS MISSING PROPER LABLING	PROVIDE PROPER LABEL.	
CLEANING SUPPLIES ARE STORED INFRONT OF THE ELECTRICAL PANELS	REMOVE ALL SUPPLIES INFRONT OF PANELS.	
DOOR DOES NOT LOCK TO KEEP UNQUALFIED PERSONS FROM ENTERING THE ELECTRICAL ROOM.	REMOVE TAPE OBSTRUCTING THE LATCHING MECHANISM OF THE DOOR.	
DOOR DOES NOT SWING OUT AND IS NOT EQUIPED WITH PANIC HARDWARE IN A ROOM CONTAINING MEDIUM VOLTAGE EQUIPMENT	REPLACE DOOR AND PROVIDE CODE REQUIRED PANIC HARDWARE	
testing TESTING	NOTHING	
TOTAL:		\$2,050