






	WORK INSTRUCTION		Effectivity Date:	January 06, 2022	
	Process Name/Title: TAPING ASSEMBLY PROCESS		Validity Date:	n/a	
	Model Code/Part Number: 178D / 7N0129-7020	Customer: TRJ	Document No.:	WI-ENG-PDE-339C	
	Purpose: <input type="checkbox"/> PROTOTYPE <input type="checkbox"/> PRE-LAUNCH <input checked="" type="checkbox"/> MASSPRO		Revision No.:	1	Page No.:

PARTS: 		1. All parts: Assy parts; Clamp 82711-52090 (W); Clamp 82711-3A540 (W); Clamp 82711-34490 (B); Black tape [4pcs.]; White tape [1pc.]		JIG:	1. Clamp assembly jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
1	P3  Table Lay-out	<div style="text-align: center;"> Table Lay-out  </div>		<div style="border: 1px dashed red; padding: 5px;"> Safety Instruction Be sure to wear required personal protective equipment during operation (gloves, finger cots, etc.) </div> <div style="border: 1px dashed red; padding: 5px;"> Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker. </div> <div style="border: 1px dashed red; padding: 5px;"> Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action. </div>	1. No missing parts/tools 2. No excess parts/tools

Revision History

Eff. Date	Rev. No	Details of Change	Revised	Reviewed	Approved	Noted	Prepared by	Reviewed by	Approved by	Noted by
01/06/22	1	Change from Pre-launch to Masspro. Improve work procedure/illustration and quality pointers; Additional Table Lay-out.	M. Catapang	J. Loterte	C. Villanueva	A. Arañes				
09/20/21	0	Initial issue	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes
							Est. Date:	September 20, 2021		

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROPCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Model Code/Part Number: **178D / 7N0129-7020**

Customer: **TRJ**

Validity Date:

n/a

Document No.:

WI-ENG-PDE-339C

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Revision No.:

1

Page No.:

2 of 6

PARTS:

1. Clamp 82711-52090 (W) [4pcs.]
2. Clamp 82711-3A540 (W)
3. Clamp 82711-34490 (B)

4. Black tape [4pcs.]
5. White tape

JIG

1. Clamp assembly jig

NO.

PROCESS NAME

1

WORK PROCEDURE/ ILLUSTRATION


TOOLS/PPE

QUALITY POINTERS

2

P3

Clamp setting



1. Get 2 pcs. of clamp **82711-52090 (W)** using both hands then insert to clamp location **5 and 1** using both hands.


2. Get 2 pcs. of clamp **82711-52090 (W)** using both hands then insert to clamp location **3 and 4** using both hands.

3. Get 1 pc. of clamp **82711-3A540 (W)** using right hand then insert to clamp location **6** using both hands.

5. Get the **Black tape** then initially attach to clamp location **5, 1, 6 and 4** using both hands.

Note: Please check the Clamp first before start of assembly to avoid wrong use of clamp.

4. Get 1 pc. of clamp **82711-34490 (B)** using right hand then insert to clamp location **2** using both hands. *(See below illustration for clamp setting)*




6. Get the **White tape** then initially attach to clamp location **3** using both hands.

n/a

STANDARD TAPING FOR CLAMP

One side tape under clamp



1. No wrong use of parts
2. No wrong use of tape
3. No damaged clamp
4. No wrong clamp position

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROPCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Model Code/Part Number: 178D / 7N0129-7020

Customer:

TRJ

Validity Date:

n/a

Document No.:

WI-ENG-PDE-339C

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Revision No.:

1

Page No.:

4 of 6

PARTS:		1. Assy parts 2. Black tape		JIG	1. Clamp assembly jig
NO.	PROCESS NAME	1 WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
3	P3 Clamp assembly	<div><div>1</div><div><div><div>CONNECTOR SETTING</div><div>82711-52090 (W)</div></div><div><div>CONNECTOR SETTING</div><div>82711-3A540(W)</div></div><div><div>82711-34490(B)</div></div><div><div>82711-52090 (W)</div></div></div><div><div>CHECKER 1</div><div>COLOR SENSOR WHITE TAPE ONLY</div></div><div><div>4. Initially tighten the band clamp on clamp location 2 using both hands.</div><div>5. Get the bando gun using right hand then cut the band clamp on location 2 using both hands. Press the SW button after cut. Continue the process if sequence light on clamp location 3 was ON.</div></div><div><div>BANDO GUN</div><div>PERPENDICULARITY NG OK NG</div><div>Note: Setting of band clamp cutter depends on the size of the COT/Vinyl tube. For: $\phi 5 - 1 \sim 2$, $\phi 7 - 3 \sim 4$</div></div><div><div><div>GOOD</div><div>NG</div></div><div><div>Fixed setting of band clamp cutter: 1~ 2</div></div></div></div>		n/a	<div>1</div> <div><div>Note: Make sure no gap between stopper jig and PCB</div><div>1. No wrong use of parts 2. No wrong use of tape 3. No damaged clamp 4. No wrong clamp position</div></div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

Process Name/Title: **TAPING ASSEMBLY PROPCESS**Model Code/Part Number: **178D / 7N0129-7020**Customer: **TRJ**Purpose: ☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Effectivity Date:

January 06, 2022

Validity Date:

n/a

Document No.:







WI-ENG-PDE-339C

Revision No.:

1

Page No.:

5 of 6

PARTS:		1. Assy parts 2. Black tape 3. White tape		JIG	1. Clamp assembly jig
NO.	PROCESS NAME	1 WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
3	P3 Clamp assembly (Continuation)	<div><div><div>1</div><div></div></div><div><div>6. Hold the tape on clamp location 3, make 3 windings of tape then cut the tape using both hands. Color sensor light will beep/buzz if sensor detects White tape. Press the SW button after taping. Continue the process if sequence light on clamp location 4 was ON.</div><div>7. Hold the tape on clamp location 4, make 3 windings of tape then cut the tape using both hands. Press the SW button after taping. Continue the process if sequence light on clamp location 5 was ON.</div><div>8. Hold the tape on clamp location 5, make 3 windings of tape then cut the tape using both hands. Press the SW button after taping. Continue the process if sequence light on clamp location 6 was ON.</div><div>9. Hold the tape on clamp location 6, make 3 windings of tape then cut the tape using both hands. Press the SW button after taping. Go sound will be heard.</div><div>10. After taping, CONDUCT POINT CHECKING before removing the harness from jig.</div></div></div> <div><div></div><div>CONNECTOR SETTING</div><div>CHECKER 1</div></div> <div><div></div><div>82711-3A540(W)</div><div></div><div>82711-34490(B)</div><div></div><div>82711-52090 (W)</div></div> <div>COLOR SENSOR WHITE TAPE ONLY</div>		n/a	<div></div> <div>Note: Make sure no gap between stopper jig and PCB</div> <div>1. No wrong use of parts 2. No wrong use of tape 3. No damaged clamp 4. No wrong clamp position</div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROPCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 178D / 7N0129-7020

Customer: TRJ

Document No.:

WI-ENG-PDE-339C

Purpose: ☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Revision No.:

1

Page No.:

6 of 6

PARTS:

n/a

JIG

n/a

NO.

PROCESS NAME

WORK PROCEDURE/ ILLUSTRATION

TOOLS/PPE

QUALITY POINTERS

4


Visual/ By two's inspection

1

1. Check the connector lock

2. Check the presence of all clamp attachment and taping condition.

3. Check the Y-Taping condition.



0-2 mm

4. Using a steel rule, check if the band cut measurement is within the required dimension (0~2mm) and should not exceed the maximum value.

5. Compare to Master Sample
Note: Please refer to GL-PRO-ASY-007 for By Two's Inspection of Sub-Assy

MASTER SAMPLE



P3


5

Measurement

1

MEASURING TAPE

Note:
Please use calibrated/verified measuring tape when getting the measurement.



FOR HATSUMONO AND OWARIMONO

1. No wrong dimension

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp