



WORK INSTRUCTION TAPING ASSEMBLY PROCESS

Process Name/Title:

Product Name/Code: **100B / 7M0592-7020B**

Customer: **TRJ**

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Effectivity Date:

August 2, 2021

Validity Date:

n/a

Document No.:

WI-ENG-PDE-311B

Revision No.:

1













Page No.:

1 of 6

PARTS: 1. Connector 6098-3810 (W)

JIG:

1. Insertion jig

NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
1	P2 Connector setting to insertion jig 6098-3810 (W)	<div><div>1. Press the lock of insertion jig using left thumb.</div><div><p>Press</p></div><div><p>Lock</p></div><div><p>Holes</p></div><div><p>I-MARK</p></div><div><p>CONNECTOR ORIENTATION</p></div><div><p>Press</p></div><div><p>Release</p></div><div><p>3. Check the holes/terminal slot for B/B wires.</p></div><div><p>2. Insert the connector 6098-3810 (W) into jig using right hand and release the lock. Note: Follow the connector orientation.</p></div></div>	<div><div>Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)</div><div>Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.</div><div>Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.</div></div>	<div><div>Connector Orientation Illustration</div><div><p>I-mark was align</p></div><div><p>2 holes were only open</p></div><div><p>I-mark is NOT align</p></div><div><p>All holes were open</p></div><div><p>1. Use the provided jig per model 2. No wrong orientation of connector 3. No wrong use of connector 4. No damaged connector</p></div></div>

Revision History

Eff. Date	Rev. No	Details of Change	Revised	Checked	Approved	Noted	Prepared by	Reviewed by	Approved by	Noted by
08/02/21	1	Transfer process owner from Production (WI-PRO-ASY-116B) to Engineering (WI-ENG-PDE-311B). Change connector color in accordance with color standardization for plastic parts (Refer to GL-COM-003). Apply some improvements and update picture/illustration in all process.	M. Catapang	C. Villanueva	A. Shimamura	A. Arañes	M. Catapang	C. Villanueva	A. Shimamura	A. Arañes
04/10/18	n/a	Previously established as Engineering instruction (EI-ENG-PDE-027). Initial issue	S. Manalo	R. Alcantara	A. Arañes	n/a	M. Catapang	C. Villanueva	A. Shimamura	A. Arañes

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Effectivity Date:

August 2, 2021

Process Name/Title:

Product Name/Code: 100B / 7M0592-7020B

Customer: TRJ

Validity Date:

n/a

Purpose:

☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Document No.:











WI-ENG-PDE-311B

Revision No.:

1

Page No.:

2 of 6

PARTS:		1. AVSSf 0.3 wires B L=668±3mm [2pcs.]			JIG	1. Insertion jig 2. Locking jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	QUALITY POINTERS
2	Wire insertion to connector 6098-3810 (W) P2	<div>WIRE FACING</div> <div>1 Black</div> <div>2 Black</div> <div></div> <div><p>1. Get the 1st Black wire then insert to connector slot 1 using right hand. Note: insertion process must be from left to right.</p><p>2. Get the 2nd Black wire then insert to connector slot 2 using right hand.</p><p>3. After insertion, push the lock using left thumb then hold the wires and gently pull out the connector from jig using right hand.</p></div> <td>n/a</td> <td><div>Note: Please hold the wire near terminal during insertion.</div><div>1. No loose insertion 2. No wrong insertion 3. One by one insertion 4. No deformed terminal 5. No wrong wire facing</div><div>1 Note: Refer to GL-PRO-ASY-029 for Pull-Push procedure.</div></td>			n/a	<div>Note: Please hold the wire near terminal during insertion.</div> <div>1. No loose insertion 2. No wrong insertion 3. One by one insertion 4. No deformed terminal 5. No wrong wire facing</div> <div>1 Note: Refer to GL-PRO-ASY-029 for Pull-Push procedure.</div>
		<div></div> <div>Before Pressing</div> <div>After Pressing</div> <div>GOOD Fully Locked</div> <div>NG Unlocked</div> <div><p>Put the connector into locking jig using both thumb then press to lock 2x. Check the connector lock if properly locked. Note: Please refer to GL-PRO-ASY-017 for the verification of connector lock.</p></div>			LOCKING JIG 	<div>NOTE: MANUAL LOCKING MAY CAUSE DAMAGED LOCK.</div> <div>1. Use the provided locking jig per model 2. No unlock/half-lock connector</div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

**WORK INSTRUCTION**

Effectivity Date:

August 2, 2021

Process Name/Title:

TAPING ASSEMBLY PROCESS

Validity Date:

n/a

Product Name/Code:

100B / 7M0592-7020B

Customer:

TRJ

Document No.:

WI-ENG-PDE-311B

Purpose:



PROTOTYPE



PRE-LAUNCH








MASSPRO

Revision No.:

1

Page No.:

3 of 6

PARTS:		1. Assy parts 2. Black corrugated tube (no slit) $\phi 5$ L=85 \pm 3mm 3. Black tape			JIG	1. Terminal cover jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS	
4	<div>1</div> Wire insertion to Black corrugated tube (no slit) $\phi 5$ L=85 \pm 3mm P2	<div><div>L</div><div>R</div></div> <div>1. Hold the wires using left hand, get the terminal cover jig using right hand then insert the B/B wires using left hand.</div> <div><div>L</div><div>R</div></div> <div>2. Get the corrugated tube (no slit) $\phi 5$ L=85\pmmm using right hand then insert the B/B wires using left hand.</div> <div><div>L</div><div>R</div></div> <div>3. After insertion, remove the terminal cover jig using right hand.</div>		<div>TERMINAL COVER JIG</div> 	1. No wrong usage of parts 2. No deformed terminal	
5	<div>1</div> Taping 1 Black corrugated tube to wire near connector	<div><div>Start of taping</div><div>L</div><div>R</div></div> <div>1. Hold the corrugated tube using left hand then start taping using right hand.</div>		n/a	1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong dimension 6. No wrong use of tape	

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Process Name/Title:

Product Name/Code: **100B / 7M0592-7020B**Customer: **TRJ**Purpose: ☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Effectivity Date:

August 2, 2021

Validity Date:

n/a

Document No.:







WI-ENG-PDE-311B

Revision No.:

1

Page No.:

4 of 6

PARTS:		1. Assy parts 2. Black tape	JIG	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
5	Taping 1 Black corrugated tube to wire near connector (Continuation)	 <p>2. Measure from end of the corrugated tube up to connector 25±3mm then continue the taping process using both hands. <i>Note: Refer to WI-PRO-ASY-001 for taping procedure</i></p>  <p>3. After taping, check the measurement and taping condition.</p>		<p>1. <i>Note:</i> <i>Please use calibrated/verified measuring tape when getting the measurement.</i></p> <ol style="list-style-type: none">1. No flip-out tape2. No peel-off tape3. No loose tape4. No missing tape5. No wrong dimension6. No wrong use of tape
6	Taping 2 Spot taping	 <p>1. Fix the hotmelted wire and terminal pointed tip using both hands.</p>  <p>2. Hold the wires using left hand, get the Black tape using right hand then make 2 windings of tape using both hands. <i>Note: Position of spot taping must be right beside Green tape.</i></p> 	n/a	<ol style="list-style-type: none">1. No flip-out tape2. No peel-off tape3. No loose tape4. No missing tape5. No wrong dimension6. No wrong use of tape

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

Effectivity Date:

August 2, 2021

Process Name/Title:

TAPING ASSEMBLY PROCESS

Validity Date:

n/a

Product Name/Code:

100B / 7M0592-7020B

Customer:

TRJ

Document No.:

WI-ENG-PDE-311B

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH




☒ MASSPRO

Revision No.:

1

Page No.:

5 of 6

PARTS:		1. Assy parts 2. Black Corrugated tube (w/slit) $\phi 5$ L=411 \pm 3mm	JIG	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
7	P2 Wire insertion to Black Corrugated tube (w/slit) $\phi 5$ L=411 \pm 3mm	<div><p>1. Hold the COT adaptor using left hand then insert the wires using right hand.</p></div> <div><p>2. Hold the COT adaptor with wires using left hand, get the Black corrugated tube (w/slit) $\phi 5$ L=411\pm4mm using right hand then insert to COT adaptor. Push the COT adaptor and pull down the COT (<i>same timing</i>) using both hands. Make sure all wires are inserted.</p></div>	<div>COT Adaptor</div> 	1. No wrong use of parts 2. No wires left inside COT with slit

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

