




	Process Name/ Title:		Document No:		WI-PRO-CNC-009	
	<b>Wire Cutting and Crimping /</b> <b>Crimp Data Gathering Procedure</b>					
	<b>WORK INSTRUCTION</b>		Effective Date:		November 18, 2024	
	Product Code/Name:		Customer Code:		Rev. No.:	6
All		All		Page No.:	1 of 2	

No.	Work Procedure/ Illustration						Records/Remarks/ Quality Pointers																																																																							
	<p>1. Produce sample, prepare jig, instrument needed and identify confirmation points using Wire Confirmation Standard.</p> <p>2. Perform wire confirmation based on Wire Confirmation Method.</p> <p>3. Input the result of confirmation and data gathered on Develop Sheet for Crimp Data on monitor</p> <p>3.1 Wire Crimp Height</p> <div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">  </div> <div> <p>Start : Measure 2 samples and write data</p> <p>Middle : Measure 1 sample and write data</p> <p>End : Measure 2 samples and write data</p> <p>Summation: start + start + middle + end + end</p> <p>Average: Average of 5 samples' data</p> <p>Range: Difference between the Maximum and Minimum value</p> </div> </div> <p>* After completing data of 5 samples, check the X chart if does not violate the control chart rules based on Figure 1.</p> <p>3.2 Wire Crimp Width</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td>Wire Crimp Width</td> <td>Start</td> <td>1.85</td> </tr> </table> <p>Measure 1 sample and input data</p> <p>3.3 Bell-mouth</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Bell -mouth</td> <td>Start</td> <td>O</td> </tr> <tr> <td>End</td> <td>O</td> </tr> </table> <p>Confirm bell-mouth of start and end sample, input O if crimped wire has bell-mouth and X if none</p> <p>3.4 Insulation Crimp Height</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Insulation Crimp Height</td> <td>Start</td> <td>3.03</td> </tr> <tr> <td>End</td> <td>3.03</td> </tr> </table> <p>Measure 1 sample at the start and input data Measure 1 sample at the end and input data</p> <p>3.5 Insulation Crimp Width</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Insulation Crimp Width</td> <td>Start</td> <td>1.80</td> </tr> <tr> <td>End</td> <td>1.80</td> </tr> </table> <p>Measure 1 sample at the start and input data Measure 1 sample at the end and input data</p> <p>3.6 Core Wire</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="3">Core Wire</td> <td>Start</td> <td>0</td> </tr> <tr> <td>Start</td> <td>0</td> </tr> <tr> <td>End</td> <td>0</td> </tr> </table> <p>Input the quantity of core wire scar, cut or pulling out. Input 0 (zero) if core wires are OK/ Good, no scar, cut or pulling out. (Strip Length is written on daily report.)</p> <p>3.7 Indentation Mark</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="3">Indentation Mark</td> <td>Start</td> <td>0</td> </tr> <tr> <td>Start</td> <td>0</td> </tr> <tr> <td>End</td> <td>0</td> </tr> </table> <p>Confirm crimp wire if no grip mark Put 0 if no indentation mark Put X if crimp wire have indentation mark</p> <p>3.8 Crimp burr height</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Crimp Burr Height</td> <td>Start</td> <td></td> </tr> <tr> <td>End</td> <td></td> </tr> </table> <p>Input data when there is instruction and / when there is no instruction.</p> <p>3.9 Confirm PCB</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Crimp Burr Height</td> <td>Start</td> <td></td> </tr> <tr> <td>End</td> <td></td> </tr> </table> <p>Input data when there is instruction and / when there is no instruction.</p> <p>3.10 Confirm Curve</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="3">Confirm Curve</td> <td>Start</td> <td>0</td> </tr> <tr> <td>Start</td> <td>0</td> </tr> <tr> <td>End</td> <td>0</td> </tr> </table> <p>Input 0 (zero) if crimp wire is no bend</p> <p>3.11 Core wire protrusion</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td>Core Wire Protrusion</td> <td>Start</td> <td>0.02</td> </tr> </table> <p>Measure 1 sample and input data</p> <p>3.12 Pressure</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Pressure</td> <td>Start</td> <td>428</td> </tr> <tr> <td>End</td> <td>433</td> </tr> </table> <p>(Apply only when model is C511, 550, 551, 555, 556, and 558) Input data on space of start and end sample. Get Actual Pressure data from Maximum Pressure displayed on machine.</p> <p>3.13 Midterm Check</p> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="2">Midterm Check (Wire Crimp Height)</td> <td></td> <td>1.01</td> </tr> <tr> <td></td> <td></td> </tr> </table> <p>If wire type and diameter is not changed pick 1 piece and check wire crimp height Produced by Machine : every 4,000 pcs Produced Manually : every 2,000 pcs Input data on space for midterm check.</p> <p>3.14 Tensile Strength</p> <div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">  </div> <table border="1" style="margin-bottom: 5px;"> <tr> <td rowspan="3">Tensile Strength</td> <td>Start</td> <td>100</td> </tr> <tr> <td>Start</td> <td>105</td> </tr> <tr> <td>End</td> <td>103</td> </tr> </table> </div> <p>Start : Conduct tensile strength (2 samples of crimp) and write data End : Conduct tensile strength (2 samples of crimp) and write data</p> <p>3.15 Note</p> <p>Input issues, change parts, change points and countermeasure if applicable.</p> <p>3.16 Judgment</p> <p>If all items are judged good based on Wire confirmation standard, input O on space for judgment.</p> <p><b>Note:</b> During data gathering, compare actual values from the standard written on the upper right portion of the develop sheet for crimp data. All actual values must be within standard.</p> <p>If at least one (1) data does not meet the standard, adjust settings, produce sample, and repeat steps 3.1 ~ 3.7</p> <p>During checking of hatsumono, Leader check the actual sample vs encoded on the developsheets and sign prior to production.</p> <p>※Upon revision develop sheet for crimp data, leader must input standard based on "terminal specification"</p>						Wire Crimp Width	Start	1.85	Bell -mouth	Start	O	End	O	Insulation Crimp Height	Start	3.03	End	3.03	Insulation Crimp Width	Start	1.80	End	1.80	Core Wire	Start	0	Start	0	End	0	Indentation Mark	Start	0	Start	0	End	0	Crimp Burr Height	Start		End		Crimp Burr Height	Start		End		Confirm Curve	Start	0	Start	0	End	0	Core Wire Protrusion	Start	0.02	Pressure	Start	428	End	433	Midterm Check (Wire Crimp Height)		1.01			Tensile Strength	Start	100	Start	105	End	103			
Wire Crimp Width	Start	1.85																																																																												
Bell -mouth	Start	O																																																																												
	End	O																																																																												
Insulation Crimp Height	Start	3.03																																																																												
	End	3.03																																																																												
Insulation Crimp Width	Start	1.80																																																																												
	End	1.80																																																																												
Core Wire	Start	0																																																																												
	Start	0																																																																												
	End	0																																																																												
Indentation Mark	Start	0																																																																												
	Start	0																																																																												
	End	0																																																																												
Crimp Burr Height	Start																																																																													
	End																																																																													
Crimp Burr Height	Start																																																																													
	End																																																																													
Confirm Curve	Start	0																																																																												
	Start	0																																																																												
	End	0																																																																												
Core Wire Protrusion	Start	0.02																																																																												
Pressure	Start	428																																																																												
	End	433																																																																												
Midterm Check (Wire Crimp Height)		1.01																																																																												
Tensile Strength	Start	100																																																																												
	Start	105																																																																												
	End	103																																																																												
11/18/2024	6	Added special characteristic "diamond mark" in wire crimp height and tensile strength and remove stabilizer width	W. Bergado	C. Calayan	W. Carbillon	Prepare	Check	Approve																																																																						
11/03/2023	5	Include checking of indentation mark in crimp wire	W. Bergado	O. Merin	O. Merin	  																																																																								
06/01/2022	4	Add details include Control Chart Rules	W. Bergado	O. Merin	O. Merin																																																																									
11/1/2021	3	Change number of sample from 3 samples to 5 samples	W. Valdez	D. Cornero	O. Merin																																																																									
Est./Rev. Date	Rev. No.	Details of change	Revise	Check	Approve	Est. date:	July 10, 2017																																																																							



Process Name/ Title:		Document No:		WI-PRO-CNC-009	
Wire Cutting and Crimping / Crimp Data Gathering Procedure					
WORK INSTRUCTION		Effective Date:		November 18, 2024	
Product Code/Name:	Customer Code:	Rev. No.:	6	Page No.:	2 of 2
All	All				

No.	Work Procedure/ Illustration	Records/Remarks/ Quality Pointers																																																
	<p style="text-align: center;"><b>Figure 1. ILLUSTRATION OF CONTROL CHART RULES</b></p> <table><thead><tr><th>Rule</th><th>Rule Name</th><th>Pattern</th></tr></thead><tbody><tr><td>1</td><td>Beyond Limits</td><td>One or more points beyond the control limits</td></tr><tr><td>2</td><td>Zone A</td><td>2 out of 3 consecutive points in Zone A or beyond</td></tr><tr><td>3</td><td>Zone B</td><td>4 out of 5 consecutive points in Zone B or beyond</td></tr><tr><td>4</td><td>Zone C</td><td>7 or more consecutive points on one side of the average (in Zone C or beyond)</td></tr><tr><td>5</td><td>Trend</td><td>7 consecutive points trending up or trending down</td></tr><tr><td>6</td><td>Mixture</td><td>8 consecutive points with no points in Zone C</td></tr><tr><td>7</td><td>Stratification</td><td>15 consecutive points in Zone C</td></tr><tr><td>8</td><td>Over-control</td><td>14 consecutive points alternating up and down</td></tr></tbody></table> <div><p><b>Figure 1.1: Rules 1 to 4</b></p><p><b>Figure 1.2: Rules 5 and 6</b></p><p><b>Figure 1.3: Rules 7 and 8</b></p></div> <table><thead><tr><th>Pattern Description</th><th>Rules</th><th>Possible Causes</th></tr></thead><tbody><tr><td>Large shifts from the average</td><td>1, 2</td><td>New person doing the job Wrong setup Measurement error Process step skipped Process step not completed Power failure Equipment breakdown</td></tr><tr><td>Small shifts from the average</td><td>3, 4</td><td>Raw material change Change in work instruction Different measurement device/calibration Different shift Person gains greater skills in doing the job Change in maintenance program Change in setup procedure</td></tr><tr><td>Trends</td><td>5</td><td>Tooling wear Temperature effects (cooling, heating)</td></tr><tr><td>Mixtures</td><td>6</td><td>More than one process present (e.g. shifts, machines, raw material.)</td></tr><tr><td>Stratifications</td><td>7</td><td>More than one process present (e.g. shifts, machines, raw materials)</td></tr><tr><td>Over-control</td><td>8</td><td>Tampering by operator Alternating raw materials</td></tr></tbody></table>	Rule	Rule Name	Pattern	1	Beyond Limits	One or more points beyond the control limits	2	Zone A	2 out of 3 consecutive points in Zone A or beyond	3	Zone B	4 out of 5 consecutive points in Zone B or beyond	4	Zone C	7 or more consecutive points on one side of the average (in Zone C or beyond)	5	Trend	7 consecutive points trending up or trending down	6	Mixture	8 consecutive points with no points in Zone C	7	Stratification	15 consecutive points in Zone C	8	Over-control	14 consecutive points alternating up and down	Pattern Description	Rules	Possible Causes	Large shifts from the average	1, 2	New person doing the job Wrong setup Measurement error Process step skipped Process step not completed Power failure Equipment breakdown	Small shifts from the average	3, 4	Raw material change Change in work instruction Different measurement device/calibration Different shift Person gains greater skills in doing the job Change in maintenance program Change in setup procedure	Trends	5	Tooling wear Temperature effects (cooling, heating)	Mixtures	6	More than one process present (e.g. shifts, machines, raw material.)	Stratifications	7	More than one process present (e.g. shifts, machines, raw materials)	Over-control	8	Tampering by operator Alternating raw materials	
Rule	Rule Name	Pattern																																																
1	Beyond Limits	One or more points beyond the control limits																																																
2	Zone A	2 out of 3 consecutive points in Zone A or beyond																																																
3	Zone B	4 out of 5 consecutive points in Zone B or beyond																																																
4	Zone C	7 or more consecutive points on one side of the average (in Zone C or beyond)																																																
5	Trend	7 consecutive points trending up or trending down																																																
6	Mixture	8 consecutive points with no points in Zone C																																																
7	Stratification	15 consecutive points in Zone C																																																
8	Over-control	14 consecutive points alternating up and down																																																
Pattern Description	Rules	Possible Causes																																																
Large shifts from the average	1, 2	New person doing the job Wrong setup Measurement error Process step skipped Process step not completed Power failure Equipment breakdown																																																
Small shifts from the average	3, 4	Raw material change Change in work instruction Different measurement device/calibration Different shift Person gains greater skills in doing the job Change in maintenance program Change in setup procedure																																																
Trends	5	Tooling wear Temperature effects (cooling, heating)																																																
Mixtures	6	More than one process present (e.g. shifts, machines, raw material.)																																																
Stratifications	7	More than one process present (e.g. shifts, machines, raw materials)																																																
Over-control	8	Tampering by operator Alternating raw materials																																																