

**WORK INSTRUCTION**Process Name/Title: **TAPING ASSEMBLY PROCESS**

Effectivity Date:

**May 05, 2022**Model Code/Part Number: **740BW / 7H0423W7020**Customer: **NBS**

Validity Date:

**n/a**Purpose: ☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Document No.:

**WI-ENG-PDE-479A**

Revision No.:

**1**


Page No.:

**1 of 5****PARTS:**

1. Connector 6098-3802 (W); AVSSf 0.3 B L=621±3mm; Black corrugated tube (no slit) ø5 L=518±5mm; Black tape [1pc.]

JIG:

1. Insertion jig
2. Locking jig
3. Terminal cover jig

NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
1	P1	Table Lay-out 	<b>Safety Instruction</b> Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)  <b>Housekeeping</b> 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.  <b>Alert level</b> For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.	<i>Note: Refer to WI-PRO-CNC-017 for Wire and Strip Length Tolerance</i>  1. No missing parts/tools 2. No excess parts/tools

## Revision History

Eff. Date	Rev. No	Details of Change	Revised	Checked	Approved	Noted	Prepared by	Reviewed by	Reviewed by	Approved by
05/05/22	1	Change document purpose from pre-launch to masspro. Additional table layout.	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes
04/20/22	0	Initial issue	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes

**CONFIDENTIAL:** Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

**NBC (Philippines)**  
**MASTER COPY**

DCC Stamp



# WORK INSTRUCTION

## TAPING ASSEMBLY PROCESS

Effectivity Date:

May 05, 2022

Process Name/Title:

Model Code/Part Number: 740BW / 7H0423W7020

Customer:

NBS

Validity Date:

n/a

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Document No.:







WI-ENG-PDE-479A

Revision No.:

1

Page No.:

2 of 5

PARTS:		1. Connector 6098-3802 (W)		JIG	1. Insertion jig 2. Locking jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
2	P1	<p>Connector setting to insertion jig 6098-3802 (W)</p>    <p>1. Press the lock of insertion jig using left thumb.</p> <p>2. Insert the connector 6098-3802 (W) into jig using right hand then release the lock. <i>Note: Follow the connector orientation.</i></p>  <p>3. Check the holes/terminal slot for B-wires.</p>		n/a	<p><b>Connector Orientation Illustration</b></p>   <p>1. Use provided jig per model 2. No wrong usage of parts 3. No wrong orientation of connector 4. No damaged connector</p>

**CONFIDENTIAL:** Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)  
MASTER COPY

DCC Stamp



## WORK INSTRUCTION

## TAPING ASSEMBLY PROCESS

Effectivity Date:

May 05, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 740BW / 7H0423W7020

Customer:

NBS

Document No.:

WI-ENG-PDE-479A

Purpose:












☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

3 of 5

PARTS:		1. AVSSf 0.3 B L=621±3mm [2pcs.]		JIG	1. Insertion jig 2. Locking jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
3	P1	<div></div> <div><p>1. Get the <b>1st Black wire</b> then insert to terminal slot <b>1</b> of connector using right hand. <i>Note: Insertion of wires must be from left to right</i></p><p>2. Get the <b>2nd Black wire</b> then insert to terminal slot <b>2</b> of connector using right hand.</p></div> <div></div> <div><p>3. After insertion, push the lock using left thumb and then hold the wires and gently pull out the connector from jig using right hand.</p></div>		n/a	<p><i>Note: Refer to WI-PRO-CNC-017 for Wire and Strip Length Tolerance</i></p> <p>1. No loose insertion 2. No wrong insertion 3. One by one insertion 4. No deform terminal 5. No wrong wire facing</p> <p>Make sure wires are properly inserted. Conduct <b>Pull-Push-Pull-Push</b> after insertion. Do not exert extra force."</p> <p><i>Note: Please hold the wire near terminal during insertion.</i></p>
4		<div></div> <div><p>1. Put the connector into locking jig both hands then press <b>2x</b> to lock using both hands. Touch the connector lock to confirm if properly locked. <i>Note: Please refer to GL-PRO-ASY-017 for the verification of connector lock.</i></p></div> <div></div> <div></div>		LOCKING JIG 	<p><b>NOTE: MANUAL LOCKING MAY CAUSE DAMAGED CONNECTOR LOCK</b></p> <p>1. Use the provided locking jig per modle 2. No unlocked/half-locked connector 2. No damaged lock</p>

**CONFIDENTIAL:** Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)  
**MASTER COPY**

DCC Stamp



## WORK INSTRUCTION

## TAPING ASSEMBLY PROCESS

Effectivity Date:

May 05, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 740BW / 7H0423W7020

Customer:

NBS

Document No.:

WI-ENG-PDE-479A

Purpose:






☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

4 of 5

PARTS:		1. Assy parts 2. Black corrugated tube (no slit) $\phi 5$ L=518 $\pm$ 5mm			JIG	1. Terminal cover jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS	
5	P1	Wire insertion to corrugated tube (no slit) $\phi 5$ L=518 $\pm$ 5mm	<div><p>1. Hold the wires using left hand, get the terminal cover jig using right hand then insert the <b>B-B wires</b> using left hand.</p></div> <div><p>2. Get the corrugated tube (<b>no slit</b>) <math>\phi 5</math> L=518<math>\pm</math>5mm using right hand then insert the <b>B-B wires</b> using left hand.</p></div> <div><p>3. After insertion, remove the terminal cover jig using right hand.</p></div>	<div><b>TERMINAL COVER JIG</b></div> 	1. No wrong usage of parts 2. No deformed terminal	
6		Taping 1 Black corrugated tube to wire near terminal	<div><p>Start of taping</p></div> <p>1. Hold the COT using left hand, get the <b>Black tape</b> using right then start pre-taping at the middle of COT and wires using both hands.</p>	n/a	1. No peel-off tape 2. No flip out tape 3. No loose tape 4. No wrong use of tape 5. No wrong dimension	

**CONFIDENTIAL:** Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)  
**MASTER COPY**

DCC Stamp



## WORK INSTRUCTION

## TAPING ASSEMBLY PROCESS

Effectivity Date:

May 05, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 740BW / 7H0423W7020

Customer:

NBS

Document No.:

WI-ENG-PDE-479A

Purpose:

☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

5 of 5

## PARTS:

1. Assy parts
2. Black tape

## JIG

n/a

## NO.

## PROCESS NAME

## WORK PROCEDURE/ ILLUSTRATION


## TOOLS/PPE

## QUALITY POINTERS


6

P1


Taping 1  
Black corrugated tube to  
wire near terminal  
(Continuation)




2. Confirm measurement of  $25 \pm 3\text{mm}$  from end of tape up to COT then continue the taping process using both hands.



3. Measure from end of COT up to terminal pointed tip  $L=65 \pm 3\text{mm}$  then continue the taping process using both hands.



4. Confirm measurement of  $40 \pm 3\text{mm}$  from end of tape up to terminal pointed tip then continue the taping process using both hands.




5. After taping, check the measurement, terminal appearance and taping condition.

## MEASURING TAPE



## Wire alignment tolerance



1. No flip-out tape
2. No peel-off tape
3. No loose tape
4. No missing tape
5. No wrong dimension
6. No wrong use of tape

*Note:*  
Please use calibrated/verified  
measuring tape when getting the  
measurement.

**CONFIDENTIAL:** Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)  
MASTER COPY

DCC Stamp