



WORK INSTRUCTION TAPING ASSEMBLY PROCESS

Effectivity Date:

May 05, 2022

Process Name/Title:

TAPING ASSEMBLY PROCESS

Validity Date:

n/a

Product Name/Code:

014B

/

17J924-7051Y

Customer:

NBS

Document No.:

WI-ENG-PDE-493A

Purpose:



PROTOTYPE



PRE-LAUNCH



MASSPRO

Revision No.:

1

Page No.:

1 of 3

PARTS:

1. Connector 1827842-1 (W)

JIG:

1. Insertion jig

NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
1	P1 Connector setting to insertion jig 1827842-1 (W)	<div><div>INSERTION JIG</div><div>Visual reference</div><div>Button</div><div>Guide Lock</div><div>CONENECTOR ORIENTATION</div><div>Double lock</div><div>1. Get the connector 1827842-1 (W) using right hand then set to insertion jig. Note: Follow the connector orientation.</div><div>2. Press the guide lock button using left index finger.</div><div>BEFORE PRESSING</div><div>AFTER PRESSING</div></div>	<div>Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)</div> <div>Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.</div> <div>Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.</div> <div>Finger COTS</div>	<div>1. Use the provided jig per model 2. No wrong usage of parts 3. No wrong orientation of connector 4. No damaged connector 5. No half-locked connector</div> <div>Note: Automatically dispose and replace the unit if once encountered Bend terminal, Difficulty of insertion, Half-locked connector.</div> <div>Note: If encountered abnormality, STOP and immediately CALL the attention of the leader. WAIT for further instruction and continue the process. Do not attempt to repair.</div> <div><div>GOOD</div><div>NG</div><div>UNLOCK</div><div>HALF-LOCKED</div></div>

Revision History

Eff. Date	Rev. No	Details of Change	Revised	Checked	Approved	Noted	Prepared by	Reviewed by	Approved by	Noted by
05/05/22	1	Change document purpose from pre-launch to masspro	M. Catapang	J. Loterte	C. Villanueva	A. Arañes				
04/28/22	0	Initial issue	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

Effectivity Date:

May 05, 2022

Process Name/Title:

TAPING ASSEMBLY PROCESS

Validity Date:

n/a

Product Name/Code:

014B / 17J924-7051Y

Customer:

NBS

Document No.:

WI-ENG-PDE-493A

Purpose:

☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:







2 of 3

PARTS:

1. CIVUS 0.13 W L=183±2mm; G L=186±2mm; R L=184±2mm; Y L=180±2mm; BR L=178±2mm; L L=184±2mm;
LG L=176±2mm; P L=177±2mm; V L=177±2mm; GR L=179±2mm; OR L=181±2mm; B L=181±2mm; G L=1±193mm; R L=192±2mm; B L=193±2mm;

JIG

1. Insertion jig

NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS																																					
2	P1 Wire insertion to connector (Group 1 & 3 wires) 1827842-1 (W)	<div><div>WIRE INSERTION ILLUSTRATION</div><div></div></div> <div><div><div>GOOD Smaller terminal</div><div></div></div><div><div>NG Long terminal</div><div></div></div></div> <div><div>Wire facing</div><div></div></div> <div><div>Note: Hold on wire during insertion must be 5mm away from terminal end.</div><div></div></div> <div><div>17J924-7051Y</div><div>X</div><table><tr><td>X</td><td>W</td><td>G</td><td>R</td><td>Y</td><td>BR</td><td>L</td><td>LG</td><td>P</td><td>LOCK</td><td>V</td><td>GR</td><td>OR</td><td>B</td><td>G</td><td>R</td><td>B</td><td>X</td><td>X</td></tr><tr><td>-</td><td>183</td><td>186</td><td>184</td><td>180</td><td>178</td><td>184</td><td>176</td><td>177</td><td>-</td><td>177</td><td>179</td><td>181</td><td>181</td><td>193</td><td>192</td><td>193</td><td>-</td><td>-</td></tr></table><div><div>1. Get the wire and hold it 5mm away from terminal.</div><div>2. Half insert the wire.</div><div>3. Release wire to check the color.</div><div>4. Hold again 5mm away from terminal</div><div>5. Fully inserted wires (avoid bending during insertion)</div><div>Note: Follow the insertion sequence based on the visual reference</div></div></div> <div><div>Finger COTS</div><div></div></div>	X	W	G	R	Y	BR	L	LG	P	LOCK	V	GR	OR	B	G	R	B	X	X	-	183	186	184	180	178	184	176	177	-	177	179	181	181	193	192	193	-	-	<div>1. No wrong wire insertion</div> <div>2. No terminal backing out</div> <div>3. No deformed terminal</div> <div>4. Make sure wires are properly inserted.</div> <div>5. Must have slight MOVEMENT after insertion</div> <div>6. No bend terminal/wires</div> <div>Note: Make sure wires are properly inserted. Conduct Pull-Push-Pull-Push after insertion. Do not exert extra force.</div> <div>Note: Automatically dispose and replace the unit if once encountered Bend terminal, Difficulty of insertion, Half-locked connector.</div> <div>Note: If encountered abnormality, STOP and immediately CALL the attention of the leader. WAIT for further instruction and continue the process. Do not attempt to repair.</div>
X	W	G	R	Y	BR	L	LG	P	LOCK	V	GR	OR	B	G	R	B	X	X																							
-	183	186	184	180	178	184	176	177	-	177	179	181	181	193	192	193	-	-																							

Note: Refer to WI-PRO-CNC-017 for Wire and Strip Length Tolerance**Note: Make sure wires are properly inserted.
Conduct Pull-Push-Pull-Push after insertion.
Do not exert extra force.****Note: Automatically dispose and replace the unit if once encountered Bend terminal, Difficulty of insertion, Half-locked connector.****Note: If encountered abnormality, STOP and immediately CALL the attention of the leader. WAIT for further instruction and continue the process.
Do not attempt to repair.**

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

Effectivity Date:

May 05, 2022

Process Name/Title:

TAPING ASSEMBLY PROCESS

Validity Date:

n/a

Product Name/Code:

014B / 17J924-7051Y

Customer:

NBS

Document No.:

WI-ENG-PDE-493A

Purpose:










☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

3 of 3

PARTS:		1. Assy parts			JIG	1. WIP Holder	
NO.	PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE		QUALITY POINTERS
2	P1	Wire insertion to connector (Group 1 & 3 wires) 1827842-1 (W) (Continuation)	<div><div><div>Button</div></div><div><div>ion must be</div></div><div><div>R</div></div><div>BEFORE PRESSING</div><div>AFTER PRESSING</div><div>6. Press the button using left thumb.</div><div>7. Hold the wires using right hand then gently pull out the connector from jig. Check the insertion condition.</div></div>		<div>Finger COTS</div> <div></div> <div>GOOD</div> <div>NG</div> <div></div> <div></div> <div><div>Damaged/whitens</div></div>		1. No wrong wire insertion 2. No terminal backing out 3. No deformed terminal 4. Make sure wires are properly inserted. 5. Must have slight MOVEMENT after insertion 6. No bend terminal/wires
			3	Pass WIP to P2	<div></div> <div>1. Pass WIP to WIP Holder. Note: One piece flow.</div>		<div>WIP HOLDER</div> <div></div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp