

**WORK INSTRUCTION**

Process Name/Title:

TAPING ASSEMBLY PROCESS

Effectivity Date:

October 09, 2023

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Document No.:

WI-ENG-PDE-724B

Purpose:

☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

1 of 9

PARTS:		1. Assy Parts 2. Black Corrugated tube $\phi 5$ L=65 \pm 3mm 3. Gray Urethane foam t=4; 75mm X 30mm		4. Black Tape 5. Gray Tpe		JIG:		1. Continuity Checker jig 2. Terminal Cover jig	
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION				TOOLS/PPE		QUALITY POINTERS	
1	P2 Table Lay-out	<div><div>1</div><div>TABLE LAY-OUT</div><div>Corrugated tube $\phi 5$ L=65\pm3mm</div><div>Gray Urethane foam t=4; 75mm X 30mm/ Foam holder</div><div>Assy Parts</div><div>Terminal Cover jig</div><div>Black tape w/ tape holder</div><div>Gray tape w/ tape holder</div></div>				<div>Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)</div> <div>Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.</div> <div>Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.</div>		1. No deformed terminal 2. No wrong usage of parts	
Revision History						Prepared by	Reviewed by	Approved by	Noted by
10/09/23	1	Change purpose from Pre-launch to Masspro. Additional table lay-out; Update Quality checkpoints; Inclusion of Continuity checking process.				A.Hernandez	J.Loterte	C. Villanueva	A. Arañes
09/06/23	0	Initial release				A.Hernandez	J.Loterte	C. Villanueva	A. Arañes
Eff. Date	Rev. No	Details of Change				Revised	Reviewed	Approved	Noted
						Est. Date:	September 06, 2023		

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

**WORK INSTRUCTION**

Process Name/Title:

TAPING ASSEMBLY PROCESS

Effectivity Date:

October 09, 2023

Validity Date:

n/a

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Document No.:

WI-ENG-PDE-724B

Purpose:





☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

2 of 9

PARTS:		1. Assy Parts 2. Black Corrugated tube (no slit) Ø5 L=65±3mm		JIG:	1. Terminal Cover jig
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
2	P2	<div><div><p>1. Hold the wires using left hand, get the terminal cover jig using right hand then insert the B and B wires using left hand.</p></div><div><p>2. Get the corrugated tube (no slit) Ø5 L=65±3mm using right hand then insert the B and B wires using left hand.</p></div><div><p>3. After insertion, remove the terminal cover jig using right hand.</p></div></div>		<div>TERMINAL COVER JIG</div> 	1. No wrong use of parts 2. No deformed terminal Document references: 1. Refer to WI-PRO-CNC-017 for Wire and Strip length tolerance.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)**MASTER COPY**

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Process Name/Title:

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Purpose:

☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Effectivity Date:

October 09, 2023

Validity Date:

n/a

Document No.:







WI-ENG-PDE-724B

Revision No.:

1

Page No.:

3 of 9

PARTS:		1. Assy parts 2. Black tape		JIG:	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
3	P2 Taping 2 Black corrugated tube to wire near terminal	<div><p>Start of taping</p></div> <div><p>60 ± 3mm</p></div> <div><p>1. Hold the COT using left hand, get the Black tape using right hand then start pre-taping using both hands.</p></div> <div><p>2. Measure from end of COT up to terminal pointed tip 60±3mm then continue the taping process using both hands.</p></div> <div><p>32 +3mm -1mm</p></div> <div><p>3. Confirm measurement of 32+3/-1mm from end of tape up to terminal pointed tip then continue the taping process using both hands.</p></div> <div><p>tape width</p><p>32+3/-1</p></div> <div><p>3. After taping, check the measurement, taping condition and terminal appearance.</p></div>		<div><p>MEASURING TAPE</p></div> <div><p>Wire alignment tolerance</p><p>0 - 1 mm</p></div>	<div><p>1. No flip-out tape</p><p>2. No peel-off tape</p><p>3. No loose tape</p><p>4. No missing tape</p><p>5. No wrong use of tape</p><p>6. No wrong dimension</p></div> <div><p>Important reminders/Note/s:</p><p>1. Please use calibrated/verified measuring tape when getting the measurement.</p></div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Process Name/Title:

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Effectivity Date:

October 09, 2023

Validity Date:

n/a

Document No.:











WI-ENG-PDE-724B

Revision No.:

1

Page No.:

4 of 9

PARTS:		1. Assy parts 2. Gray tape		JIG:	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
4	P2	Y-TAPING	<div><p>No gap between Corrugated tubes</p><p>1. Fix the corrugated tube.</p><p>Note: Do not exert excessive force during pulling & winding of tape</p><p>2. Start taping at the middle of combined Corrugated tubes, then wind the tape to left side, measurement from end of connector up to end of tape must be 56mm.</p><p>3. Wind the tape 1/3 shifting until it reach the other side of corrugated tube (must be tape width)</p><p>4. Wind the tape backward 1/2 shifting.</p><p>5. Wind the tape 1/2 shifting going to other side of corrugated tube then cut the tape. After taping, check the condition of tape.</p></div>		 <p>Good Measurement</p>  <p>GOOD FACING</p>  <p>NG FACING</p> <p>Important reminders/Note/s:</p> <ol style="list-style-type: none">1. Used Yellow tape for easy visualization of shifting lines, but actual should be GRAY TAPE.2. Please use calibrated/verified measuring tape when getting the measurement. <ol style="list-style-type: none">1.No flip out tape2.No tape peeling3. No loose tape4. No wrong use of tape5. No gap between Corrugated tubes6. No exposed wire

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

**WORK INSTRUCTION****TAPING ASSEMBLY PROCESS**

Effectivity Date:

October 09, 2023

Process Name/Title:

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Validity Date:

n/a

Document No.:

WI-ENG-PDE-724B

Purpose:














☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

5 of 9

PARTS:		1. Gray Urethane foam t=4; 75mm X 30mm 2. Assy parts		JIG:	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
5	P2 Urethane foam manual attachment to connector	<div><div>Step 1: Identify the right facing to attached the foam</div><div><div>COT</div><div>Connector</div><div></div></div><div><div>Step 2: Get the Urethane foam and begin the attachment. Note: Foam and connector must be align</div><div><div>L</div><div>R</div><div></div></div><div><div>Step 3: Attached the foam in all sides of the connector. Note: Follow the attachment sequence based on the illustration</div><div><div>L</div><div>R</div><div></div><div></div><div></div><div><div>L</div><div>R</div><div></div><div></div><div>Step 4: Press the Urethane foam side by side after attachment.</div></div></div></div><td>N/A</td><td><div>DO NOT STRETCH THE URETHANE FOAM</div><div><div></div><div>GOOD</div><div><div>Over-stretched</div><div>Excess foam</div><div></div><div>NG</div><div></div><div>0~3mm tolerance from Urethane foam to Connector</div></div><div>1. No damaged Urethane foam 2. No missing Urethane foam 3. No stretched Urethane foam</div></div></td></div></div>		N/A	<div>DO NOT STRETCH THE URETHANE FOAM</div> <div><div></div><div>GOOD</div><div><div>Over-stretched</div><div>Excess foam</div><div></div><div>NG</div><div></div><div>0~3mm tolerance from Urethane foam to Connector</div></div><div>1. No damaged Urethane foam 2. No missing Urethane foam 3. No stretched Urethane foam</div></div>

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Effectivity Date:

October 09, 2023

Process Name/Title:

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Validity Date:

n/a

Document No.:

WI-ENG-PDE-724B

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH





















☒ MASSPRO


Revision No.:

1

Page No.:



7 of 9

PARTS:		1. Assembled parts 2. Master sample		JIG:	n/a									
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS									
7	P2	Visual/By Two's Inspection			1. No skip checking during inspection.									
		<div><div><p>Assemble parts</p></div><div><p>ACTUAL PRODUCTS</p></div><div><p>2. Check the connector lock condition, insertion and terminal.</p></div><div><p>3. Check the taping condition of COT to wire near connector</p></div><div><p>4. Check the presence of attached urethane foam.</p></div><div><p>1. Conduct alignment of harness (Master sample vs. Assembled part) using right hands.</p></div><div><p>5. Check the Y-taping condition. Color of tape must be <u>GRAY</u> only.</p></div><div><p>6. Check the taping condition from COT to wire near terminal</p></div><div><p>7. Check the terminal appearance. Must be no deformed terminal.</p></div></div>		<div><p>CONNECTOR ILLUSTRATION</p><table><tr><td>GOOD</td><td>NG</td></tr><tr><td></td><td></td></tr><tr><td>7282-1028 (W)</td><td>7282-1020 (W)</td></tr></table><p>CONNECTOR ILLUSTRATION</p><table><tr><td>GOOD</td><td>NG</td></tr><tr><td></td><td></td></tr><tr><td>7283-1138 (W)</td><td>7283-1030 (W)</td></tr></table></div>		GOOD	NG			7282-1028 (W)	7282-1020 (W)	GOOD	NG	
GOOD	NG													
														
7282-1028 (W)	7282-1020 (W)													
GOOD	NG													
														
7283-1138 (W)	7283-1030 (W)													



CONNECTOR ILLUSTRATION



GOOD NG



7282-1028 (W) 7282-1020 (W)

CONNECTOR ILLUSTRATION

GOOD NG



7283-1138 (W) 7283-1030 (W)

1. No skip checking during inspection.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

**WORK INSTRUCTION****TAPING ASSEMBLY PROCESS**

Process Name/Title:

Effectivity Date:

October 09, 2023

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Validity Date:

n/a

Document No.:

WI-ENG-PDE-724B

Purpose:


☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

8 of 9

PARTS:		n/a		JIG:	n/a
NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
8	Measurement				1. No wrong dimension Important reminders/Note/s: 1. Please use calibrated/verified measuring tape when getting the measurement 2. For Hatsumono and Owarimono only
	P2				

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY

DCC Stamp



WORK INSTRUCTION

Process Name/Title:

TAPING ASSEMBLY PROCESS

Effectivity Date:

October 09, 2023

Validity Date:

n/a

Model code/Part number:

TP1 / 7L0144-7020A

Customer:

TRQSS

Car Model:

SUBARU-ASCENT

Document No.:

WI-ENG-PDE-724B

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Revision No.:

1

Page No.:

9 of 9

PARTS:

n/a

JIG:

n/a

1 QUALITY CHECKPOINTS

P2

7L0144-7020A



GOOD




NO GOOD



GOOD



NO GOOD



GOOD



NO GOOD

① No Unlocked/ Half Locked Connector

② No Terminal Backing Out

③ ④ No wrong insert

⑤ No Missing Sponge tape

⑥ ⑦ ⑧ No Missing Tape/ No wrong color of tape

⑨ No Deformed Terminal

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp