

# Test Procedures

## Introduction:

The purpose of this test procedure is for Hold Down and Cycling on package parts WS1050 from 16 DUT board, and this test procedure is using in WiSpry Lab in Irvine only.

### Hardware and Software requirement:

- a. Hardware:
  1. Agilent 3631A, for VDD, +3.3V, -3.3V
  2. Ke2000 for current measurement
  3. Ke2400 for VSA test
  4. PXI 1033 chassis
  5. NI PXI-7813R, FPGA Card for RFFE and I2C

- b. Software:

**Test program: WS1050, 16 DUT Reliability HD\_Cycling Ver1.4**

[illegible]

This test program will be found at the link below:

S:\Software\_Control\Released\16 DUT Board\WS1050 16 DUT Reliability HD\_Cycling  
Ver1.4

## Set up and run Test Program:

1. Set temperatures from the oven/chamber:  
Adjust temperatures from the oven/chamber to meet the requirement (25C, 45C, 55C, 65C or 85C with no control RH)

2. Verify Socket button should be “ON” when you run repeat measurement to verify




socket stable

**Note: look up table will be different when you run repeat measurement. The look up table file name is “Looping”**





3. Verify Socket button was set “OFF” by default to run HD/Cycling.

4. Open the test program at the link above. Click on  this button to run the test program. **Note: the test program will ask for a look up table, the look up table will be found on the desktop under 16 Sockets Read point folder, with the file name “16 socket cycling new”**


5. Sockets Calibration:


Make sure the conditions to run the test from oven/chamber meet the



requirement then click on  button to zero out the 16 sockets, verify C1, C2 and C3 at window below are ~0 (zeroes).


| AD7747 Values |        |             |        |             |        |             |  |
|---------------|--------|-------------|--------|-------------|--------|-------------|--|
|               | C1 Sta | C1 Cap (pF) | C2 Sta | C2 Cap (pF) | C3 Sta | C3 Cap (pF) |  |
| DUT 01        | 0x02   | 0.152438    | 0x02   | -0.058442   | 0x02   | 0.067255    |  |
| DUT 02        | 0x02   | 0.033258    | 0x02   | 0.005974    | 0x02   | 0.014205    |  |
| DUT 03        | 0x02   | 0.226388    | 0x02   | 0.003757    | 0x02   | 0.168344    |  |
| DUT 04        | 0x02   | 0.030068    | 0x02   | 0.004873    | 0x02   | 0.017689    |  |
| DUT 05        | 0x02   | 0.032447    | 0x02   | 0.029040    | 0x02   | 0.053197    |  |
| DUT 06        | 0x02   | 0.045178    | 0x02   | -0.065956   | 0x02   | -0.139374   |  |
| DUT 07        | 0x02   | -0.010476   | 0x02   | -0.020510   | 0x02   | 0.018441    |  |
| DUT 08        | 0x02   | 0.012951    | 0x02   | 0.004848    | 0x02   | 0.028392    |  |
| DUT 09        | 0x02   | 0.027858    | 0x02   | 0.004833    | 0x02   | 0.018257    |  |
| DUT 10        | 0x02   | 0.027373    | 0x02   | 0.008214    | 0x02   | 0.016012    |  |
| DUT 11        | 0x02   | -0.151929   | 0x02   | 0.059726    | 0x02   | -0.044856   |  |
| DUT 12        | 0x02   | 0.203760    | 0x02   | 0.043981    | 0x02   | 0.245991    |  |
| DUT 13        | 0x02   | 0.027700    | 0x02   | 0.007252    | 0x02   | 0.015369    |  |
| DUT 14        | 0x02   | 0.021777    | 0x02   | 0.003091    | 0x02   | 0.014485    |  |
| DUT 15        | 0x02   | 0.030861    | 0x02   | 0.004624    | 0x02   | 0.018500    |  |
| DUT 16        | 0x02   | 0.028230    | 0x02   | 0.010058    | 0x02   | 0.021235    |  |

6. Click on  button to stop the calibration
7. Set the CP voltage to HD/Cycle by selecting CP voltage was setting on this box




CP HDC 40.25V

8. Set the CP voltage to measure capacitance by selecting CP voltage was setting




CP HDC 40.25V


9. Set the CP voltage to measure VPI by selecting CP voltage setting on this box



CP HDC 30.5V

10. Verify VDD = 3.7V on this box 

11. Set percent duty cycle by selecting percent duty cycle was setting on this box



25%\_DC

RFFE CLK


12. Enter Lot #, Wafer # into this box

| Lot#   | Wafer# |
|--------|--------|
| WS1050 | T7-EB  |

13. Enter serial number of 16 DUT

|   |   |   |   |   |   |   |   |   |    |    |    |    |    |    |    |
|---|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 |
|---|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|


14. File name:



CYC\_WS1050\_T7\_EB\_65C\_40V\_50DC\_EMPTY\_BRD3\_140423\_10


Cyc\_Lot #\_Wafer #\_Design\_Temperature\_Voltage Cycle\_Duty  
Cycle\_Board\_Date\_Run #

15. Directory to save the test data: this is by default




C:\WS1050 16 DUT Data

16. Set the number of cycles to complete: Enter the number of cycles you want to



2000



2000

**Note: These two numbers should be the same for cycling, and not the same for HD.**

17. You have an option to start the test immediately by clicking on start test button or you can select date/time to start running the test program.

Current Date: 5/2/2014  
Current Time: 1657  
Start Date: 4/24/2014  
Start Time: 1542  
START TEST

18. You have an option to run HD/Cycle with E-Fuse ON/OFF by clicking on this

EFUSE ON/OFF  
OFF

button

19. You have an option to run HD/Cycle with DVA ON/OFF by clicking on this button

DVA On/OFF  
OFF

20. You also have an option to measure VPI, VSA by selecting Yes/No on these two

VPI Test YES  
VSA Test YES

buttons

, these two buttons were set “Yes” by default.

HD/Cycles  
Cycles

21. This button was set by default “Cycles”

HS Test  
YES

22. Handshake check was set “YES” by default

23. Load parts into 16 sockets and verify Cmin at the window below. Cmin is ~1.2pF for all 3 banks, C1, C2 and C3.

| AD7747 Values |        |             |        |             |        |             |  |
|---------------|--------|-------------|--------|-------------|--------|-------------|--|
|               | C1 Sta | C1 Cap (pF) | C2 Sta | C2 Cap (pF) | C3 Sta | C3 Cap (pF) |  |
| DUT 01        | 0x02   | 0.152438    | 0x02   | -0.058442   | 0x02   | 0.067255    |  |
| DUT 02        | 0x02   | 0.033258    | 0x02   | 0.005974    | 0x02   | 0.014205    |  |
| DUT 03        | 0x02   | 0.226388    | 0x02   | 0.003757    | 0x02   | 0.168344    |  |
| DUT 04        | 0x02   | 0.030068    | 0x02   | 0.004873    | 0x02   | 0.017689    |  |
| DUT 05        | 0x02   | 0.032447    | 0x02   | 0.029040    | 0x02   | 0.053197    |  |
| DUT 06        | 0x02   | 0.045178    | 0x02   | -0.065956   | 0x02   | -0.139374   |  |
| DUT 07        | 0x02   | -0.010476   | 0x02   | -0.020510   | 0x02   | 0.018441    |  |
| DUT 08        | 0x02   | 0.012951    | 0x02   | 0.004848    | 0x02   | 0.028392    |  |
| DUT 09        | 0x02   | 0.027858    | 0x02   | 0.004833    | 0x02   | 0.018257    |  |
| DUT 10        | 0x02   | 0.027373    | 0x02   | 0.008214    | 0x02   | 0.016012    |  |
| DUT 11        | 0x02   | -0.151929   | 0x02   | 0.059726    | 0x02   | -0.044856   |  |
| DUT 12        | 0x02   | 0.203760    | 0x02   | 0.043981    | 0x02   | 0.245991    |  |
| DUT 13        | 0x02   | 0.027700    | 0x02   | 0.007252    | 0x02   | 0.015369    |  |
| DUT 14        | 0x02   | 0.021777    | 0x02   | 0.003091    | 0x02   | 0.014485    |  |
| DUT 15        | 0x02   | 0.030861    | 0x02   | 0.004624    | 0x02   | 0.018500    |  |
| DUT 16        | 0x02   | 0.028230    | 0x02   | 0.010058    | 0x02   | 0.021235    |  |