

How to Set Up the Height Sensor


Height Sensor: If the height of the workpiece is not 100% consistent from part-to-part, using this optional accessory and function could improve your contact dispense outcomes. A properly installed and adjusted contact probe height sensor will detect the height of discreet points along a workpiece and automatically adjust the tip height before the robot dispenses. **The contact probe height sensor should not be dragged along a continuous line!**

Follow the steps outlined in the 7361667 "Instructions for Height Sensor Installation" (document # 7362786) to install the Height Sensor onto the robot. (Remember to set the probe height 5-8mm above the level of the dispense tip and to set the probe regulator to 0.2MPa)

After wiring the Height Sensor cables to the robot I/O Connector, you can trigger the I/O Output to verify the I/O Output and Input pins you are using. (When you click on the Output, the probe will toggle down, and the associated Input will illuminate.) These are the I/O pin values you will set for the Height Sensor.


1. Adjust the air pressure to 0.5 MPa (≈ 70 PSI)

6mm Regulator. "IN"




4mm Regulator "OUT"
(To Sol. "IN")

2. Adjust Height sensor (A is pneumatic cylinder, B is an optical sensor)





4mm Probe "IN"
(From Sol. "OUT")

- To adjust the pneumatic cylinder pressure, loosen the “B” locking screw and adjust the “A” knob/set screw. (The tighter A is, the faster the probe retracts). Adjust “A” until the pneumatic cylinder retracts smoothly and then tighten “B” locking screw.




- Optical sensor signal. Input 5 is OFF, means the optical sensor light barrier is not broken (pneumatic cylinder is going up). Input 5 is ON, means the optical sensor light barrier is broken (pneumatic cylinder is going down). Hint: Use Machine IO to check (System Setup IO).




Robot I/O Port Pin Assignments			
Pin 1	Input 1	Pin 14	Output 1
Pin 2	Input 2	Pin 15	Output 2
Pin 3	Input 3	Pin 16	Output 3
Pin 4	Input 4	Pin 17	Output 4
Pin 5	Input 5	Pin 18	Output 5
Pin 6	Input 6	Pin 19	Output 6
Pin 7	Input 7	Pin 20	Output 7
Pin 8	Input 8	Pin 21	Output 8
Pin 9	n/a	Pin 22	n/a
Pin 10	n/a	Pin 23	n/a
Pin 11	Ground	Pin 24	+24 VDC
Pin 12	Ground	Pin 25	+24 VDC
Pin 13	Ground	n/a	n/a

5. Solenoid valve. When Output 5 is OFF, the LED of the solenoid is dark (When I/O is off, the pneumatic cylinder is going up).



When Output 5 is ON, the LED of the solenoid lights up (When I/O is on, the pneumatic cylinder is going down)



How to Use Height Sensor

Enable Height Sensor

- Click <System Setup> then click <Open>
- Check "Height Sensor" – the <Toggle Probe> button in the Tab bar – means function enabled!
- **Note:** Complete the "Robot Initial Setup" before using the Height Sensor

Height Sensor Setup

1. Click <CAMERA> tab, click <Setup> (top of camera screen), then click on Height Sensor tab – above keypad.
2. The Height Sensor fields appear
3. In fields, top right corner of Height Sensor box, enter
 - a. Probe Output – I/O Output pin you are using (default = 5)
 - b. Sensor Input – I/O Input pin you are using (default = 5)
 - c. Detect Speed (mm/s) – **1mm/s** (recommended) Range: 1-20mm/s
 - d. Travel Limit (mm): **15mm** (recommended) Range: 1-100mm

The screenshot shows the 'Height Sensor' setup screen. It features several input fields and buttons. At the top left, there are fields for 'Sensor move' (87.941), 'Set' (83.866), and a '0' field. Below these are 'Toggle Probe' (a black square button) and 'Initial Height Detect' (5.794). To the right, under the 'Offsets' section, are 'Probe move' (32.577, 39.322, 5.827) and 'Camera move' (121.255, 35.544, 11.561). At the bottom, there are fields for 'Probe Output' (5), 'Sensor Input' (5), 'Detect Speed (mm/s)' (1), and 'Travel Limit (mm)' (50). A 'Ccd Setup' button is at the bottom left, and a 'Height Sensor' tab is at the bottom right.


Notes: Detect Speed = Z-head speed to workpiece, after probe extends
Travel Limit = range of Z-axis movement to detect part

4. Click <Toggle Probe> - the probe extends from height sensor.


5. Jog the extended probe tip to a target dispense location on the workpiece – lower the extended probe until it is centered over the target and touching the substrate – then Z-up to set the probe ~3mm above the same target.



6. Click <Set> next to <Sensor Move>, the robot will record the current positional coordinates for the deployed probe at ~3mm above the target. Then click <Initial Height Detect>, the robot will move the probe up and then down again until it touches the target on the substrate. (This establishes the Current Z-Height Value).



7. Now, set the Probe-to-Camera Offset.
8. Hit the <Toggle Probe> button to extend the probe and jog the probe over a target on the workpiece. With the probe centered over the target click the <Set> button next to >ProbeMove



9. Hit the <Toggle Probe> button to retract the probe, then jog the camera over the same target, until the target is centered and in sharp focus, then click <Set> next to <Camera Move>.




10. DONE! The Height Sensor is now setup and ready to use.

Note: If you click <Offset Program> at this point the system will update the Z-height values in the open program. (The system will lower and raise the probe. If the Z-height value is different, the system prompts user to confirm and accept the new values – click <YES>)

Use Height Sensor in Program

1. Open the desired dispense program, then click <Toggle Probe>
2. Jog to the target location for the height check on the workpiece
3. Jog the Z-axis to place probe ~3mm above the target on the workpiece
4. Double-click on the Address Row where you want to install a Height Sensor command, then select "Height Sensor" command from the drop-down menu
5. Click <OK> to accept the current XYZ values
6. Click <Toggle Probe> to retract the probe



The system will now check the workpiece height at that target location each time the program runs.

