

## Tx Rx Filter v1.0 PCB Errata

17th Aug, 2017


18th Oct, 2017

ji1udd

There is two known errata.

### 1) Wrong Silk

The silks near RF2 and RF3 are swapped



RF3  
from HPF  
to RX (HLv2)

RF2  
from PA (HLv2)  
to T/R relay

### 2) Leakage current

Leakage occurred from DB10-1(+12V source) to +3.3V through Relay driver (TPL 7407) while HL2 turned off. Add high side switch.

