

SDK 6.5.20

Release Notes

Table of Contents

[Section 1: About This Document](#)

[Section 2: New Devices added to this release](#)

[Section 2.1: Supported DNX Switch Devices](#)

[Section 3: Information per Device](#)

[This release is an increment version for DPP, DNX, DNXF, DFE family devices.](#)

[Section 3.1: DNX-Family](#)

[Section 3.1.1: Important Notes](#)

[Section 3.1.1.1: Backward Compatible Important Notes](#)

[Section 3.1.2: SDK build & load](#)

[Section 3.1.3: New Features since 6.5.19](#)

[Section 3.2: DNXF-Family \(BCM88790-Family\)](#)

[Section 3.2.1: Important Notes](#)

[Section 3.3: DPP-Family - BCM88670/680/470/270 Family GA Release](#)

[Section 3.3.1: New Features since 6.5.19](#)

[Section 3.4: DFE-Family - BCM88770 \(FE3600\) Release](#)

Section 1: About This Document

This document contains the release notes for DNX devices affected by the Broadcom network switching Software Development Kit (SDK) release 6.5.20.

The document provides a general description of the SDK and its new features. It also describes the DNX chips supported by the release, BCM API additions or changes, resolved issues, and any relevant open issues.

Only new features are described in this document. For a comprehensive review of the DNX SDK features and issues, refer to earlier release notes for SDK 6.5.x.

For the full resolved list (Both Bugs and Improvement), please reference the file SDK-6.5.20-Resolved-Issues-Improvements.xlsx in the RELDOCS directory in the release package.

Section 2: New Devices added to this release

For any given SDK release, support for certain devices may be provided in preview or supported status. Devices in “Supported DNX Switch Devices” have completed the full QA process and are intended for use in production systems. It is expected that customers would integrate the version of the SDK which provides "Supported" status for their use on actual development or production systems.

Devices in “Preview DNX Switch Devices” are provided to allow early integration of the customer's application with the SDK APIs that support that device. This software has not been fully tested on the physical target device and is not expected to fully function.

Section 2.1: Supported DNX Switch Devices

| <i>Family</i> | <i>Devices</i> | <i>Description</i> |
|----------------------|-----------------------|---------------------------|
| BCM8828X | | Q2U - GA quality |
| BCM8880X | | J2C - GA quality |
| BCM8848X | | Q2A - GA quality |
| BCM8869X | | J2 - GA quality |
| BCM8879X | | Ramon - GA quality |
| BCM8868X | | J+ - GA quality |
| BCM8837X/BCM8867X | | JR - GA quality |
| BCM8827X | | QUX - GA quality |
| BCM8847X | | QAX - GA quality |

Section 3: Information per Device

This release is an increment version for DPP, DNX, DNXF, DFE family devices.

The subsequent sections describe the increment in available features compared to 6.5.19, backward-compatible notes, major bug-fixes and known issues.

It is very important to carefully go over the release-notes prior to adapting a new release.

The following sections describe the features validated for this release, known issues and bring-up guidelines.

Section 3.1: DNX-Family

This section includes the following family devices:

- **BCM8869X-Family (Jericho2)**
- **BCM8880X/BCM8882X-Family (Jericho2C)**
- **BCM8848X-Family (Qumran2A)**
- **BCM8828X-Family (Qumran2U)**

Please use the PCIe firmware version 2.5.1-DNX with this release.

This version can be found under Firmware/pcie/dnx/v2.5.1/.

Section 3.1.1: Important Notes

Before integrating the new release, review this section thoroughly.

| JIRA | Module | Description | Affected Devices |
|------|--------|---|---------------------------|
| - | KBPSDK | <p>SDK is aligned to KBPSDK version 1.5.13</p> <p>Note: KBPSDK is required for DPP devices or when DNX family devices are working with external KBP. For DNX devices there is no need to to use KBPSDK for KAPs. To compile without KBPSDK remove from FEATURE_LIST KBP</p> | 88690, 88800, 88480 |
| - | MBIST | <p>We require that after running a Memory Built In Self Test (MBIST), that the device it runs on either be powered off or system reset (hardware reset by de-asserting the signal SYS_RST_N from the board).</p> <p>Without this action we do not guarantee that the device will work properly, and therefore from this release the software enforces it.</p> <p>This is a new requirement for BCM8869x (Jericho 2), independent of the SDK release.</p> <p>For BCM8880x, BCM8882x (Jericho 2C), BCM8848x (Qumran 2A) we previously required a power off, and now also accept a system reset.</p> | 88690, 88800, 88480 |



| | | | |
|--|--|---|--|
| | | <p>Note that both powering off the device and a system reset of the device, also involve a PCIe reset of the device, and the PCIe link of the device going down; so the customer BDE needs to support this operation if done while the BDE and SDK are running.</p> <p>We provide a callback function skeleton <code>dnxc_perform_system_reset()</code> in <code>src/appl/reference/dnxc/appl_ref_board.c</code> that may be used to perform these operations automatically on the customer board.</p> <p>An example of how this function is registered in the sample application can be seen in the <code>dnxc_perform_system_reset()</code> in <code>src/appl/reference/dnxc/appl_ref_init_deinit.c</code>.</p> <p>To have the call back function used automatically after running MBIST, and enable to continue running the SDK later, use this new soc property: <code>perform_system_reset_when_needed=1</code>.</p> <p>If a device power off, or system reset is not actually performed, the SDK will recognize this, fail, and not continue running, and not run when started again.</p> <p>The MBIST is meant to test memories when there is a suspicion of device malfunction and is not mandatory. As described here, with some effort it is possible to run MBIST before each SDK runs, but this is not the intention of the test.</p> <p>The changed MBIST and CPU2TAP code in the release, together with the new requirement, fix possible PCIe issues in 8869x (Jericho 2).</p> | |
|--|--|---|--|

Section 3.1.1.1: Backward Compatible Important Notes

SW Compatibility Guidelines 6.5.19 to 6.5.20

Please go over the list carefully.

Note: This document is written with the assumption that upgrade is done from 6.5.19 to 6.5.20.
In case upgrade is done from older releases, users must first go over previous release notes.

| JIRA | Module | Description | Affected Devices |
|------------|------------|--|--|
| SDK-219645 | QOS | bcmQosControlMplsIngressPopQoS Preserve now requires flag BCM_QOS_MAP_L3 to be set with the right type (IPv4, IPv6) | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-217217 | VSWITCH | bcm_vswitch_cross_connect_traverse returns now flag BCM_VSWITCH_CROSS_CONNECT_DIRECTIONAL. In previous, flag was not returned and then fails to delete cross-connection which is created with flag BCM_VSWITCH_CROSS_CONNECT_DIRECTIONAL. This release fixes the issue and changes the return flags compared to the previous release. | 88480_A0, 88480_B0, 88690_B1, 88800_A0 |
| SDK-217140 | FC | Improve accuracy of API bcm_cosq_pfc_deadlock_control_set with type bcmCosqPFCDeadlockDetectionTimer. Implications are that the actual detection time will be as close to the user set value as possible, which might be different than previous behavior(depending on the value that was set). Also, a check for the pulse generator period was improved, which means that it may fail in some scenarios that were previously passing when the values of pulse generator period and detection timer are very close to each other. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-216939 | INT-ET | bcm_instru_gport_control_set with bcmInstruGportControlTraceProbability was not set correctly, instead of setting percentage to X%, the API set percentage to (100-X)%. This is now fixed. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-216836 | COE | PCP/DEI of COE tag can be sourced from port now by calling bcm_switch_control_port_set(unit,coe_port,bcmSwitchTagPcpDeiSrc,3). PCP/DEI in COE tag is sourced from out port's attribute as default with value zero and not from Out-AC as before. | 88480_A0, 88480_B0, 88800_A0 |
| SDK-216201 | L3-IPV6-MC | Support was added for split selection for IPv4 and IPv6 forwarding type in case the IPMC routing is disabled. Using the flag BCM_L3_INGRESS_L3_MCAST_L2 when creating a RIF the user | 88480_A0, 88480_B0, 88690_A0, |



SDK-6.5.20 Release Notes

| | | | |
|------------|----------|---|--|
| | | can now indicate that v4MC forwarding type will be used. Default is v4Bridge if the flag is missing. Using the newly introduced flag BCM_L3_INGRESS_IP6_L3_MCAST_L2 - the user specifies v6MC forwarding type. Default is v6Bridge which will be selected if the flag is missing. In previous versions, BCM_L3_INGRESS_L3_MCAST_L2 related also to BCM_L3_INGRESS_IP6_L3_MCAST_L2 by mistake. In case user wish to allow both types (IPv4 and IPv6), it should call both flags. | 88690_B1, 88800_A0 |
| SDK-214175 | TRAP | Force forward application will not work if the injected packet has ITMH header. ITMH application was refactored to not overwrite the traps with highest strength (0xF). Thus allowing force forwarded packets can reach their destination (regardless of the ITMH header). This change is true for all trap-actions of strength 0xF prior to PMF application (for ITMH injected packets). | 88480_A0, 88480_B0 |
| SDK-213934 | INT-IFA | TTL field on Metadata should be outgoing TTL (incoming TTL -1) and not incoming TTL. | 88480_B0, 88690_B1, 88800_A0 |
| SDK-212714 | L2 | The following list of BCM APIs delete MACT entries according to one or more properties of the entries: bcm_l2_addr_delete_by_port() bcm_l2_addr_delete_by_mac() bcm_l2_addr_delete_by_vlan() bcm_l2_addr_delete_by_trunk() bcm_l2_addr_delete_by_mac_port() bcm_l2_addr_delete_by_vlan_trunk() bcm_l2_addr_delete_by_vlan_port() The above APIs did not support the flag BCM_L2_DELETE_STATIC properly. When the flag wasn't set, the APIs still deleted static entries. This is fixed. Now static entries are deleted only when BCM_L2_DELETE_STATIC is set. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-212572 | LAG-PP | bcm_port_control_set bcmPortControlSystemPortInjectedMap does not support trunk-member port anymore. Instead, it is expected to be called only with local ports or trunk gports. In case of trunk gport, the mapping of trunk SPA with masked members and the relevant pp port per core is done. The API returns an error if it is called with trunk member. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-212462 | COSQ-ING | VOQ bundle can be allocated in the limits of one queue region. An error is returned now in case of VOQ allocation outside the limits of a queue region. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-211382 | PTP | APIs bcm_port_timesync_config_set/get, bcmPortControl1588P2PDelay are now supported according to Trunk-member (local-port) and not according to Trunk-group | 88480_A0, 88480_B0, |



SDK-6.5.20 Release Notes

| | | | |
|------------|----------|--|--|
| | | (trunk-gport). The change is due to give the ability for the user to configure different values per Trunk-member. APIs call are now different than the previous release, trunk-gport will return an error, while local-port should be used instead when the port is part of the LAG. | 88690_A0, 88690_B1, 88800_A0 |
| SDK-211294 | SBFD | In the previous release, seamless bfd reflector didn't support local State change. In this release, this issue has been addressed. This may break backwards compatibility from previous version - in the past, State was copied from incoming packet, now State is taken from endpoint-create. | 88480_A0, 88480_B0, 88690_B1, 88800_A0 |
| SDK-210904 | OAM, PMF | OAM/BFD: when injecting ITMH + PPH packets from the OAMP, ingress PMF will strip and rebuild the PPH. This allows supporting Hierarchical LM counting over LIFs in OAM (supported in SDK-200941) and BFD over VXLAN (supported in SDK-206144). The side-effect of this is that the calling sequence for is that the calling sequence for OAMP punt and protection packet configuration has changed: 1. User must now allocate a user-defined trap with ID < 255 for each punt/protection packet. Traps are still allocated with the bcm_rx_trap_type_create API. A trap code may be created with or without ID. 2. When calling bcm_rx_trap_set() use the flag BCM_RX_TRAP_TRAP. 3. In order to change the trap code of a punt packet, destroy the trap and then recreate it with a new trap code. Punt/Protection packet configuration has been modified in appl_ref_oam_init.c. As a result, punt/protection packets will arrive at the CPU with a different trap code than in previous releases. An example of how to change the trap code can be found in maid_trap_set() in cint_sand_oam.c | 88480_A0, 88480_B0, 88690_B1, 88800_A0 |
| SDK-210640 | L3 | IPMC flows were slightly changed. For the case of double KAPS DB, IPv6 MC LEM entry with VRF = 0: in the previous release, it was allowed, from this release it will return error as SDK doesn't support public anymore (aligns to LPM). In this JIRA, also support for working in a state of a single KAPS DB was added. The L3 and IPMC APIs can now work correctly when the capacity of public KAPS is 0. See more information in the PG document "IPMC section". | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-210026 | LAG-PP | When a port is removed from a Trunk group, its PP port properties are lost and its properties are being reset to its header-type defaults. In previous versions, once such action happened, PP port properties were reset according to the PP default Application and not aligned to SDK port default configuration. This is now changed and port is now reset to its header-type defaults (the same as adding port in the system without running PP default application). | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |



SDK-6.5.20 Release Notes

| | | | |
|------------|-------------|--|--|
| | | <p>In order to mimic the application properties, an example was added. Please see CINT cint_port_packet_processing_example.c function: cint_port_packet_processing_removed_trunk_member_pp_properties_set.</p> <p>Bonus: An additional functionality was added to show what pp port properties should be reset before port is removed from trunk group, see function cint_port_packet_processing_pp_properties_unset.</p> <p>Note: Currently on this operation, API doesn't touch port learn property and its IngressMissDrop action. This may change in a future version. It is expected that the user will call bcm_port_learn_set, bcm_vlan_control_port_set bcmVlanTranslateIngressMissDrop to configure its expected values after port is created/removed from trunk.</p> | |
| SDK-209800 | RCY | <p>bcm_l2_egress_get API returned local-port when dest_port attribute was given to BCM_L2_EGRESS_DEST_PORT.</p> <p>API also assumed that port exists in the local-device.</p> <p>From this release, API bcm_l2_egress_set/get uses either trunk gport or system port gport in dest_port. Other types such as Local port are not supported.</p> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-209714 | TRAP | <p>bcmRxTrapDfltRedirectToCpuPacket which is configured on init, is now configured with flag BCM_RX_TRAP_TRAP which will result in adding FHEI header to the packet.</p> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-209345 | COSQ-ING | <p>Changed the error type returned by bcm_cosq_gport_get API in case of non-existing VOQ. Instead of E_NONE to an actual error. This was done to be consistent with Jericho family.</p> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-207228 | COUNTERS-PP | <p>When using VSI statistics, using API bcm_vlan_control_vlan_set, it is expected that egress_stat_id field will be equal to VSI. So far the API ignored the field. Now, it must be set with the same value with VSI once egress_stat_pp_profile is non 0.</p> | 88480_A0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-206602 | FABRIC | <p>Validation was added for all valid Fabric speed + FEC combinations so a clear error message will be returned if any invalid port resource combination is set for a fabric link.</p> | 88690_A0, 88690_B1, 88800_A0 |
| SDK-204230 | PMF | <p>bcmFieldActionParsingStartType Action now should get input bcm_field_layer_type_t. supported values are: bcmFieldLayerTypeEth, bcmFieldLayerTypeIp4, bcmFieldLayerTypeIp6, bcmFieldLayerTypeMpls, bcmFieldLayerTypeArp, bcmFieldLayerTypeFcoe, bcmFieldLayerTypePppoe, bcmFieldLayerTypeSrv6Endpoint, bcmFieldLayerTypeSrv6Beyond, bcmFieldLayerTypeTm, bcmFieldLayerTypeForwardingMPLS, bcmFieldLayerTypeUnknown,</p> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |



SDK-6.5.20 Release Notes

| | | | |
|------------|------------|---|---|
| | | <p>bcmFieldLayerTypeSctp.</p> <p>In order to get same functionality as before the change please use bcmFieldActionParsingStartTypeRaw instead.</p> | |
| SDK-200941 | OAM | <p>In order to support hierarchical loss measurement for injected OAM over MPLS-TP, below sequence should be followed:</p> <ol style="list-style-type: none"> 1. Identify y1731 OAM over PWE in egress parser by calling <code>bcm_switch_control_indexed_set</code> Please Refer to <code>dnx_oam_identify_y1731_oam_over_pwe_egress</code> in <code>cint_dnx_utils_oam.c</code> 2. Always enable counter in egress LIF profile by calling <code>bcm_oam_profile_action_set</code>. Please refer to <code>dnx_oam_egress_with_update_counter_in_egr_profile</code> in <code>cint_dnx_utils_oam.c</code> 3. For injected DMM/Rs, LMM/Rs, and piggyback CCMs (dual ended LM) over MPLS, control whether these packets should increment LM counters by calling API <code>bcm_oam_profile_action_set</code> with reserved egress acc profile, based on opcode. Please refer to <code>appl_dnx_oam_hlm_egress_with_update_counter_in_egr_acc_profile</code> in <code>appl_ref_oam_init.c</code> <p>Note, with this code change, The number of available egress acc profile is reduced to 14. Profile 0 is default profile, profile 15 is reserved for injected OAM over MPLS</p> <ol style="list-style-type: none"> 4. For OAM packets not mentioned above, counter increment indication can be controlled through the egress LIF profile, with <code>bcm_oam_profile_action_set</code>. 5. When an injected OAM packet also hits a LIF on a lower hierarchy on which another OAM endpoint exists, the OAM packet will be treated as a data packet on the lower hierarchy. For example If there are OAM MEPs with LM on a PWE and LSP LIF and the injected PWE OAM packet also hits the LSP LIF then the PWE OAM packets increment the LM counters on the LSP MEP. <p>Note that changes from SDK-210904, SDK-213820 are also required for this JIRA. Steps 1 and 2 may affect backwards compatibility to 6.5.19. Existing OAM over PWE/MPLS applications may have to be updated accordingly.</p> | 88480_A0, 88690_B1, 88800_A0 |
| SDK-191857 | OAMP-LM-DM | <p>In order to update the LM statistics for SLM entry upon reception of an SLR packet, the <code>bcm_oam_loss_add()</code> needs to be called with <code>BCM_OAM_LOSS_UPDATE_NEXT_RECEIVED_SLR</code> flag set and "id" set for endpoints with offloaded memory type, and "loss_id" set for endpoints with self-contained memory type.</p> <p>In previous releases this wasn't required for offloaded memory types, however functionality wasn't correct.</p> | 88480_A0, 88480_B0, 88690_B1, 88800_A0 |
| SDK-191419 | NIF | <p>Changed the soc property name from "use_fabric_links_for_ilkn_nif" to "ilkn_use_fabric_links".</p> | 88690_A0, 88690_B1, 88800_A0 |
| SDK-167463 | DBAL | <p>Change in string management. In order to maintain more efficient memory footprint</p> | 88480_A0, |



| | | |
|--|--|---|
| | of SDK, the strings representing enum values was reduced. This change may affect SDK CMD diagnostics , since now, users doesn't need to set the full value name, but only a shorten value name for example setting value for field PORT_TERMINATION_PTC_PROFILE: was: PORT_TERMINATION_PTC_PROFILE=PORT_TERMINATION_PTC_PROFILE_P TCH2 now: PORT_TERMINATION_PTC_PROFILE=PTCH2 | 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
|--|--|---|

Section 3.1.2: SDK build & load

Compile and set config files :

```
setenv SDK `pwd`
```

Example of SLK CPU compilation :

```
# Copy pre compiled mdb and kaps libraries into the relevant build folder.
# For SLK CPU big endian 64b build flavor, Following are the relevant 2 libraries and the
# relevant build folder (names in build folder must be libkaps.a & libmdb.a):
mkdir -p $SDK/build/unix-user/slk_be/
cp $SDK/libs/bin/dnx/SLK_64B_libkaps.a $SDK/build/unix-user/slk_be/libkaps.a
cp $SDK/libs/bin/dnx/SLK_64B_libmdb.a $SDK/build/unix-user/slk_be/libmdb.a
# Additional mdb and kaps libraries flavors can be found under $SDK/libs/bin/.
```

Compile SDK

```
cd $SDK/systems/linux/user/slk_be/
make MAKE_LOCAL=$SDK/make/local/dnx/Make.custom.dnx_kbp_slk
```

Common config files:

```
ln -fs $SDK/rc/rc.soc
ln -fs $SDK/rc/dnx.soc
ln -fs $SDK/rc/config-jer2pemla.bcm
ln -fs $SDK/tools/sand/db
ln -fs $SDK/rc/dnx_sku
ln -fs $SDK/rc/dnx_dram
ln -sf $SDK/rc/cmfcfw/linkscan_led_fw.bin
ln -sf $SDK/rc/cmfcfw/custom_led.bin
```

BCM8869X specific links:



SDK-6.5.20 Release Notes

```
In -fs $SDK/rc/config-jr2.bcm config.bcm
In -fs $SDK/rc/bcm88690_revB_board.bcm
In -sf $SDK/rc/bcm88690_board.bcm
In -sf $SDK/rc/bcm88690_legacy_interop_board.bcm
```

BCM8880X/BCM8882X specific links:

```
In -fs $SDK/rc/config-j2c.bcm config.bcm
In -sf $SDK/rc/bcm88800_board.bcm
```

BCM8848X/BCM8828X specific links:

```
In -fs $SDK/rc/config-q2a.bcm config.bcm
In -fs $SDK/rc/bcm88480_board.bcm
```

Run :

```
./bcm.user
```

Section 3.1.3: New Features since 6.5.19

The following list below specifies new features

| JIRA | Module | Description | Affected Devices |
|------------|-----------------|---|--|
| SDK-218370 | PMF-PROG-SELECT | Adding support to qualify on the MSB bit of the AcnLifWideData in CS of iPMF1. bcmQualifyAcnLifWideData should be used in bcm_field_presel_set() to qualify upon that bit. Cint example: cint_field_presel_ac_inlif_wide_data.c | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-214274 | MPLS | RA label and other special labels can be trapped with below steps: 1. Disable the auto termination by bcm_switch_control_indexed_set() with bcmSwitchMplsSpecialLabelAutoTerminateDisable; 2. Create an MPLS tunnel for this label by bcm_mpls_tunnel_switch_create(); 3. Create per In-LIF trap for the tunnel LIF created in step 2 by bcm_rx_trap_lif_set(); Note: All the signals resolved by auto termination logic are reset, such as signal "force_is_oam" for RA label. | 88480_B0, 88690_B1, 88800_A0 |
| SDK-213820 | PMF | ITMH_PPH application, also supports rebuilding FHEI type of VLAN-Edit if injected. For example if injected packet is ITMH_TSH_PPH_FHEI(vland-edit) then Ingress PMF rebuild all the system headers and the output will be FTMH_TSH_PPH_FHEI(vlan). This is required to support OAM Down MEP injection after the changes in SDK-210904 | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |



SDK-6.5.20 Release Notes

| | | | |
|------------|----------|---|--|
| SDK-213191 | PMF | New feature add, trap profile. That allow to set 1b profile when configuring trap <code>bcm_rx_trap_set()</code> , later can be qualified upon in iPMF3. Tap flag was added: <code>BCM_RX_TRAP_FLAGS2_UPDATE_ACL_PROFILE</code> Preselector qualifier was added for iPMF3 stage: <code>bcmFieldQualifyRxTrapProfile</code> Cint example of qualifier usage: <code>cint_field_presel_rx_trap_profile.c</code> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-212985 | NIF, PHY | <code>bcm_port_phy_control_set()</code> can now dynamically set the TX/RX polarity for ports on both CDU and CLU, using <code>BCM_PORT_PHY_CONTROL_TX_POLARITY</code> or <code>BCM_PORT_PHY_CONTROL_RX_POLARITY</code> controls. | 88480_A0, 88690_B1, 88800_A0 |
| SDK-209506 | RCY | Add support for a new port 'in header type' <code>BCM_SWITCH_PORT_HEADER_TYPE_RCH_1</code> - for that port types, the SSPA is taken from the RCH (RCY header), which the pp port is updated according to a mapping table, which maps the SSPA to the pp port. The mapping table can be set with API: <code>bcm_port_control_set()</code> with <code>type=bcmPortControlSystemPortInjectedMap</code> . <code>BCM_SWITCH_PORT_HEADER_TYPE_RCH_1</code> is expected to be used when the recycle is done on the Rx device, so the original SSPA is on the same device in the 2nd pass. <code>BCM_SWITCH_PORT_HEADER_TYPE_RCH_0</code> should be used when the RCY is not on the RX device, so the PRT of the other device cannot map the original SSPA to pp_port. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-209030 | LIF-MGMT | AC IN-LIF Wide data extension - Option to extend the wide data up to 58b, by additional lookup in ingress pipeline, when the key is the wide (generic) data from the AC IN-LIF. Can be used as ACL qualifier (<code>bcmFieldQualifyAcInLifWideDataExtended</code>). New APIs introduced: <code>bcm_switch_wide_data_extension_add/delete/get/traverse</code> New functionality is introduced in CINT: <code>cint_inlif_wide_data.c</code> | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-208830 | PMF | Field Group type of <code>bcmFieldGroupTypeDirectExtraction</code> is not supported for stage <code>bcmFieldStageEgress</code> . Maximum key size is 32bits. Cint example: <code>cint_field_dir_ext_epmf.c</code> | 88480_A0, 88480_B0, 88800_A0 |
| SDK-206896 | PMF-INGR | Parser now supports ETH1/2 classification according to <code>EtherType</code> . Classification was added as bit 14 of Ethernet Layer Qualifier for all parser stages. <code>bcmFieldQualifyL2Format</code> was add in PMF stage to qualify on such packets, value 0 qualifies on ETH-II while value 1 qualifies on ETH-I. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-206144 | BFD | Support for accelerated BFD over VXLAN, IPv4 and IPv6. If a VXLAN encapsulation FEC is defined, it can be used in the <code>egress_if</code> field when creating or modifying a BFD endpoint over UDP, including single-hop or multi-hop, and IPv4 or IPv6. Only IPv4 Underlay is supported with up to one VLAN tag for the underlay L2 header. Note: SDK-210904 is required, to support injecting ITMH + PPH rebuild by PMF (also for the case of BFD over VXLAN). | 88480_B0, 88690_B1, 88800_A0 |



SDK-6.5.20 Release Notes

| | | | |
|------------|---------------|---|--|
| | | Example usages: set use_vxlan_fec=1 or use_vxlan6_fec=1 in cint_sand_bfd.c or cint_sand_bfd_ipv6.c respectively. | |
| SDK-205415 | METER | Added support for managing meter profile with-id, using bcm_policer_create using flag BCM_POLICER_REPLACE_SHARED with pol_cfg.entropy_id != 0 . For further details refer to UM. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-203609 | PMF-QUAL-ACT | Parser now supports up to 2 IPv6 extension headers, first header gets parsed but second only gets recognized. To identify such packets in PMF bcmFieldQualifyIp6SecondAdditionalHeaderExist was add as Layer Record qualifier which can be checked in IPv6 Layer. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-199313 | MIRROR-PP | Sequence number in GRE header of an ERSPAN tunnel is now supported. Tunnel API can be used for that BCM_TUNNEL_INIT_ERSPAN_WITH_SN and two new fields: stat_cmd and counter_command_id. See more information in CINT: src/examples/dnx/cint_dnx_mirror_example.c | 88480_A0, 88480_B0, 88690_B1, 88800_A0 |
| SDK-197627 | COSQ-ING | New BCM API, bcm_cosq_gport_enable_set() / bcm_cosq_gport_enable_get(), was implemented to drop traffic at the ingress based on destination (system port). | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-191394 | FC | Added a new type bcmPortControlPFCStatus to API bcm_port_control_get that will give the user the ability to retrieve the current received PFC status of a port. The API will return a bitmap with priorities that are currently under PFC. | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |
| SDK-182658 | COSQ-SCH | New shell command ('dnx tm scheduler fsm ') was added to control and read Flow Status Message counters. | 88690_A0, 88690_B1 |
| SDK-176626 | METER | Meter: Support for meter expansion per TC is added. | 88480_A0, 88480_B0, 88800_A0 |
| SDK-162459 | PMF-TCAM-MGMT | Entry add by location support, in order to use feature: 1) Specify bcmFieldTcamBankAllocationModeSelectWithLocation for bank_allocation_mode on tcam_params when adding a new Field Group, and specify a list of banks to pre-allocate (user can add banks later by calling 'bcm_field_tcam_bank_add()' function). 2) When adding a new entry for the field group, entry priority now points to the absolute TCAM location of the new entry to add, while still perceiving TCAM terminology for location structure (bank_id/bank_offset), even offsets are for single-sized/double-sized keys while odd offsets can be used to point to msb-half-entries for half-sized key entries | 88480_A0, 88480_B0, 88690_A0, 88690_B1, 88800_A0 |



SDK-6.5.20 Release Notes

| | | | |
|------------|----------|--|------------------------------------|
| | | cint example: cint_field_tcam_entry_add_by_location.c | |
| SDK-109605 | COSQ-SCH | E2E port priority propagation is supported. For details, see User Manual | 88480_A0, 88480_B0, 88800_A0 |

Section 3.2: DNXF-Family (BCM88790-Family)

Please use the PCIe firmware version 2.5.1-DNX with this release.

This version can be found under Firmware/pcie/dnx/v2.5.1/.

Section 3.2.1: Important Notes

Before integrating the new release, review this section thoroughly.

| JIRA | Module | Description | Affected Devices |
|------|--------|---|------------------|
| - | MBIST | <p>We require that after running a Memory Built In Self Test (MBIST), that the device it ran on either be powered off or system reset (hardware reset by de-asserting the signal SYS_RST_N from the board).</p> <p>Without this action we do not guarantee that the device will work properly, and therefore from this release the software enforces it.</p> <p>This is a new requirement, independent of the SDK release.</p> <p>Note that both powering off the device and a system reset of the device, also involve a PCIe reset of the device, and the PCIe link of the device going down; so the customer BDE needs to support this operation if done while the BDE and SDK are running.</p> <p>We provide a callback function skeleton <code>dnxc_perform_system_reset()</code> in <code>src/appl/reference/dnxc/appl_ref_board.c</code> that may be used to perform these operations automatically on the customer board.</p> <p>An example of how this function is registered in the sample application can be seen in the <code>dnxc_perform_system_reset()</code> in <code>src/appl/reference/dnxc/appl_ref_init_deinit.c</code>.</p> <p>To have the call back function used automatically after running MBIST, and enable to continue running the SDK later, use this new soc property: <code>perform_system_reset_when_needed=1</code>.</p> <p>If a device power off, or system reset is not actually performed, the SDK will recognize this, fail, and not continue running, and not run when started again.</p> <p>The MBIST is meant to test memories when there is a suspicion of device malfunction and is not mandatory. As described here, with some effort it is possible to run MBIST before each SDK runs, but this is not the intention of the test.</p> <p>The changed MBIST code in the release, together with the new requirement, fixes</p> | 88790 |



| | | | |
|--|--|--|--|
| | | possible false MBIST failures and possible PCIe issues | |
|--|--|--|--|

Section 3.3: DPP-Family - BCM88670/680/470/270 Family GA Release

This release contains:

- BCM88670 (Jericho) family product lines.
- BCM88270 (QUX) family product line
- BCM88470 (QAX) family product line
- BCM88680 (Jericho+) family product line

Section 3.3.1: New Features since 6.5.19

The following list below specifies new features.

| JIRA | Module | Description | Affected Devices |
|------------|----------|--|---|
| SDK-197627 | COSQ-ING | New BCM API, bcm_cosq_gport_enable_set() / bcm_cosq_gport_enable_get(), was implemented to drop traffic at the ingress based on destination (system port). | 88270_A0, 88470_A0, 88470_B0, 88670_A0, 88670_B0, 88680_A0 |

Section 3.4: DFE-Family - BCM88770 (FE3600) Release

None