



Process Planning



How are we feeling after our Flex Week break?



Total Results: 157

Announcements

- The CNC Machining Assessment peer review submission is due this (Week 7) Thursday at 09:00pm.
- It is entirely optional but it gives you a great opportunity to get feedback from your peers and see other student's CAM strategies
- Don't forget, if you pass the manufacturability review the first-time round, you get a bonus 7.5% to the mark you achieve.
 - This is not too hard but you need to pay close attention to your CAM programming
 - Review the entire simulation, **CAREFULLY!!!**
- Tutorials are up and running this week! "Machining and its Importance in Engineering"

Announcements

- I know that the panic can be super real sometimes so I will be organizing some additional open consultations
 - **Wednesday 17:00 (Additional Consult)**
 - **Thursday 11:00 (Additional Consult)**
 - **Thursday 21:00 (Last Minute Consult)**
 - **Friday 12:30 (SOS CONSULT)**


Topics

- Process Plans
- Component Drawings
- Assembly Drawings
- Bill of Materials
- Assembly Chart
- Routing Chart
- Work Method Sheet

Process Plans

- Process plans are a set of documents that detail how to achieve a desired manufacturing outcome.
- You already have some experience in creating process plans, what do you think they would be?

Which of these are process planning documents/files?




Process Plans


- Process plans are a set of documents that detail how to achieve the manufacturing outcome.
- You already have some experience in creating process plans, what do you think they would be?
- Processing planning documents:
 - Component drawings
 - Assembly drawings
 - Bill of Materials
 - Assembly Chart
 - Work Method Sheet
 - Routing Chart

Component Drawings

- A component drawing focuses on an individual part
- It gives all the information needed to understand how to manufacture the component



Who typically creates a component drawing?



Engineer

✓ 113

Machinist

4

Total Results: 117


Assembly Drawings

- An assembly drawing provides all the information on how various component fit together
- They contain information to facilitate the assembly
- Assembly drawings are sometimes called “installation drawings”
- An exploded view is not strictly necessary but can assist with readability
- A table listing all the parts required for the assembly is usually included

Assembly Parts List

ITEM	PART #	DESCRIPTION	QUANTITY
1	SS7-FS-0035	PUSHROD CARBON TUBE	1
2	SS7-FS-0037	PUSHROD END FITTING	2
3	00227154	M10 THIN NUT	2
4	GAR10-LK	10MM MALE ROD END	2

Dimensions



ROD ENDS SHOULD BE PARALLEL

FRONT VIEW

Assembly notes


BOND END FITTINGS INTO CARBON TUBE USING
3M DP420 OR SIMILAR ADHESIVE

EXPLODED ISOMETRIC VIEW

SUNSWIFT RACING 2020/21					
DIMENSION IN MILLIMETRES	SURFACE FINISH UNLESS NOTED OTHERWISE	TITLE	FRONT PUSHROD	DRAWN BY	ALEX AIR
DO NOT SCALE	N/A	CHECKED BY	BEN HEINA	DRAWING NUMBER	SS7-FS-0033
	TOLERANCE UNLESS NOTED OTHERWISE	APPROVED BY	CHRIS JENKINS	SHEET NO	2
	N/A	MATL	VARIOUS	SCALE	1:2
	IF IN DOUBT ASK	REV	01	DATE	28/03/2021
				TOTAL SHEETS	1
				QTY PER	2

SOLIDWORKS Educational Product. For Instructional Use Only.

Who typically creates an assembly drawing?



Engineer

✓ 106

Machinist

15

Total Results: 121

Bill of Materials

- This lists everything that is needed to manufacture and assembly your design
 - Contains much more detail for each component such as unit cost, supplier, manufacturer, order status, etc.
 - Very important when it comes to costing our products

QTY	Part Type	Designator	Footprint (Package type)	Description	Manufacturer	Supplier	Order Status (20/5/2020)	R = Rework W = Wave S H = Hand S N = Non	Cost per unit Ex GST	Total Cost Ex GST	N
1	22K	R43	0805(ACTUAL)	Res 1%	Open.PHYCOMP 232273462203	Open.FEC: 9237788	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich		0.09	0.09	
1	38K	R44	0805(ACTUAL)	Res 1%	Open.PHYCOMP 232273462982	Open.FEC: 9237829	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich		0.09	0.09	
1	74HC14 HEX SCHRMITT	U7	SOIC8	HEX NON Inverting Schmitt Trigger	Open e.g. NXP Semiconductors: 74HC14MD	Open e.g. Digkey: 569-14100-5-ND	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	1.15	1.15	
4	Jumper	JP2, JP4, JP3, JP1	JUMPER_3PIN	CON, JUMPER, Through Hole 0.1"	Open	Open e.g. FEC: 9237977 & 1008684	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	1.71	6.84	
1	98K	R45	0805(ACTUAL)	Res 1%	Open.MULTICOMP MC 0.1V 0805 1% 98K	Open.FEC: 9323843	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich		0.06	0.06	
11	100K	R6, R12, R10, R46, R47, R18, R19, R3, R8, R10, R4	0805(ACTUAL)	Res 1%	Open.PHYCOMP 232273463004	Open.FEC: 9237973	Ordered: Farnell (RECEIVED)		0.09	0.99	
22	100N	C18, C6, C5, C14, C24, C17, C7, C4, C8, C3, C5, C2, C12, C11, C9, C10, C21, C18, C1, C13, C20, C19	0805(ACTUAL)	Cap, 50V, 5%, NPO	Open. AVX 0805C104KAZ2A	Open.FEC: 1508905	Ordered: Farnell (RECEIVED)		0.63	13.26	
1	200R	R16	0805(ACTUAL)	Res 1%	Open.MULTICOMP MC 0.1V 0805 1% 200R	Open.FEC: 9322799	Ordered: Farnell (RECEIVED)		0.06	0.06	
2	220N	C19, C15	SMD_CAP_CASE_G	Electrolyte 220u 50V +/-20%	Open e.g. PANASONIC: EEEFY3423P	Open e.g. FEC: 9695966	Ordered: Farnell (RECEIVED)	RoHS	2.02	4.04	
4	500R	R12, R18, R17, R12, R19, R12, R10, R10, R19, R15, R14, R14, R12	0805(ACTUAL)	Res 1%	Open.MULTICOMP MC 0.1V 0805 1% 500R	Open.FEC: 9333332	Ordered: Farnell (RECEIVED)		0.06	0.94	
2		U2, U10	2391-RELAY-DRIVER	High Side Driver, I _{max} (Source) 500mA, V _{max} 50V	ALLEGRO MICROSYSTEMS:A282SLV-T	Open e.g. Farnell: 9326220	Ordered: Farnell (RECEIVED) At BCS	RoHS	4.03	8.06	
1	ADM1232 BROWN OUT/TIMEOUT	U9	SOIC8	A/D voltage monitor 4.5V or 4.75V, A/D strobe monitor with 85ms, 600ms, 12s options	ANALOG DEVICES: ADM1232APR2	Open e.g. FEC: 1438932	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	3.9	3.9	
2	B55108	Q2, Q1	SOPT23_M08	MOSFET	Open.FAIRCHILD SEMICONDUCTOR B55108...	Open.FEC: 9845330	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich		0.76	1.52	
2	0NP	C22, C23	0805(ACTUAL)	Cap	0NP	0NP	N/A			0	
1	DPDT REED RELAY	U6	OMRON-GRK-2F-5VDC	DPDT reed relay, Coil Voltage 5V, I _{max} 10V, I _{coil} 150R, I _{mat} 6.5A	OMRON: GRK-2F-DC5	Farnell: 4963714	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	5.92	5.92	
1	Diode Connector	P1	CM26VERT_LATCHED	Conn, Through, 26 Pin, DC Keyed Board Header with Latch	MULTICOMP: MC16102-2434, 3M N1423-4302PB, HARTING: 0918 526 7904	Open e.g. FEC: 3165569, 3099029, 9828109, 997009	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	17	17	
1	EP1M10K10Q100-10M	U3	PQFP168	IC, FPGAs, Programmable Logic Device (FPGA)	Altera: EP1M10K10Q100-10	Open e.g. Digkey: EP1M10K10Q100-10	Ordered: Austec (RECEIVED) At BCS		52.5	52.5	
1	ICD_3PIN	P3	ICD1WERT	Conn, Through, 10 Pin, DC Keyed Board Header, 0.1"	Open*	Open e.g. FEC: 10199254, Elertec: PPH100 (Not RoHS)	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	0.93	0.93	
1	L298 Motor Driver	U1	L298 MOTOR DRIVER	Dual H-bridge motor driver, V _s up to 48V, Total DC Current 2A, Over temp protection	ST Microelectronics: L298	Open e.g. Digkey: 457-3624-1-ND (Prelimed), RS Components: 370-4953, FEC: 402395	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	6.26	6.26	
1	LM6102	U11	SOIC8	IC: SOIC8 DUAL OPAMP, Rail to Rail input, Rail to Rail output, 2.7V to 24V	NATIONAL SEMICONDUCTOR: LM6102AIM	Open e.g. FEC: 3490043	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	7.07	7.07	
1	Laser Diode Driver	S1	CON:DB5-FEMALE-VERTICAL	Conn, Through, DB9S Straight, Female	TYCO ELECTRONICS: 3 AMP, 3-834223-2	Open e.g. FEC: 5882967	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	4.14	4.14	
1	Over Temp Conn	J2	CON:MOLEX-3	Conn, Through, MOLEX KK 2.54mm, 3 Pin Straight	Molex: 22-27-2031	Open e.g. FEC: 9721056	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich	RoHS	156	156	
1	PBBA-2405C	U5	PBBA-2405C	Vin 24V, V _{out} 5V, I _{out} 1.2A, P _{max} 6V, I _{out} 150mV ripple	Powertech: PBBA-2405C	Powertech: PBBA-2405C	Ordered: Farnell (RECEIVED) Sent to C.M. Enrich		55	55	

Assembly Chart

- An assembly chart shows the order of assembly.
 - This is given to factory workers in order to assemble a product.
- The assembly chart clearly groups the various parts that make up each sub-assembly.
- It is NOT an exploded view.

Assembly Chart


BOM

No.	Part No.	Part Name
1	51292	Outlet End
2	51284	Handle
3	52043	Switch & Insulator
4	51576	Electric Cord
5	51265	Rear Housing
6	51268	Motor Mounting Plate
7	51495	Motor Assy. & Fan Spacer
8	51270	Screw & Lock Washer Assy.
9	51273	Stationary Fan
10	51488	Rotary Fan & Spacer Assy.
11	51281	Front Fan Cover
12	51272	Forward Housing
13	51286	Air Filter
14	52388	Reusable Bag
15	51288	Inlet End Assy.
16	51642	Upholstery Tool
17	52074	Crevice Tool
18	50815	Dusting Tool
19	57432	Packaging Material (not shown)


Exploded View



Assembly Chart



Who typically creates an assembly chart?



Engineer

✓ 100

Machinist

21

0 20 40 60 80 100

Total Results: 121

Work Method Sheet

- A work method sheet shows in detail HOW a component is to be manufactured
- Individual operations required to manufacture a component are listed
- Important details for each operation are required such as:
 - Operation times
 - Required tools, fixtures, gauges
 - Machine set up
 - Risk assessment and OHS issues

Work Method Sheet

Part Name: Valve Body						
Part No: 302						
Customer Name: Midwest Valve Co.						
Quantity: 15						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time	Risk Assessment
10	Inspect forging, check hardness	Rockwell tester				
20	Rough machine flanges	Lathe No. 5				
30	Check Settings & Start	Lathe No. 5				
40	Bore & counter bore holes	Boring mill No. 1				
50	Turn internal grooves	Boring mill No. 1				
60	Drill & tap holes	Drill press No. 2				
70	Grind flange end faces	Grinder No. 2				
80	Grind bore	Int. grinder No. 1				
90	Clean	Vapour degreaser				
100	Inspect	Ultrasonic tester				

Who typically creates a work method sheet?


Part Name: Valve Body						
Part No: 302						
Customer Name: Midwest Valve Co.						
Quantity: 15						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time	Risk Assessment
10	Inspect forging, check hardness	Rockwell tester				
20	Rough machine flanges	Lathe No. 5				
30	Check Settings & Start	Lathe No. 5				
40	Bore & counter bore holes	Boring mill No. 1				
50	Turn internal grooves	Boring mill No. 1				
60	Drill & tap holes	Drill press No. 2				
70	Grind flange end faces	Grinder No. 2				
80	Grind bore	Int. grinder No. 1				
90	Clean	Vapour degreaser				
100	Inspect	Ultrasonic tester				

Engineer

25

Machinist


✓ 100




Total Results: 125

Routing Chart

- A routing chart is a graphical representation of the entire manufacturing process.
- It is used in conjunction with the work method sheet.
 - The operation number provides more information for a given stage in the routing chart.



Who typically creates a routing chart?



Engineer

A

Machinist

B

✓ 119

0 20 40 60 80 100

Total Results: 129


Let's See How it Works for a Case Study

- We have now covered off a range of process planning documents.
- These allow us (in theory) to successfully manufacture parts in an efficient and effective manner.
- Let's consider a very simple product, a G-clamp!




Process Planning for a G-clamp

- First, we would need some engineering drawings!
- Here is an example of the various drawings needed for the clamp assembly!




Process Planning for a G-clamp

- Next, let's get an assembly drawing



Process Planning for a G-clamp

- Once we are ready to begin preparing for manufacture we can create a routing chart.
- This assists in visualising the required manufacturing processes.




Process Planning for a G-clamp

- Finally, a work method sheet would be generated for each component to be used by workshop staff.

Part Name: Clamp Body Part No: 302 Customer Name: Midwest Valve Co. Qty: 100						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time (min)	Risk Assessment
10	Inspect casting, check hardness	Rockwell tester			1	
25	Drill 10mm hole for clamp screw	Drill press No.2	500 rpm	10 mm twist drill bit	3	
30	Tap M10 for the clamp screw hole	Drill press No.2	500 rpm	M10 tapping bit	2	
40	Drill 5 mm hole for lower shoe	Drill press No.2	500 rpm	5mm twist drill bit	3	
50	Tap M5 for the lower shoe hole	Drill press No.2	500 rpm	M5 tapping bit	2	
60	Inspect	Calipper			1	

Process Planning for a G-clamp



Part Name: Clamp Body Part No: 302 Customer Name: Midwest Valve Co. Qty: 100						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time (min)	Risk Assessment
10	Inspect casting, check hardness	Rockwell tester			1	
25	Drill 10mm hole for clamp screw	Drill press No.2	500 rpm	10 mm twist drill bit	3	
30	Tap M10 for the clamp screw hole	Drill press No.2	500 rpm	M10 tapping bit	2	
40	Drill 5 mm hole for lower shoe	Drill press No.2	500 rpm	5mm twist drill bit	3	
50	Tap M5 for the lower shoe hole	Drill press No.2	500 rpm	M5 tapping bit	2	
60	Inspect	Calliper			1	