

PIC24FJ128GA204 Family Silicon Errata and Data Sheet Clarification

The PIC24FJ128GA204 family devices that you have received conform functionally to the current Device Data Sheet (DS30010038B), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC24FJ128GA204 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (B3).

Data Sheet clarifications and corrections start on [page 7](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select Programmer > Reconnect.
 - b) For MPLAB X IDE, select Window > Dashboard and click the **Refresh Debug Tool Status** icon ().
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24FJ128GA204 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾
		B3
PIC24FJ128GA204	0x4C53	0x04
PIC24FJ128GA202	0x4C52	
PIC24FJ64GA204	0x4C51	
PIC24FJ64GA202	0x4C50	

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC24FJXXGA2/GB2 Family Flash Programming Specification" (DS30000510) for detailed information on Device and Revision IDs for your specific device.

PIC24FJ128GA204 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾
				B3
UART	Break Character Transmission	1.	The Transmit Shift Register Empty (TRMT) bit is unreliable when there is back-to-back Break character transmission.	X
A/D Converter	Band Gap Voltage Measurement	2.	Incorrect Band Gap Reference (V _{BG} /2) measurement with the A/D Converter at full speed.	X
Input Capture	Synchronous Cascade mode	3.	Even numbered timer does not reset on a source clock rollover in synchronous cascaded operation.	X
Output Compare 3, 4, 5 and 6	PWM mode	4.	In the scaled down timer source for the Output Compare module, the first PWM pulse may not appear on the OCx pin.	X
CTMU		5.	The Edge Enable bit (EDGEN) generates a glitch on the CTEDx input.	X
UART1 and UART2	SmartCard/ Interrupt	6.	Early interrupt for the last byte in T = 1 mode.	X
UART1 and UART2	SmartCard/ Guard Time Counter	7.	Guard Time Counter (GTC) is off by one count in T = 0 and T = 1 modes.	X
POR/BOR	Reset	8.	If the Brown-out Reset (BOR) is disabled, the part may fail to come out of the Reset state during the V _{DD} power-down and the subsequent power-up condition.	X
POR/BOR	Reset	9.	When the BOR is disabled, the part may not start at the minimum V _{DD} specification.	X
Output Compare	Sync Mode	10.	The Output Compare (OC) module does not get synchronized with the source timer in Sync mode when the source timer is running with an external clock.	X
Input Capture	Sync Mode	11.	The Input Capture (IC) module does not get synchronized with the source timer in Sync mode when the source timer is running with an external clock.	X
UART1 and UART2	SmartCard/ Receive	12.	Receive interrupt is asserted early, affecting SmartCard operation.	X
UART1 and UART2	SmartCard/ Interrupt	13.	Clearing a UxSCINT register status bit clears all status bits.	X
UART1 and UART2	SmartCard/ Waiting Time Counter	14.	Waiting time is extended by 11 ETUs when WTCx > 10.	X
SPI	Master Mode	15.	Transmit watermark interrupt is not asserted in Master mode with more than one data packet in FIFO.	X
I ² C	Slave Mode	16.	Bus data corruption with multiple slaves on bus.	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24FJ128GA204 FAMILY

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**B3**).

1. Module: UART

The Transmit Shift Register Empty (TRMT) bit is unreliable when there is back-to-back Break character transmission.

For back-to-back Break characters, the TRMT bit may not reflect the actual status. If user software is polling for this bit to be set, it may result in dummy bytes getting transmitted instead of Break characters.

Work around

Poll the UARTx Transmit Break bit, UTXBRK (UxSTA<11>), to be cleared instead of the TRMT bit (UxSTA<8>) to be set. The UTXBRK status bit will be cleared after a Break character transmission.

Affected Silicon Revisions

B3							
X							

2. Module: A/D Converter

Incorrect VBG/2 voltage measurement of the A/D Converter at full speed.

When the A/D Converter is converting at full speed (500 kps for 10-bit and 200 kps for 12-bit), the A/D Converter count may not match the VBG/2 voltage.

Work around

The A/D Converter clock should be lowered to below 100 kps (in 12-bit mode) to read the correct value of the VBG/2 voltage. In 10-bit mode, the clock must be lowered to below 200 kps.

Affected Silicon Revisions

B3							
X							

3. Module: Input Capture

The even numbered timer does not reset on a source clock rollover in Synchronous Cascaded mode operation.

In the cascaded configuration, ICy:ICx (ICy represents the even numbered modules and ICx represents the odd numbered modules) form a single 32-bit module. In Synchronous Cascaded mode (IC32 = 1, ICTRIG = 0 and the SYNCSEL<4:0> bits are not equal to 0h), both timers, ICyTMR:ICxTMR, must reset on a Sync_trig input from the 32-bit source timers, but only the odd timer (ICxTMR) is getting reset on a Sync_trig input.

Work around

None.

Affected Silicon Revisions

B3							
X							

4. Module: Output Compare 3, 4, 5 and 6

The first PWM pulse may not appear on the OCx pin if the timer source of the Output Compare x module is scaled down.

The first pulse on the OCx pin is missed in PWM mode when the timer source for the Output Compare x module is scaled down (1:8, 1:64 or 1:256) using the Timerx Input Clock Prescale Select bits, TCKPS<1:0> (TxCON<5:4>) bits.

Work around

- Configure the prescaler for the source timer to 1:1 for Output Compare 3, 4, 5 and 6.
- The Output Compare 1 or 2 module can be used. The scaled down timer (1:8, 1:64 or 1:256) can be used as a source for the Output Compare 1 and 2 modules.

Affected Silicon Revisions

B3							
X							

PIC24FJ128GA204 FAMILY

5. Module: CTMU

The Edge Enable bit, EDGEN (CTMUCON1<11>), generates a glitch on the CTEDx input.

Enabling the edges (EDGEN = 1) generates a glitch (edge):

- If the CTMU External Edge Input (CTEDx) is set for a falling edge and the level on this pin is low;
or
- If CTEDx is set for a rising edge and the level on this pin is high.

Work around

None.

Affected Silicon Revisions

B3							
X							

6. Module: UART1 and UART2

This issue applies to SmartCard/ISO7816 operation.

In T = 1 mode, for the last byte and when the LAST bit is set, an interrupt shall always be generated after 22 Elementary Time Units (ETUs), irrespective of the Guard Time Interrupt Enable, GTCIE (UxSCINT<0>), bit state. The interrupt is occurring before 22 ETUs.

Work around

To use the Guard Time Counter (GTC) for T = 1 block guard time, the last byte in a message block must have the GTC value set to 11 ETUs and the GTCIE (UxSCINT<0>) bit set. The LAST bit (UxTXREG<15>) should not be set.

Affected Silicon Revisions

B3							
X							

7. Module: UART1 and UART2

This issue applies to SmartCard/ISO7816 operation.

The Guard Time Counter (GTC) is off by one count in T = 0 and T = 1 modes.

The GTC value stored in the UxGTC register is off by one count in both T = 0 and T = 1 modes. The actual guard time is, a +1 ETU more, than the value specified in the GTC<8:0> bit.

Work around

The guard time value to be programmed in the GTC<8:0> bits must be decremented by one count.

Affected Silicon Revisions

B3							
X							

8. Module: POR/BOR

If Brown-out Reset (BOR) is disabled, the part may fail to come out of the Reset state during the VDD power-down and the subsequent power-up condition.

When BOR is disabled, in extremely rare cases, the part remains in the Reset state during the VDD power-down (not till Vss), followed by the subsequent power-up condition.

Work around

There are three known work arounds for this issue:

- Always enable BOR by setting the Configuration Fuse bit, BOREN = 1 (CW3<12>).
- Use an external voltage supervisor chip on the MCLR pin to hold the MCLR low when the power supply voltage is between 1.4V and 2.0V. Release MCLR after the VDD is in the operating range.
- Make sure that VDD goes all the way to Vss before powering on.

Affected Silicon Revisions

B3							
X							

9. Module: POR/BOR

When BOR is disabled, the part may not start at the minimum VDD specification.

Work around

There are two known work arounds for this issue:

- Always enable BOR by setting the Configuration Fuse bit, BOREN (CW3<12>) = 1.
- For initial start-up, make sure that the minimum VDD is more than 2.2V. Once the device is powered, it will operate down to the minimum VDD voltage specified in the data sheet specifications. This is a typical battery-operated application with a fully charged battery installed into the application. The part will continue to operate to the data sheet specifications.

Affected Silicon Revisions

B3								
X								

10. Module: Output Compare

The Output Compare x module does not get synchronized with the source timer in Sync mode when the source timer is running with an external clock.

In Synchronous mode, the internal 16-bit counter, OCxTMR, is synchronized with TMRx. When the source clock (TMRx) to the OCx module is running on an external clock, TCS (TxCON<1>) = 1, the OCxTMR is not synchronized with TMRx.

Work around

None.

Affected Silicon Revisions

B3								
X								

11. Module: Input Capture

The Input Capture x module does not get synchronized with the source timer in Sync mode when the source timer is running with an external clock.

In Synchronous mode, the internal 16-bit counter, ICxTMR, is synchronized with TMRx. When the source clock (TMRx) to the ICx module is running on an external clock, TCS (TxCON<1>) = 1, the ICxTMR is not synchronized with TMRx.

Work around

None.

Affected Silicon Revisions

B3								
X								

12. Module: UART1 and UART2

The UARTx Receive Interrupt (UxRXIF) may be asserted early, before the entire incoming data byte is received. As a result, during SmartCard operations, the data byte read from the UARTx Receive Buffer will not be valid.

Work around

None.

Affected Silicon Revisions

B3								
X								

13. Module: UART1 and UART2

Clearing any one of the interrupt status bits in the UxSCINT register (i.e., GTCIF, WTCIF, TXRPTIF or RXRPTIF) may result in clearing of all of the status bits. The status of corresponding interrupt enable bits is not affected.

Work around

Before clearing any of the UxSCINT status bits, copy the contents of the register to memory.

Affected Silicon Revisions

B3								
X								

PIC24FJ128GA204 FAMILY

14. Module: UART1 and UART2

When the value of the Waiting Time Counter (WTC) stored in UxWTC is greater than 10, the actual waiting time is extended by an additional 11 Elementary Time Units (ETUs). For example, when UxWTC = 11, the application will assert a waiting time of 22 ETUs.

Work around

None.

Affected Silicon Revisions

B3							
X							

15. Module: SPI

While operating in Master mode (MSTEN = 1), the Transmit watermark interrupt is not asserted if there is more than one entry in the FIFO buffer. This means, for various modes, that the interrupt is not asserted for:

- More than one byte to be transmitted in 8-bit mode;
- More than one word to be transmitted in 16-bit mode; or
- More than one double word to be transmitted in 32-bit mode.

Work around

None.

Affected Silicon Revisions

B3							
X							

16. Module: I²C

In applications with multiple I²C™ slaves, bus data can become corrupted when the data payload sent to an addressed slave device matches the bus address of another (unaddressed) slave device.

Work around

Keep track of the bus address and data phases in software. When Address Hold Enable is used (the AHEN bit is set), the application can assert a NACK for any of the received bytes (invalid addresses and data bytes for other slave devices) until a Stop bit is received.

Affected Silicon Revisions

B3							
X							

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS30010038B):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Triple Comparator

In Register 25-1 (CMxCON), the definitions for the EVPOL<1:0> bits are changed to read as shown below. In addition, Footnote 1 is added to the register. (Changes and additions in **bold**; bold in original removed for clarity.)

REGISTER 26-1: CMxCON: COMPARATOR x CONTROL REGISTER (PARTIAL PRESENTATION)

bit 7-6 EVPOL<1:0>: Trigger/Event/Interrupt Polarity Select bits⁽¹⁾
11 = **Trigger/event/interrupt is generated on any change of the comparator output (while CEVT = 0)**
10 = **Trigger/event/interrupt is generated on the high-to-low transition of the comparator output**
01 = **Trigger/event/interrupt is generated on the low-to-high transition of the comparator output**
00 = Trigger/event/interrupt generation is disabled

Note 1: If EVPOL<1:0> are set to any value other than '00', the first interrupt will occur on any transition of COUT. Subsequent interrupts will occur based on the setting of EVPOL<1:0>.

2. Module: Packaging


The package markings for all PIC24FJ128GA204 family devices have changed. Package markings are now limited to the short part number, manufacturing date code, trace code and Microchip trademark (where space is available). The operating temperature code and packaging code have been removed from the marking as redundant.

The diagrams in **Section 33.1 “Package Marking Information”** are changed, as shown in [Figure 1](#) and [Figure 2](#) (following pages), to reflect these modifications.

Note: The full device part number, including temperature and package codes, is still required for ordering. This information is available in the Product Information System located at the end of the device data sheet.

PIC24FJ128GA204 FAMILY


FIGURE 1: UPDATED PACKAGE MARKINGS



PIC24FJ128GA204 FAMILY

FIGURE 2: UPDATED PACKAGE MARKINGS (CONTINUED)


44-Lead QFN




Example



44-Lead TQFP



Example



PIC24FJ128GA204 FAMILY

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (6/2014)

Initial release of this document; issued for silicon revision B3.

This version includes the following silicon issues 1 ([UART](#)), 2 ([A/D Converter](#)), 3 ([Input Capture](#)), 4 ([Output Compare 3, 4, 5 and 6](#)), 5 ([CTMU](#)), 6-7 ([UART1 and UART2](#)), 8-9 ([POR/BOR](#)), 10 ([Output Compare](#)) and 11 ([Input Capture](#)).

Rev B Document (1/2015)

Adds silicon issues 12 through 14 ([UART1 and UART2](#)), 15 ([SPI](#)) and 16 ([I²C](#)).

Updates the title of existing silicon issues 6 and 7 as “[UART1 and UART2](#)”, in accordance with standard documentation practice. The actual issues themselves, as they relate to the SmartCard/ISO7816 functionality of the UART, remain unchanged.

Adds data sheet clarifications 1 ([Triple Comparator](#)) and 2 ([Packaging](#)).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, flexPWR, JukeBlox, KEELoQ, KEELoQ logo, Klear, LANCheck, MediaLB, MOST, MOST logo, MPLAB, OptoLyzer, PIC, PICSTART, PIC³² logo, RightTouch, SpyNIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

The Embedded Control Solutions Company and mTouch are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, ECAN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, KlearNet, KlearNet logo, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, RightTouch logo, REAL ICE, SQI, Serial Quad I/O, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2014-2015, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-63276-960-2

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949 ==

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110

Canada - Toronto
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2943-5100
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-8792-8115
Fax: 86-571-8792-8116

China - Hong Kong SAR
Tel: 852-2943-5100
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8864-2200
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-3019-1500

Japan - Osaka
Tel: 81-6-6152-7160
Fax: 81-6-6152-9310

Japan - Tokyo
Tel: 81-3-6880-3770
Fax: 81-3-6880-3771

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Dusseldorf
Tel: 49-2129-3766400

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Pforzheim
Tel: 49-7231-424750

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Venice
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Poland - Warsaw
Tel: 48-22-3325737

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820