

PIC24FV32KA304 Family Silicon Errata and Data Sheet Clarification

The PIC24FV32KA304 family devices that you have received conform functionally to the current Device Data Sheet (DS39995D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC24FV32KA304 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A6).

Data sheet clarifications and corrections start on [Page 6](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKit™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKit™ 3.
2. From the main menu in MPLAB IDE, select Configure>Select Device, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (Debugger>Select Tool).
4. Perform a "Connect" operation to the device (Debugger>Connect). Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24FV32KA304 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾		Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾	
		A4	A6			A4	A6
PIC24F32KA304	4516h	0004h	0006h	PIC24FV32KA304	4517h	0004h	0006h
PIC24F32KA302	4512h			PIC24FV32KA302	4513h		
PIC24F32KA301	4518h			PIC24FV32KA301	4519h		
PIC24F16KA304	4506h			PIC24FV16KA304	4507h		
PIC24F16KA302	4502h			PIC24FV16KA302	4503h		
PIC24F16KA301	4508h			PIC24FV16KA301	4509h		

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format, "DEVID DEVREV".

2: Refer to the "PIC24FXXKA1XX/FVXXKA3XX Flash Programming Specifications" (DS39919) for detailed information on Device and Revision IDs for your specific device.

PIC24FV32KA304 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾	
				A4	A6
Core	Low-Voltage Regulator	1.	High-voltage programming entry unavailable in Low-Voltage Sleep modes.	X	
Reset	BOR	2.	Unexpected BOR events when BOR is disabled in Sleep mode.	X	X
A/D	Threshold Detect	3.	Auto-scan feature may not trigger correctly in Sleep mode.	X	
UART	TX Buffer	4.	Out-of-order transmit data when buffer is filled.	X	
UART	Transmit	5.	UTXBF flag may not indicate correctly.	X	
A/D	Threshold Detect	6.	Current in Auto-Scan mode may exceed expected values.	X	
A/D	Threshold Detect	7.	Interrupt may not trigger in certain Auto-Scan modes.	X	
HLVD	DC18 Value Changes	8.	Change in trip points.	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24FV32KA304 FAMILY

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A6).

1. Module: Core (Low-Voltage Regulator)

When operating in Low-Voltage Sleep mode, $LVREN = 1$ ($RCON<12>$) and $LVRCFG = 0$ ($FPOR<2>$), the device may not be able to enter programming modes using high-voltage entry (V_{IH} applied to $MCLR$).

Work around

If entry into a programming mode is required while the device is in Low-Voltage Sleep mode, use low-voltage entry into programming. Verify that $MCLR$ functionality is enabled, $MCLRE = 1$ ($FPOR<7>$), before attempting programming.

Affected Silicon Revisions

A4	A6						
X							

2. Module: Reset (BOR)

Under certain conditions, the device may improperly perform a Brown-out Reset upon wake-up from a Sleep mode. This has been observed under two conditions:

1. When the BOR is disabled in Sleep mode, $BOREN<1:0> = 10$ ($FPOR<1:0>$), a BOR may occur when the device wakes from Sleep, regardless of the supply voltage.
2. When the BOR is configured for software control ($BOREN<1:0> = 01$), the device enters and wakes from Sleep normally while the BOR is disabled in software, $SBOREN = 0$ ($RCON<13>$). However, if the BOR was disabled prior to entering Sleep mode and is subsequently enabled after waking from Sleep, a BOR may occur, regardless of the supply voltage.

BOR functions normally when it is always enabled or disabled ($BOREN<1:0> = 11$ or 00).

Work around

Do not use Sleep mode when $BOREN<1:0> = 10$.

If the BOR is to operate under software control, always enable the HLVD module, $HLVDEN = 1$ ($HLVDCON<15>$), before enabling the BOR in software ($SBOREN = 1$). This procedure activates the internal band gap reference and assures its stability for the BOR circuit.

Affected Silicon Revisions

A4	A6						
X	X						

3. Module: A/D (Threshold Detect)

When the auto-scan feature of the Threshold Detect is enabled ($AD1CON5<15> = 1$), auto-scan may fail when these conditions occur together:

- the Device is in Sleep mode, and
- Timer1 is selected as the sample trigger clock source ($AD1CON1<7:4> = 0101$).

Timer1 and other timers will function correctly as sample triggers in other power-saving modes, such as Idle mode.

Work around

If auto-scan functionality is required during Sleep, use $INT0$ as the sample trigger.

Affected Silicon Revisions

A4	A6						
X							

PIC24FV32KA304 FAMILY

4. Module: UART (TX Buffer)

If the transmit buffer is filled sequentially with four characters, the characters may not be transmitted in the correct order.

Work around

Do not completely fill the buffer before transmitting data; send three characters or less at a time.

Affected Silicon Revisions

A4	A6						
X							

5. Module: UART (Transmit)

The UARTx Transmit Buffer Full flag, UTXBF (UxSTA<9>), may become cleared before data starts moving out of the full buffer. If the flag is used to determine when data can be written to the buffer, new data may not be accepted and data may not be transmitted.

Work around

Poll the Transmit Buffer Empty flag (TRMT, UxSTA<8>) to determine when the transmit buffer is empty and can be written to.

Alternatively, configure the UART to set the UARTx Transmit Interrupt Flag (UTXIF) whenever a character is shifted into the Transmit Shift Register (UTXISEL<1:0> = 00). When a transmit interrupt occurs, this indicates that at least one buffer position is open and that the buffer can be written to.

Affected Silicon Revisions

A4	A6						
X							

6. Module: A/D (Threshold Detect)

In Auto-Scan mode, with low power enabled (AD1CON5<15> = 1, AD1CON5<14> = 1) and the device in Sleep mode, the ADRC may not turn off between scans, resulting in a higher current draw than anticipated.

Work around

None.

Affected Silicon Revisions

A4	A6						
X							

7. Module: A/D (Threshold Detect)

In Auto-Scan mode (AD1CON5<15> = 1), when the Auto-Scan Interrupt mode bits are set to '11' (AD1CON5<9:8> = 11), the highest number channel selected for scanning in AD1CSSL or AD1CSSH may not trigger an interrupt on a valid comparison.

Work around

Add a dummy channel to the scanning sequence. For example, when scanning AN0 and AN1, set AD1CSSL to 0x0007 or 0x8003, or whatever is practical given the implementation.

Also, if the highest number channel needs to be scanned, the AD1CHITH register can be polled to observe a valid comparison.

Affected Silicon Revisions

A4	A6						
X							

PIC24FV32KA304 FAMILY

8. Module: HLVD (DC18 Value Changes)

The maximum and minimum values of the High/Low-Voltage Detect Characteristics (DC18), shown in Table 29-4 of the data sheet, have changed for this revision. The new values are shown in [Table 3](#).

Affected Silicon Revisions

A4	A6						
X	X						

TABLE 3: HIGH/LOW-VOLTAGE DETECT CHARACTERISTICS

Standard Operating Conditions: 1.8V to 3.6V PIC24F32KA3XX 2.0V to 5.5V PIC24FV32KA3XX							
Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for Industrial							
Param No.	Symbol	Characteristic		Min	Typ	Max	Units
DC18	VHLVD	HLVD Voltage on VDD Transition	HLVDL<3:0> = 0000 ⁽²⁾	—	—	2.01	V
			HLVDL<3:0> = 0001	1.91	—	2.25	V
			HLVDL<3:0> = 0010	2.12	—	2.48	V
			HLVDL<3:0> = 0011	2.27	—	2.67	V
			HLVDL<3:0> = 0100	2.36	—	2.76	V
			HLVDL<3:0> = 0101	2.55	—	2.99	V
			HLVDL<3:0> = 0110	2.79	—	3.27	V
			HLVDL<3:0> = 0111	2.93	—	3.43	V
			HLVDL<3:0> = 1000	3.06	—	3.60	V
			HLVDL<3:0> = 1001	3.23	—	3.79	V
			HLVDL<3:0> = 1010 ⁽¹⁾	3.40	—	4.00	V
			HLVDL<3:0> = 1011 ⁽¹⁾	3.61	—	4.23	V
			HLVDL<3:0> = 1100 ⁽¹⁾	3.83	—	4.49	V
			HLVDL<3:0> = 1101 ⁽¹⁾	4.08	—	4.80	V
			HLVDL<3:0> = 1110 ⁽¹⁾	4.38	—	5.14	V

Note 1: These trip points should not be used on PIC24FXXKA30X devices.

Note 2: This trip point should not be used on PIC24FVXXKA30X devices.

PIC24FV32KA304 FAMILY

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39995D):

1. Module: Electrical Characteristics

The extended temperature data, shown in bold, has been added to [Table 29-21](#).

TABLE 29-21: AC CHARACTERISTICS: INTERNAL RC ACCURACY

AC CHARACTERISTICS		Standard Operating Conditions: 1.8V to 3.6V PIC24F32KA3XX 2.0V to 5.5V PIC24FV32KA3XX Operating temperature -40°C ≤ TA ≤ +85°C for Industrial -40°C ≤ TA ≤ +125°C for Extended					
Param No.	Characteristic	Min	Typ	Max	Units	Conditions	
F20	Internal FRC Accuracy @ 8 MHz ⁽¹⁾						
	FRC	-2	—	+2	%	+25°C	3.0V ≤ VDD ≤ 3.6V, F device 3.2V ≤ VDD ≤ 5.5V, FV device
		-5	—	+5	%	-40°C ≤ TA ≤ +85°C	1.8V ≤ VDD ≤ 3.6V, F device 2.0V ≤ VDD ≤ 5.5V, FV device
		-6	—	+6	%	-40°C ≤ TA ≤ +125°C	1.8V ≤ VDD ≤ 3.6V, F device 2.0V ≤ VDD ≤ 5.5V, FV device
F21	LPRC @ 31 kHz ⁽²⁾						
		-15	—	15	%		

Note 1: Frequency is calibrated at +25°C and 3.3V. The OSCTUN bits can be used to compensate for temperature drift.

2: The change of LPRC frequency as VDD changes.

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (3/2011)

Initial release of this document; issued for revision A4. Includes silicon issues 1 (Core, Low-Voltage Regulator) and 2 (Reset, BOR).

Rev B Document (5/2011)

Adds silicon issue 3 (A/D, Threshold Detect) to silicon revision A4.

Adds data sheet clarifications 1 (Overview and Other Locations), 2 (Overview) and 3 (A/D, Threshold Detect) for data sheet revision B.

Rev C Document (9/2011)

Adds silicon issues 4 (UART, TX Buffer), 5 (UART, Transmit), 6 (A/D, Threshold Detect), 7 (A/D, Threshold Detect) and 8 (HLVD, DC18 Value Changes) to silicon revision A4. Typographical correction in issue 1 (Core, Low-Voltage Regulator).

Adds data sheet clarifications 4 through 7 (A/D Converter), 8 and 9 (Comparator), 10 (Flash Program Memory), 11 (Electrical Specifications), 12 (A/D Converter) and 13 (Pin Diagrams) to data sheet revision B.

Rev D Document (8/2012)

Adds latest silicon revision (A6) and shows that both silicon issues 2 (Reset, BOR) and 8 (HLVD, DC18 Value Changes) are affected. Removes all data sheet clarifications that were addressed in the latest release of the data sheet.

Rev E Document (11/2013)

Adds data sheet clarification 1 (Electrical Characteristics).

PIC24FV32KA304 FAMILY

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.


Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, SQL, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2011-2013, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-62077-605-6

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
= ISO/TS 16949 =

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

Worldwide Sales and Service

AMERICAS

Corporate Office
 2355 West Chandler Blvd.
 Chandler, AZ 85224-6199
 Tel: 480-792-7200
 Fax: 480-792-7277
 Technical Support:
<http://www.microchip.com/support>
 Web Address:
www.microchip.com

Atlanta
 Duluth, GA
 Tel: 678-957-9614
 Fax: 678-957-1455

Austin, TX
 Tel: 512-257-3370

Boston
 Westborough, MA
 Tel: 774-760-0087
 Fax: 774-760-0088

Chicago
 Itasca, IL
 Tel: 630-285-0071
 Fax: 630-285-0075

Cleveland
 Independence, OH
 Tel: 216-447-0464
 Fax: 216-447-0643

Dallas
 Addison, TX
 Tel: 972-818-7423
 Fax: 972-818-2924

Detroit
 Novi, MI
 Tel: 248-848-4000

Houston, TX
 Tel: 281-894-5983

Indianapolis
 Noblesville, IN
 Tel: 317-773-8323
 Fax: 317-773-5453

Los Angeles
 Mission Viejo, CA
 Tel: 949-462-9523
 Fax: 949-462-9608

New York, NY
 Tel: 631-435-6000

San Jose, CA
 Tel: 408-735-9110

Canada - Toronto
 Tel: 905-673-0699
 Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
 Suites 3707-14, 37th Floor
 Tower 6, The Gateway
 Harbour City, Kowloon
 Hong Kong
 Tel: 852-2401-1200
 Fax: 852-2401-3431

Australia - Sydney
 Tel: 61-2-9868-6733
 Fax: 61-2-9868-6755

China - Beijing
 Tel: 86-10-8569-7000
 Fax: 86-10-8528-2104

China - Chengdu
 Tel: 86-28-8665-5511
 Fax: 86-28-8665-7889

China - Chongqing
 Tel: 86-23-8980-9588
 Fax: 86-23-8980-9500

China - Hangzhou
 Tel: 86-571-2819-3187
 Fax: 86-571-2819-3189

China - Hong Kong SAR
 Tel: 852-2943-5100
 Fax: 852-2401-3431

China - Nanjing
 Tel: 86-25-8473-2460
 Fax: 86-25-8473-2470

China - Qingdao
 Tel: 86-532-8502-7355
 Fax: 86-532-8502-7205

China - Shanghai
 Tel: 86-21-5407-5533
 Fax: 86-21-5407-5066

China - Shenyang
 Tel: 86-24-2334-2829
 Fax: 86-24-2334-2393

China - Shenzhen
 Tel: 86-755-8864-2200
 Fax: 86-755-8203-1760

China - Wuhan
 Tel: 86-27-5980-5300
 Fax: 86-27-5980-5118

China - Xian
 Tel: 86-29-8833-7252
 Fax: 86-29-8833-7256

China - Xiamen
 Tel: 86-592-2388138
 Fax: 86-592-2388130

China - Zhuhai
 Tel: 86-756-3210040
 Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
 Tel: 91-80-3090-4444
 Fax: 91-80-3090-4123

India - New Delhi
 Tel: 91-11-4160-8631
 Fax: 91-11-4160-8632

India - Pune
 Tel: 91-20-3019-1500

Japan - Osaka
 Tel: 81-6-6152-7160
 Fax: 81-6-6152-9310

Japan - Tokyo
 Tel: 81-3-6880-3770
 Fax: 81-3-6880-3771

Korea - Daegu
 Tel: 82-53-744-4301
 Fax: 82-53-744-4302

Korea - Seoul
 Tel: 82-2-554-7200
 Fax: 82-2-558-5932 or
 82-2-558-5934

Malaysia - Kuala Lumpur
 Tel: 60-3-6201-9857
 Fax: 60-3-6201-9859

Malaysia - Penang
 Tel: 60-4-227-8870
 Fax: 60-4-227-4068

Philippines - Manila
 Tel: 63-2-634-9065
 Fax: 63-2-634-9069

Singapore
 Tel: 65-6334-8870
 Fax: 65-6334-8850

Taiwan - Hsin Chu
 Tel: 886-3-5778-366
 Fax: 886-3-5770-955

Taiwan - Kaohsiung
 Tel: 886-7-213-7830

Taiwan - Taipei
 Tel: 886-2-2508-8600
 Fax: 886-2-2508-0102

Thailand - Bangkok
 Tel: 66-2-694-1351
 Fax: 66-2-694-1350

EUROPE

Austria - Wels
 Tel: 43-7242-2244-39
 Fax: 43-7242-2244-393

Denmark - Copenhagen
 Tel: 45-4450-2828
 Fax: 45-4485-2829

France - Paris
 Tel: 33-1-69-53-63-20
 Fax: 33-1-69-30-90-79

Germany - Dusseldorf
 Tel: 49-2129-3766400

Germany - Munich
 Tel: 49-89-627-144-0
 Fax: 49-89-627-144-44

Germany - Pforzheim
 Tel: 49-7231-424750

Italy - Milan
 Tel: 39-0331-742611
 Fax: 39-0331-466781

Italy - Venice
 Tel: 39-049-7625286

Netherlands - Drunen
 Tel: 31-416-690399
 Fax: 31-416-690340

Poland - Warsaw
 Tel: 48-22-3325737

Spain - Madrid
 Tel: 34-91-708-08-90
 Fax: 34-91-708-08-91

Sweden - Stockholm
 Tel: 46-8-5090-4654

UK - Wokingham
 Tel: 44-118-921-5800
 Fax: 44-118-921-5820