


Name of Employee	Nanteesworon		Badge No.	30040922		Actual Severity:	1
Safety Awareness Training Date	10/27/2019		Proof of Training	Induction		Worst Potential Severity:	3
Name of Line Manager	Amr Ahmed Mahmoud Mohamed		Badge No.	30104091	Profession/ Designation	Sr. Engineer - Civil	
Name of Supervisor	Ibrahim Sabry Ibrahim Kheriba		Badge No.	31032055			
Division / Department	Civil Department		Project Name	Catering Auditorium & Recreation Facilities	Project Location	JUC	
Place of the Incident/Injury	Auditorium		Date of Incident	2/22/2021	Time of Incident	9.40AM	
Nature of the Incident/Injury	Occupational Incident/Injury	No	Near Miss		Other, Please specify :		
	Road Traffic Incident/ Injury	No	Yes				
Brief Description of the Incident/Injury	Today around 0940 carpenter team was working on a scaffold platform for slab shuttering and beneath them one scaffolding team was working. Carpenter team kept some loose timber on the platform where toe board removed for shuttering purpose. Suddenly one timber fell to the ground from the height of 9 meter where scaffolding team was working. Fortunately timber didn't hit anyone. No property or injury happened						
Property damage	N/A						
First Aid Given?	No	Name of First Aider					
Name of Hospital where patient was treated/transferred				Address/Location of the hospital			
Medical leave given by administering Hospital/Clinic or Doctor	No	Number of Days		Hospitalization		No	
Property damage	No	Estimated percentage of damage		Estimated Cost of damaged (SAR)			
Property Details	Type / Function of the property			Location of affected property			
	Name of Manufacturer						
	Model of the Property			Plate Number			
	Vehicle Registration Number			Company Fleet Number			

Was Pre- Task / Toolbox meeting conducted	Yes	Was the person using required Personal Protective Equipment (PPE)	Yes			
Specify the Personal Protective Equipment (PPE)	Safety Shoes, Safety Goggles, Helmet, Vest, Gloves					
What was the injured person/employee doing at the time of the incident?	N/A					
What was the machine/equipment doing at the time of the incident?	N/A					
What was the material/s / substance/s doing at the time of the incident	Timbers lying on the scaffolding platform					
Immediate Cause/s of the Incident/injury:						
Timber fall from the gap where toe board removed by carpenter						
Root Cause/s of the Incident/injury:	People: No proper supervision from the supervisor and foreman.					
	Process / Procedure- Procedure was not ok as they removed toe board from the platform.					
	Equipment: N/A					
	Workplace: Loose material kept on platform by worker. No housekeeping on the platform.					
Corrective Action to prevent reoccurrence:	Elimination: N/A					
	Substitution: N/A					
	Engineering Control: Edge protection and toe board must be checked before start of work on platform					
	Administrative Control: Two team must not perform simultaneously activity at the same Location. Proper supervision from concerned person must be present for close monitory					
	PPE: Necessary PPEs at site must be worn.					
Were there any witnesses?	Yes	Type of witness/s	Employee	✓	Public	
Witness Details Mohammad Irfan Khan		Badge Number	40977	Mobile Number		
Witness Statement: As per witness he was working near the incident location and sudden he saw one timber fell down from height.						

Initial Investigation Conducted by: Krishna Pillai <i>V. Krishna Pillai 6/19/21</i>	Noted by: Mustafa Ali <i>[Signature]</i>	Date	28-2-2021
--	---	------	-----------

Additional Details:



Investigation Report Verified by:	Noted by:	Date	
-----------------------------------	-----------	------	--