

Fill the Information Below

Company: Rezayat Company Limited

Date: 3/9/2021

Location: Al Farouk Sector, Jubail

Time: 03:00 pm

Project/ Site Name: Improvement of Schools

Worst Potential Severity: 5

Actual Severity: 1

Related Work Case

Person(s) Involved:

Employee

Contractor

Others

1. Muhammad Fiaz (37113)

3.

2.

Other(s).

Type of Incident:

RTA

Injury Location by Body Parts (Select one or more if necessary):

Head	Chest	Hand	Eyes
Face	Leg	Arm	Hip
Neck	Abdomen	Wrist	Ankle/Foot
Back	Stomach	Elbow	Knee
Nose/ Ears	Shoulder	Fingers/ Thumb	Toes

Type of Injury Sustained (Select one or more if necessary):

Fracture	Cut/ Laceration	Scalping	Bruising
Loss of Sight	Loss of Consciousness	Heat	Amputation
Dislocation	Crush Injury	Cold	Other(s)
Abrasion	Suffocation	Burn	

Immediate Cause(s) (Select one or more if necessary):

Safety Rule Violated	Lack of Resources	Drugs/ Alcohol Related	Inadequate Visibility
Lack of Task Skill	Method Deviation	Poor Housekeeping	Employee Morale
Lack of Supervision	Poor Weather Conditions	Inadequate Lighting	Employee Attitude
Improper Lifting (MH)	Lack of Task Knowledge	Poor Team Work	Behavior Problem
Not Paying Attention	Lack of Communication	No Risk Assessment	Poor Ground Conditions
Human Error	Incorrect Tools/Equip	Defective Equipment	Improper Lifting (crane)
Inadequate PPE	Defective Tools	Unprotected excavation	Unprotected Edge
Animals	Violence	Horseplay	Improper/ Poor Slings
Heat Stress	STF Above Ground	STF on the Same Level	Manual Handling
Misuse of Hand Tools	Grinding/ Welding	Knives/ Sharps	Hit by Vehicle
Hit by Static Machinery	Heavy Equipment	Splashes from C.P.O.L.	Other(s) : X
Stress	Fatigue	Vandalism	

Equipment(s) Involved:

Light Vehicle:	X	Heavy Vehicle:	Plant Equipment:	Static Plant Equipment:
Building:		Structure:	Scaffold:	Excavation:
Other(s):				


Description of the Event:

He was deployed to transport the employees from one site to another site for C34 project. When he reached the signal and stopped his vehicle due to red signal. He is waiting for the signal to open but that time, one of the public vehicle came and struck against the Hi-ace (Backside). There is no employees inside the HIACE except the driver. As a result of this incident, minor property damage is occurred for both parties vehicle.

Immediate Action(s) Taken to Prevent Reoccurrence (If Any):

Driver initiated the emergency reporting protocol by informing his supervisor until it reached the PM, SM, CM of the project. Informed the NAJM and placed the triangle 30 meters away from the vehicle.

Person Created the Report:

Name: Praveen Kumar Thirumurugan	Position: Safety Manager – 628 C34	Signature: 	Date: 3/11/2021
-------------------------------------	---------------------------------------	--	-----------------