

Name of Employee	Ichara Malik	Badge No.	30038958	Actual Severity:	1		
Safety Awareness Training Date	10/16/2019	Proof of Training	Induction Training register	Worst Potential Severity:	4		
Name of Line Manager	Amr Algendy	Badge No.		Profession/ Designation	Area Suprintendent		
Name of Supervisor	Ibrahim Sabri	Badge No.					
Division / Department	Civil	Project Name	097-C76R	Project Location	JUC		
Place of the Incident/Injury	Area 1 (Part-2)	Date of Incident	1/28/2021	Time of Incident	10:00 AM		
Nature of the Incident/Injury	Occupational Incident/Injury	No	Near Miss	Other, Please specify :			
	Road Traffic Incident/ Injury	No	Yes				
Brief Description of the Incident/Injury	While removing the shuttering of the column in part 2, steel rod that was given as a support on the shuttering (as shown in the picture) fell onto the ground. The area was not barricaded and no one was present downside to monitor. Fortunately no injury and material damage was observed.						
Details of the Injury (Specify affected body parts)	N/A						
First Aid Given?	No	Name of First Aider					
Name of Hospital where patient was treated/transferred			Address/Location of the hospital				
Medical leave given by administering Hospital/Clinic or Doctor	No	Number of Days		Hospitalization	No		
Property damage	No	Estimated percentage of damage		Estimated Cost of damaged (SAR)			
Property Details	Type / Function of the property			Location of affected property			
	Name of Manufacturer						
	Model of the Property			Plate Number			
	Vehicle Registration Number			Company Fleet Number			

Was Pre- Task / Toolbox meeting conducted	Yes	Was the person using required Personal Protective Equipment (PPE)	Yes			
Specify the Personal Protective Equipment (PPE)	Safety Shoes, Safety Goggles, Helmet, Vest, Gloves, Full body harness					
What was the injured person/employee doing at the time of the incident?	Removing the shuttering plate of the column					
What was the machine/equipment doing at the time of the incident?	N/A					
What was the material/s / substance/s doing at the time of the incident	Steel rods were used as a support for the shuttering					
Immediate Cause/s of the Incident/injury: While the steel rod was removed, the worker cut the binding wire from one side and he didn't grabbed the steel rod, hoping that the other side binding wire will hold the steel rod. The Steel rod slipped from the binding wire on the other side.						
Root Cause/s of the Incident/injury:	People: No proper supervision from the foreman.					
	Process / Procedure: Procedure was not OK as the worker did not grabbed the steel rod while cutting the binding wire.					
	Equipment: Equipment was Ok.					
	Workplace: Workplace was not OK as the area was not barricaded.					
Corrective Action to prevent reoccurrence:	Elimination: N/A					
	Substitution: N/A					
	Engineering Control: Before removing the shuttering, tie the supporting rod with binding wires to avoid falling. Hold the rod					
	Administrative Control: Proper supervision must be ensure. While working at height, area must be barricaded from downside. Signage must be provided with the barrication or one person must stand downside for warning the pedestrians.					
	PPE: Necessary PPEs must be worn. In this case helmet and safety shoes were important for the people on the ground level.					
Were there any witnesses?	None	Type of witness/s	Employee		Public	
Witness Details		Badge Number		Mobile Number		
Witness Statement:						
Initial Investigation Conducted by: Krishna Pillai (SM)			Noted by: Mustafa Ali (PM)		Date	1/28/2021

Additional Details:



Investigation Report Verified by:

Noted by:

Date

1/28/2021