


Name of Employee	Abdur Rahman	Badge No.	34537	Actual Severity:	N/A		
Safety Awareness Training Date	10/19/2019	Proof of Training	Induction	Worst Potential Severity:	N/A		
Name of Line Manager	Mustafa Ali	Badge No.	3104094	Profession/ Designation	Project Manager		
Name of Supervisor	Ibrahim Sabry	Badge No.	31032055				
Division / Department	Civil Department	Project Name	097-C76 R	Project Location	JUC		
Place of the Incident/Injury	Auditorium part 1	Date of Incident	12/16/2020	Time of Incident	1030		
Nature of the Incident/Injury	Occupational Incident/Injury	No	Near Miss	Other, Please specify :			
	Road Traffic Incident/ Injury	No	Yes				
Brief Description of the Incident/Injury	At 1030 hours scaffolding team was erecting a platform beneath the other yellow tagged platform. One scaffolding pipe (length 1meter) fall from the yellow tagged platform where steel team was working and hit the ground near to the scaffolder who was working over there. Fortunately no injury or property damage happened.						
Details of the Injury (Specify affected body parts)	N/A						
First Aid Given?	No	Name of First Aider	N/A				
Name of Hospital where patient was treated/transferred	N/A		Address/Location of the hospital	N/A			
Medical leave given by administering Hospital/Clinic or Doctor	No	Number of Days	N/A	Hospitalization	No		
Property damage	No	Estimated percentage of damage	N/A	Estimated Cost of damaged (SAR)	N/A		
Property Details	Type / Function of the property	N/A		Location of affected property	N/A		
	Name of Manufacturer	N/A					
	Model of the Property	N/A		Plate Number	N/A		
	Vehicle Registration Number	N/A		Company Fleet Number	N/A		

Was Pre- Task / Toolbox meeting conducted	Yes	Was the person using required Personal Protective Equipment (PPE)	Yes			
Specify the Personal Protective Equipment (PPE)	Helmet, safety shoes, vest, gloves and goggles					
What was the injured person/employee doing at the time of the incident?	N/A					
What was the machine/equipment doing at the time of the incident?	N/A					
What was the material/s / substance/s doing at the time of the incident	Scaffold pipes lying on the scaffolding platform					
Immediate Cause/s of the Incident/injury: Loose material kept on scaffold near the open gaps						
Root Cause/s of the Incident/injury:	People: Lack of supervision and carelessness from the scaffolders to leave the loose scaffolding materials on the scaffolding after finishing their job					
	Process / Procedure - Loose material on platform, poor housekeeping					
	Equipment: N/A					
	Workplace: Workplace was not Ok as there were gaps in the scaffolding.					
Corrective Action to prevent reoccurrence:	Elimination: N/A					
	Substitution: N/A					
	Engineering Control: Close the gaps on platform as much as possible.					
	Administrative Control: Housekeeping, removal of scaffolding materials after erecting the scaffold. Avoid working downside of the working platform, barricade the area to restrict any movement of workers.					
	PPE: All necessary PPEs at site must be worn, in this case helmet and safety shoes must have to be worn if there is any person downside.					
Were there any witnesses?	Yes	Type of witness/s	Employee	✓	Public	
Witness Details - Mehar Zaman		Badge Number	40754	Mobile Number		
Witness Statement : As per witness they were erecting scaffold structure beneath the platform when one of scaffolding tube fell from height near to them.						

Initial Investigation Conducted by: Krishan Pillai <i>V.K. Pillai</i>	Noted by: Mustafa Ali <i>[Signature]</i>	Date	12/16/2020
---	--	-------------	-------------------

Additional Details:



Investigation Report Verified by:	Noted by:	Date	12/16/2020
--	------------------	-------------	-------------------