



## Additional instructions for Basic-Line electrical installation kit

## Introduction

These additional instructions contain supplementary information on the “Assembly instructions for the CNC portal milling machine Basic-Line” in order to prepare the CNC portal milling machine for electrical installation.

The supplied electrical assembly kit is only intended for installation on the Basic Line CNC portal milling machines.



### Caution!

Only carry out the work if you are familiar with the necessary actions and have suitable Tools available.

Sorotec GmbH assumes no liability for damage to property or personal injury that occurs during the assembly or operation of the CNC portal milling machine!

## Scope of delivery

| Illustration | Description   | Number        |
|--------------|---|---------------|
|              | <b>71</b> Drag chain<br>18x37 mm<br>Length each 1000 mm | 2             |
|              | <b>72</b> Connection kit<br>Drag chain                  | 2             |
|              | Terminal box (not ITG)<br>80 x 60 x 40 mm               | 3<br>(ITG 0)  |
|              | Grommet<br>(not ITG)<br>DA 40/80/15 SRT                 | 3<br>(ITG 0)  |
|              | Grommet<br>(not ITG)<br>DTS-M20                         | 5<br>(ITG 0)  |
|              | Starting plate with<br>Terminal block<br>(not ITG)      | 3<br>(ITG 0)  |
|              | End plate<br>terminal block<br>(not ITG)                | 3<br>(ITG 0)  |
|              | Terminal block<br>(not ITG)                             | 15<br>(ITG 0) |
|              | Cabel Canal<br>40 x 40 x 250 mm<br>with lid             | 1             |
|              | Housing reference<br>(2 parts)                          | 3             |
|              | Cable gland<br>M12 with nut                             | 1             |

| Illustration | Description  | Number |
|--------------|--|--------|
|              | Hammer nut<br>Slot 8 M4 <b>G0</b>  |        |
|              | Button flange head screw<br>with pressed washer<br>ISO 7380<br>M4 x 10 <b>1</b>          |        |
|              | Flat headed screw ISO 7380<br>M5 x 8 <b>K1</b>   |        |
|              | Nut DIN 934<br>M4 <b>P1</b><br>M5 <b>P2</b>  |        |
|              | Countersunk screw DIN 7991<br>M4 x 6 <b>R1</b><br>M4 x 10 <b>R2</b><br>M4 x 16 <b>R3</b> |        |
|              | Large washer<br>4,2 <b>Y1</b>  |        |

## Required tools

The following tools and aids must or should be available during assembly:

- Common hand tools, such as Allen keys, screwdrivers, plastic hammers, etc.
- Marking tools and center punch
- Drill bits 3.3 mm, 4.2 mm, 5 mm, 8 mm, 12.5 mm and 20 mm<sup>1)</sup>
- Taps M4, M5 and M6

<sup>1)</sup> 20 mm preferably as a peeling or step drill


## Assembly



### Note:

*The drag chain of the X-axis is mounted on the left side of the machine with cable feed from the rear.*

*Some of the components shown are part of the CNC portal milling machine kit.*

*The supplied drag chains with 1 m each can be shortened or lengthened as required.*

*The terminal boxes  are not required for a machine with integrated drives (output stage on stepper or servo motor). The relevant parts of this manual can then be ignored.*



Figures 1 and 2: drag chains on the X and Y axes of the Basic Line

## Drag chain X axis

- Screw the 20 x 20 mm bracket angle **34** to the rear face plate using cylinder head screws **C1** and nuts **P2**.
- Screw the drag chain holder **37** with countersunk screws **R2** and nuts **P1** to the 20 x 20 mm angle.
- Mount the mounting bracket **38** with the cylinder head screw **C1** and washer **Y2** together with the drag chain on the portal cheek.




Fig. 3: Drag chain holder and mounting bracket

- Equip the end of the drag chain **71** with a connection kit **72** bestücken.
- Screw the drag chain to the bracket **38** using countersunk screws **R3**, washers **Y1** and nuts **P1**.




Fig. 4: Mounting drag chain with connection kit on bracket

- Equip the other end of the drag chain **71** with a connection kit **72**.
- Screw the drag chain to the drag chain holder **37** using countersunk screws **R1**.




Fig. 5: Mounting drag chain with connection kit on holder

## Drag chain Y axis

Equip the end of the drag chain **71** with the connection kit **72** and screw it to the motor flange Z **19** using countersunk screws **R2**.




Fig. 6: Mounting drag chain on motor flange

Equip the other end of the drag chain **71** with the connection kit **72** and screw it to the aluminum profile of the portal with countersunk screw **R3** and hammer nut **G0**.




Fig. 7: Installation of drag chain on portal profile

## Cable Canal

Screw the cable duct **79** to the portal cheek using flat-head screws **K1**.




Fig. 8: Installation of drag chain on portal cheek



## Housing for reference switch

The housings for the reference switches are made in two parts each. When installing, the shims from the CNC portal milling machine kit are no longer used.

The connection cables of the reference switches are led outside through the recess in the switch housing.

The assembly takes place at the installation locations described in the assembly instructions for the milling kit:

- X axis - page 11
- Y axis - page 16
- Z axis - page 21




Fig. 9: Housing with reference switch. The red arrow indicates the cut-out for cable entry

## Terminal boxes (not ITG-version\*)

The terminal boxes (73) are intended for connecting the reference switches and the axis drives.

### **Note:**

*In machines with integrated drives, the cables are routed through the respective drag chain directly to the control without intermediate clamping.*

- Small grommets (74) fit for reference switch cables
- The M12 cable gland (81) (see illustration on page 5 above) holds the X-axis supply cable
- Large grommets (75) fit the supply cables of the Y and Z axes as well as all axis drives.

When connecting the cables later, 1 start plate with terminal block (76), 5 terminal blocks (78) and 1 end plate (77) must be strung together to connect the cables.




Fig. 10: Terminal box with bushings and terminal blocks

## Terminal box X axis:

- Drill and deburr the terminal box 73 with  $\varnothing$  5 mm
- Drill and deburr the terminal box on the side with  $\varnothing$  20 mm for large grommets 75.
- Drill and deburr the terminal box on the side with  $\varnothing$  12.5 mm for M12 cable gland 81.
- Drill and deburr the bottom of the terminal box with  $\varnothing$  8 mm for small grommets 74.

Two M4 threads are required in the rear faceplate 32 to screw the terminal box together and an 8 mm hole is required for the cable entry.

- Position the terminal box, transfer 5 mm and 8 mm holes in the bottom of the terminal box.
- Remove terminal box and punch holes.
- Drill and lower the fixing holes  $\varnothing$  3.3 mm and then cut M4 thread.
- Drill and deburr the hole for the cable entry  $\varnothing$  8 mm.
- Insert grommets 74 / 75 and M12 cable gland into the terminal box.
- Screw the terminal box with fastening screws.





Fig. 11: Assembly of the X-axis terminal box

## Terminal box Y axis:

- Drill and deburr the terminal box 73 with  $\varnothing$  5 mm.
- Drill and deburr the terminal box with  $\varnothing$  20 mm for large grommets 75.
- Drill and deburr the terminal box with  $\varnothing$  8 mm for small grommet 74.

Two M4 threads are required to screw the terminal box into the gantry beam 21.

- Position the terminal box, transfer 5 mm and 8 mm holes in the bottom of the terminal box.
- Remove terminal box and punch holes.
- Drill and lower the fixing holes  $\varnothing$  3.3 mm and then cut M4 thread.
- Drill and deburr the hole for the cable entry  $\varnothing$  8 mm.
- Insert grommets 74 / 75 and M12 cable gland into the terminal box.
- Screw the terminal box with fastening screws.





Fig. 12: Installation of terminal box Y-axis



## Terminal box Z axis:

- Drill and deburr the terminal box 73 with  $\varnothing$  5 mm
- Drill and deburr the terminal box with  $\varnothing$  20 mm for large grommets 75.
- Drill and deburr the terminal box with  $\varnothing$  8 mm for small grommet 74.

Two M4 threads are required in the motor flange Z 19 to screw the terminal box.

- Position the terminal box, transfer 5 mm and 8 mm holes in the bottom of the terminal box.
- Remove terminal box and punch holes.
- Drill and lower the fixing holes  $\varnothing$  3.3 mm and then cut M4 thread.
- Drill and deburr the hole for the cable entry  $\varnothing$  8 mm.
- Insert grommets 74 / 75 and M12 cable gland into the terminal box.
- Screw the terminal box with fastening screws M.




Fig. 13: Installation of Z-axis terminal box