

Change visual properties during a simulation

You will use the display changer to change the color of a part.

1. Open **mcd01_training_plant_f**.


2. Play the simulation to see the results and then stop the simulation.

The parts are carried down the conveyors until they fall to the floor. The **base motor** uses a time based operation and is active until it reaches the defined location. The **arm motor** does not activate to push the parts into the **bin**.

3. Choose **Home** tab→**Electrical** group→**Collision Sensor** .

4. In the graphics window, select **MCD01_RECTANGLE_SINK**.


Note The collision sensor is placed where you want to trigger the change.




5. In the **Name** box, type **display sensor**, and then click **OK**.

6. Choose **Home** tab→**Mechanical** group→**Display Changer** .

7. In the graphics window, select **display sensor**.



8. In the **Name** box, type **display change color**, and then click **OK**.
9. Choose **Home** tab→**Automation** group→**Operation** .
10. In the **Type** group, from the list, select **Operation**.
11. In the **Physics Navigator**, under the **Sensors and Actuators** node, select **display change color**.
12. In the **Runtime Parameter** group, set the following:
- **execute mode** check box = ☒
 - **execute mode** value = **Always**
 - **color** check box = ☒
13. In the **Edit Parameter** group, click the color swatch.
14. In the **Color** dialog box, in the **ID** box, type **186**, and then press Enter.
15. Click **OK**.
16. In the **Name** box, type **change operation**, and then click **OK**.
17. Run the simulation to see the results and then stop the simulation.
- The parts are moved down the conveyors. The part changes color when the collision sensor triggers the display changer operation.
18. Close the part.