



# 40106 Switching - Grounded input true bypass onboard relay with strain relief


## COMPONENT SIDE VIEWS



Completed board, component side




Completed cuts with soldered links




2: Place (double) links and solder.


## TRACE SIDE VIEWS



Completed board, trace side



3: Verify continuity for all



1: Cut board and make trace cuts.

### Special notes:

Notice cut between 40106 pin 10 and CLR

Vero size: 13 x 19  
Number of cuts: 14  
Number of links: 14

### Revision notes:

Removed unnecessary cut at transistor  
Changed position of links  
Changed electrolytic cap mounting orientation

### Bill of materials:

R1: 1M C1: 4.7n  
R2: 100k C2: 47n  
R3: 6k8 C3: 100u / 25V  
R4: 150k Q1: 2N3904  
R5: 15k Q2: 2N3906  
R6: 47R D1: 1N4148

IC1: CD40107 / HEF40106  
K1: AL5WN-K, EA2-5SNJ or other  
DIP single coil latching DPDT relay

AL5WN-K pinout:  
SET = 1+ / 10-  
RESET = 10+ / 1-  
COM = 3, 8  
NC = 2, 9 (RESET STATE)  
NO = 4, 7 (RESET STATE)

40106 pinout:  
INPUT = 1, 3, 5, 9, 11, 13  
OUTPUT = 2, 4, 6, 8, 10, 12  
VDD = 14  
VSS = 7

### Rev. 1 prototype notes:

Due to IC1 not getting proper supply voltage, a 100 uF capacitor was soldered on the trace side.  
This capacitor may affect functionality - IT IS NOT ON THE SCHEMATIC OR LAYOUT!

100n and 200n caps were replaced with 4n7 and 47n for proper switching action