

# ILOC Faulty Trip Supervision Relay


HOL011 ILOC DEF/OOC during Feeder OCEF Injection

Dated 14/07/2023


**Karl M.H. LAI**

# Background



- On 14/07/2023, SCE informed that **ILOC DEF/OOC alarm** was activated during **11kV Feeder OCEF Injection Test**.
- The alarm was NOT activated with **10s delay** (for BBP lockout relay) due to prolonged injection.
- After site investigation, it was discovered that **BBP Trip Supply Supervision LED blinked** when site engineers (NR) performed OCEF timing test.
- There was **NO lockout** activated during the injection.
- The ILOC DEF/OOC alarm was activated due to **bad contact** of trip supply supervision relay MVUA11.




Bad Contact of MVUA11 Relay  
(Contact 5-7, 9-11 in Closed Status)



# ILOC Normal Condition with Feeder OCEF Activated




# ILOC with Feeder OCEF Injection




After **OC3 START** operated, no contact will be reconnected for BBP Blocking Relay.  
 → Breaking of P91 – P97 path


# ILOC with Feeder OCEF Injection





Before BBP Blocking Relay De-energized -



After BBP Blocking Relay De-energized -



# ILOC with Feeder OCEF Injection



\* 01, 69534    011 BB \_BBP  
 Composite ID: HOL.019.BB.\_BBP  
 Area : Dist+Tuen Mun    Default : PD  
 RTU 260    DI POINT 197    comments :  
 1. PROTN SUPPLY FAIL  
 2. LOCKOUT  
 3. OOC

RTS  
 STATUS: C  
 Picture : HOL


/ DEF/OOC

## Lockout Possibility –

1. BBP Blocking Relay (Broken P91 – P97)
2. WD due to faulty OCEF relay
3. VTS / DOC5 BLK REV TRIP

- **BBP DEF/OOC due to supply supervision** (only alarming purpose) does NOT affect the actual function of ILOC.
- It does NOT lead to lockout (from 5s to 10s).
- It just blinds the actual lockout alarm if any.

# ILOC with Prolonged Injection



### 11kV Ring Feeder (CT: 400/5)

OC3 START: **7.5A**, 0s


BFP1: 5A, 0.15s

After **OC3 START** operated, no contact will be reconnected for BBP Blocking Relay.

→ Breaking of P91 – P97 path


→ BI1 & BI3 for **Blocking DOC5 REV** will be initiated.

# ILOC with Prolonged Injection




## DOC5 BLK REV TRIP

(activated with broken P91-P97 path)  
in the **LOCKOUT** circuit will lead to lockout  
if it was activated continuously for **10s**.



**1. Leading to BBP Lockout and  
No further ILOC tripping  
(Require Hand Reset)**



**2. Leading to BBP DEF/OOC alarm**