


## Performance characteristic of Instrument :-

The problem with any measuring instrument is error. Hence it is necessary to select the appropriate instrument and measuring processor which minimize the error.



### Static characteristic :-

It is defined for the instrument used to measure the quantity which is independent of time.

#### Accuracy :-

The degree of closeness of measured quantity to the true value is known as accuracy.

$A_t = 5V \rightarrow$  True value

$A_m = 4.2V \rightarrow$  Measured value

4.8V

4.99V  $\rightarrow$  More accuracy

3.5V  $\rightarrow$  Least accuracy

#### Resolution :-

It is the smallest observable change in input then the instrument can response is called resolution.

Ex:- If  $9p$  is  $1V$  then  $o/p$  is  $2V$


1.1V	} 0.2V	2V
1.2V		2.5
1.3V		2.5
1.4V		3V

Here the observable change is 0.2V hence the resolution is 0.2V

$$R = \frac{\text{full scale scale Voltage}}{\text{total no. of divisions}}$$

→ A Zero (0) to 10V voltmeter with number of divisions of divisions of 100 and we can estimate  $1/10^{\text{th}}$  of the scale division very accurately?

$$R = \frac{10}{1000} = 0.01$$



### Precision:

The Most repeatable Value or reproducible value among a set of records is called precision.

Ex:-  $A_t = 10V$

$A_m = 9.1V, 9.2, 9.3, 9.4, 9.5 \rightarrow$  low precision, low accuracy

$9.9V, 9.9, 9.9, 9.7, 9.6 \rightarrow$  high precision, high accuracy

$9.1, 9.2, 9.2, 9.2, 9.6 \rightarrow$  low accuracy, high accuracy

$$P = 1 - \left| \frac{x_n - \bar{x}_n}{\bar{x}_n} \right|$$

P- precision

$x_n$  -  $n^{\text{th}}$  Value of measurement

$\bar{x}_n$  - Average set of recorded

precision is supporting characteristic of accuracy

The accurate instruments may be precise but precise will not conform any accuracy.



## Expected Value:-

The Most probable Value that calculation one should expect to measure.

The difference of Measured value to the true value is known as error

$$E = A_m - A_t$$

$E \rightarrow$  error

$A_m \rightarrow$  Measure Value,  $A_t \rightarrow$  true Value

$E$  is +ve when  $A_m > A_t$

$E$  is -ve when  $A_m < A_t$

Ex:-  $A_t = 5V$

$$A_m = 4.5$$

$$E = -0.5V$$

We have to add or subtract some Quantity to the measured value in order to get the true value is called as Correction factor ( $C_f$ )

If error +ve then  $C_f$  is -ve

If error -ve then  $C_f$  is +ve

Sensitivity:- It is defined as ratio of magnitude of output signal to magnitude of i/p signal.

$$S = \frac{\text{mag of o/p signal}}{\text{mag of i/p signal}}$$

When a small change in i/p will effect a large change in o/p signal, then the Instrument is called high sensitivity instrument

→ We always prefer high sensitivity instrument then we may not lose any accuracy

→ Sensitivity Can also be expressed as

$$S = \frac{I}{V}$$

$$S = 1/V/I$$

$$S = \frac{1}{I_{fSD}}$$

fSD:- full scale deflection Current

Sensitivity  $\uparrow$   $\rightarrow$  loading error  $\downarrow$   $\rightarrow$  Accuracy  $\uparrow$